

Unit Job History

| WO Open Date | Meter 1 | Meter 2 | Work Order | Job Code | Job Description | Date Completed | Job Location | Job Reason | Job Status | Total Cost |
|---|---------|---------|------------|------------|-----------------------------------|----------------------|--------------|------------|------------|------------|
| Unit No: Q1060 - 2007 JOHN DEERE 310SG | | | | | | | | | | |
| 02-Jul-2012 12 | 2,006 | 0 | 91209 | 02-032-004 | Clean Battery Cables and Ends | 17-Jul-2012 08:39:48 | BBKHOE | I | DON | 31.40 |
| 02-Jul-2012 12 | 2,006 | 0 | 91209 | 14-034-007 | Install Signaling Devices | 16-Jul-2012 15:00:00 | BBKHOE | I | DON | 299.88 |
| 02-Jul-2012 12 | 2,006 | 0 | 91209 | 14-052-003 | Install Radio Equipment | 16-Jul-2012 14:59:21 | BBKHOE | Q | DON | 819.44 |
| 02-Jul-2012 12 | 2,006 | 0 | 91209 | 14-059-002 | Install Pintle Hook Assembly | 17-Jul-2012 07:36:32 | BBKHOE | Q | DON | 171.70 |
| 02-Jul-2012 12 | 2,006 | 0 | 91209 | 14-063-003 | Install Transceiver - GPS Tracker | 09-Jul-2012 15:00:00 | BBKHOE | Y | DON | 61.06 |
| 02-Jul-2012 12 | 2,006 | 0 | 91209 | 24-310-003 | Repair Boom Pins | 10-Jul-2012 13:45:01 | BBKHOE | I | DON | 15.54 |
| 02-Jul-2012 12 | 2,006 | 0 | 91209 | 31-514 | Rotate Bucket | 17-Jul-2012 07:36:42 | BBKHOE | Q | DON | 90.77 |
| 02-Jul-2012 12 | 2,006 | 0 | 91209 | 38-100-001 | Service DO NOT USE - PMI Service | 10-Jul-2012 13:20:29 | BBKHOE | P | DON | 190.48 |
| 02-Jul-2012 12 | 2,006 | 0 | 91209 | 99-513 | Machine Attachment | 11-Jul-2012 09:00:00 | BWELD | N | DON | 238.00 |
| 25-Apr-2013 1 | 2,006 | 0 | 115232 | 02-310 | Clean Backhoe (Rubber Tire) | 26-Apr-2013 14:20:28 | BWASH | J | DON | 42.33 |
| 25-Apr-2013 1 | 2,006 | 0 | 115232 | 38-310 | Service Backhoe (Rubber Tire) | 10-May-2013 06:36:44 | BBKHOE | P | DON | 13.82 |
| 26-Apr-2013 1 | 2,006 | 0 | 115397 | 03-045-024 | Replace Seal - Crankshaft (Front) | 13-Jul-2013 08:56:09 | BBKHOE | I | DON | 637.86 |
| 26-Apr-2013 1 | 2,006 | 0 | 115397 | 03-065-007 | Replace Hoses & Fittings | 06-May-2013 13:23:42 | BBKHOE | I | DON | 593.57 |
| 26-Apr-2013 1 | 2,006 | 0 | 115397 | 03-310-003 | Replace Boom Pins | 13-Jul-2013 08:56:06 | BBKHOE | I | DON | 1,819.39 |
| 26-Apr-2013 1 | 2,006 | 0 | 115397 | 38-310 | Service Backhoe (Rubber Tire) | 13-Jul-2013 08:56:00 | BBKHOE | P | DON | 275.82 |
| 16-May-2013 (| 2,307 | 0 | 117113 | 03-065-007 | Replace Hoses & Fittings | 16-May-2013 17:00:00 | MPNOFC | B | DON | 61.86 |
| 21-Aug-2013 1 | 2,365 | 0 | 127810 | 24-030 | Repair Electrical Group | 21-Aug-2013 12:52:34 | BBKHOE | B | DON | 1,387.81 |
| 08-Oct-2013 0 | 2,365 | 0 | 133102 | 02-310 | Clean Backhoe (Rubber Tire) | 15-Apr-2014 10:31:28 | BWASH | J | DON | 93.30 |
| 08-Oct-2013 0 | 2,365 | 0 | 133102 | 24-030 | Repair Electrical Group | 19-Feb-2014 12:12:23 | BBKHOE | B | DON | 1,412.22 |
| 15-Apr-2014 1 | 2,395 | 0 | 154193 | 03-063-003 | Replace Transceiver - GPS Tracker | 14-Jul-2014 16:52:52 | BBKHOE | C | DON | 39.22 |
| 15-Apr-2014 1 | 2,395 | 0 | 154193 | 06-032-001 | Inspect Battery | 14-Jul-2014 16:53:08 | BBKHOE | I | DON | 79.37 |
| 15-Apr-2014 1 | 2,395 | 0 | 154193 | 24-002-029 | Repair Trim - Seat | 14-Jul-2014 16:53:21 | BBKHOE | I | DON | 176.60 |
| 15-Apr-2014 1 | 2,395 | 0 | 154193 | 24-034 | Repair Lighting System | 24-Apr-2014 14:16:36 | BBKHOE | I | DON | 407.24 |
| 15-Apr-2014 1 | 2,395 | 0 | 154193 | 24-310-016 | Repair Operator Controls | 14-Jul-2014 16:53:15 | BBKHOE | I | DON | 403.39 |
| 15-Apr-2014 1 | 2,395 | 0 | 154193 | 34-022-003 | Rescal Differential Carrier | 14-Jul-2014 16:57:41 | BBKHOE | I | DON | 2,760.44 |
| 15-Apr-2014 1 | 2,395 | 0 | 154193 | 38-100-PMA | Service A PMI | 24-Apr-2014 06:54:42 | BBKHOE | P | DON | 645.70 |
| 10-Feb-2015 0 | 2,664 | 0 | 190823 | 12-514 | Refinish Bucket | 10-Mar-2015 08:18:40 | BBODY | K | DON | 32.63 |
| 10-Feb-2015 0 | 2,664 | 0 | 190823 | 15-514 | Paint Prep Bucket | 10-Mar-2015 08:18:12 | BBODY | K | DON | 0.00 |
| 10-Feb-2015 0 | 2,664 | 0 | 190823 | 24-514-002 | Repair Shanks or Teeth | 10-Mar-2015 08:02:20 | BBKHOE | I | DON | 146.24 |

Unit Job History

| WO Open Date | Meter 1 | Meter 2 | Work Order | Job Code | Job Description | Date Completed | Job Location | Job Reason | Job Status | Total Cost |
|---|---------|---------|------------|------------|---|----------------------|--------------|------------|------------|------------|
| Unit No: Q1060 - 2007 JOHN DEERE 310SG | | | | | | | | | | |
| 10-Feb-2015 0 | 2,664 | 0 | 190823 | 38-032 | Service Cranking System | 10-Mar-2015 06:49:47 | BBKHoe | P | DON | 189.63 |
| 10-Feb-2015 0 | 2,664 | 0 | 190823 | 38-100-PMA | Service A PMI | 10-Mar-2015 06:49:42 | BBKHoe | P | DON | 898.55 |
| 18-Mar-2015 1 | 2,664 | 0 | 195049 | 03-063-003 | Replace Transceiver - GPS Tracker | 18-Mar-2015 17:06:12 | GPSINS | Q | DON | 283.94 |
| 28-Apr-2015 0 | 2,665 | 0 | 199144 | 03-017-011 | Replace Tire - Foam Filled | 02-May-2015 08:35:34 | BBKHoe | N | DON | 34.13 |
| 28-Apr-2015 0 | 2,665 | 0 | 199144 | 24-310-016 | Repair Operator Controls | 02-May-2015 10:13:04 | BBKHoe | I | DON | 69.88 |
| 22-Jan-2016 1 | 2,665 | 0 | 230361 | 02-002 | Clean Cab & Sheet Metal | 25-Jan-2016 07:10:28 | BSETUP | J | DON | 95.23 |
| 01-Feb-2016 0 | 2,776 | 0 | 231647 | 03-065-007 | Replace Hoses & Fittings | 16-Feb-2016 14:12:32 | BBKHoe | I | DON | 380.68 |
| 01-Feb-2016 0 | 2,776 | 0 | 231647 | 03-310-007 | Replace Outrigger Pads | 17-Feb-2016 08:55:58 | BBKHoe | N | DON | 343.05 |
| 01-Feb-2016 0 | 2,776 | 0 | 231647 | 06-100-PMB | Inspect B PMI | 17-Feb-2016 08:55:38 | BBKHoe | P | DON | 196.25 |
| 01-Feb-2016 0 | 2,776 | 0 | 231647 | 11-310-016 | Rebuild Operator Controls | 17-Feb-2016 08:55:48 | BBKHoe | I | DON | 101.67 |
| 01-Feb-2016 0 | 2,776 | 0 | 231647 | 24-514 | Repair Bucket | 17-Feb-2016 08:55:43 | BBKHoe | N | DON | 751.72 |
| 01-Feb-2016 0 | 2,776 | 0 | 231647 | 25-052-003 | Remove Radio Equipment | 17-Feb-2016 08:55:53 | BBKHoe | Q | DON | 38.84 |
| 24-May-2016 1 | 2,776 | 0 | 245625 | 06-100-PMA | Inspect A PMI | 17-Feb-2016 08:55:53 | BBKHoe | P | CAN | 0.00 |
| 25-Aug-2016 0 | 2,776 | 0 | 257046 | 24-044-007 | Repair Throttle Controls | 20-Sep-2016 11:32:07 | MPNSHP | B | DON | 471.61 |
| 09-May-2017 1 | 2,805 | 0 | 288305 | 02-002 | Clean Cab & Sheet Metal | 11-May-2017 13:08:41 | BSETUP | J | DON | 72.05 |
| 09-May-2017 1 | 2,805 | 0 | 288305 | 06-100-PMA | Inspect A PMI | 17-Feb-2016 08:55:53 | BBKHoe | P | CAN | 0.00 |
| 09-May-2017 1 | 2,805 | 0 | 288305 | 14-027 | Install Transmission - Main, Automatic | 19-Jun-2017 16:14:14 | BBKHoe | U | DON | 530.67 |
| 09-May-2017 1 | 2,805 | 0 | 288305 | 25-027 | Remove Transmission - Main, Automatic | 24-Jul-2017 16:51:59 | BBKHoe | U | DON | 185.14 |
| 09-May-2017 1 | 2,805 | 0 | 288305 | 35-027 | Diagnose Transmission - Main, Automatic | 24-Jul-2017 16:51:20 | BBKHoe | O | DON | 17,286.87 |
| 09-May-2017 1 | 2,805 | 0 | 288305 | 35-037-001 | Diagnose Modules - Multiple Use | 24-Jul-2017 16:51:48 | BBKHoe | I | DON | 22.81 |
| 07-Aug-2017 1 | 2,805 | 0 | 299970 | 03-049-002 | Replace ECM Module | 26-Aug-2017 10:23:26 | BBKHoe | I | DON | 1,144.04 |
| 07-Aug-2017 1 | 2,805 | 0 | 299970 | 06-100-PMA | Inspect A PMI | 26-Aug-2017 10:23:19 | BBKHoe | P | DON | 197.88 |
| 18-Oct-2017 0 | 2,805 | 0 | 309551 | 06-042-002 | Inspect Radiator | 20-Oct-2017 07:51:38 | ME0546 | P | DON | 31.86 |
| 04-Jan-2018 0 | 2,805 | 0 | 319977 | 06-027 | Inspect Transmission - Main, Automatic | 18-Jan-2018 06:46:21 | MB2290 | I | DON | 84.26 |
| 12-Mar-2018 0 | 2,877 | 0 | 326918 | 06-100-PMA | Inspect A PMI | 05-Oct-2018 09:17:00 | BBKHoe | P | DON | 736.69 |
| 12-Mar-2018 0 | 2,877 | 0 | 326918 | 14-027 | Install Transmission - Main, Automatic | 05-Oct-2018 09:27:10 | BBKHoe | Q | DON | 17,993.71 |
| 12-Mar-2018 0 | 2,877 | 0 | 326918 | 14-514 | Install Bucket | 05-Oct-2018 09:27:20 | BBKHoe | Q | DON | 422.13 |
| 12-Mar-2018 0 | 2,877 | 0 | 326918 | 25-027 | Remove Transmission - Main, Automatic | 13-Sep-2018 05:50:48 | BBKHoe | I | DON | 1,142.24 |
| 12-Mar-2018 0 | 2,877 | 0 | 326918 | 25-063-003 | Remove Transceiver - GPS Tracker | 13-Mar-2018 07:28:55 | BBKHoe | Q | DON | 24.79 |

Unit Job History

| WO Open Date | Meter 1 | Meter 2 | Work Order | Job Code | Job Description | Date Completed | Job Location | Job Reason | Job Status | Total Cost |
|---|---------|---------|------------|------------|---|----------------------|--------------|------------|------------|------------|
| Unit No: Q1060 - 2007 JOHN DEERE 310SG | | | | | | | | | | |
| 12-Mar-2018 0 | 2,877 | 0 | 326918 | 35-027 | Diagnose Transmission - Main, Automatic | 05-Oct-2018 09:27:05 | BBKHOE | I | DON | 314.68 |
| 12-Mar-2018 0 | 2,877 | 0 | 326918 | 38-032 | Service Cranking System | 05-Oct-2018 09:27:00 | BBKHOE | I | DON | 159.96 |
| 18-Dec-2018 1 | 2,970 | 0 | 365257 | 03-310-017 | Replace Cutting Edges | 19-Dec-2018 13:56:14 | BBKHOE | I | DON | 537.68 |
| 18-Dec-2018 1 | 2,970 | 0 | 365257 | 06-042-003 | Inspect Fan | 26-Dec-2018 08:37:59 | BBKHOE | I | DON | 128.52 |
| 18-Dec-2018 1 | 2,970 | 0 | 365257 | 06-100-PMB | Inspect B PMI | 20-Dec-2018 07:13:42 | BBKHOE | P | DON | 565.35 |
| 18-Dec-2018 1 | 2,970 | 0 | 365257 | 15-310-013 | Paint Prep Implement | 19-Dec-2018 17:00:01 | BBKHOE | P | DON | 60.11 |
| 18-Dec-2018 1 | 2,970 | 0 | 365257 | 21-509 | Fabricate Guard | 19-Dec-2018 15:44:32 | BBKHOE | I | DON | 80.31 |
| 12-Feb-2019 0 | 2,984 | 0 | 372135 | 03-024 | Replace Driveshafts | 21-Feb-2019 07:04:21 | BBKHOE | B | DON | 656.83 |
| 23-Oct-2019 1 | 0 | 0 | 409041 | 06-100-PMB | Inspect B PMI | 31-Oct-2019 10:38:53 | FKVSHP | P | DON | 0.00 |
| 23-Oct-2019 1 | 0 | 0 | 409041 | 06-100-WIN | Inspect Winterization Inspection | 31-Oct-2019 10:38:56 | FKVSHP | P | DON | 0.00 |
| 23-Oct-2019 1 | 0 | 0 | 409041 | 38-100-PMB | Service B PMI | 24-Oct-2019 12:06:59 | FKVSHP | P | DON | 238.20 |
| 26-Jan-2021 1 | 0 | 0 | 484739 | 07-360 | Lubricate Loader / Skid-Steer | 01-Feb-2021 09:36:39 | FKVSHP | P | DON | 36.51 |
| 20-Apr-2021 1 | 0 | 0 | 501709 | 02-002 | Clean Cab & Sheet Metal | 26-May-2021 15:42:06 | FKVSHP | O | DON | 122.73 |
| 20-Apr-2021 1 | 0 | 0 | 501709 | 07-330 | Lubricate Excavator | 26-May-2021 12:06:50 | FKVSHP | O | DON | 185.14 |
| 20-Apr-2021 1 | 0 | 0 | 501709 | 24-002-037 | Repair Seat Assembly | 26-May-2021 14:02:11 | FKVSHP | I | DON | 261.40 |
| 20-Apr-2021 1 | 0 | 0 | 501709 | 24-034-014 | Repair Auxiliary Work / Flood Light | 21-Jun-2021 11:13:55 | FKVSHP | I | DON | 960.65 |
| 20-Apr-2021 1 | 0 | 0 | 501709 | 24-065-001 | Repair Hydraulic Systems | 23-Apr-2021 12:03:18 | FKVSHP | O | DON | 479.18 |
| 12-Aug-2021 1 | 0 | 0 | 524600 | 03-063-003 | Replace Transceiver - GPS Tracker | 02-Sep-2021 11:26:20 | FKVSHP | Q | DON | 327.21 |
| 11-Mar-2022 1 | 3,086 | 0 | 573893 | 03-051-009 | Replace Fire Extinguisher | 25-Mar-2022 11:31:55 | FKVSUP | I | DON | 25.66 |
| 11-Mar-2022 1 | 3,086 | 0 | 573893 | 06-100-PMB | Inspect B PMI | 25-Mar-2022 11:32:31 | FKVSHP | P | DON | 1.81 |
| 11-Mar-2022 1 | 3,086 | 0 | 573893 | 06-310-013 | Inspect Implement | 11-Mar-2022 14:18:30 | FKVSHP | I | DON | 44.22 |
| 11-Mar-2022 1 | 3,086 | 0 | 573893 | 38-100-PMB | Service B PMI | | FKVSHP | P | CAN | 0.00 |
| 11-May-2023 1 | 3,086 | 0 | 673752 | 03-051-009 | Replace Fire Extinguisher | 11-May-2023 14:08:01 | FKVSHP | Q | DON | 72.32 |
| 11-May-2023 1 | 3,086 | 0 | 673752 | 06-310 | Inspect Backhoe (Rubber Tire) | 11-May-2023 14:40:16 | FKVSHP | I | DON | 20.00 |
| 25-Apr-2024 0 | 3,086 | 0 | 755190 | 06-100-PMA | Inspect A PMI | | FKVSHP | P | CAN | 0.00 |
| 25-Apr-2024 0 | 3,086 | 0 | 755190 | 06-100-PMB | Inspect B PMI | 29-Apr-2024 09:53:37 | FKVSHP | P | DON | 0.00 |
| 25-Apr-2024 0 | 3,086 | 0 | 755190 | 24-032-001 | Repair Battery | 29-Apr-2024 09:53:45 | FKVSHP | N | DON | 269.09 |
| 10-May-2024 1 | 3,086 | 0 | 758910 | 06-310 | Inspect Backhoe (Rubber Tire) | 17-May-2024 13:35:42 | BBKHOE | P | DON | 41.55 |
| 10-May-2024 1 | 3,086 | 0 | 758910 | OS-310 | Out-Service Backhoe (Rubber Tire) | 17-May-2024 13:31:03 | BBKHOE | Z | DON | 181.71 |

Unit Job History

Unit No: Q1060 - 2007 JOHN DEERE 310SG

10-May-2024 | 3,086 | 0 | 758910 | 02-310 | Clean Backhoe (Rubber Tire) | 16-May-2024 10:41:22 | B WASH | Z | DON | 223.99

Unit No: Q1060 Count: 88 62,672.20