

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: A0626 - 2005 INTERNATIONAL 4300										
21-Dec-2009	42,214	0	35355	06-100-002	Inspect DO NOT USE - DOT Federal Insp	21-Dec-2009 15:24:58	BURNSV	P	DON	0.00
01-Dec-2010	56,252	0	54737	03-017-001	Replace Tire - Pneumatic	01-Dec-2010 07:44:14	BTIRE	F	DON	16.50
06-Dec-2010	56,252	0	55978	31-017-001	Rotate Tire - Pneumatic	06-Dec-2010 07:23:23	BTIRE	O	DON	16.50
13-Dec-2010	56,706	0	64166	06-100-002	Inspect DO NOT USE - DOT Federal Insp	13-Dec-2010 10:40:34	BVLOFC	P	DON	0.00
11-May-2011	58,429	0	65971	24-034-002	Repair Stop, Tail, Turn & License	11-May-2011 14:20:38	BVLOFC	B	DON	27.74
23-May-2011	58,429	0	65966	24-034-002	Repair Stop, Tail, Turn & License		BVLOFC	B	CAN	0.00
09-Nov-2011	68,351	0	88380	03-043-003	Replace Muffler	09-Nov-2011 06:00:00	BVLOFC	N	DON	20.40
09-Nov-2011	68,351	0	88380	03-043-007	Replace Exhaust Pipe/Elbow	09-Nov-2011 07:00:00	BVLOFC	N	DON	20.40
13-Dec-2011	69,503	0	86441	06-100-DOT	Inspect DOT Federal Inspection	13-Dec-2011 14:42:21	BVLOFC	P	DON	30.60
13-Dec-2011	69,503	0	86441	06-100-PMB	Inspect B PMI	13-Dec-2011 14:43:40	BVLOFC	P	DON	30.60
13-Dec-2011	69,503	0	86441	03-013-003	Replace Brake Chamber - Parking	13-Dec-2011 14:43:40	BVLOFC	N	DON	30.60
13-Dec-2011	69,503	0	86441	03-044-002	Replace Filters	13-Dec-2011 14:43:40	BVLOFC	P	DON	20.40
13-Dec-2011	69,503	0	86441	03-059-002	Replace Pintle Hook Assembly	13-Dec-2011 14:43:40	BVLOFC	N	DON	30.60
13-Dec-2011	69,503	0	86441	03-045	Replace Power Plant	13-Dec-2011 14:43:40	BVLOFC	N	DON	45.90
21-Jun-2012	73,098	0	97067	24-040	Repair Engine / Motor Systems Group	22-Jun-2012 17:11:20	BVLOFC	N	DON	720.66
17-Aug-2012	75,855	0	96179	03-017-001	Replace Tire - Pneumatic	17-Aug-2012 07:02:15	BTIRE	F	DON	620.85
06-Sep-2012	75,855	0	96553	03-017-001	Replace Tire - Pneumatic	06-Sep-2012 06:59:59	BTIRE	F	DON	1,045.83
19-Dec-2012	84,462	0	106105	03-044-002	Replace Filters	19-Dec-2012 08:19:46	BVLOFC	P	DON	10.20
19-Dec-2012	84,462	0	106105	06-100-DOT	Inspect DOT Federal Inspection	19-Dec-2012 08:20:39	BVLOFC	P	DON	20.40
19-Dec-2012	84,462	0	106105	06-100-PMB	Inspect B PMI	19-Dec-2012 08:18:39	BVLOFC	P	DON	10.20
19-Dec-2012	84,462	0	106105	24-043-004	Repair Turbocharger	19-Dec-2012 08:21:20	BVLOFC	N	DON	40.80
19-Dec-2012	84,462	0	106105	24-026-016	Repair Gear Shifter & Linkage	19-Dec-2012 08:27:03	BVLOFC	N	DON	20.40
19-Dec-2012	84,462	0	106105	01-013-013	Adjust Air Disc Brakes	19-Dec-2012 08:28:09	BVLOFC	N	DON	10.20
20-Dec-2012	84,468	0	110463	24-026-016	Repair Gear Shifter & Linkage	21-Dec-2012 14:39:41	BVLOFC	F	DON	264.98
20-Dec-2012	84,468	0	110463	03-065-031	Replace Seal / Gasket - Pump	21-Dec-2012 14:39:41	BVLOFC	F	DON	326.76
14-Jun-2013	91,536	0	123626	03-031-006	Replace Belt - Alternator	14-Jun-2013 11:43:50	BVLOFC	O	DON	22.99
06-Sep-2013	91,536	0	130820	03-063-003	Replace Transceiver - GPS Tracker	06-Sep-2013 00:00:00	BURNSV	C	DON	221.24
11-Dec-2013	101,063	0	143115	06-100-PMA	Inspect A PMI	11-Dec-2013 17:00:00	LAKEVL	P	DON	21.01
11-Dec-2013	101,063	0	143115	07-100-000	Lubricate On Road Equip / Field Service	11-Dec-2013 17:00:00	LAKEVL	P	DON	21.01

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: A0626 - 2005 INTERNATIONAL-4300										
11-Dec-2013	0	101,063	0	143115	06-100-DOT	Inspect DOT Federal Inspection	LAKEVL	P	DON	21.01
14-Mar-2014	0	105,111	0	153144	03-013-002	Replace Rear Brakes & Drums	LAKEVL	F	DON	147.30
17-Mar-2014	0	105,111	0	153140	03-026-009	Replace Cover Assembly	LAKEVL	I	DON	36.83
17-Mar-2014	0	105,111	0	153140	03-032-002	Replace Starter	LAKEVL	I	DON	73.65
02-Jun-2014	0	108,426	0	164813	03-013-024	Replace Air Tank (Pri / Sec / Wet)	LAKEVL	F	DON	73.65
30-Jun-2014	0	108,426	0	167966	03-002-024	Replace Glass / Windshield	BVLOFC	F	DON	324.20
11-Jul-2014	06	108,426	0	167975	03-002-024	Replace Glass / Windshield	BVLOFC	F	DON	324.20
17-Jul-2014	06	110,826	0	168802	03-013-010	Replace Air Brake Valve	LAKEVL	F	DON	73.65
29-Aug-2014	0	112,834	5,320	170876	08-045	Overhaul Power Plant	BTRUCK	I	DON	9,708.63
29-Sep-2014	0	112,834	5,320	181138	20-MSC-004	Tow Travel Time - To/From Job Site	BVLOFC	F	DON	518.70
01-Oct-2014	0	112,834	5,320	174193	03-045-009	Replace Oil Pump & Distribution System	BTRUCK	I	DON	2,383.57
23-Dec-2014	0	117,723	5,320	185608	03-043-004	Replace Turbocharger	BTRUCK	I	DON	3,005.82
29-Dec-2014	1	117,723	5,320	185856	09-015	Align Steering	BTRUCK	I	CAN	0.00
08-Jan-2015	0	117,768	5,320	200081	06-100-DOT	Inspect DOT Federal Inspection	LAKEVL	P	DON	0.00
18-Dec-2015	1	134,608	6,662	226090	01-023	Adjust Clutch	BTRUCK	I	DON	83.08
18-Dec-2015	1	134,608	6,662	226090	02-002	Clean Cab & Sheet Metal	BSETUP	J	DON	207.32
18-Dec-2015	1	134,608	6,662	226090	03-002-009	Replace Sun Visor	BTRUCK	I	DON	317.04
18-Dec-2015	1	134,608	6,662	226090	03-013-001	Replace Front Brakes & Drums	BTRUCK	I	DON	581.10
18-Dec-2015	1	134,608	6,662	226090	03-013-004	Replace Brake Chamber - Service	BTRUCK	I	DON	159.77
18-Dec-2015	1	134,608	6,662	226090	03-013-010	Replace Air Brake Valve	BTRUCK	I	DON	111.87
18-Dec-2015	1	134,608	6,662	226090	03-013-011	Replace Anti-Lock Sensor Assembly	BTRUCK	I	DON	283.93
18-Dec-2015	1	134,608	6,662	226090	03-013-016	Replace Air Dryer / Purge Valve	BTRUCK	I	DON	277.95
18-Dec-2015	1	134,608	6,662	226090	03-013-035	Replace Clevis Pins	BTRUCK	I	DON	199.32
18-Dec-2015	1	134,608	6,662	226090	03-024-005	Replace Universal Joint	BTRUCK	I	DON	264.62
18-Dec-2015	1	134,608	6,662	226090	03-032-001	Replace Battery	BTRUCK	I	DON	598.28
18-Dec-2015	1	134,608	6,662	226090	03-042-009	Replace Coolant Pre-Heater- Electrical	BTRUCK	I	DON	311.29
18-Dec-2015	1	134,608	6,662	226090	03-044-001	Replace Tank - Fuel, Liquid	BTRUCK	I	DON	71.22
18-Dec-2015	1	134,608	6,662	226090	03-051-009	Replace Fire Extinguisher	BTRUCK	P	CAN	0.00
18-Dec-2015	1	134,608	6,662	226090	03-053-005	Replace Markings - Vehicle - Decals	BSETUP	J	DON	14.52

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: A0626 - 2005 INTERNATIONAL 4300										
18-Dec-2015 1	134,608	6,662	226090	03-078-009	Replace Mud Flaps and Hanger Brackets	01-Mar-2016 11:35:22	BTRUCK	I	DON	129.17
18-Dec-2015 1	134,608	6,662	226090	06-100-DOT	Inspect DOT Federal Inspection	07-Mar-2016 08:30:39	BTRUCK	P	DON	0.00
18-Dec-2015 1	134,608	6,662	226090	06-100-PMB	Inspect B PMI	01-Mar-2016 11:35:20	BTRUCK	P	DON	1,172.45
18-Dec-2015 1	134,608	6,662	226090	12-002	Refinish Cab & Sheet Metal	28-Mar-2016 12:16:06	BBODY	C	DON	421.92
18-Dec-2015 1	134,608	6,662	226090	12-071-001	Refinish Floor / Decking / Flatbed	26-Mar-2016 10:01:20	BBODY	C	DON	967.50
18-Dec-2015 1	134,608	6,662	226090	14-034-002	Install Stop, Tail, Turn & License	12-Apr-2016 07:55:15	BTRUCK	C	DON	860.43
18-Dec-2015 1	134,608	6,662	226090	14-051-009	Install Fire Extinguisher	12-Apr-2016 08:12:28	BTRUCK	I	DON	9.58
18-Dec-2015 1	134,608	6,662	226090	14-079-009	Install Tape - Reflective, Conspicuity	11-Apr-2016 17:02:47	BTRUCK	I	DON	89.32
18-Dec-2015 1	134,608	6,662	226090	15-002	Paint Prep Cab & Sheet Metal	29-Mar-2016 10:32:42	BBODY	C	DON	1,086.34
18-Dec-2015 1	134,608	6,662	226090	15-071-001	Paint Prep Floor / Decking / Flatbed	29-Mar-2016 09:59:09	BSAND	C	DON	585.42
18-Dec-2015 1	134,608	6,662	226090	21-519-003	Fabricate Hitch Assembly	27-Apr-2016 13:12:03	BWELD	C	DON	1,037.42
18-Dec-2015 1	134,608	6,662	226090	24-001-002	Repair Heating & Ventilating	01-Mar-2016 11:36:10	BTRUCK	I	DON	56.76
18-Dec-2015 1	134,608	6,662	226090	24-002-010	Repair Mirrors	01-Mar-2016 11:36:07	BTRUCK	I	DON	99.91
18-Dec-2015 1	134,608	6,662	226090	24-023	Repair Clutch	01-Mar-2016 11:36:16	BTRUCK	I	DON	38.13
18-Dec-2015 1	134,608	6,662	226090	24-034-003	Repair Signal, Parking, Backup Lamps	01-Mar-2016 11:35:50	BTRUCK	I	DON	384.30
18-Dec-2015 1	134,608	6,662	226090	24-034-010	Repair Socket - Trailer Light Cord	11-Apr-2016 06:39:48	BTRUCK	I	DON	31.71
18-Dec-2015 1	134,608	6,662	226090	24-044-014	Repair Injectors - Electronic	01-Mar-2016 11:35:30	BTRUCK	I	DON	2,960.97
18-Dec-2015 1	134,608	6,662	226090	24-045	Repair Power Plant	01-Mar-2016 11:35:33	BTRUCK	I	DON	3,207.22
18-Dec-2015 1	134,608	6,662	226090	34-026-016	Reseal Gear Shifter & Linkage	01-Mar-2016 11:35:36	BTRUCK	I	DON	200.88
03-Jun-2016 1	134,608	6,662	246869	24-054-001	Repair Horn & Mounting	03-Jun-2016 12:25:20	LAVSHP	I	DON	18.17
25-Aug-2016 C	139,466		258681	03-013-007	Replace Brake Lines & Fittings - Hydraulic & A	26-Aug-2016 07:00:00	LAVSHP	N	DON	22.36
25-Aug-2016 C	139,466		258681	07-100-000	Lubricate On Road Equip / Field Service	25-Aug-2016 07:00:00	LAVSHP	R	DON	22.36
25-Aug-2016 C	139,466		258681	06-100-PMA	Inspect A PMI	25-Aug-2016 07:00:00	LAVSHP	P	DON	22.36
28-Oct-2016 0'	143,101		267018	06-100-PMA	Inspect A PMI	28-Oct-2016 07:00:00	LAVSHP	P	DON	11.18
28-Oct-2016 0'	143,101		267018	07-100-000	Lubricate On Road Equip / Field Service	28-Oct-2016 07:00:00	LAVSHP	R	DON	22.36
28-Oct-2016 0'	143,101		267018	03-044-002	Replace Filters	28-Oct-2016 07:00:00	LAVSHP	P	DON	5.59
28-Oct-2016 0'	143,101		267018	03-044-024	Replace Fuel / Water Separator	28-Oct-2016 07:00:00	LAVSHP	P	DON	5.59
01-Nov-2016 1	143,103		265201	03-044-014	Replace Injectors - Electronic	01-Nov-2016 16:42:16	BTRUCK	I	DON	1,280.20
06-Jan-2017 0'	145,868		272139	03-044-018	Replace Fuel Hose / Line	06-Jan-2017 08:30:39	ROGSHP	I	DON	57.87

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: A0626 - 2005 INTERNATIONAL 4300										
06-Jan-2017 0:	145,868		272139	06-040	Inspect Engine / Motor Systems Group	06-Jan-2017 08:05:16	ROGSHP	B	DON	28.66
23-Feb-2017 1:	147,636		278530	03-017-001	Replace Tire - Pneumatic	24-Feb-2017 10:23:16	ROGSHP	J	DON	1,713.81
23-Feb-2017 1:	147,636		278530	06-013-001	Inspect Front Brakes & Drums	24-Feb-2017 12:52:31	ROGSHP	B	DON	22.73
23-Feb-2017 1:	147,636		278530	06-100-DOT	Inspect DOT Federal Inspection	24-Feb-2017 13:37:41	BURNSV	P	DON	94.83
23-Feb-2017 1:	147,636		278530	03-018-011	Replace Seal - Wheel	24-Feb-2017 15:45:33	ROGSHP	I	DON	118.67
23-Feb-2017 1:	147,636		278530	03-034-004	Replace Clearance & Marker Lamps	24-Feb-2017 13:35:01	ROGSHP	I	DON	14.05
23-Feb-2017 1:	147,636		278530	14-053-004	Install Safety Equipment	24-Feb-2017 13:41:13	ROGSHP	I	DON	17.61
23-Feb-2017 1:	147,636		278530	06-013-013	Inspect Air Disc Brakes	27-Feb-2017 07:21:50	ROGSHP	B	DON	18.33
23-Mar-2017 1:	148,402	7,431	282422	03-041-001	Replace Air Cleaner	24-Mar-2017 11:42:59	ROGSHP	P	DON	48.11
23-Mar-2017 1:	148,402	7,431	282422	03-100-PMB	Replace B PMI	24-Mar-2017 11:37:01	ROGSHP	P	DON	62.33
23-Mar-2017 1:	148,402	7,431	282422	06-100-PMA	Inspect A PMI		ROGSHP	P	CAN	0.00
07-Apr-2017 1:	149,032	7,432	284356	14-030	Install Electrical Group	14-Apr-2017 11:55:51	ROGSHP	B	DON	315.01
07-Apr-2017 1:	149,032	7,432	284356	24-026-012	Repair Transmission Assembly - Manual	16-May-2017 09:53:51	ROGSHP	B	DON	5,440.26
07-Apr-2017 1:	149,032	7,432	284356	03-045-009	Replace Oil Pump & Distribution System	14-Apr-2017 15:14:51	ROGSHP	P	DON	92.63
07-Apr-2017 1:	149,032	7,432	284356	35-040	Diagnose Engine / Motor Systems Group	16-May-2017 09:53:57	ROGSHP	B	DON	541.78
07-Apr-2017 1:	149,032	7,432	284356	03-017-001	Replace Tire - Pneumatic	18-Apr-2017 16:10:26	ROGSHP	B	DON	425.69
07-Apr-2017 1:	149,032	7,432	284356	06-013-001	Inspect Front Brakes & Drums		ROGSHP	O	CAN	0.00
07-Apr-2017 1:	149,032	7,432	284356	03-023-004	Replace Clutch Disc	16-May-2017 09:54:01	ROGSHP	B	DON	1,035.42
07-Apr-2017 1:	149,032	7,432	284356	03-044-014	Replace Injectors - Electronic	16-May-2017 09:54:17	ROGSHP	B	DON	1,795.76
07-Apr-2017 1:	149,032	7,432	284356	35-026-001	Diagnose Transmission Case	16-May-2017 09:54:09	ROGSHP	B	DON	138.52
07-Apr-2017 1:	149,032	7,432	284356	03-045-025	Replace Seal - Crankshaft (Rear)	16-May-2017 09:54:05	ROGSHP	B	DON	404.95
07-Apr-2017 1:	149,032	7,432	284356	01-056-003	Adjust Powershift PTO	16-May-2017 09:54:22	ROGSHP	B	DON	96.52
16-Aug-2017 C	150,897	7,457	301289	03-013-010	Replace Air Brake Valve	16-Aug-2017 11:20:10	ROGSHP	B	DON	275.89
27-Sep-2017 0:	150,897	7,457	306603	06-300	Inspect Heavy Equipment Group	27-Sep-2017 14:40:14	ROGSHP	Q	DON	4.58
27-Sep-2017 1:	150,984		306692	24-002-020	Repair Side Door Mechanism	29-Sep-2017 13:08:25	LAVSHP	B	DON	430.81
29-Nov-2017 C	153,983	7,669	313982	03-034-020	Replace Dome / Reading Light	01-Dec-2017 14:11:51	ROGSHP	B	DON	42.18
29-Nov-2017 C	153,983	7,669	313982	24-034-004	Repair Clearance & Marker Lamps	29-Nov-2017 07:06:21	ROGSHP	B	DON	18.49
06-Feb-2018 1:	154,714		322567	06-100-DOT	Inspect DOT Federal Inspection	06-Feb-2018 16:51:31	LAVSHP	P	DON	49.05
06-Feb-2018 1:	154,714		322567	06-100-PMA	Inspect A PMI	06-Feb-2018 18:29:51	LAVSHP	P	DON	203.62

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: A0626 - 2005 INTERNATIONAL 4300										
06-Feb-2018	1	154,714	322567	06-032-001	Inspect Battery	07-Feb-2018 08:55:36	LAVSHP	P	DON	38.24
06-Feb-2018	1	154,714	322567	03-032-001	Replace Battery	07-Feb-2018 11:13:18	LAVSHP	I	DON	475.04
06-Feb-2018	1	154,714	322567	03-045-020	Replace Engine Assembly	15-Feb-2018 13:37:51	LAVSHP	I	DON	462.62
06-Feb-2018	1	154,714	322567	03-002-069	Replace Support Hood Lift-Gas Charged	15-Feb-2018 14:13:55	LAVSHP	I	DON	88.37
16-Jul-2018	11	157,195	343912	03-034-010	Replace Socket - Trailer Light Cord	16-Jul-2018 12:29:31	ROGSHP	O	DON	26.10
31-Aug-2018	1	157,944	350604	03-031-001	Replace Generator/Alternator	05-Sep-2018 08:28:59	LAVSHP	O	DON	27.83
31-Aug-2018	1	157,944	350604	11-031-001	Rebuild Generator/Alternator	01-Oct-2018 13:56:04	LAVSHP	B	DON	90.24
31-Aug-2018	1	157,944	350604	24-002-023	Repair Handles - Inner & Outer	31-Aug-2018 12:05:40	LAVSHP	O	DON	47.61
11-Oct-2018	1	158,941	356212	03-034-010	Replace Socket - Trailer Light Cord	11-Oct-2018 15:53:13	ROGSHP	N	DON	37.68
11-Oct-2018	1	158,941	356212	24-034-004	Repair Clearance & Marker Lamps	11-Oct-2018 15:24:12	ROGSHP	N	DON	34.24
16-Jan-2019	1	162,394	368599	03-045-025	Replace Seal - Crankshaft (Rear)	26-Feb-2019 10:06:41	ROGSHP	N	DON	3,973.44
16-Jan-2019	1	162,394	368599	06-100-DOT	Inspect DOT Federal Inspection	16-Jan-2019 14:56:20	ROGSHP	P	DON	60.85
16-Jan-2019	1	162,394	368599	03-002-035	Replace Windshield Wiper & Washer	16-Jan-2019 16:06:47	ROGSHP	I	DON	30.12
16-Jan-2019	1	162,394	368599	03-041-007	Replace Filter - Outer	16-Jan-2019 16:03:20	ROGSHP	P	DON	42.82
16-Jan-2019	1	162,394	368599	03-043-003	Replace Muffler	18-Jan-2019 18:34:08	ROGSHP	I	DON	448.37
16-Jan-2019	1	162,394	368599	07-100-PMA	Lubricate A PMI	16-Jan-2019 16:01:10	ROGSHP	P	DON	53.69
16-Jan-2019	1	162,394	368599	07-100-PMB	Lubricate B PMI	16-Jan-2019 17:03:49	ROGSHP	P	DON	65.16
16-Jan-2019	1	162,394	368599	03-053-017	Replace First Aid Kit	16-Jan-2019 16:08:30	ROGSHP	I	DON	27.94
16-Jan-2019	1	162,394	368599	03-034-010	Replace Socket - Trailer Light Cord	16-Jan-2019 17:56:37	ROGSHP	P	DON	47.45
16-Jan-2019	1	162,394	368599	24-034-004	Repair Clearance & Marker Lamps	16-Jan-2019 16:11:06	ROGSHP	I	DON	14.86
16-Jan-2019	1	162,394	368599	24-043-007	Repair Exhaust Pipe/Elbow	18-Jan-2019 18:13:44	ROGSHP	I	DON	727.45
16-Jan-2019	1	162,394	368599	03-017-001	Replace Tire - Pneumatic	20-Feb-2019 08:25:00	ROGSHP	I	DON	641.53
16-Jan-2019	1	162,394	368599	02-040	Clean Engine / Motor Systems Group	02-Apr-2019 09:39:34	ROGSHP	Q	DON	76.93
16-Jan-2019	1	162,394	368599	35-040	Diagnose Engine / Motor Systems Group	02-Apr-2019 09:39:48	ROGSHP	Q	DON	306.51
16-Jan-2019	1	162,394	368599	24-706-003	Repair Wiring	02-Apr-2019 09:39:55	ROGSHP	N	DON	268.25
16-Jan-2019	1	162,394	368599	24-034-001	Repair Headlamps / Fog Lamps	02-Apr-2019 09:40:01	ROGSHP	N	DON	76.54
16-Jan-2019	1	162,394	368599	24-044	Repair Fuel System	02-Apr-2019 09:40:06	ROGSHP	N	DON	1,288.89
30-Sep-2019	1	165,780	405148	14-062-003	Install Compressor Assembly	30-Sep-2019 14:09:47	ROGSHP	O	DON	29.25
02-Dec-2019	1	166,185	414847	03-013-002	Replace Rear Brakes & Drums	09-Dec-2019 09:09:35	ROGSHP	I	DON	1,420.23

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: A0626 - 2005 INTERNATIONAL 4300										
02-Dec-2019	166,185		414847	03-022-008	Replace Pinion Seal	09-Dec-2019 09:09:15	ROGSHP	I	DON	416.00
02-Dec-2019	166,185		414847	24-024	Repair Driveshafts	09-Dec-2019 09:10:52	ROGSHP	I	DON	591.49
02-Dec-2019	166,185		414847	24-056-003	Repair Powershift PTO	09-Dec-2019 09:10:13	ROGSHP	I	DON	548.09
02-Dec-2019	166,185		414847	06-100-DOT	Inspect DOT Federal Inspection	02-Dec-2019 18:56:10	ROGSHP	P	DON	35.81
17-Jan-2020	166,776		421538	03-034-004	Replace Clearance & Marker Lamps	17-Jan-2020 08:24:35	ROGSHP	N	DON	21.46
09-Apr-2020	167,794		435143	24-072-006	Repair Door Latch Mechanism	09-Apr-2020 08:32:43	ROGSHP	O	DON	62.88
09-Apr-2020	167,794		435143	03-018-011	Replace Seal - Wheel	09-Apr-2020 09:29:31	ROGSHP	N	DON	102.32
15-May-2020	168,778		441001	01-023	Adjust Clutch	15-May-2020 11:59:01	ROGSHP	O	DON	17.04
26-May-2020	168,856	8,717	442265	03-023-002	Replace Clutch Assembly	26-May-2020 09:13:12	LAVSHP	B	DON	3,441.86
26-May-2020	168,856	8,717	442265	03-043-007	Replace Exhaust Pipe/Elbow	26-May-2020 09:13:09	LAVSHP	I	DON	1,027.67
26-May-2020	168,856	8,717	442265	12-045-004	Refinish Flywheel	26-May-2020 09:13:15	LAVSHP	B	DON	143.52
05-Aug-2020	169,425		454403	06-100-PMA	Inspect A PMI	05-Aug-2020 13:11:25	ROGSHP	P	DON	13.62
05-Aug-2020	169,425		454403	03-002-035	Replace Windshield Wiper & Washer	05-Aug-2020 15:25:03	ROGSHP	I	DON	33.07
05-Aug-2020	169,425		454403	38-100-PMA	Service A PMI	05-Aug-2020 15:18:45	ROGSHP	P	DON	242.11
05-Aug-2020	169,425		454403	24-044	Repair Fuel System	05-Aug-2020 15:40:51	ROGSHP	I	DON	135.46
09-Sep-2020	169,656		460379	01-023	Adjust Clutch	14-Sep-2020 09:50:50	ROGSHP	O	DON	28.68
09-Nov-2020	170,866	8,767	470979	03-045-023	Replace Engine Belts	09-Nov-2020 15:42:24	ROGSHP	I	DON	156.32
09-Nov-2020	170,866	8,767	470979	03-045-026	Replace Tensioner - Engine Belts	09-Nov-2020 13:30:59	ROGSHP	I	DON	211.59
09-Nov-2020	170,866	8,767	470979	06-100-DOT	Inspect DOT Federal Inspection	09-Nov-2020 09:40:46	ROGSHP	P	DON	37.94
09-Nov-2020	170,866	8,767	470979	24-034-002	Repair Stop, Tail, Turn & License	09-Nov-2020 09:49:26	ROGSHP	I	DON	5.77
09-Nov-2020	170,866	8,767	470979	24-034-006	Repair Warning Lamps - Special Application	09-Nov-2020 11:23:11	ROGSHP	I	DON	236.95
09-Nov-2020	170,866	8,767	470979	24-045-010	Repair Oil Filler & Level Indicator	09-Nov-2020 12:02:05	ROGSHP	I	DON	9.07
09-Nov-2020	170,866	8,767	470979	24-056-003	Repair Powershift PTO	09-Nov-2020 13:19:56	ROGSHP	I	DON	36.09
07-Dec-2020	171,123		475573	14-053-005	Install Markings - Vehicle - Decals	07-Dec-2020 12:26:06	ROGSHP	Q	DON	40.71
11-Mar-2021	171,446		493418	03-059-006	Replace Towing Hitch Assembly	11-Mar-2021 10:46:00	ROGSHP	I	DON	414.23
11-Mar-2021	171,446		493418	06-100-PMIB	Inspect B PMI	11-Mar-2021 10:02:34	SCHED	P	DON	52.99
11-Mar-2021	171,446		493418	14-053-013	Install Permit Holder	11-Mar-2021 10:49:14	ROGSHP	I	DON	11.83
11-Mar-2021	171,446		493418	24-026	Repair Transmission - Main, Manual	11-Mar-2021 15:56:05	ROGSHP	I	DON	265.03
17-Nov-2021	175,624		547464	07-040	Lubricate Engine / Motor Systems Group	17-Nov-2021 13:21:05	OTSSHP	P	DON	19.65

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: A0626 - 2005 INTERNATIONAL 4300										
17-Nov-2021	175,624		547464	06-100-DOT	Inspect DOT Federal Inspection	18-Nov-2021 17:01:28	OTSSHP	P	DON	82.33
17-Nov-2021	175,624		547464	06-100-PMA	Inspect A PMI	18-Nov-2021 16:14:54	OTSSHP	P	DON	24.99
17-Nov-2021	175,624		547464	03-034-002	Replace Stop, Tail, Turn & License	19-Nov-2021 08:32:35	OTSSHP	I	DON	4.47
17-Nov-2021	175,624		547464	01-002-064	Adjust Washer Fluid Reservoir	18-Nov-2021 16:16:57	OTSSHP	I	DON	1.50
17-Nov-2021	175,624		547464	07-510-002	Lubricate Tool Box	19-Nov-2021 09:48:04	OTSSHP	I	DON	55.31
17-Nov-2021	175,624		547464	24-510-002	Repair Tool Box	19-Nov-2021 09:49:11	OTSSHP	I	DON	17.47
09-Dec-2021	175,624		552353	03-051-009	Replace Fire Extinguisher	09-Dec-2021 08:13:11	OTSSHP	N	DON	71.63
01-Jun-2022	175,624		592759	03-063-003	Replace Transceiver - GPS Tracker	01-Jun-2022 14:36:59	ELEC02	Q	DON	625.79
30-Aug-2022	176,585	9,184	613080	03-032-001	Replace Battery	30-Aug-2022 13:40:24	OTSSHP	I	DON	354.82
09-Sep-2022	176,585	9,184	615157	01-042-014	Adjust Coolant Overflow Reservoir	14-Sep-2022 06:16:33	OTSSHP	O	DON	10.20
09-Sep-2022	176,585	9,184	615157	06-042	Inspect Cooling System	09-Sep-2022 15:27:26	OTSSHP	O	DON	75.25
01-Nov-2022	177,231		628723	03-053-017	Replace First Aid Kit	01-Nov-2022 12:26:37	OTSSHP	Q	DON	54.80
01-Nov-2022	177,231		628723	06-100-DOT	Inspect DOT Federal Inspection	01-Nov-2022 12:18:13	OTSSHP	P	DON	38.17
01-Nov-2022	177,231		628723	14-062	Install Mobile Air Compressor	01-Nov-2022 11:06:07	OTSSHP	O	DON	55.20
15-Nov-2022	177,234		632466	07-040	Lubricate Engine / Motor Systems Group	15-Nov-2022 06:17:32	OTSSHP	O	DON	32.71
15-Nov-2022	177,234		632466	06-100-PMA	Inspect A PMI	15-Nov-2022 07:43:56	OTSSHP	P	DON	13.92
28-Nov-2022	177,393	9,235	635227	06-706-001	Inspect Engine	30-Nov-2022 14:15:00	OTSSHP	O	DON	74.55
28-Nov-2022	177,393	9,235	635227	24-706-001	Repair Engine	08-Dec-2022 14:12:00	OTSSHP	B	DON	8,312.27
05-May-2023	178,626	9,277	672543	01-042-014	Adjust Coolant Overflow Reservoir	05-May-2023 11:47:18	OTSSHP	O	DON	20.47
25-May-2023	178,628	9,394	676882	03-013-024	Replace Air Tank (Pri / Sec / Wet)	12-Jun-2023 06:20:12	OTSSHP	I	DON	1,549.13
25-May-2023	178,628	9,394	676882	03-014-005	Replace Battery Support / Battery Box	08-Jun-2023 10:40:00	OTSSHP	I	DON	768.26
25-May-2023	178,628	9,394	676882	03-032-001	Replace Battery	25-May-2023 12:01:58	OTSSHP	I	DON	347.00
25-May-2023	178,628	9,394	676882	06-023	Inspect Clutch	12-Jun-2023 08:52:58	OTSSHP	O	DON	20.91
25-May-2023	178,628	9,394	676882	06-032-001	Inspect Battery	25-May-2023 09:25:29	OTSSHP	O	DON	30.90
25-May-2023	178,628	9,394	676882	24-034-004	Repair Clearance & Marker Lamps	12-Jun-2023 08:27:07	OTSSHP	I	DON	75.20
24-Oct-2023	178,860	9,412	715270	03-013-003	Replace Brake Chamber - Parking	01-Nov-2023 10:49:43	OTSSHP	I	DON	139.65
24-Oct-2023	178,860	9,412	715270	03-051-009	Replace Fire Extinguisher	31-Oct-2023 15:39:07	OTSSHP	Q	DON	64.54
24-Oct-2023	178,860	9,412	715270	06-100-DOT	Inspect DOT Federal Inspection	31-Oct-2023 15:30:58	OTSSHP	P	DON	43.00
24-Oct-2023	178,860	9,412	715270	24-034-006	Repair Warning Lamps - Special Application	31-Oct-2023 16:24:24	OTSSHP	I	DON	47.05

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: A0626 - 2005 INTERNATIONAL 4300										
09-Feb-2024	178,860	9,412	738245	03-032-001	Replace Battery	09-Feb-2024 15:40:00	OTSSHP	N	DON	364.00
01-May-2024	179,547	9,448	756541	25-062	Remove Mobile Air Compressor	01-May-2024 11:01:45	OTSSHP	N	DON	20.59
10-May-2024	179,548	9,456	758829	02-002	Clean Cab & Sheet Metal	05-Jun-2024 11:21:29	BSETUP	Z	DON	159.92
10-May-2024	179,548	9,456	758829	06-100-009	Inspect Safety Check	22-May-2024 06:53:49	BTRUCK	P	DON	64.13
10-May-2024	179,548	9,456	758829	12-018-003	Refinish Wheels	05-Jun-2024 11:21:03	BSETUP	Z	DON	256.63
10-May-2024	179,548	9,456	758829	12-519-001	Refinish Front Bumper	05-Jun-2024 10:13:33	BSETUP	N	DON	86.35
10-May-2024	179,548	9,456	758829	25-051	Remove General Accessories	28-May-2024 12:21:40	BSETUP	Z	DON	95.93

Unit No: A0626 Count: 210 85,444.61