

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: A0822 - 2013 INTERNATIONAL 4300										
22-Dec-2012 1	642	26	103149	06-100-DOT	Inspect DOT Federal Inspection	19-Mar-2013 10:10:16	BTRUCK	P	DON	209.55
22-Dec-2012 1	642	26	103149	14-052-003	Install Radio Equipment	14-Mar-2013 07:30:18	BBODY	C	DON	824.60
22-Dec-2012 1	642	26	103149	14-063-003	Install Transceiver - GPS Tracker	26-Dec-2012 05:23:21	BTRUCK	C	DON	282.35
22-Dec-2012 1	642	26	103149	15-071-001	Paint Prep Floor / Decking / Flatbed	12-Mar-2013 14:24:35	BSAND	C	DON	1,036.22
22-Dec-2012 1	642	26	103149	12-071-001	Refinish Floor / Decking / Flatbed	13-Mar-2013 08:47:51	BBODY	C	DON	460.05
22-Dec-2012 1	642	26	103149	14-517	Install Safety Equipment	14-Mar-2013 08:16:09	BBODY	J	DON	86.64
22-Dec-2012 1	642	26	103149	14-053-005	Install Markings - Vehicle - Decals	14-Mar-2013 08:45:27	BBODY	J	DON	13.98
22-Dec-2012 1	642	26	103149	21-519-003	Fabricate Hitch Assembly	01-Mar-2013 06:50:46	BWELD	C	DON	4,753.06
22-Dec-2012 1	642	26	103149	14-034-002	Install Stop, Tail, Turn & License	18-Mar-2013 11:43:31	BTRUCK	C	DON	1,420.31
22-Dec-2012 1	642	26	103149	14-013-012	Install Electric Brakes	18-Mar-2013 10:04:57	BTRUCK	C	DON	170.36
22-Dec-2012 1	642	26	103149	14-001-016	Install Filter - Cab Ventilation	23-Mar-2013 05:32:07	BTRUCK	C	DON	60.21
22-Dec-2012 1	642	26	103149	14-032-001	Install Battery	18-Mar-2013 13:21:25	BTRUCK	C	DON	106.96
22-Dec-2012 1	642	26	103149	06-045	Inspect Power Plant		BTRUCK	I	CAN	0.00
22-Dec-2012 1	642	26	103149	15-519-001	Paint Prep Front Bumper	01-Apr-2013 09:32:57	BBODY	C	DON	154.37
22-Dec-2012 1	642	26	103149	12-519-001	Refinish Front Bumper	01-Apr-2013 09:33:00	BBODY	C	DON	158.10
22-Dec-2012 1	642	26	103149	15-519	Paint Prep Bumper	01-Apr-2013 09:33:11	BSAND	K	DON	163.28
22-Dec-2012 1	642	26	103149	14-078-009	Install Mud Flaps and Hanger Brackets	01-Apr-2013 09:33:05	BBODY	C	DON	70.31
18-Apr-2013 0	2,522		116168	06-100-PMA	Inspect A PMI	18-Apr-2013 09:30:22	BVLOFC	P	DON	21.01
18-Apr-2013 0	2,522		116168	07-100-000	Lubricate On Road Equip / Field Service	18-Apr-2013 09:30:22	BVLOFC	P	DON	21.01
12-Jun-2013 0	11,497		123621	06-100-PMA	Inspect A PMI	12-Jun-2013 11:32:41	BVLOFC	P	DON	0.00
12-Jun-2013 0	11,497		123621	07-100-000	Lubricate On Road Equip / Field Service	12-Jun-2013 11:32:41	BVLOFC	P	DON	22.99
09-Aug-2013 1			131988	06-100-PMB	Inspect B PMI	09-Aug-2013 15:03:49	BVLOFC	P	DON	300.73
05-Sep-2013 0	11,497		130779	03-063-003	Replace Transceiver - GPS Tracker	05-Sep-2013 00:00:00	BHVYEQ	C	DON	221.24
04-Oct-2013 1	27,845		141703	06-100-007	Inspect In-Service Inspection	20-Nov-2013 10:45:31	BVLOFC	P	DON	120.78
04-Oct-2013 1	27,845		141703	01-023	Adjust Clutch	20-Nov-2013 10:45:31	BVLOFC	F	DON	46.43
04-Oct-2013 1	27,845		141703	03-044-002	Replace Filters	20-Nov-2013 10:45:31	BVLOFC	F	DON	105.35
04-Oct-2013 1	27,845		141703	06-100-PMB	Inspect B PMI	20-Nov-2013 10:45:31	BVLOFC	P	DON	293.60
04-Oct-2013 1	27,845		141703	38-015	Service Steering	20-Nov-2013 10:45:31	BVLOFC	F	DON	78.54
06-Dec-2013 1	36,795		142874	24-002-035	Repair Windshield Wiper & Washer	06-Dec-2013 14:44:42	BVLOFC	F	DON	68.68

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: A0822 - 2013 INTERNATIONAL 4300										
06-Dec-2013 1	36,795		142874	38-049	Service Electronic Management System	06-Dec-2013 14:44:42	BVLOFC	F	DON	0.00
06-Dec-2013 1	36,795		142874	06-100-PMB	Inspect B PMI	06-Dec-2013 14:44:42	BVLOFC	P	DON	522.42
31-Mar-2014 0	38,708		159401	06-100-DOT	Inspect DOT Federal Inspection	31-Mar-2014 17:00:00	BHVEYEQ	P	DON	0.00
12-Jun-2014 0	48,909		161351	06-100-PMB	Inspect B PMI	12-Jun-2014 10:24:43	BTRUCK	P	DON	397.50
12-Jun-2014 0	48,909		161351	01-023-002	Adjust Clutch Assembly	12-Jun-2014 10:24:50	BTRUCK	I	DON	69.77
12-Jun-2014 0	48,909		161351	03-001-016	Replace Filter - Cab Ventilation	12-Jun-2014 10:24:54	BTRUCK	I	DON	120.79
12-Jun-2014 0	48,909		161351	03-041-001	Replace Air Cleaner	12-Jun-2014 10:24:52	BTRUCK	I	DON	109.04
12-Jun-2014 0	48,909		161351	03-041-010	Replace Air Filter Restriction Gauge	12-Jun-2014 10:24:47	BTRUCK	I	DON	35.93
12-Jun-2014 0	48,909		161351	24-044-002	Repair Filters	12-Jun-2014 10:24:45	BTRUCK	P	DON	80.00
08-Aug-2014 0	60,282		168401	06-100-PMA	Inspect A PMI	10-Aug-2014 16:47:07	BTRUCK	P	DON	305.58
25-Aug-2014 1	62,737		170373	24-001-008	Repair Motor - Blower		BTRUCK	O	CAN	0.00
25-Aug-2014 1	62,737		170373	24-042-016	Repair Fan Clutch	26-Aug-2014 13:54:34	BTRUCK	O	DON	214.25
25-Aug-2014 1	62,737		170373	24-049-001	Repair ECM Fault Code	26-Aug-2014 14:00:58	BTRUCK	O	DON	178.85
25-Aug-2014 1	62,737		170373	24-034-020	Repair Dome / Reading Light	26-Aug-2014 14:02:38	BTRUCK	O	DON	67.11
18-Sep-2014 1	64,589		172810	24-042	Repair Cooling System	18-Sep-2014 13:17:29	BTRUCK	W	DON	0.00
18-Sep-2014 1	64,589		172810	24-049-001	Repair ECM Fault Code	18-Sep-2014 13:14:51	BTRUCK	W	DON	0.00
18-Sep-2014 1	64,589		172810	37-049-002	Calibrate ECM Module	18-Sep-2014 13:11:41	BTRUCK	I	DON	73.65
28-Oct-2014 0	66,311		177844	01-023-002	Adjust Clutch Assembly	28-Oct-2014 05:36:31	BTRUCK	I	DON	98.23
28-Oct-2014 0	66,311		177844	24-045	Repair Power Plant	28-Oct-2014 05:41:24	BTRUCK	W	DON	0.00
04-Dec-2014 0	77,571		183223	03-044-002	Replace Filters	04-Dec-2014 06:35:19	BTRUCK	I	DON	97.14
04-Dec-2014 0	77,571		183223	06-100-PMA	Inspect A PMI	04-Dec-2014 06:34:45	BTRUCK	P	DON	317.14
04-Dec-2014 0	77,571		183223	24-011-002	Repair King Pin	04-Dec-2014 06:53:06	BTRUCK	I	DON	83.69
04-Dec-2014 0	77,571		183223	24-013-011	Repair Anti-Lock Sensor Assembly	04-Dec-2014 06:36:51	BTRUCK	I	DON	66.96
04-Dec-2014 0	77,571		183223	24-049-001	Repair ECM Fault Code	04-Dec-2014 06:52:22	BTRUCK	W	DON	0.00
13-Feb-2015 0	81,232		191377	03-041-007	Replace Filter - Outer	02-Mar-2015 16:00:49	BTRUCK	I	DON	138.46
13-Feb-2015 0	81,232		191377	06-100-009	Inspect Safety Check		BTRUCK	P	CAN	0.00
13-Feb-2015 0	81,232		191377	24-013-007	Repair Brake Lines & Fittings - Hydraulic & Air	02-Mar-2015 15:59:01	BTRUCK	I	DON	176.38
13-Feb-2015 0	81,232		191377	24-013-011	Repair Anti-Lock Sensor Assembly	02-Mar-2015 16:07:02	BTRUCK	W	DON	0.00
13-Feb-2015 0	81,232		191377	24-044	Repair Fuel System	02-Mar-2015 16:15:49	BTRUCK	W	DON	0.00

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: A0822 - 2013 INTERNATIONAL 4300										
18-Mar-2015 0	81,604		197272	06-100-DOT	Inspect DOT Federal Inspection	18-Mar-2015 17:00:00	LAKEVL	P	DON	21.01
02-May-2015 (88,747		199677	03-002-010	Replace Mirrors	11-May-2015 07:11:12	BTRUCK	I	DON	180.62
02-May-2015 (88,747		199677	03-041-001	Replace Air Cleaner	11-May-2015 07:11:08	BTRUCK	P	DON	113.17
02-May-2015 (88,747		199677	03-044-002	Replace Filters	11-May-2015 07:11:04	BTRUCK	P	DON	99.67
02-May-2015 (88,747		199677	06-100-PMA	Inspect A PMI	11-May-2015 07:11:00	BTRUCK	P	DON	393.91
02-May-2015 (88,747		199677	38-045	Service Power Plant		BTRUCK	P	CAN	0.00
26-May-2015 1	92,320		202035	01-023-002	Adjust Clutch Assembly	05-Jun-2015 10:07:44	BTRUCK	I	DON	76.75
26-May-2015 1	92,320		202035	03-026-011	Replace Transmission External Control	26-May-2015 10:18:37	BTRUCK	W	DON	0.00
06-Jul-2015 05	97,980		206537	06-100-PMA	Inspect A PMI	08-Jul-2015 06:05:20	BTRUCK	P	DON	630.75
08-Sep-2015 0	106,418		213793	03-044-002	Replace Filters	09-Sep-2015 14:11:42	BTRUCK	P	DON	79.03
08-Sep-2015 0	106,418		213793	01-023-001	Adjust Linkage - Mechanical Clutch	09-Sep-2015 14:11:46	BTRUCK	P	DON	135.27
08-Sep-2015 0	106,418		213793	37-049-002	Calibrate ECM Module	09-Sep-2015 14:09:13	BTRUCK	W	DON	0.00
08-Sep-2015 0	106,418		213793	06-100-PMA	Inspect A PMI	09-Sep-2015 14:11:40	BTRUCK	P	DON	401.58
07-Oct-2015 0	106,418		217616	03-017-001	Replace Tire - Pneumatic	07-Oct-2015 07:18:01	BTIRE	N	DON	950.59
16-Nov-2015 0	116,906		230268	06-100-PMA	Inspect A PMI	16-Nov-2015 08:35:37	LAVSHIP	P	DON	82.06
16-Nov-2015 0	116,906		230268	07-100-000	Lubricate On Road Equip / Field Service	16-Nov-2015 08:36:24	LAVSHIP	F	DON	82.06
01-Mar-2016 1	120,350		235577	06-100-DOT	Inspect DOT Federal Inspection	02-Mar-2016 13:37:55	LAVSHIP	P	DON	36.53
01-Mar-2016 1	120,350		235577	06-100-PMA	Inspect A PMI	02-Mar-2016 15:17:47	LAVSHIP	P	DON	114.35
06-Apr-2016 0	123,362		240192	24-043-008	Repair EGR Valve / System	07-Apr-2016 13:42:08	BTRUCK	I	DON	4,204.12
06-Apr-2016 0	123,362		240192	03-041-001	Replace Air Cleaner	07-Apr-2016 13:42:08	BTRUCK	I	DON	112.68
06-Apr-2016 0	123,362		240192	37-049-002	Calibrate ECM Module	07-Apr-2016 13:42:08	BTRUCK	I	DON	230.29
10-May-2016 0	128,718		247359	24-045	Repair Power Plant	10-May-2016 07:12:34	BVLOFC	O	DON	619.39
09-Jun-2016 0	133,586		247560	06-100-PMA	Inspect A PMI	09-Jun-2016 10:38:16	LAVSHIP	P	DON	131.56
27-Jul-2016 07	140,950		255015	03-044-002	Replace Filters	27-Jul-2016 07:00:00	LAVSHIP	P	DON	19.59
27-Jul-2016 07	140,950		255015	06-100-PMA	Inspect A PMI	27-Jul-2016 07:00:00	LAVSHIP	P	DON	58.78
27-Jul-2016 07	140,950		255015	07-100-000	Lubricate On Road Equip / Field Service	27-Jul-2016 07:00:00	LAVSHIP	R	DON	78.37
01-Aug-2016 0	141,537		257036	03-013-009	Replace Air Compressor	01-Aug-2016 07:00:00	LAVSHIP	O	DON	22.36
22-Sep-2016 0	149,084		262577	06-100-PMA	Inspect A PMI	22-Sep-2016 07:00:00	LAVSHIP	P	DON	22.36
22-Sep-2016 0	149,084		262577	07-100-000	Lubricate On Road Equip / Field Service	22-Sep-2016 07:00:00	LAVSHIP	R	DON	22.36

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: A0822 - 2013 INTERNATIONAL 4300										
18-Nov-2016 C	149,084		269832	03-056-001	Replace Power Take Off	29-Nov-2016 11:08:54	ROGSHP	P	DON	23.55
18-Nov-2016 C	149,084		269832	06-100-PMB	Inspect B PMI	29-Nov-2016 11:08:54	ROGSHP	P	DON	123.41
28-Feb-2017 0	162,100		279007	24-013-009	Repair Air Compressor	07-Mar-2017 14:17:12	ROGSHP	B	DON	292.53
28-Feb-2017 0	162,100		279007	06-002-067	Inspect Keys - Door / Ignition	07-Mar-2017 08:20:52	ROGSHP	B	DON	64.75
28-Feb-2017 0	162,100		279007	03-034-001	Replace Headlamps / Fog Lamps		ROGSHP	I	CAN	0.00
28-Feb-2017 0	162,100		279007	06-100-DOT	Inspect DOT Federal Inspection	28-Feb-2017 09:45:29	ROGSHP	P	DON	16.90
28-Feb-2017 0	162,100		279007	03-002-024	Replace Glass / Windshield	02-Mar-2017 06:20:44	ROGSHP	N	DON	421.77
28-Feb-2017 0	162,100		279007	03-026-016	Replace Gear Shifter & Linkage	28-Feb-2017 14:01:43	ROGSHP	I	DON	22.67
28-Feb-2017 0	162,100		279007	03-042-013	Replace Fan Belt	28-Feb-2017 10:17:39	ROGSHP	I	DON	47.86
28-Feb-2017 0	162,100		279007	03-034-002	Replace Stop, Tail, Turn & License	28-Feb-2017 09:54:51	ROGSHP	I	DON	4.70
28-Feb-2017 0	162,100		279007	03-013-007	Replace Brake Lines & Fittings - Hydraulic & A	28-Feb-2017 11:47:47	ROGSHP	I	DON	36.32
28-Feb-2017 0	162,100		279007	03-017-001	Replace Tire - Pneumatic	01-Mar-2017 07:40:17	ROGSHP	I	DON	2,046.27
28-Feb-2017 0	162,100		279007	06-042-002	Inspect Radiator	09-Mar-2017 07:46:53	ROGSHP	B	DON	37.33
23-Mar-2017 0	163,561		282284	24-043-005	Repair Exhaust Brake	23-Mar-2017 17:08:16	ROGSHP	B	DON	1,650.03
05-Apr-2017 0	165,183		283961	06-100-PMA	Inspect A PMI	05-Apr-2017 06:42:08	ROGSHP	P	DON	86.96
22-May-2017 1	170,253	5,960	289882	03-043-008	Replace EGR Valve / System	22-May-2017 15:35:49	ROGSHP	B	DON	2,956.83
22-May-2017 1	170,253	5,960	289882	01-023-004	Adjust Clutch Disc	22-May-2017 14:40:22	ROGSHP	B	DON	43.20
22-May-2017 1	170,253	5,960	289882	03-001-001	Replace Air Conditioning Assembly	22-May-2017 15:35:49	ROGSHP	Q	DON	241.29
22-May-2017 1	170,253	5,960	289882	03-001-006	Replace Dryer Assembly	22-May-2017 15:35:49	ROGSHP	B	DON	761.74
22-May-2017 1	170,253	5,960	289882	03-043-002	Replace Exhaust Manifold	22-May-2017 15:35:49	ROGSHP	B	DON	821.25
22-May-2017 1	170,253	5,960	289882	03-043-026	Replace Exhaust Cooler	22-May-2017 15:35:49	ROGSHP	B	DON	0.00
22-May-2017 1	170,253	5,960	289882	06-040	Inspect Engine / Motor Systems Group	22-May-2017 15:35:49	ROGSHP	B	DON	518.33
22-May-2017 1	170,253	5,960	289882	03-100-PMA	Replace A PMI	22-May-2017 15:35:49	ROGSHP	P	DON	223.77
15-Jun-2017 1	172,623	5,960	293110	03-013-003	Replace Brake Chamber - Parking	15-Jun-2017 16:33:31	ROGSHP	I	DON	93.27
15-Jun-2017 1	172,623	5,960	293110	38-100-PMA	Service A PMI	15-Jun-2017 15:55:42	ROGSHP	P	DON	46.13
18-Jul-2017 16	178,186		297296	03-001-010	Replace Compressor Assembly - Air Cond	19-Jul-2017 06:33:06	ROGSHP	B	DON	1,249.93
28-Aug-2017 C	182,561		302674	07-100-PMA	Lubricate A PMI	28-Aug-2017 07:10:53	ROGSHP	P	DON	109.99
05-Sep-2017 1	183,376	6,597	303772	03-044-007	Replace Throttle Controls	06-Sep-2017 07:31:31	ROGSHP	B	DON	495.47
05-Sep-2017 1	183,376	6,597	303772	35-040	Diagnose Engine / Motor Systems Group	06-Sep-2017 07:31:31	ROGSHP	O	DON	418.48

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: A0822 - 2013 INTERNATIONAL 4300										
12-Oct-2017	189,225	6,801	308655	07-100-PMA	Lubricate A PMI	13-Oct-2017 06:12:12	ROGSHP	P	DON	66.93
25-Oct-2017	192,688	7,011	310162	03-013-007	Replace Brake Lines & Fittings - Hydraulic & A	25-Oct-2017 12:26:14	ROGSHP	N	DON	47.87
25-Oct-2017	192,688	7,011	310162	03-053-005	Replace Markings - Vehicle - Decals	06-Nov-2017 16:33:12	ROGSHP	Q	DON	11.57
09-Nov-2017	193,237		312022	35-040	Diagnose Engine / Motor Systems Group	21-Nov-2017 16:50:27	ROGSHP	B	DON	610.77
27-Mar-2018	195,367	7,120	328858	03-032-001	Replace Battery	30-Mar-2018 09:53:37	ROGSHP	I	DON	431.98
27-Mar-2018	195,367	7,120	328858	03-034-010	Replace Socket - Trailer Light Cord	30-Mar-2018 10:13:13	ROGSHP	I	DON	24.89
27-Mar-2018	195,367	7,120	328858	06-013-002	Inspect Rear Brakes & Drums	30-Mar-2018 09:32:14	ROGSHP	P	DON	19.79
27-Mar-2018	195,367	7,120	328858	06-100-DOT	Inspect DOT Federal Inspection	30-Mar-2018 10:51:34	ROGSHP	P	DON	68.07
27-Mar-2018	195,367	7,120	328858	24-026-016	Repair Gear Shifter & Linkage	30-Mar-2018 09:36:47	ROGSHP	I	DON	13.55
02-Apr-2018	195,367	7,120	329649	24-052-003	Repair Radio Equipment	04-Apr-2018 15:42:44	ROGSHP	O	DON	218.65
02-Apr-2018	195,367	7,120	329649	03-002-024	Replace Glass / Windshield	05-Apr-2018 09:55:09	ROGSHP	A	DON	387.57
11-Apr-2018	195,367	7,120	331086	03-034-010	Replace Socket - Trailer Light Cord	11-Apr-2018 16:15:48	ROGSHP	B	DON	34.84
24-Apr-2018	198,210		332734	07-100-PMA	Lubricate A PMI	25-Apr-2018 09:07:50	ROGSHP	P	DON	66.05
24-Apr-2018	198,210		332734	03-002-035	Replace Windshield Wiper & Washer	25-Apr-2018 09:18:31	ROGSHP	N	DON	21.65
24-Apr-2018	198,210		332734	03-041-007	Replace Filter - Outer	25-Apr-2018 09:22:32	ROGSHP	P	DON	112.64
24-Apr-2018	198,210		332734	24-041	Repair Air Intake System	30-Apr-2018 17:31:13	ROGSHP	B	DON	207.20
07-May-2018	198,210		334549	03-002-010	Replace Mirrors	08-May-2018 08:27:25	ROGSHP	B	DON	117.01
09-May-2018	201,215	7,336	334911	24-034-001	Repair Headlamps / Fog Lamps	09-May-2018 06:45:45	ROGSHP	N	DON	11.93
01-Jun-2018	204,322	7,364	338041	03-042-012	Replace Clamps and Hoses	01-Jun-2018 13:34:11	LAVSHP	B	DON	422.60
13-Jun-2018	206,996	7,552	339642	07-100-PMA	Lubricate A PMI	13-Jun-2018 17:44:45	ROGSHP	P	DON	202.58
09-Aug-2018	217,298	7,930	347544	07-100-PMA	Lubricate A PMI	09-Aug-2018 15:05:14	ROGSHP	P	DON	52.82
09-Aug-2018	217,298	7,930	347544	14-055-012	Install Cargo Restraints	09-Aug-2018 15:23:21	ROGSHP	O	DON	79.83
28-Aug-2018	219,990	8,052	350107	24-034-001	Repair Headlamps / Fog Lamps	28-Aug-2018 08:22:29	ROGSHP	N	DON	5.65
08-Oct-2018	227,729	8,060	355589	03-013-002	Replace Rear Brakes & Drums	10-Oct-2018 18:24:17	ROGSHP	N	DON	474.58
08-Oct-2018	227,729	8,060	355589	03-054-002	Replace Alarm - Reverse Signal	09-Oct-2018 09:38:21	ROGSHP	N	DON	81.87
08-Oct-2018	227,729	8,060	355589	07-100-PMA	Lubricate A PMI	09-Oct-2018 09:10:48	ROGSHP	P	DON	113.95
08-Oct-2018	227,729	8,060	355589	03-023	Replace Clutch	18-Oct-2018 06:12:01	ROGSHP	N	DON	4,034.66
14-Nov-2018	233,040		360617	03-100-PMB	Replace B PMI	19-Nov-2018 09:40:37	ROGSHP	P	DON	57.88
14-Nov-2018	233,040		360617	24-032-007	Repair Pre-Heater	19-Nov-2018 09:16:08	ROGSHP	N	DON	228.92

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: A0822 - 2013 INTERNATIONAL 4300										
14-Nov-2018 C	233,040		360617	35-040	Diagnose Engine / Motor Systems Group	09-Jan-2019 14:04:58	ROGSHP	O	DON	448.50
14-Nov-2018 C	233,040		360617	24-042-012	Repair Clamps and Hoses	19-Nov-2018 09:44:08	ROGSHP	N	DON	82.21
14-Nov-2018 C	233,040		360617	03-043-009	Replace Diesel Particulate Filter - DPF	09-Jan-2019 13:53:35	ROGSHP	N	DON	5,138.47
28-Dec-2018 I			366199	03-017-001	Replace Tire - Pneumatic	31-Dec-2018 16:27:00	BTIRE	P	DON	1,153.83
28-Dec-2018 I			366199	06-100-DOT	Inspect DOT Federal Inspection		LAVSHP	P	CAN	0.00
28-Dec-2018 I			366199	07-100-PMB	Lubricate B PMI		LAVSHP	O	CAN	0.00
27-Mar-2019 I	235,464	8,583	378541	06-100-PMB	Inspect B PMI	28-Mar-2019 14:16:06	ROGSHP	P	DON	205.92
27-Mar-2019 I	235,464	8,583	378541	06-100-DOT	Inspect DOT Federal Inspection	27-Mar-2019 16:16:02	ROGSHP	P	DON	53.20
27-Mar-2019 I	235,464	8,583	378541	03-002-035	Replace Windshield Wiper & Washer	28-Mar-2019 12:04:48	ROGSHP	I	DON	34.07
27-Mar-2019 I	235,464	8,583	378541	03-018-011	Replace Seal - Wheel	27-Mar-2019 18:45:43	ROGSHP	I	DON	211.26
27-Mar-2019 I	235,464	8,583	378541	24-026	Repair Transmission - Main, Manual	28-Mar-2019 11:04:11	ROGSHP	I	DON	114.43
27-Mar-2019 I	235,464	8,583	378541	24-053-008	Repair Hoses & Tubings & Fittings	28-Mar-2019 11:29:17	ROGSHP	I	DON	15.23
27-Mar-2019 I	235,464	8,583	378541	24-034-004	Repair Clearance & Marker Lamps	28-Mar-2019 11:55:33	ROGSHP	I	DON	17.39
27-Mar-2019 I	235,464	8,583	378541	02-034-001	Clean Headlamps / Fog Lamps	28-Mar-2019 15:58:49	ROGSHP	I	DON	93.88
29-Apr-2019 I	239,372		383371	03-026-012	Replace Transmission Assembly - Manual	30-Apr-2019 09:37:01	LAVSHP	C	DON	5,085.70
13-May-2019 I	236,219		385592	03-034-010	Replace Socket - Trailer Light Cord	13-May-2019 17:29:22	ROGSHP	P	DON	42.23
13-May-2019 I	236,219		385592	06-100-PMA	Inspect A PMI	13-May-2019 15:35:08	ROGSHP	P	DON	3.23
13-May-2019 I	236,219		385592	38-100-PMA	Service A PMI	13-May-2019 16:07:21	ROGSHP	P	DON	84.09
21-May-2019 C	244,155		386643	20-400	Tow Small Equipment Group	22-May-2019 08:53:55	ROGSHP	B	DON	350.87
21-May-2019 C	244,155		386643	35-040	Diagnose Engine / Motor Systems Group	29-May-2019 08:35:43	ROGSHP	B	DON	467.64
21-May-2019 C	244,155		386643	03-044-014	Replace Injectors - Electronic	29-May-2019 08:35:37	ROGSHP	N	DON	4,660.90
03-Jun-2019 I	245,746	8,924	388465	03-013-001	Replace Front Brakes & Drums	04-Jun-2019 17:25:39	LAVSHP	I	DON	349.12
03-Jun-2019 I	245,746	8,924	388465	03-034-020	Replace Dome / Reading Light	04-Jun-2019 17:46:30	LAVSHP	I	DON	59.33
03-Jun-2019 I	245,746	8,924	388465	06-100-007	Inspect In-Service Inspection	03-Jun-2019 16:05:08	LAVSHP	O	DON	14.41
30-Dec-2019 0	248,673	9,115	418539	24-013-012	Repair Electric Brakes	30-Dec-2019 15:29:28	ROGSHP	I	DON	272.05
30-Dec-2019 0	248,673	9,115	418539	06-100-DOT	Inspect DOT Federal Inspection	30-Dec-2019 10:10:51	ROGSHP	P	DON	43.54
30-Dec-2019 0	248,673	9,115	418539	03-002-035	Replace Windshield Wiper & Washer	30-Dec-2019 10:23:26	ROGSHP	I	DON	30.60
30-Dec-2019 0	248,673	9,115	418539	03-051-009	Replace Fire Extinguisher	30-Dec-2019 10:20:02	ROGSHP	I	DON	5.57
30-Dec-2019 0	248,673	9,115	418539	24-026	Repair Transmission - Main, Manual	30-Dec-2019 14:44:53	ROGSHP	I	DON	172.55

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: A0822 - 2013 INTERNATIONAL 4300										
09-Jan-2020 08	249,181	9,172	420164	03-042-009	Replace Coolant Pre-Heater- Electrical	10-Jan-2020 13:31:51	ROGSHP	N	DON	148.49
09-Jan-2020 08	249,181	9,172	420164	06-100-PMB	Inspect B PMI	10-Jan-2020 13:39:27	ROGSHP	P	DON	0.00
09-Jan-2020 08	249,181	9,172	420164	24-042	Repair Cooling System	10-Jan-2020 12:47:46	ROGSHP	I	DON	14.84
09-Jan-2020 08	249,181	9,172	420164	38-100-PMB	Service B PMI	10-Jan-2020 12:25:17	ROGSHP	P	DON	196.34
06-Feb-2020 10			425169	03-043-004	Replace Turbocharger	10-Feb-2020 10:05:09	ROGSHP	I	DON	5,470.89
06-Feb-2020 10			425169	06-040	Inspect Engine / Motor Systems Group	10-Feb-2020 10:09:27	ROGSHP	O	DON	107.74
06-Feb-2020 10			425169	03-047-001	Replace Engine Filter Kits	07-Feb-2020 14:54:56	ROGSHP	I	DON	739.15
04-Mar-2020 0			429351	24-026	Repair Transmission - Main, Manual	16-Mar-2020 07:21:48	ROGSHP	B	DON	10,981.35
24-Sep-2020 1	250,727	9,765	463246	06-100-PMA	Inspect A PMI	24-Sep-2020 16:34:28	ROGSHP	P	DON	28.60
24-Sep-2020 1	250,727	9,765	463246	24-034-002	Repair Stop, Tail, Turn & License	24-Sep-2020 17:50:12	ROGSHP	I	DON	21.19
24-Sep-2020 1	250,727	9,765	463246	38-100-PMA	Service A PMI	24-Sep-2020 17:21:17	ROGSHP	P	DON	287.46
24-Sep-2020 1	250,727	9,765	463246	03-051-009	Replace Fire Extinguisher	24-Sep-2020 17:24:31	ROGSHP	I	DON	2.55
10-Dec-2020 0	254,098	9,917	476210	03-002-061	Replace Seat Cushion	15-Dec-2020 17:33:15	ROGSHP	O	DON	416.03
10-Dec-2020 0	254,098	9,917	476210	03-034-002	Replace Stop, Tail, Turn & License	10-Dec-2020 07:19:17	ROGSHP	O	DON	13.29
25-Jan-2021 08	259,435	9,989	484236	24-034-001	Repair Headlamps / Fog Lamps	25-Jan-2021 07:10:59	ROGSHP	O	DON	19.19
25-Jan-2021 10	259,435	9,989	484405	03-051-009	Replace Fire Extinguisher	26-Jan-2021 10:20:49	ROGSHP	I	DON	8.64
25-Jan-2021 10	259,435	9,989	484405	03-078-009	Replace Mud Flaps and Hanger Brackets	26-Jan-2021 13:19:27	ROGSHP	I	DON	231.62
25-Jan-2021 10	259,435	9,989	484405	24-510-002	Repair Tool Box	26-Jan-2021 13:01:07	ROGSHP	I	DON	72.85
25-Jan-2021 10	259,435	9,989	484405	06-100-DOT	Inspect DOT Federal Inspection	26-Jan-2021 10:15:48	ROGSHP	P	DON	95.50
25-Jan-2021 10	259,435	9,989	484405	06-100-PMA	Inspect A PMI	25-Jan-2021 17:38:07	ROGSHP	P	DON	25.17
25-Jan-2021 10	259,435	9,989	484405	38-100-PMA	Service A PMI	25-Jan-2021 18:30:18	ROGSHP	P	DON	221.65
08-Feb-2021 0	259,435	9,989	486833	01-042-014	Adjust Coolant Overflow Reservoir	08-Feb-2021 08:04:29	ROGSHP	P	DON	16.16
22-Feb-2021 0	260,234	10,006	489445	06-706-001	Inspect Engine	25-Feb-2021 12:35:50	ROGSHP	O	DON	145.63
22-Feb-2021 0	260,234	10,006	489445	24-041	Repair Air Intake System	24-Feb-2021 17:37:23	ROGSHP	O	DON	391.17
08-Jun-2021 0	260,234	10,006	511315	14-034-001	Install Headlamps / Fog Lamps	08-Jun-2021 07:13:39	ROGSHP	N	DON	12.07
21-Jun-2021 08	260,234	10,006	513850	07-706-001	Lubricate Engine	21-Jun-2021 06:53:12	ROGSHP	P	DON	24.24
28-Dec-2021 0	260,234	10,006	555903	02-010	Clean Chassis Group	28-Dec-2021 14:25:08	OTSSHP	P	DON	25.88
28-Dec-2021 0	260,234	10,006	555903	03-015-014	Replace Filter - Power Steering	29-Dec-2021 07:01:14	OTSSHP	I	DON	12.79
28-Dec-2021 0	260,234	10,006	555903	03-034-001	Replace Headlamps / Fog Lamps	29-Dec-2021 06:43:47	OTSSHP	I	DON	427.51

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: A0822 - 2013 INTERNATIONAL 4300										
28-Dec-2021 0	260,234	10,006	555903	03-051-009	Replace Fire Extinguisher	28-Dec-2021 14:25:13	OTSSHP	I	DON	67.41
28-Dec-2021 0	260,234	10,006	555903	03-053-017	Replace First Aid Kit	28-Dec-2021 14:25:25	OTSSHP	I	DON	48.91
28-Dec-2021 0	260,234	10,006	555903	03-063-003	Replace Transceiver - GPS Tracker	28-Dec-2021 14:25:03	OTSSHP	Q	DON	422.90
28-Dec-2021 0	260,234	10,006	555903	06-100-DOT	Inspect DOT Federal Inspection	28-Dec-2021 17:09:25	OTSSHP	P	DON	79.40
28-Dec-2021 0	260,234	10,006	555903	06-100-PMA	Inspect A PMI	28-Dec-2021 14:24:56	SCHED	P	DON	48.42
28-Dec-2021 0	260,234	10,006	555903	38-100-PMA	Service A PMI	04-Jan-2022 15:04:36	SCHED	P	DON	1,427.81
17-Aug-2022 0	260,234	10,006	610078	03-031-001	Replace Generator/Alternator	17-Aug-2022 09:45:11	TRK400	I	DON	471.21
20-Sep-2022 0	260,234	10,006	617732	20-400	Tow Small Equipment Group	21-Sep-2022 09:23:19	OTSSHP	B	DON	866.61
20-Sep-2022 0	260,234	10,006	617732	06-706-001	Inspect Engine	11-Oct-2022 07:19:00	OTSSHP	B	DON	678.11
20-Sep-2022 0	260,234	10,006	617732	14-024	Install Driveshafts	11-Oct-2022 07:23:00	OTSSHP	B	DON	105.19
20-Sep-2022 0	260,234	10,006	617732	02-040	Clean Engine / Motor Systems Group	11-Oct-2022 07:58:00	OTSSHP	I	DON	82.73
20-Sep-2022 0	260,234	10,006	617732	18-100-009	Test Safety Check	11-Oct-2022 08:03:00	OTSSHP	I	DON	99.28
20-Sep-2022 0	260,234	10,006	617732	24-040	Repair Engine / Motor Systems Group	11-Oct-2022 08:19:00	OTSSHP	I	DON	46,062.67
24-Oct-2022 1	260,234	10,006	626660	24-002-035	Repair Windshield Wiper & Washer	24-Oct-2022 16:05:14	OTSSHP	O	DON	73.31
24-Oct-2022 1	260,234	10,006	626660	24-054-002	Repair Alarm - Reverse Signal	24-Oct-2022 15:36:21	OTSSHP	O	DON	92.64
21-Nov-2022 1	268,551		634054	01-023-002	Adjust Clutch Assembly	29-Nov-2022 14:34:00	OTSSHP	I	DON	1,473.11
21-Nov-2022 1	268,551		634054	03-013-002	Replace Rear Brakes & Drums	29-Nov-2022 14:28:00	OTSSHP	I	DON	1,264.08
21-Nov-2022 1	268,551		634054	03-013-004	Replace Brake Chamber - Service	11-Jan-2023 07:18:58	OTSSHP	I	DON	485.51
21-Nov-2022 1	268,551		634054	03-013-009	Replace Air Compressor	29-Nov-2022 14:53:00	OTSSHP	N	DON	3,208.85
21-Nov-2022 1	268,551		634054	03-023	Replace Clutch	29-Nov-2022 15:16:00	OTSSHP	I	DON	3,727.19
21-Nov-2022 1	268,551		634054	03-034-004	Replace Clearance & Marker Lamps	22-Nov-2022 13:34:51	OTSSHP	I	DON	92.39
21-Nov-2022 1	268,551		634054	03-034-020	Replace Dome / Reading Light	10-Jan-2023 11:51:57	OTSSHP	I	DON	56.17
21-Nov-2022 1	268,551		634054	03-042-012	Replace Clamps and Hoses	10-Jan-2023 11:20:08	OTSSHP	I	DON	20.57
21-Nov-2022 1	268,551		634054	03-045-002	Replace Cylinder Block & Crankcase	29-Nov-2022 15:16:00	OTSSHP	I	DON	2,585.06
21-Nov-2022 1	268,551		634054	03-051-009	Replace Fire Extinguisher	22-Nov-2022 11:44:11	OTSSHP	Q	DON	63.45
21-Nov-2022 1	268,551		634054	03-053-017	Replace First Aid Kit	22-Nov-2022 11:43:54	OTSSHP	Q	DON	50.62
21-Nov-2022 1	268,551		634054	06-100-DOT	Inspect DOT Federal Inspection	10-Jan-2023 07:47:40	OTSSHP	P	DON	253.72
21-Nov-2022 1	268,551		634054	06-100-PMA	Inspect A PMI	10-Jan-2023 10:46:57	OTSSHP	P	DON	34.79
21-Nov-2022 1	268,551		634054	24-015	Repair Steering	29-Nov-2022 15:00:00	OTSSHP	N	DON	428.83

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: A0822 - 2013 INTERNATIONAL 4300										
21-Nov-2022	1	268,551	634054	24-519-002	Repair Rear Bumper	10-Jan-2023 13:18:52	OTSSHP	I	DON	43.75
21-Nov-2022	1	268,551	634054	38-100-PMA	Service A PMI	10-Jan-2023 12:43:56	OTSSHP	P	DON	229.18
05-Apr-2023	1	268,551	664827	06-032-001	Inspect Battery	05-Apr-2023 14:51:34	TRK401	O	DON	34.72
05-Apr-2023	1	268,551	664827	03-032-001	Replace Battery	05-Apr-2023 15:13:00	TRK401	I	DON	329.17
07-Apr-2023	1	268,593	665422	03-053-015	Replace Tool Box	20-Apr-2023 10:25:50	OTSSHP	O	DON	1,238.15
07-Apr-2023	1	268,593	665422	03-017-001	Replace Tire - Pneumatic	21-Apr-2023 15:29:00	OTSSHP	N	DON	2,136.45
21-Apr-2023	1	268,593	669099	03-034-019	Replace Switch (Other)	21-Apr-2023 16:44:20	TRK401	I	DON	122.03
21-Apr-2023	1	268,593	669099	06-034	Inspect Lighting System	21-Apr-2023 15:39:27	TRK401	O	DON	65.06
23-May-2023	1	268,593	676497	14-053-015	Install Tool Box	30-May-2023 13:37:19	OTSSHP	O	DON	571.18
23-May-2023	1	268,593	676497	14-078-024	Install Ladder Rack/Holder	07-Jun-2023 15:14:09	OTSSHP	O	DON	854.77
23-May-2023	1	268,593	676497	14-094-006	Install Reel Assembly - Line W/Hose & Fittings	08-Jun-2023 09:45:45	OTSSHP	O	DON	947.68
23-May-2023	1	268,593	676497	14-506-006	Install Mixing Tank	30-May-2023 10:48:41	OTSSHP	O	DON	85.21
23-May-2023	1	268,593	676497	14-702	Install Mud Pump	30-May-2023 12:37:07	OTSSHP	O	DON	81.09
23-May-2023	1	268,593	676497	14-079-009	Install Tape - Reflective, Conspicuity	30-May-2023 14:11:15	OTSSHP	I	DON	23.14
05-Feb-2024	1	268,593	736853	04-701	Rig / Unrig Mud Rig	06-Feb-2024 07:13:14	OTSSHP	N	DON	96.34
13-Mar-2024	1	270,294	745556	06-100-009	Inspect Safety Check	14-Mar-2024 07:49:54	BTRUCK	P	DON	122.69
13-Mar-2024	1	270,294	745556	24-049-001	Repair ECM Fault Code	14-Mar-2024 08:18:51	BTRUCK	N	DON	26.37
13-Mar-2024	1	270,294	745556	02-002	Clean Cab & Sheet Metal	04-Apr-2024 06:23:24	BSETUP	N	DON	999.54
13-Mar-2024	1	270,294	745556	12-018-003	Refinish Wheels	01-Apr-2024 13:05:36	BSETUP	N	DON	237.49
08-Jun-2024	0'		764867	02-002	Clean Cab & Sheet Metal	10-Jun-2024 16:30:00	BSETUP	Z	DON	138.37
08-Jun-2024	0'		764867	25-051	Remove General Accessories	10-Jun-2024 14:51:38	BSETUP	Z	DON	252.79

Unit No: A0822

Count: 253

156,800.15