

# Unit Job History

| WO Open Date                                     | Meter 1 | Meter 2 | Work Order | Job Code   | Job Description                             | Date Completed       | Job Location | Job Reason | Job Status | Total Cost |
|--|---------|---------|------------|------------|---|----------------------|--------------|------------|------------|------------|
| <b>Unit No: E1081 - 2001 FREIGHTLIN BLUEBIRD</b> |         |         |            |            |   |                      |              |            |            |            |
| 18-Feb-2013 0                                    | 7,612   | 85,853  | 108302     | 24-017-001 | Repair Tire - Pneumatic                     | 14-Mar-2013 04:56:24 | BTRUCK       | I          | DON        | 88.48      |
| 18-Feb-2013 0                                    | 7,612   | 85,853  | 108302     | 24-034-002 | Repair Stop, Tail, Turn & License           | 27-Feb-2013 05:34:31 | BTRUCK       | I          | DON        | 67.48      |
| 18-Feb-2013 0                                    | 7,612   | 85,853  | 108302     | 24-044-002 | Repair Filters                              | 27-Feb-2013 05:34:19 | BTRUCK       | I          | DON        | 142.76     |
| 18-Feb-2013 0                                    | 7,612   | 85,853  | 108302     | 24-002-010 | Repair Mirrors                              | 27-Feb-2013 05:34:26 | BTRUCK       | I          | DON        | 8.51       |
| 18-Feb-2013 0                                    | 7,612   | 85,853  | 108302     | 24-003-001 | Repair Gauges & Warning Devices             | 27-Feb-2013 05:34:29 | BTRUCK       | I          | DON        | 198.07     |
| 18-Feb-2013 0                                    | 7,612   | 85,853  | 108302     | 24-013-017 | Repair Slack Adjuster                       | 27-Feb-2013 05:34:33 | BTRUCK       | I          | DON        | 239.22     |
| 18-Feb-2013 0                                    | 7,612   | 85,853  | 108302     | 03-013-002 | Replace Rear Brakes & Drums                 | 27-Feb-2013 05:34:23 | BTRUCK       | I          | DON        | 613.45     |
| 18-Feb-2013 0                                    | 7,612   | 85,853  | 108302     | 03-032-002 | Replace Starter                             | 27-Feb-2013 05:34:35 | BTRUCK       | I          | DON        | 1,301.78   |
| 18-Feb-2013 0                                    | 7,612   | 85,853  | 108302     | 03-042-014 | Replace Coolant Overflow Reservoir          | 27-Feb-2013 05:34:21 | BTRUCK       | I          | DON        | 165.30     |
| 18-Feb-2013 0                                    | 7,612   | 85,853  | 108302     | 03-017-001 | Replace Tire - Pneumatic                    | 04-Mar-2013 05:12:03 | BTRUCK       | I          | DON        | 921.30     |
| 18-Feb-2013 0                                    | 7,612   | 85,853  | 108302     | 21-014-002 | Fabricate Bumpers & Attaching Parts         | 11-Mar-2013 06:59:52 | BWELD        | C          | DON        | 661.15     |
| 18-Feb-2013 0                                    | 7,612   | 85,853  | 108302     | 21-059-006 | Fabricate Towing Hitch Assembly             |                      | BWELD        | C          | CAN        | 0.00       |
| 18-Feb-2013 0                                    | 7,612   | 85,853  | 108302     | 14-034-011 | Install Plug - Trailer Light Cord           |                      | BTRUCK       | C          | CAN        | 0.00       |
| 18-Feb-2013 0                                    | 7,612   | 85,853  | 108302     | 03-034-006 | Replace Warning Lamps - Special Application | 01-Mar-2013 15:15:38 | BTRUCK       | I          | DON        | 143.30     |
| 18-Feb-2013 0                                    | 7,612   | 85,853  | 108302     | 06-100-DOT | Inspect DOT Federal Inspection              | 13-Mar-2013 11:24:26 | BTRUCK       | P          | DON        | 107.07     |
| 18-Feb-2013 0                                    | 7,612   | 85,853  | 108302     | 06-100-PMB | Inspect B PMI                               | 27-Feb-2013 05:34:10 | BTRUCK       | P          | DON        | 545.28     |
| 18-Feb-2013 0                                    | 7,612   | 85,853  | 108302     | 24-045     | Repair Power Plant                          | 27-Feb-2013 05:34:16 | BTRUCK       | I          | DON        | 628.66     |
| 18-Feb-2013 0                                    | 7,612   | 85,853  | 108302     | 12-002     | Refinish Cab & Sheet Metal                  | 07-Mar-2013 15:34:45 | BTRUCK       | C          | DON        | 6,435.95   |
| 18-Feb-2013 0                                    | 7,612   | 85,853  | 108302     | 14-063-003 | Install Transceiver - GPS Tracker           | 01-Mar-2013 17:11:10 | BTRUCK       | C          | DON        | 333.41     |
| 18-Feb-2013 0                                    | 7,612   | 85,853  | 108302     | 14-079-003 | Install Strap, Anti-Static                  | 14-Mar-2013 11:10:20 | BTRUCK       | I          | DON        | 16.03      |
| 18-Feb-2013 0                                    | 7,612   | 85,853  | 108302     | 03-051-009 | Replace Fire Extinguisher                   | 04-Mar-2013 07:51:54 | BTRUCK       | I          | DON        | 161.35     |
| 18-Feb-2013 0                                    | 7,612   | 85,853  | 108302     | 14-079     | Install Safety Devices                      | 04-Mar-2013 07:53:24 | BTRUCK       | I          | DON        | 60.83      |
| 18-Feb-2013 0                                    | 7,612   | 85,853  | 108302     | 19-034-011 | Wire/Rewire Plug - Trailer Light Cord       | 13-Mar-2013 12:00:21 | BTRUCK       | C          | DON        | 300.75     |
| 18-Feb-2013 0                                    | 7,612   | 85,853  | 108302     | 14-052-003 | Install Radio Equipment                     | 05-Mar-2013 13:16:03 | BBODY        | C          | DON        | 583.23     |
| 18-Feb-2013 0                                    | 7,612   | 85,853  | 108302     | 14-053-005 | Install Markings - Vehicle - Decals         | 06-Mar-2013 15:14:19 | BBODY        | C          | DON        | 25.25      |
| 18-Feb-2013 0                                    | 7,612   | 85,853  | 108302     | 12-014-002 | Refinish Bumpers & Attaching Parts          | 11-Mar-2013 12:23:57 | BBODY        | C          | DON        | 156.90     |
| 18-Feb-2013 0                                    | 7,612   | 85,853  | 108302     | 15-014-002 | Paint Prep Bumpers & Attaching Parts        | 12-Mar-2013 07:37:00 | BBODY        | C          | DON        | 86.48      |
| 18-Feb-2013 0                                    | 7,612   | 85,853  | 108302     | 15-018-003 | Paint Prep Wheels                           | 11-Mar-2013 15:25:47 | BDETL        | J          | DON        | 57.33      |
| 18-Feb-2013 0                                    | 7,612   | 85,853  | 108302     | 12-018-003 | Refinish Wheels                             | 12-Mar-2013 10:31:46 | BDETL        | J          | DON        | 733.16     |

# Unit Job History

| WO Open Date                                     | Meter 1 | Meter 2 | Work Order | Job Code   | Job Description                             | Date Completed       | Job Location | Job Reason | Job Status | Total Cost |
|--|---------|---------|------------|------------|---|----------------------|--------------|------------|------------|------------|
| <b>Unit No: E1081 - 2001 FREIGHTLIN BLUEBIRD</b> |         |         |            |            |   |                      |              |            |            |            |
| 18-Feb-2013 C                                    | 7,612   | 85,853  | 108302     | 24-002-004 | Repair Hood                                 | 13-Mar-2013 10:45:08 | BTRUCK       | I          | DON        | 283.62     |
| 20-Aug-2013 C                                    | 7,612   |         | 127576     | 02-002-044 | Clean Cab - Complete                        | 07-Sep-2013 10:00:17 | BDETL        | J          | DON        | 104.79     |
| 20-Aug-2013 C                                    | 7,612   |         | 127576     | 03-002-035 | Replace Windshield Wiper & Washer           | 30-Aug-2013 08:57:21 | BTRUCK       | I          | DON        | 26.54      |
| 20-Aug-2013 C                                    | 7,612   |         | 127576     | 03-034-006 | Replace Warning Lamps - Special Application | 05-Sep-2013 14:41:08 | BTRUCK       | I          | DON        | 137.95     |
| 20-Aug-2013 C                                    | 7,612   |         | 127576     | 03-051-009 | Replace Fire Extinguisher                   | 05-Sep-2013 14:59:06 | BTRUCK       | I          | DON        | 123.84     |
| 20-Aug-2013 C                                    | 7,612   |         | 127576     | 06-100-DOT | Inspect DOT Federal Inspection              | 10-Sep-2013 10:30:50 | BTRUCK       | P          | DON        | 0.00       |
| 20-Aug-2013 C                                    | 7,612   |         | 127576     | 06-100-PMB | Inspect B PMI                               | 30-Aug-2013 08:56:47 | BTRUCK       | P          | DON        | 531.01     |
| 20-Aug-2013 C                                    | 7,612   |         | 127576     | 03-063-003 | Replace Transceiver - GPS Tracker           | 29-Aug-2013 16:54:48 | BTRUCK       | C          | DON        | 0.00       |
| 20-Aug-2013 C                                    | 7,612   |         | 127576     | 06-100-009 | Inspect Safety Check                        | 06-Sep-2013 06:44:37 | BTRUCK       | P          | DON        | 65.50      |
| 20-Aug-2013 C                                    | 7,612   |         | 127576     | 24-043-007 | Repair Exhaust Pipe/Elbow                   | 06-Sep-2013 06:18:18 | BTRUCK       | I          | DON        | 39.03      |
| 20-Aug-2013 C                                    | 7,612   |         | 127576     | 03-079-003 | Replace Strap, Anti-Static                  | 06-Sep-2013 07:05:19 | BTRUCK       | I          | DON        | 15.73      |
| 20-Aug-2013 C                                    | 7,612   |         | 127576     | 24-001-008 | Repair Motor - Blower                       | 30-Aug-2013 08:56:52 | BTRUCK       | I          | DON        | 0.00       |
| 20-Aug-2013 C                                    | 7,612   |         | 127576     | 24-002-004 | Repair Hood                                 | 30-Aug-2013 08:56:55 | BTRUCK       | I          | DON        | 390.31     |
| 20-Aug-2013 C                                    | 7,612   |         | 127576     | 24-002-018 | Repair Cab Or Front Door Mechanism          | 30-Aug-2013 08:57:00 | BTRUCK       | I          | DON        | 71.42      |
| 20-Aug-2013 C                                    | 7,612   |         | 127576     | 24-013-003 | Repair Brake Chamber - Parking              | 30-Aug-2013 08:56:57 | BTRUCK       | I          | DON        | 639.68     |
| 20-Aug-2013 C                                    | 7,612   |         | 127576     | 24-013-023 | Repair Air Governor                         | 30-Aug-2013 08:57:02 | BTRUCK       | I          | DON        | 35.71      |
| 20-Aug-2013 C                                    | 7,612   |         | 127576     | 24-052-003 | Repair Radio Equipment                      | 30-Aug-2013 08:57:04 | BTRUCK       | I          | DON        | 871.69     |
| 20-Aug-2013 C                                    | 7,612   |         | 127576     | 03-078-009 | Replace Mud Flaps and Hanger Brackets       | 30-Aug-2013 08:57:24 | BTRUCK       | I          | DON        | 62.92      |
| 20-Aug-2013 C                                    | 7,612   |         | 127576     | 24-002-008 | Repair Instrument Panel                     | 30-Aug-2013 08:57:19 | BTRUCK       | I          | DON        | 17.85      |
| 20-Aug-2013 C                                    | 7,612   |         | 127576     | 24-013-017 | Repair Slack Adjuster                       | 30-Aug-2013 08:57:17 | BTRUCK       | I          | DON        | 40.62      |
| 20-Aug-2013 C                                    | 7,612   |         | 127576     | 24-014-005 | Repair Battery Support / Battery Box        | 30-Aug-2013 08:57:06 | BTRUCK       | I          | DON        | 89.27      |
| 20-Aug-2013 C                                    | 7,612   |         | 127576     | 24-016-002 | Repair Chassis Spring - Front               | 30-Aug-2013 08:57:26 | BTRUCK       | I          | DON        | 17.85      |
| 20-Aug-2013 C                                    | 7,612   |         | 127576     | 24-022-001 | Repair Axle Housing, Rear                   | 30-Aug-2013 08:57:11 | BTRUCK       | I          | DON        | 35.71      |
| 20-Aug-2013 C                                    | 7,612   |         | 127576     | 24-027-039 | Repair Cooler Assembly                      | 30-Aug-2013 08:57:13 | BTRUCK       | I          | DON        | 26.78      |
| 20-Aug-2013 C                                    | 7,612   |         | 127576     | 24-045-013 | Repair Oil Pan                              | 30-Aug-2013 08:57:15 | BTRUCK       | I          | DON        | 496.97     |
| 20-Aug-2013 C                                    | 7,612   |         | 127576     | 31-017-001 | Rotate Tire - Pneumatic                     | 30-Aug-2013 08:57:09 | BTRUCK       | I          | DON        | 133.91     |
| 23-Aug-2013 I                                    | 7,612   |         | 128347     | 14-063-003 | Install Transceiver - GPS Tracker           | 23-Aug-2013 14:48:34 | GPSINS       | C          | DON        | 221.43     |
| 27-Nov-2013 C                                    | 7,612   | 90,843  | 159509     | 07-100-300 | Lubricate Off Road Equip / Field Service    | 27-Nov-2013 17:00:00 | U31015       | P          | DON        | 36.83      |
| 27-Nov-2013 C                                    | 7,612   | 90,843  | 159509     | 06-100-PMB | Inspect B PMI                               | 27-Nov-2013 17:00:00 | U31015       | P          | DON        | 147.30     |

# Unit Job History

| WO Open Date                                     | Meter 1 | Meter 2 | Work Order | Job Code   | Job Description                                  | Date Completed       | Job Location | Job Reason | Job Status | Total Cost |
|--|---------|---------|------------|------------|--|----------------------|--------------|------------|------------|------------|
| <b>Unit No: E1081 - 2001 FREIGHTLIN BLUEBIRD</b> |         |         |            |            |  |                      |              |            |            |            |
| 12-Jan-2014 00                                   | 7,612   | 90,843  | 158492     | 06-100-PMA | Inspect A PMI                                    | 12-Jan-2014 17:00:00 | BTRUCK       | P          | DON        | 80.18      |
| 01-Feb-2014 0                                    |         |         | 162469     | 06-100-007 | Inspect In-Service Inspection                    | 21-Jun-2014 08:03:43 | U31015       | P          | DON        | 187.93     |
| 13-Nov-2014 0                                    |         |         | 183974     | 06-100-DOT | Inspect DOT Federal Inspection                   | 13-Nov-2014 17:00:00 | BVLOFC       | P          | DON        | 0.00       |
| 29-Apr-2016 1                                    |         |         | 245329     | 02-002     | Clean Cab & Sheet Metal                          | 29-Apr-2016 14:29:41 | BVLOFC       | O          | DON        | 215.90     |
| 29-Apr-2016 1                                    |         |         | 245329     | 06-100-DOT | Inspect DOT Federal Inspection                   | 29-Apr-2016 14:29:13 | BTRUCK       | P          | DON        | 44.68      |
| 29-Apr-2016 1                                    |         |         | 245329     | 24-033-001 | Repair Ignition Switch                           | 29-Apr-2016 14:31:12 | BVLOFC       | O          | DON        | 151.81     |
| 16-May-2016 0                                    |         |         | 246458     | 03-032-001 | Replace Battery                                  | 04-Jun-2016 06:48:14 | U60950       | F          | DON        | 73.65      |
| 16-May-2016 0                                    |         |         | 246458     | 03-034-004 | Replace Clearance & Marker Lamps                 | 04-Jun-2016 06:48:14 | U60950       | F          | DON        | 73.65      |
| 16-May-2016 0                                    |         |         | 246458     | 03-018     | Replace Wheels, Rims, Hubs & Bearings            | 04-Jun-2016 06:48:14 | U60950       | F          | DON        | 73.65      |
| 16-May-2016 0                                    |         |         | 246458     | 13-033-001 | Assemble Ignition Switch                         | 04-Jun-2016 06:48:14 | U60950       | F          | DON        | 73.65      |
| 16-May-2016 0                                    |         |         | 246458     | 07-053-999 | Lubricate Vehicle Fluids, Lubricants, Gases, & I | 04-Jun-2016 06:48:14 | U60950       | F          | DON        | 105.63     |
| 07-Jun-2016 1                                    |         |         | 248698     | 06-017     | Inspect Tires, Tubes, Liners & Valves            | 17-Jun-2016 14:10:32 | U60950       | F          | DON        | 1,095.14   |
| 08-Jun-2016 1                                    |         |         | 248062     | 03-017     | Replace Tires, Tubes, Liners & Valves            | 13-Jun-2016 12:07:01 | U60950       | F          | DON        | 984.66     |
| 09-Jun-2016 1                                    |         |         | 247646     | 03-017-001 | Replace Tire - Pneumatic                         | 09-Jun-2016 14:17:27 | BTIRE        | F          | DON        | 1,077.88   |
| 10-Aug-2016 1                                    |         |         | 255423     | 03-017-001 | Replace Tire - Pneumatic                         | 16-Aug-2016 10:42:59 | BTIRE        | E          | DON        | 1,587.88   |
| 10-Aug-2016 1                                    |         |         | 255423     | 03-045-023 | Replace Engine Belts                             | 27-Dec-2016 11:26:49 | U60950       | F          | DON        | 42.05      |
| 16-Sep-2016 0                                    |         |         | 259689     | 01-045-026 | Adjust Tensioner - Engine Belts                  | 20-Sep-2016 07:38:22 | BTRUCK       | I          | DON        | 23.57      |
| 16-Sep-2016 0                                    |         |         | 259689     | 03-002-010 | Replace Mirrors                                  | 27-Sep-2016 16:40:56 | BTRUCK       | I          | DON        | 82.71      |
| 16-Sep-2016 0                                    |         |         | 259689     | 03-002-024 | Replace Glass / Windshield                       | 27-Sep-2016 16:04:50 | BTRUCK       | I          | DON        | 213.13     |
| 16-Sep-2016 0                                    |         |         | 259689     | 03-013-016 | Replace Air Dryer / Purge Valve                  | 19-Sep-2016 06:51:29 | BTRUCK       | I          | DON        | 84.65      |
| 16-Sep-2016 0                                    |         |         | 259689     | 03-024-005 | Replace Universal Joint                          | 28-Sep-2016 15:40:33 | BTRUCK       | I          | DON        | 119.67     |
| 16-Sep-2016 0                                    |         |         | 259689     | 03-043-003 | Replace Muffler                                  | 28-Sep-2016 12:01:38 | BTRUCK       | I          | DON        | 561.11     |
| 16-Sep-2016 0                                    |         |         | 259689     | 06-100-009 | Inspect Safety Check                             | 16-Sep-2016 11:50:45 | BTRUCK       | P          | DON        | 98.60      |
| 16-Sep-2016 0                                    |         |         | 259689     | 07-010-001 | Lubricate All Axles                              | 28-Sep-2016 16:43:04 | BTRUCK       | I          | DON        | 34.79      |
| 16-Sep-2016 0                                    |         |         | 259689     | 07-013-035 | Lubricate Clevis Pins                            | 20-Sep-2016 07:06:37 | BTRUCK       | I          | DON        | 20.91      |
| 16-Sep-2016 0                                    |         |         | 259689     | 14-078-009 | Install Mud Flaps and Hanger Brackets            | 19-Sep-2016 09:14:41 | BTRUCK       | I          | DON        | 89.76      |
| 16-Sep-2016 0                                    |         |         | 259689     | 18-032-001 | Test Battery                                     | 16-Sep-2016 14:09:43 | BTRUCK       | I          | DON        | 31.70      |
| 16-Sep-2016 0                                    |         |         | 259689     | 24-034-002 | Repair Stop, Tail, Turn & License                | 16-Sep-2016 15:21:04 | BTRUCK       | I          | DON        | 51.58      |
| 16-Sep-2016 0                                    |         |         | 259689     | 24-043-007 | Repair Exhaust Pipe/Elbow                        | 28-Sep-2016 14:35:48 | BTRUCK       | I          | DON        | 640.42     |

# Unit Job History

| WO Open Date                                     | Meter 1 | Meter 2 | Work Order | Job Code   | Job Description                     | Date Completed       | Job Location | Job Reason | Job Status | Total Cost |
|--|---------|---------|------------|------------|-------------------------------------|----------------------|--------------|------------|------------|------------|
| <b>Unit No: E1081 - 2001 FREIGHTLIN BLUEBIRD</b> |         |         |            |            |                                     |                      |              |            |            |            |
| 16-Sep-2016 0                                    |         |         | 259689     | 24-052-003 | Repair Radio Equipment              | 16-Sep-2016 16:48:13 | BTRUCK       | I          | DON        | 205.88     |
| 17-May-2017 (                                    |         |         | 289290     | 03-032-001 | Replace Battery                     | 25-May-2017 07:42:34 | BTRUCK       | O          | DON        | 508.36     |
| 17-May-2017 (                                    |         |         | 289290     | 06-100-DOT | Inspect DOT Federal Inspection      | 26-May-2017 05:58:23 | BTRUCK       | P          | DON        | 64.03      |
| 17-May-2017 (                                    |         |         | 289290     | 24-063-003 | Repair Transceiver - GPS Tracker    | 25-May-2017 09:18:21 | BTRUCK       | Q          | DON        | 2.91       |
| 17-May-2017 (                                    |         |         | 289290     | 02-002     | Clean Cab & Sheet Metal             | 03-Jul-2017 12:16:15 | BSETUP       | J          | DON        | 317.15     |
| 17-May-2017 (                                    |         |         | 289290     | 12-018-003 | Refinish Wheels                     | 03-Jul-2017 08:43:22 | BSETUP       | I          | DON        | 217.21     |
| 17-May-2017 (                                    |         |         | 289290     | 38-045     | Service Power Plant                 | 25-May-2017 16:01:26 | BTRUCK       | P          | DON        | 215.59     |
| 17-May-2017 (                                    |         |         | 289290     | 06-100-PMB | Inspect B PMI                       | 26-May-2017 05:33:53 | BTRUCK       | P          | DON        | 127.03     |
| 17-May-2017 (                                    |         |         | 289290     | 03-041-001 | Replace Air Cleaner                 | 05-Jun-2017 05:33:12 | BTRUCK       | I          | DON        | 195.24     |
| 17-May-2017 (                                    |         |         | 289290     | 03-041-007 | Replace Filter - Outer              | 05-Jun-2017 05:59:12 | BTRUCK       | I          | DON        | 14.47      |
| 17-May-2017 (                                    |         |         | 289290     | 03-051-009 | Replace Fire Extinguisher           | 25-May-2017 10:24:21 | BTRUCK       | I          | DON        | 109.86     |
| 17-May-2017 (                                    |         |         | 289290     | 03-034-020 | Replace Dome / Reading Light        | 25-May-2017 11:42:19 | BTRUCK       | I          | DON        | 58.88      |
| 17-May-2017 (                                    |         |         | 289290     | 03-002-010 | Replace Mirrors                     | 05-Jun-2017 08:40:34 | BTRUCK       | I          | DON        | 85.76      |
| 17-May-2017 (                                    |         |         | 289290     | 03-002-035 | Replace Windshield Wiper & Washer   | 25-May-2017 15:23:25 | BTRUCK       | I          | DON        | 18.81      |
| 17-May-2017 (                                    |         |         | 289290     | 03-034-010 | Replace Socket - Trailer Light Cord | 07-Jul-2017 15:39:04 | BTRUCK       | I          | DON        | 227.83     |
| 17-May-2017 (                                    |         |         | 289290     | 26-059-006 | Weld Towing Hitch Assembly          | 06-Jul-2017 08:04:55 | BWELD        | I          | DON        | 341.48     |
| 17-May-2017 (                                    |         |         | 289290     | 01-022-001 | Adjust Axle Housing, Rear           | 25-May-2017 16:21:34 | BTRUCK       | I          | DON        | 351.36     |
| 17-May-2017 (                                    |         |         | 289290     | 03-034     | Replace Lighting System             | 05-Jun-2017 07:42:33 | BTRUCK       | I          | DON        | 84.32      |
| 08-Dec-2017 0                                    |         |         | 315300     | 12-002-004 | Refinish Hood                       | 14-Dec-2017 10:26:35 | BBODY        | K          | DON        | 198.73     |
| 08-Dec-2017 0                                    |         |         | 315300     | 24-002-004 | Repair Hood                         | 15-Dec-2017 11:07:21 | BBODY        | K          | DON        | 193.71     |
| 22-Feb-2018 1                                    |         |         | 324774     | 01-042-013 | Adjust Fan Belt                     | 26-Feb-2018 08:36:14 | BTRUCK       | I          | DON        | 100.07     |
| 22-Feb-2018 1                                    |         |         | 324774     | 03-016-010 | Replace Air Spring                  | 26-Feb-2018 12:00:19 | BTRUCK       | I          | DON        | 341.94     |
| 22-Feb-2018 1                                    |         |         | 324774     | 03-034-001 | Replace Headlamps / Fog Lamps       | 26-Feb-2018 05:47:23 | BTRUCK       | I          | DON        | 83.33      |
| 22-Feb-2018 1                                    |         |         | 324774     | 03-051-009 | Replace Fire Extinguisher           | 23-Feb-2018 06:41:48 | BTRUCK       | I          | DON        | 110.98     |
| 22-Feb-2018 1                                    |         |         | 324774     | 06-100-DOT | Inspect DOT Federal Inspection      | 26-Feb-2018 05:58:07 | BTRUCK       | P          | DON        | 97.53      |
| 22-Feb-2018 1                                    |         |         | 324774     | 06-100-PMB | Inspect B PMI                       | 24-Feb-2018 10:00:58 | BTRUCK       | P          | DON        | 202.52     |
| 22-Feb-2018 1                                    |         |         | 324774     | 07-010-001 | Lubricate All Axles                 |                      | BTRUCK       | P          | CAN        | 0.00       |
| 22-Feb-2018 1                                    |         |         | 324774     | 24-002-022 | Repair Rear Door Mechanism          | 23-Feb-2018 12:00:16 | BTRUCK       | I          | DON        | 19.68      |
| 22-Feb-2018 1                                    |         |         | 324774     | 24-013-004 | Repair Brake Chamber - Service      | 23-Feb-2018 16:33:19 | BTRUCK       | I          | DON        | 16.46      |

# Unit Job History

| WO Open Date                                     | Meter 1 | Meter 2 | Work Order | Job Code   | Job Description                                 | Date Completed       | Job Location | Job Reason | Job Status | Total Cost |
|--|---------|---------|------------|------------|---|----------------------|--------------|------------|------------|------------|
| <b>Unit No: E1081 - 2001 FREIGHTLIN BLUEBIRD</b> |         |         |            |            |   |                      |              |            |            |            |
| 22-Feb-2018 I                                    |         |         | 324774     | 24-034-003 | Repair Signal, Parking, Backup Lamps            | 23-Feb-2018 16:03:44 | BTRUCK       | I          | DON        | 8.31       |
| 22-Feb-2018 I                                    |         |         | 324774     | 24-034-004 | Repair Clearance & Marker Lamps                 | 23-Feb-2018 14:54:51 | BTRUCK       | I          | DON        | 15.19      |
| 22-Feb-2018 I                                    |         |         | 324774     | 38-045     | Service Power Plant                             | 23-Feb-2018 13:22:19 | BTRUCK       | P          | DON        | 146.58     |
| 30-Aug-2019 C                                    |         |         | 401013     | 03-045-027 | Replace Idler Pulley                            | 02-Sep-2019 05:00:00 | 180950       | B          | DON        | 234.81     |
| 30-Aug-2019 C                                    |         |         | 401013     | 06-100-DOT | Inspect DOT Federal Inspection                  | 02-Sep-2019 05:00:00 | 180950       | P          | DON        | 0.00       |
| 30-Aug-2019 C                                    |         |         | 401013     | 03-032-001 | Replace Battery                                 | 02-Sep-2019 05:00:00 | 180950       | B          | DON        | 0.00       |
| 30-Aug-2019 C                                    |         |         | 401013     | 11-031-001 | Rebuild Generator/Alternator                    | 02-Sep-2019 05:00:00 | 180950       | B          | DON        | 58.30      |
| 10-Oct-2019 I                                    |         |         | 407004     | 01-013     | Adjust Brakes                                   | 11-Oct-2019 08:22:11 | WSHSHP       | I          | DON        | 202.23     |
| 10-Oct-2019 I                                    |         |         | 407004     | 03-001-016 | Replace Filter - Cab Ventilation                | 11-Oct-2019 08:22:11 | WSHSHP       | P          | DON        | 134.72     |
| 10-Oct-2019 I                                    |         |         | 407004     | 03-002-010 | Replace Mirrors                                 | 11-Oct-2019 08:22:11 | WSHSHP       | I          | DON        | 489.38     |
| 10-Oct-2019 I                                    |         |         | 407004     | 03-013-001 | Replace Front Brakes & Drums                    | 11-Oct-2019 08:22:11 | WSHSHP       | I          | DON        | 557.44     |
| 10-Oct-2019 I                                    |         |         | 407004     | 03-013-015 | Replace Desiccant Cartridge Kit - Air           | 11-Oct-2019 08:22:11 | WSHSHP       | P          | DON        | 140.62     |
| 10-Oct-2019 I                                    |         |         | 407004     | 03-014-004 | Replace Cab & Body Mountings                    | 11-Oct-2019 08:22:11 | WSHSHP       | I          | DON        | 815.78     |
| 10-Oct-2019 I                                    |         |         | 407004     | 03-032-001 | Replace Battery                                 | 11-Oct-2019 08:22:11 | WSHSHP       | I          | DON        | 445.27     |
| 10-Oct-2019 I                                    |         |         | 407004     | 03-034-004 | Replace Clearance & Marker Lamps                | 11-Oct-2019 08:22:11 | WSHSHP       | I          | DON        | 75.70      |
| 10-Oct-2019 I                                    |         |         | 407004     | 03-034-020 | Replace Dome / Reading Light                    | 11-Oct-2019 08:22:11 | WSHSHP       | I          | DON        | 30.89      |
| 10-Oct-2019 I                                    |         |         | 407004     | 03-041-006 | Replace Filter - Inner                          | 11-Oct-2019 08:22:11 | WSHSHP       | P          | DON        | 48.35      |
| 10-Oct-2019 I                                    |         |         | 407004     | 03-052-010 | Replace Fan - Auxiliary                         | 11-Oct-2019 08:22:11 | WSHSHP       | I          | DON        | 249.03     |
| 10-Oct-2019 I                                    |         |         | 407004     | 03-078-009 | Replace Mud Flaps and Hanger Brackets           | 11-Oct-2019 08:22:11 | WSHSHP       | I          | DON        | 157.52     |
| 10-Oct-2019 I                                    |         |         | 407004     | 03-079-009 | Replace Tape - Reflective, Conspicuity          | 11-Oct-2019 08:22:11 | WSHSHP       | I          | DON        | 111.39     |
| 10-Oct-2019 I                                    |         |         | 407004     | 06-100-DOT | Inspect DOT Federal Inspection                  | 11-Oct-2019 08:22:11 | WSHSHP       | P          | DON        | 348.60     |
| 10-Oct-2019 I                                    |         |         | 407004     | 06-100-PMB | Inspect B PMI                                   | 11-Oct-2019 08:22:11 | WSHSHP       | P          | DON        | 647.37     |
| 10-Oct-2019 I                                    |         |         | 407004     | 34-045-029 | Reseal Rocker Box                               | 11-Oct-2019 08:22:11 | WSHSHP       | I          | DON        | 589.20     |
| 10-Oct-2019 I                                    |         |         | 407004     | 38-100-PMB | Service B PMI                                   | 11-Oct-2019 08:22:11 | WSHSHP       | P          | DON        | 0.00       |
| 05-Nov-2020 I                                    |         |         | 471097     | 38-032-006 | Service Emergency Start                         | 05-Nov-2020 23:00:00 | WSHSHP       | B          | DON        | 162.17     |
| 22-Dec-2020 0                                    |         |         | 483365     | 03-032-001 | Replace Battery                                 | 19-Jan-2021 23:00:00 | WSHSHP       | N          | DON        | 274.89     |
| 05-Apr-2021 I                                    |         |         | 501113     | 06-100-DOT | Inspect DOT Federal Inspection                  | 08-Apr-2021 23:00:00 | WSHSHP       | P          | DON        | 75.75      |
| 05-Apr-2021 I                                    |         |         | 501113     | 24-013-007 | Repair Brake Lines & Fittings - Hydraulic & Air | 08-Apr-2021 23:00:00 | WSHSHP       | I          | DON        | 331.40     |
| 05-Apr-2021 I                                    |         |         | 501113     | 24-034     | Repair Lighting System                          | 08-Apr-2021 23:00:00 | WSHSHP       | I          | DON        | 242.30     |



# Unit Job History

| WO Open Date                                     | Meter 1 | Meter 2 | Work Order | Job Code   | Job Description                                | Date Completed       | Job Location | Job Reason | Job Status | Total Cost |
|--|---------|---------|------------|------------|--|----------------------|--------------|------------|------------|------------|
| <b>Unit No: E1081 - 2001 FREIGHTLIN BLUEBIRD</b> |         |         |            |            |  |                      |              |            |            |            |
| 05-Apr-2021 1                                    |         |         | 501113     | 34-013-009 | Reseal Air Compressor                          | 08-Apr-2021 23:00:00 | WSHSHP       | I          | DON        | 1,186.37   |
| 05-Apr-2021 1                                    |         |         | 501113     | 34-045-028 | Reseal Valve Cover                             | 08-Apr-2021 23:00:00 | WSHSHP       | I          | DON        | 1,363.71   |
| 08-Jun-2021 1                                    |         |         | 511410     | 03-017-001 | Replace Tire - Pneumatic                       | 25-Jun-2021 16:18:00 | PIPE13       | I          | DON        | 1,123.18   |
| 08-Jun-2021 1                                    |         |         | 511410     | 03-044-014 | Replace Injectors - Electronic                 | 25-Jun-2021 16:18:00 | PIPE13       | N          | DON        | 863.03     |
| 04-Feb-2022 1                                    |         |         | 579771     | 02-071     | Clean Body                                     | 14-Apr-2022 23:00:00 | WSHSHP       | Q          | DON        | 111.40     |
| 04-Feb-2022 1                                    |         |         | 579771     | 03-001-016 | Replace Filter - Cab Ventilation               | 14-Apr-2022 23:00:00 | WSHSHP       | P          | DON        | 76.04      |
| 04-Feb-2022 1                                    |         |         | 579771     | 03-002-035 | Replace Windshield Wiper & Washer              | 14-Apr-2022 23:00:00 | WSHSHP       | N          | DON        | 6.64       |
| 04-Feb-2022 1                                    |         |         | 579771     | 03-013-007 | Replace Brake Lines & Fittings - Hydraulic & A | 14-Apr-2022 23:00:00 | WSHSHP       | N          | DON        | 401.11     |
| 04-Feb-2022 1                                    |         |         | 579771     | 03-013-015 | Replace Desiccant Cartridge Kit - Air          | 14-Apr-2022 23:00:00 | WSHSHP       | P          | DON        | 171.61     |
| 04-Feb-2022 1                                    |         |         | 579771     | 03-027-045 | Replace Filter Assembly                        | 14-Apr-2022 23:00:00 | WSHSHP       | P          | DON        | 106.36     |
| 04-Feb-2022 1                                    |         |         | 579771     | 03-032-001 | Replace Battery                                | 14-Apr-2022 23:00:00 | WSHSHP       | N          | DON        | 484.88     |
| 04-Feb-2022 1                                    |         |         | 579771     | 03-034-004 | Replace Clearance & Marker Lamps               | 14-Apr-2022 23:00:00 | WSHSHP       | N          | DON        | 86.51      |
| 04-Feb-2022 1                                    |         |         | 579771     | 03-034-010 | Replace Socket - Trailer Light Cord            | 14-Apr-2022 23:00:00 | WSHSHP       | B          | DON        | 276.48     |
| 04-Feb-2022 1                                    |         |         | 579771     | 03-041-001 | Replace Air Cleaner                            | 14-Apr-2022 23:00:00 | WSHSHP       | P          | DON        | 81.02      |
| 04-Feb-2022 1                                    |         |         | 579771     | 03-043-007 | Replace Exhaust Pipe/Eibow                     | 14-Apr-2022 23:00:00 | WSHSHP       | N          | DON        | 794.28     |
| 04-Feb-2022 1                                    |         |         | 579771     | 06-100-DOT | Inspect DOT Federal Inspection                 | 30-Mar-2022 15:43:00 | WSHSHP       | P          | DON        | 2.38       |
| 04-Feb-2022 1                                    |         |         | 579771     | 06-100-PMA | Inspect A PMI                                  | 14-Apr-2022 23:00:00 | WSHSHP       | P          | DON        | 76.87      |
| 04-Feb-2022 1                                    |         |         | 579771     | 24-044-001 | Repair Tank - Fuel, Liquid                     | 14-Apr-2022 23:00:00 | WSHSHP       | N          | DON        | 308.39     |
| 04-Feb-2022 1                                    |         |         | 579771     | 24-071-004 | Repair Roof Assembly & Skylight                | 14-Apr-2022 23:00:00 | WSHSHP       | B          | DON        | 1,037.45   |
| 04-Feb-2022 1                                    |         |         | 579771     | 38-100-PMA | Service A PMI                                  | 14-Apr-2022 23:00:00 | WSHSHP       | P          | DON        | 474.46     |
| 16-Mar-2022 0                                    |         |         | 574826     | 03-063-003 | Replace Transceiver - GPS Tracker              | 16-Mar-2022 08:20:30 | ELEC02       | Q          | DON        | 429.16     |
| 28-Mar-2023 0                                    |         |         | 663395     | 06-100-DOT | Inspect DOT Federal Inspection                 | 28-Mar-2023 10:05:00 | WSHSHP       | P          | DON        | 349.84     |
| 28-Mar-2023 0                                    |         |         | 663395     | 06-100-PMA | Inspect A PMI                                  | 28-Mar-2023 10:05:00 | WSHSHP       | P          | DON        | 0.00       |
| 28-Mar-2023 0                                    |         |         | 663395     | 24-018-001 | Repair Front Axle Hubs & Bearings              | 03-Apr-2023 14:58:11 | WSHSHP       | I          | DON        | 215.92     |
| 19-Aug-2023 C                                    |         |         | 701145     | 03-016-010 | Replace Air Spring                             | 09-Nov-2023 10:05:09 | PIPE19       | B          | DON        | 170.00     |
| 30-Aug-2023 C                                    |         |         | 701186     | 06-100-PMA | Inspect A PMI                                  | 26-Oct-2023 09:51:44 | WSHSHP       | P          | DON        | 0.00       |
| 30-Aug-2023 C                                    |         |         | 701186     | 14-032-009 | Install Switch - Master Disconnect             | 26-Oct-2023 09:51:44 | WSHSHP       | N          | DON        | 0.00       |
| 30-Aug-2023 C                                    |         |         | 701186     | 38-100-PMA | Service A PMI                                  | 26-Oct-2023 09:51:44 | WSHSHP       | P          | DON        | 0.00       |
| 15-May-2024 (                                    |         |         | 759888     | 06-100-009 | Inspect Safety Check                           | 15-May-2024 16:00:54 | BTRUCK       | P          | DON        | 37.69      |

# Unit Job History

| WO Open Date                                     | Meter 1 | Meter 2 | Work Order | Job Code | Job Description            | Date Completed       | Job Location | Job Reason | Job Status | Total Cost |
|--|---------|---------|------------|----------|----------------------------|----------------------|--------------|------------|------------|------------|
| <b>Unit No: E1081 - 2001 FREIGHTLIN BLUEBIRD</b> |         |         |            |          |                            |                      |              |            |            |            |
| 23-May-2024 (                                    |         |         | 761673     | 25-051   | Remove General Accessories | 28-May-2024 15:46:22 | BSETUP       | Z          | DON        | 157.10     |
| 23-May-2024 (                                    |         |         | 761673     | 02-002   | Clean Cab & Sheet Metal    |                      | BSETUP       | Z          | WND        | 201.27     |

Unit No: E1081

Count: 176

49,065.12