

# Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
<b>Unit No: E1514 - 2018 JOHN DEERE 320E</b>										
25-Jan-2018 10:00	4	0	321071	03-017-005	Replace Tire - Solid	27-Jan-2018 05:50:29	BBKHOE	Q	DON	3,876.59
25-Jan-2018 10:00	4	0	321071	14-063-003	Install Transceiver - GPS Tracker	25-Jan-2018 16:44:46	BBKHOE	Q	DON	288.32
25-Jan-2018 10:00	4	0	321071	21-360-001	Fabricate Bucket and Attachments	26-Jan-2018 10:23:36	BBKHOE	I	DON	120.06
21-Dec-2018 0	444	0	365749	02-002	Clean Cab & Sheet Metal	03-Jan-2019 10:15:31	BSETUP	I	DON	36.81
21-Dec-2018 0	444	0	365749	06-100-PMA	Inspect A PMI	02-Jan-2019 08:19:36	BBKHOE	P	DON	1,022.58
21-Dec-2018 0	444	0	365749	10-360-011	Rebush Quick-Attach Coupling Assembly	31-Dec-2018 14:17:04	BBKHOE	P	DON	49.39
21-Dec-2018 0	444	0	365749	14-002-027	Install Seat Frames & Springs	28-Dec-2018 13:10:45	BBKHOE	Q	DON	1,046.47
21-Dec-2018 0	444	0	365749	14-032-009	Install Switch - Master Disconnect	31-Dec-2018 12:00:44	BBKHOE	Q	DON	133.32
21-Dec-2018 0	444	0	365749	24-063-003	Repair Transceiver - GPS Tracker	28-Dec-2018 10:33:30	BBKHOE	Q	DON	319.17
07-Nov-2019 0	0	0	411501	03-360-003	Replace Drive Train	07-Nov-2019 13:43:39	BBKHOE	B	DON	586.81
10-Nov-2019 0	0	0	412297	11-065-004	Rebuild Cylinder	12-Nov-2019 11:44:46	BVLOFC	N	DON	750.27
27-Dec-2019 0	942	0	418413	03-017-002	Replace Tire - Semi-Pneumatic	09-Jan-2020 15:39:37	BBKHOE	I	DON	1,531.99
27-Dec-2019 0	942	0	418413	03-360-003	Replace Drive Train	03-Jan-2020 10:09:42	BBKHOE	P	DON	492.40
27-Dec-2019 0	942	0	418413	06-100-PMA	Inspect A PMI	10-Jan-2020 11:01:40	BBKHOE	P	DON	265.52
27-Dec-2019 0	942	0	418413	24-360-011	Repair Quick-Attach Coupling Assembly	06-Jan-2020 10:04:11	BBKHOE	I	DON	729.49
27-Dec-2019 0	942	0	418413	38-100-PMC	Service C PMI	03-Jan-2020 14:57:04	BBKHOE	I	DON	480.67
11-Mar-2020 0	0	0	430451	06-100-PMA	Inspect A PMI	11-Mar-2020 08:07:38	BSMEQP	P	DON	0.00
11-Mar-2020 0	0	0	430451	38-100-PMA	Service A PMI	11-Mar-2020 08:07:40	BHVYEQ	P	DON	290.95
26-Aug-2020 1	1,355	0	458216	24-360-011	Repair Quick-Attach Coupling Assembly	30-Sep-2020 09:37:13	BHVYEQ	O	DON	929.70
23-Oct-2020 0	0	0	468329	24-017-001	Repair Tire - Pneumatic	23-Oct-2020 06:48:02	BTIRE	I	DON	12.92
28-Oct-2020 1	1,470	0	469270	24-049-001	Repair ECM Fault Code	28-Oct-2020 14:23:06	BHVYEQ	B	DON	867.66
17-Nov-2020 0	0	0	472449	03-017-001	Replace Tire - Pneumatic	20-Nov-2020 12:49:56	BTIRE	N	DON	0.00
28-Jan-2021 1	1,677	0	485148	02-360	Clean Loader / Skid-Steer	01-Feb-2021 12:07:18	BWASH	N	DON	714.37
28-Jan-2021 1	1,677	0	485148	03-063-003	Replace Transceiver - GPS Tracker	05-Feb-2021 08:57:52	BBKHOE	Q	DON	319.46
28-Jan-2021 1	1,677	0	485148	03-065-004	Replace Cylinder	04-Feb-2021 14:05:30	BBKHOE	I	DON	517.32
28-Jan-2021 1	1,677	0	485148	03-065-007	Replace Hoses & Fittings	05-Feb-2021 17:00:14	BBKHOE	I	DON	616.70
28-Jan-2021 1	1,677	0	485148	03-360-003	Replace Drive Train	03-Feb-2021 16:52:37	BBKHOE	P	DON	2,203.28
28-Jan-2021 1	1,677	0	485148	06-100-PMA	Inspect A PMI	08-Feb-2021 14:00:22	BBKHOE	P	DON	307.01
28-Jan-2021 1	1,677	0	485148	24-043-004	Repair Turbocharger	05-Feb-2021 07:25:55	BBKHOE	I	DON	28.75

# Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
<b>Unit No: E1514 - 2018 JOHN DEERE 320E</b>										
28-Jan-2021 11	1,677	0	485148	24-360-011	Repair Quick-Attach Coupling Assembly	05-Feb-2021 10:11:52	BBKHOE	I	DON	539.89
28-Jan-2021 11	1,677	0	485148	38-100-PMC	Service C PMI	04-Feb-2021 11:14:48	BBKHOE	I	DON	854.96
08-Apr-2021 1	1,679	0	499345	03-017-001	Replace Tire - Pneumatic	13-Apr-2021 07:10:47	BTIRE	I	DON	880.20
24-Feb-2022 0	2,276	0	569534	02-360	Clean Loader / Skid-Steer	03-Mar-2022 10:55:09	BWASH	N	DON	225.78
24-Feb-2022 0	2,276	0	569534	03-021-001	Replace Axle Assembly - Driven, Front Steering	16-Mar-2022 06:28:36	BBKHOE	I	DON	1,433.80
24-Feb-2022 0	2,276	0	569534	03-054-001	Replace Horn & Mounting	18-Mar-2022 06:41:15	BBKHOE	I	DON	94.67
24-Feb-2022 0	2,276	0	569534	03-065-004	Replace Cylinder	16-Mar-2022 06:28:29	BBKHOE	N	DON	1,429.61
24-Feb-2022 0	2,276	0	569534	03-065-008	Replace Line / Tubing Assembly	21-Mar-2022 05:27:31	BBKHOE	I	DON	507.57
24-Feb-2022 0	2,276	0	569534	03-360-003	Replace Drive Train	16-Mar-2022 06:28:50	BBKHOE	N	DON	608.39
24-Feb-2022 0	2,276	0	569534	03-360-009	Replace Bucket Tooth / Cutting Edge	24-Feb-2022 14:52:28	BBKHOE	P	DON	270.81
24-Feb-2022 0	2,276	0	569534	06-100-PMA	Inspect A PMI	21-Mar-2022 05:27:07	BBKHOE	P	DON	200.00
24-Feb-2022 0	2,276	0	569534	06-100-PMB	Inspect B PMI	21-Mar-2022 05:27:01	BBKHOE	P	DON	0.00
24-Feb-2022 0	2,276	0	569534	24-360-011	Repair Quick-Attach Coupling Assembly	17-Mar-2022 13:10:15	BBKHOE	N	DON	1,350.38
24-Feb-2022 0	2,276	0	569534	38-100-PMC	Service C PMI	16-Mar-2022 06:28:22	BBKHOE	P	DON	914.48
25-Mar-2022 1	2,276	0	577399	24-017-001	Repair Tire - Pneumatic	25-Mar-2022 16:21:16	BTIRE	O	DON	26.83
26-Apr-2022 1	2,276	0	584554	03-054-001	Replace Horn & Mounting	26-Apr-2022 13:16:24	BHVEYQ	O	DON	62.75
26-Apr-2022 1	2,276	0	584554	03-065-006	Replace Filters, Strainers, Screens & Housing	26-Apr-2022 13:16:27	BHVEYQ	O	DON	69.27
27-Jun-2022 1	2,276	0	598885	03-041-006	Replace Filter - Inner	27-Jun-2022 13:18:17	BHVEYQ	O	DON	42.05
27-Jun-2022 1	2,276	0	598885	03-041-007	Replace Filter - Outer	27-Jun-2022 13:17:59	BHVEYQ	O	DON	45.32
27-Jun-2022 1	2,276	0	598885	03-044-002	Replace Filters	27-Jun-2022 13:17:42	BHVEYQ	O	DON	69.59
27-Jun-2022 1	2,276	0	598885	03-045-011	Replace Filter Assembly - Oil	27-Jun-2022 13:17:25	BHVEYQ	O	DON	18.50
27-Jun-2022 1	2,276	0	598885	03-065-006	Replace Filters, Strainers, Screens & Housing	27-Jun-2022 13:16:53	BHVEYQ	O	DON	66.85
12-Jul-2022 08	2,276	0	601838	03-017-001	Replace Tire - Pneumatic	12-Jul-2022 09:56:42	BTIRE	O	DON	11.49
10-Aug-2022 1	2,276	0	608612	03-017-001	Replace Tire - Pneumatic	10-Aug-2022 13:41:38	BTIRE	O	DON	10.22
26-Aug-2022 0	2,276	0	612198	03-001-016	Replace Filter - Cab Ventilation		BHVEYQ	O	CAN	0.00
26-Aug-2022 0	2,276	0	612198	03-002-035	Replace Windshield Wiper & Washer		BHVEYQ	O	CAN	0.00
26-Aug-2022 0	2,276	0	612198	03-041-007	Replace Filter - Outer		BHVEYQ	O	CAN	0.00
07-Sep-2022 1	2,276	0	614588	03-065-004	Replace Cylinder	07-Sep-2022 16:01:30	BBKHOE	I	DON	1,033.82
07-Sep-2022 1	2,276	0	614588	03-065-006	Replace Filters, Strainers, Screens & Housing	14-Sep-2022 05:16:05	BBKHOE	P	DON	225.93

# Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
<b>Unit No: E1514 - 2018 JOHN DEERE 320E</b>										
13-Dec-2022 0	0	638908	02-360	02-360	Clean Loader / Skid-Steer	14-Dec-2022 12:20:06	BWASH	N	DON	225.21
13-Dec-2022 0	0	638908	03-032-009	03-032-009	Replace Switch - Master Disconnect	06-Jan-2023 08:37:41	BBKHOE	P	DON	160.00
13-Dec-2022 0	0	638908	06-100-PMA	06-100-PMA	Inspect A PMI	18-Jan-2023 05:58:37	BBKHOE	P	DON	134.67
13-Dec-2022 0	0	638908	24-034-001	24-034-001	Repair Headlamps / Fog Lamps	06-Jan-2023 11:03:52	BBKHOE	P	DON	182.33
13-Dec-2022 0	0	638908	24-360-004	24-360-004	Repair Final Drive	06-Jan-2023 10:28:10	BBKHOE	I	DON	132.57
13-Dec-2022 0	0	638908	24-360-011	24-360-011	Repair Quick-Attach Coupling Assembly	09-Jan-2023 10:26:23	BBKHOE	P	DON	1,060.63
13-Dec-2022 0	0	638908	38-100-PMB	38-100-PMB	Service B PMI	06-Jan-2023 07:46:02	BBKHOE	P	DON	658.25
10-May-2023 0	0	673295	24-360-006	24-360-006	Repair Lift Arm Assembly	10-May-2023 11:23:05	TRK005	B	DON	658.82
17-May-2023 0	0	675167	24-513-002	24-513-002	Repair Quick Attachment	17-May-2023 12:59:24	BBKHOE	O	DON	9.63
16-Oct-2023 0	0	713238	03-001-016	03-001-016	Replace Filter - Cab Ventilation		BHVYEQ	O	CAN	0.00
16-Oct-2023 0	0	713238	03-041-006	03-041-006	Replace Filter - Inner		BHVYEQ	O	CAN	0.00
16-Oct-2023 0	0	713238	03-041-007	03-041-007	Replace Filter - Outer		BHVYEQ	O	CAN	0.00
18-Oct-2023 0	0	713872	38-100-PMA	38-100-PMA	Service A PMI	18-Oct-2023 10:58:41	BHVYEQ	O	DON	181.93
13-Nov-2023 0	0	720197	24-044-007	24-044-007	Repair Throttle Controls	13-Nov-2023 16:35:50	BHVYEQ	B	DON	1,510.79
04-Jan-2024 0	0	730281	03-065-006	03-065-006	Replace Filters, Strainers, Screens & Housing	04-Jan-2024 13:16:15	BHVYEQ	P	DON	73.57
04-Jan-2024 0	0	730281	38-100-PMA	38-100-PMA	Service A PMI	04-Jan-2024 13:15:57	BHVYEQ	P	DON	179.95
11-Mar-2024 0	0	744829	03-017-001	03-017-001	Replace Tire - Pneumatic	11-Mar-2024 15:23:43	BTIRE	N	DON	27.54
18-Mar-2024 0	0	746480	03-041-006	03-041-006	Replace Filter - Inner	18-Mar-2024 12:35:46	BHVYEQ	P	DON	72.08
18-Mar-2024 0	0	746480	03-041-007	03-041-007	Replace Filter - Outer	18-Mar-2024 12:35:05	BHVYEQ	P	DON	79.46
28-Mar-2024 0	0	748805	03-044-007	03-044-007	Replace Throttle Controls	03-Apr-2024 16:00:25	TRK005	N	DON	863.78
22-May-2024 0	3,066	761621	02-360	02-360	Clean Loader / Skid-Steer	11-Jun-2024 11:15:08	BWASH	N	DON	236.23
22-May-2024 0	3,066	761621	06-049-003	06-049-003	Inspect ECM Wiring Harness	25-Jun-2024 06:06:49	BBKHOE	N	DON	177.70
22-May-2024 0	3,066	761621	06-100-PMA	06-100-PMA	Inspect A PMI	18-Jun-2024 06:56:53	BBKHOE	P	DON	0.00
22-May-2024 0	3,066	761621	06-100-PMB	06-100-PMB	Inspect B PMI	18-Jun-2024 06:56:59	BBKHOE	P	DON	151.91
22-May-2024 0	3,066	761621	24-044-007	24-044-007	Repair Throttle Controls	27-Jun-2024 14:24:56	BHVYEQ	N	DON	357.78
22-May-2024 0	3,066	761621	OS-360	OS-360	Out-Service Loader / Skid-Steer	25-Jun-2024 06:06:44	BBKHOE	N	DON	232.15