

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: Z1123 - 2016 VERMEER D24X40III										
22-Nov-2016 1	7	0	267549	14-063-003	Install Transceiver - GPS Tracker	23-Nov-2016 12:00:00	BDDRIL	Q	DON	1,080.31
23-Mar-2017 0	7	0	286207	24-700	Repair Directional Drilling Group	23-Mar-2017 07:00:00	BVLOFC	F	DON	1,875.22
27-Mar-2017 0	7	0	284766	24-MSC	Repair Miscellaneous	27-Mar-2017 07:00:00	BVLOFC	F	DON	862.28
05-Jul-2017 15	392	0	295649	24-065-007	Repair Hoses & Fittings	05-Jul-2017 15:53:03	ROGSHP	B	DON	63.21
03-Aug-2017 1	501	0	299561	24-044-018	Repair Fuel Hose / Line	09-Aug-2017 13:26:42	LAVSHP	B	DON	6.53
03-Aug-2017 1	501	0	299561	19-049-003	Wire/Rewire ECM Wiring Harness	09-Aug-2017 13:25:29	LAVSHP	W	DON	0.00
03-Aug-2017 1	501	0	299561	03-065-020	Replace Control Valve	09-Aug-2017 13:25:26	LAVSHP	W	DON	0.00
03-Aug-2017 1	501	0	299561	03-065-007	Replace Hoses & Fittings	09-Aug-2017 13:25:32	LAVSHP	I	DON	340.28
03-Aug-2017 1	501	0	299561	24-065-007	Repair Hoses & Fittings	09-Aug-2017 13:25:35	LAVSHP	W	DON	0.00
03-Aug-2017 1	501	0	299561	24-702	Repair Mud Pump	09-Aug-2017 13:25:38	LAVSHP	W	DON	0.00
03-Aug-2017 1	501	0	299561	95-MSC-004	Travel Travel Time - To/From Job Site	09-Aug-2017 13:26:42	LAVSHP	J	DON	212.29
03-Aug-2017 1	501	0	299561	03-044-002	Replace Filters	09-Aug-2017 13:26:42	LAVSHP	I	DON	209.06
05-Sep-2017 1	643	0	305388	03-708-004	Replace Starter Rod	18-Sep-2017 10:28:14	BVLOFC	F	DON	394.57
07-Sep-2017 1	643	0	304088	06-100-PMA	Inspect A PMI	07-Sep-2017 18:05:01	LAVSHP	P	DON	201.79
23-Oct-2017 1	754	0	309788	35-702	Diagnose Mud Pump	24-Oct-2017 08:20:03	LAVSHP	B	DON	129.12
23-Oct-2017 1	754	0	309788	37-704-006	Calibrate Rotation Planetaries	24-Oct-2017 08:20:13	LAVSHP	W	DON	0.00
23-Oct-2017 1	754	0	309788	34-704-007	Reseal Hydraulic Motor	24-Oct-2017 08:20:10	LAVSHP	W	DON	0.00
23-Oct-2017 1	754	0	309788	01-704-001	Adjust Pads and Slides	24-Oct-2017 08:27:17	LAVSHP	I	DON	159.41
23-Oct-2017 1	754	0	309788	03-065-006	Replace Filters, Strainers, Screens & Housing	24-Oct-2017 08:27:12	LAVSHP	I	DON	938.47
30-Jan-2018 1	0	0	321658	06-700	Inspect Directional Drilling Group	31-Jan-2018 08:47:56	ROGSHP	P	DON	14.77
30-Jan-2018 1	0	0	321658	03-041-007	Replace Filter - Outer	31-Jan-2018 10:08:22	ROGSHP	P	DON	65.92
30-Jan-2018 1	0	0	321658	24-267	Repair Drilling and Boring	01-Feb-2018 11:02:04	ROGSHP	I	DON	166.71
30-Jan-2018 1	0	0	321658	07-100-PMA	Lubricate A PMI	31-Jan-2018 11:08:33	ROGSHP	P	DON	21.34
30-Jan-2018 1	0	0	321658	07-100-PMB	Lubricate B PMI	31-Jan-2018 10:02:00	ROGSHP	P	DON	118.62
30-Jan-2018 1	0	0	321658	24-002-004	Repair Hood	01-Feb-2018 14:11:08	ROGSHP	I	DON	42.28
19-Apr-2018 0	908	0	332892	35-704	Diagnose Drill Rig	25-Apr-2018 09:15:58	LAVSHP	B	DON	433.12
19-Apr-2018 0	908	0	332892	95-MSC-004	Travel Travel Time - To/From Job Site	25-Apr-2018 09:16:02	LAVSHP	J	DON	606.11
19-Apr-2018 0	908	0	332892	03-049-004	Replace ECM Sensor	25-Apr-2018 09:16:05	LAVSHP	I	DON	373.29
07-Jun-2018 0	1,129	0	338783	03-065-032	Replace Seal / O-Ring General	07-Jun-2018 09:23:09	ROGSHP	N	DON	28.98

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: Z1123 - 2016 VERMEER D24X40III										
07-Jun-2018 0	1,129	0	338783	07-100-PMA	Lubricate A PMI	07-Jun-2018 08:55:15	ROGSHP	P	DON	60.56
13-Jul-2018 13	1,192	0	343735	24-704-004	Repair Drilling Subs	16-Jul-2018 05:26:59	LAVSHP	B	DON	33.97
26-Jul-2018 12	1,286	0	345534	03-704-001	Replace Pads and Slides	26-Jul-2018 14:46:33	LAVSHP	I	DON	438.51
26-Jul-2018 12	1,286	0	345534	03-704-022	Replace Rotation Thrust / Bearing Box	26-Jul-2018 14:46:23	LAVSHP	I	DON	459.69
26-Jul-2018 12	1,286	0	345534	35-704	Diagnose Drill Rig	26-Jul-2018 14:46:28	LAVSHP	B	DON	122.11
09-Aug-2018 C	1,335	0	347461	35-267-005	Diagnose Controls	10-Aug-2018 12:18:23	ROGSHP	B	DON	43.38
09-Aug-2018 C	1,335	0	347461	03-267-005	Replace Controls	10-Aug-2018 12:18:07	ROGSHP	B	DON	358.80
21-Aug-2018 1	1,378	0	349158	03-065-007	Replace Hoses & Fittings	22-Aug-2018 07:35:22	LAVSHP	B	DON	100.72
21-Aug-2018 1	1,378	0	349158	06-100-PMA	Inspect A PMI	21-Aug-2018 12:55:58	LAVSHP	P	DON	88.49
21-Aug-2018 1	1,378	0	349158	21-065-007	Fabricate Hoses & Fittings	24-Aug-2018 13:01:21	LAVSHP	B	DON	133.80
30-Aug-2018 C	1,407	0	350408	03-706-004	Replace Controls	10-Sep-2018 13:32:41	LAVSHP	E	DON	1,583.43
30-Aug-2018 C	1,407	0	350408	35-704-018	Diagnose Operator Console / Station	10-Sep-2018 13:32:48	LAVSHP	E	DON	153.64
30-Aug-2018 C	1,407	0	350408	95-MSC-004	Travel Travel Time - To/From Job Site	10-Sep-2018 13:32:45	LAVSHP	E	DON	529.50
17-Oct-2018 0	1,577	0	356894	24-704	Repair Drill Rig	17-Oct-2018 10:05:59	ROGSHP	B	DON	17.11
17-Oct-2018 0	1,577	0	356894	07-100-PMA	Lubricate A PMI	17-Oct-2018 10:48:27	ROGSHP	P	DON	16.75
17-Oct-2018 0	1,577	0	356894	07-100-PMB	Lubricate B PMI	17-Oct-2018 14:17:09	ROGSHP	P	DON	155.45
17-Oct-2018 0	1,577	0	356894	07-100-PMC	Lubricate C PMI	17-Oct-2018 14:21:21	ROGSHP	P	DON	151.04
17-Oct-2018 0	1,577	0	356894	03-041-006	Replace Filter - Inner	17-Oct-2018 12:00:20	ROGSHP	P	DON	58.50
17-Oct-2018 0	1,577	0	356894	03-041-007	Replace Filter - Outer	17-Oct-2018 12:02:47	ROGSHP	P	DON	52.48
17-Oct-2018 0	1,577	0	356894	03-047-001	Replace Engine Filter Kits	17-Oct-2018 13:04:28	ROGSHP	P	DON	80.57
25-Oct-2018 1	1,610	0	358251	24-704-019	Repair Drill Head	25-Oct-2018 16:28:42	ROGSHP	N	DON	64.08
14-Nov-2018 1	1,694	0	360686	03-053-008	Replace Hoses & Tubings & Fittings	15-Nov-2018 11:02:03	ROGSHP	B	DON	312.76
14-Nov-2018 1	1,694	0	360686	03-701-002	Replace Plumbing / Valves (water)	14-Nov-2018 14:38:24	ROGSHP	N	DON	143.51
30-May-2019 1	2,018	0	387991	03-053-008	Replace Hoses & Tubings & Fittings	31-May-2019 13:38:11	ROGSHP	B	DON	979.67
29-Jul-2019 07	2,236	0	396189	06-100-PMA	Inspect A PMI	05-Aug-2019 10:49:41	LAVSHP	P	DON	0.00
29-Jul-2019 07	2,236	0	396189	03-053-004	Replace Safety Equipment	05-Aug-2019 10:49:44	LAVSHP	I	DON	219.82
29-Jul-2019 07	2,236	0	396189	03-706-004	Replace Controls	05-Aug-2019 10:49:28	LAVSHP	I	DON	625.68
29-Jul-2019 07	2,236	0	396189	38-100-PMC	Service C PMI	LAVSHP	P	CAN	0.00	
29-Jul-2019 07	2,236	0	396189	03-049-004	Replace ECM Sensor	05-Aug-2019 10:49:35	LAVSHP	I	DON	350.01

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: Z1123 - 2016 VERMEER D24X40IH										
29-Jul-2019 07	2,236	0	396189	03-704-017	Replace Rod Loader System	05-Aug-2019 10:49:47	LAVSHP	I	DON	540.78
29-Jul-2019 07	2,236	0	396189	03-704-001	Replace Pads and Slides	05-Aug-2019 10:49:38	LAVSHP	I	DON	423.59
29-Jul-2019 07	2,236	0	396189	03-053-007	Replace Hardware - Expendable Items	05-Aug-2019 10:49:31	LAVSHP	I	DON	167.44
29-Jul-2019 07	2,236	0	396189	11-705	Rebuild Vise	05-Aug-2019 10:49:17	LAVSHP	I	DON	3,808.48
29-Jul-2019 07	2,236	0	396189	03-065-007	Replace Hoses & Fittings	05-Aug-2019 10:49:25	LAVSHP	I	DON	251.16
29-Jul-2019 07	2,236	0	396189	01-704-015	Adjust Track	05-Aug-2019 10:49:14	LAVSHP	I	DON	125.58
29-Jul-2019 07	2,236	0	396189	38-100-PMB	Service B PMI	05-Aug-2019 10:50:49	BSDRIL	P	DON	2,036.15
29-Jul-2019 07	2,236	0	396189	06-100-PMB	Inspect B PMI	05-Aug-2019 10:50:49	BSDRIL	P	DON	718.70
02-Oct-2019 1	2,460	0	405674	06-100-PMA	Inspect A PMI	03-Oct-2019 12:59:12	ROGSHP	P	DON	0.00
02-Oct-2019 1	2,460	0	405674	38-100-PMA	Service A PMI	03-Oct-2019 10:43:33	ROGSHP	P	DON	400.60
19-Nov-2019 1	2,641	0	413441	01-704-001	Adjust Pads and Slides	19-Nov-2019 13:56:55	ROGSHP	N	DON	27.33
28-Jan-2020 1	2,722	0	423472	06-100-PMB	Inspect B PMI	29-Jan-2020 14:06:58	LAVSHP	P	DON	322.39
28-Jan-2020 1	2,722	0	423472	03-049-004	Replace ECM Sensor	29-Jan-2020 14:06:55	LAVSHP	I	DON	660.59
28-Jan-2020 1	2,722	0	423472	24-704-017	Repair Rod Loader System	29-Jan-2020 14:07:06	LAVSHP	I	DON	489.75
28-Jan-2020 1	2,722	0	423472	01-704-001	Adjust Pads and Slides	29-Jan-2020 14:07:03	LAVSHP	I	DON	185.40
28-Jan-2020 1	2,722	0	423472	24-702-002	Repair Discharge Manifold	29-Jan-2020 14:06:34	LAVSHP	I	DON	608.50
18-May-2020 1	2,913	0	441183	06-100-PMA	Inspect A PMI	27-May-2020 06:57:40	ROGSHP	P	DON	0.00
18-May-2020 1	2,913	0	441183	38-100-PMA	Service A PMI	18-May-2020 10:03:07	ROGSHP	P	DON	257.41
17-Jun-2020 0	2,988	0	445962	24-065-001	Repair Hydraulic Systems	17-Jun-2020 07:55:08	ROGSHP	O	DON	16.43
17-Jun-2020 0	2,988	0	445962	24-043-004	Repair Turbocharger	19-Jun-2020 15:51:42	ROGSHP	N	DON	127.17
27-Jul-2020 12	3,049	0	452724	24-065-001	Repair Hydraulic Systems	27-Jul-2020 13:29:21	ROGSHP	O	DON	26.46
03-Aug-2020 1	3,068	0	454032	03-053-008	Replace Hoses & Tubings & Fittings	05-Aug-2020 06:42:52	ROGSHP	B	DON	273.26
07-Aug-2020 1	3,085	0	454879	01-065-001	Adjust Hydraulic Systems	07-Aug-2020 14:37:51	ROGSHP	P	DON	123.28
07-Aug-2020 1	3,085	0	454879	03-098-002	Replace Butterfly Valve Assembly	07-Aug-2020 11:56:39	ROGSHP	O	DON	689.82
17-Aug-2020 0	3,122	0	456377	03-053-008	Replace Hoses & Tubings & Fittings	17-Aug-2020 14:18:12	ROGSHP	B	DON	356.88
01-Sep-2020 1	3,160	0	459385	06-100-PMA	Inspect A PMI	03-Sep-2020 06:48:33	ROGSHP	P	DON	0.00
01-Sep-2020 1	3,160	0	459385	38-100-PMA	Service A PMI	02-Sep-2020 14:50:59	ROGSHP	P	DON	336.61
19-Nov-2020 0	3,253	0	472993	03-065-005	Replace Drive - Motor / Pump	19-Nov-2020 13:09:49	ROGSHP	I	DON	5,052.27
19-Nov-2020 0	3,253	0	472993	06-065-001	Inspect Hydraulic Systems	19-Nov-2020 10:46:23	ROGSHP	O	DON	26.25

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: Z1123 - 2016 VERMEER D24X40HII										
29-Mar-2021	1	3,365	0	497165	01-065-007	Adjust Hoses & Fittings	LAVSHP	I	DON	86.87
29-Mar-2021	1	3,365	0	497165	03-002-065	Replace Hood Latch	LAVSHP	I	DON	112.55
29-Mar-2021	1	3,365	0	497165	03-031-005	Replace Battery Charger - Electrically Propelled	LAVSHP	I	DON	512.22
29-Mar-2021	1	3,365	0	497165	03-042-014	Replace Coolant Overflow Reservoir	LAVSHP	I	DON	508.35
29-Mar-2021	1	3,365	0	497165	03-065-004	Replace Cylinder	LAVSHP	I	DON	1,435.16
29-Mar-2021	1	3,365	0	497165	03-065-005	Replace Drive - Motor / Pump	LAVSHP	I	DON	5,039.79
29-Mar-2021	1	3,365	0	497165	03-267-013	Replace Wear Pads	LAVSHP	I	DON	1,501.86
29-Mar-2021	1	3,365	0	497165	03-512-007	Replace Bearings	LAVSHP	I	DON	2,277.46
29-Mar-2021	1	3,365	0	497165	03-704-001	Replace Pads and Slides	LAVSHP	I	DON	485.22
29-Mar-2021	1	3,365	0	497165	06-100-PMB	Inspect B PMI	LAVSHP	P	DON	772.65
29-Mar-2021	1	3,365	0	497165	11-705	Rebuild Vise	LAVSHP	I	DON	1,975.05
29-Mar-2021	1	3,365	0	497165	24-065-007	Repair Hoses & Fittings	LAVSHP	I	DON	260.61
29-Mar-2021	1	3,365	0	497165	24-704-017	Repair Rod Loader System	LAVSHP	I	DON	541.36
29-Mar-2021	1	3,365	0	497165	26-704-011	Weld Frame / Chassis	LAVSHP	I	DON	260.61
29-Mar-2021	1	3,365	0	497165	35-065-017	Diagnose Reservoir/Tank	LAVSHP	I	DON	260.61
29-Mar-2021	1	3,365	0	497165	35-065-020	Diagnose Control Valve	LAVSHP	I	DON	86.87
29-Mar-2021	1	3,365	0	497165	37-704-015	Calibrate Track	LAVSHP	I	DON	130.30
29-Mar-2021	1	3,365	0	497165	38-100-PMB	Service B PMI	LAVSHP	P	DON	2,064.39
06-Apr-2021	1	3,365	0	498814	03-049	Replace Electronic Management System	TRK400	O	DON	701.67
05-May-2021	1	3,365	0	504705	06-100-PMA	Inspect A PMI	SCHED	P	DON	15.19
05-May-2021	1	3,365	0	504705	24-002-004	Repair Hood	ROGSHP	I	DON	191.04
05-May-2021	1	3,365	0	504705	38-100-PMA	Service A PMI	ROGSHP	P	DON	253.81
06-Aug-2021	1	3,365	0	523591	03-098-001	Replace Ball Valve Assembly (Blowdown Valve	ME1371	O	DON	707.77
22-Sep-2021	0	3,365	0	533205	06-065-004	Inspect Cylinder	TRK401	O	DON	38.92
22-Sep-2021	0	3,365	0	533205	03-065-004	Replace Cylinder	TRK401	I	DON	539.25
22-Sep-2021	0	3,365	0	533205	06-100-PMA	Inspect A PMI	SCHED	P	DON	37.61
22-Sep-2021	0	3,365	0	533205	38-100-PMA	Service A PMI	TRK401	P	DON	166.05
29-Sep-2021	1	3,365	0	535146	03-065-007	Replace Hoses & Fittings	LAVSHP	B	DON	505.03
01-Oct-2021	1	3,365	0	535935	03-045-026	Replace Tensioner - Engine Belts	ME1371	O	DON	384.36

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: Z1123 - 2016 VERMEER D24X40III										
01-Oct-2021	I	3,365	0	535935	24-910-030	Repair Magnet	ME1371	O	DON	50.39
06-Oct-2021	I	3,365	0	537273	03-705-002	Replace Clamp Cylinders	TRK400	B	DON	664.90
11-Oct-2021	I	3,365	0	538360	06-030	Inspect Electrical Group	TRK400	O	DON	127.28
12-Oct-2021	I	3,365	0	538617	06-702	Inspect Mud Pump	TRK400	O	DON	128.82
12-Oct-2021	I	3,365	0	538617	03-702	Replace Mud Pump	TRK400	I	DON	1,143.10
12-Oct-2021	I	3,365	0	538617	03-704-007	Replace Hydraulic Motor	TRK400	I	DON	2,664.30
29-Oct-2021	I	4,034	0	542809	06-049-001	Inspect ECM Fault Code	ME1371	I	DON	75.72
29-Oct-2021	I	4,034	0	542809	01-704-001	Adjust Pads and Slides	ME1371	O	DON	550.87
29-Oct-2021	I	4,034	0	542809	03-046-004	Replace Controls - Electronic (Solid State), Elec	ME1371	O	DON	1,860.29
29-Oct-2021	I	4,034	0	542809	03-052-013	Replace Antenna and Mounting	ME1371	O	DON	39.46
15-Nov-2021	I	4,034	0	546812	06-049-003	Inspect ECM Wiring Harness	TRK401	O	DON	76.38
16-Nov-2021	I	4,034	0	547227	03-910-001	Replace Dies - Jaw	OTSSHP	N	DON	319.82
21-Feb-2022	I	4,034	0	568739	03-704-016	Replace Stem Rack	BSDRIL	O	DON	21,001.95
02-Mar-2022	O	4,177	0	571018	03-063-003	Replace Transceiver - GPS Tracker	TRK401	Q	DON	260.94
10-Mar-2022	O	4,311	0	605354	01-030	Adjust Electrical Group	OTSSHP	I	DON	200.92
10-Mar-2022	O	4,311	0	605354	03-002-065	Replace Hood Latch	OTSSHP	I	DON	484.74
10-Mar-2022	O	4,311	0	605354	03-016-051	Replace U-Bolt	OTSSHP	I	DON	1,006.46
10-Mar-2022	O	4,311	0	605354	03-065-004	Replace Cylinder	OTSSHP	I	DON	5,328.22
10-Mar-2022	O	4,311	0	605354	03-704-001	Replace Pads and Slides	OTSSHP	I	DON	880.99
10-Mar-2022	O	4,311	0	605354	03-704-013	Replace Stakedown	OTSSHP	I	DON	5,748.21
10-Mar-2022	O	4,311	0	605354	03-705	Replace Vis	OTSSHP	I	DON	327.08
10-Mar-2022	O	4,311	0	605354	03-H01-452	Replace Fan Motor	OTSSHP	I	DON	2,021.11
10-Mar-2022	O	4,311	0	605354	38-100-WIN	Service Winterization Inspection	OTSSHP	P	DON	2,737.00
10-Mar-2022	O	4,311	0	605354	38-100-PMA	Service A PMI	OTSSHP	P	DON	2,376.12
10-Mar-2022	O	4,311	0	605354	35-042	Diagnose Cooling System	OTSSHP	I	DON	-564.08
10-Mar-2022	O	4,311	0	605354	24-705	Repair Vis	OTSSHP	I	DON	3,429.98
10-Mar-2022	O	4,311	0	605354	03-H02-151	Replace Filter	OTSSHP	P	DON	50.23
10-Mar-2022	O	4,311	0	605354	24-702	Repair Mud Pump	OTSSHP	I	DON	904.15
10-Mar-2022	O	4,311	0	605354	26-267-008	Weld Rod Holder	OTSSHP	I	DON	703.23

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: Z1123 - 2016 VERMEER D24X40HII										
10-Mar-2022 0	4,311	0	605354	24-704-017	Repair Rod Loader System	10-Mar-2022 10:23:00	OTSSHP	I	DON	1,548.19
10-Mar-2022 0	4,311	0	605354	24-065-001	Repair Hydraulic Systems	10-Mar-2022 11:02:00	OTSSHP	I	DON	401.85
10-Mar-2022 0	4,311	0	605354	03-708-007	Replace Sub Saver	10-Mar-2022 11:16:00	OTSSHP	I	DON	465.54
10-Mar-2022 0	4,311	0	605354	24-043-003	Repair Muffler	10-Mar-2022 11:35:00	OTSSHP	I	DON	1,414.42
10-Mar-2022 0	4,311	0	605354	26-704	Weld Drill Rig	10-Mar-2022 11:30:00	OTSSHP	I	DON	200.92
10-Mar-2022 0	4,311	0	605354	24-704-001	Repair Pads and Slides	10-Mar-2022 11:19:00	OTSSHP	I	DON	1,485.65
10-Mar-2022 0	4,311	0	605354	24-014	Repair Frame	10-Mar-2022 11:33:00	OTSSHP	I	DON	941.96
10-Mar-2022 0	4,311	0	605354	03-713	Replace Drill Motor	10-Mar-2022 11:24:00	OTSSHP	I	DON	11,946.85
10-Mar-2022 0	4,311	0	605354	06-100-PMA	Inspect A PMI	10-Mar-2022 09:11:00	OTSSHP	P	DON	0.00
24-May-2022 1			590994	02-704	Clean Drill Rig	25-May-2022 12:15:27	BWASH	N	DON	379.13
27-May-2022 1			591906	06-100-PMA	Inspect A PMI	10-Jun-2022 08:40:28	BSDRIL	P	DON	166.97
27-May-2022 1			591906	06-100-PMB	Inspect B PMI	14-Jun-2022 08:19:08	BSDRIL	P	DON	210.20
27-May-2022 1			591906	24-704-016	Repair Stem Rack	10-Jun-2022 08:41:16	BSDRIL	N	DON	623.85
27-May-2022 1			591906	24-704-018	Repair Operator Console / Station	10-Jun-2022 08:40:39	BSDRIL	I	DON	1,682.76
27-May-2022 1			591906	24-704-022	Repair Rotation Thrust / Bearing Box	10-Jun-2022 08:41:18	BSDRIL	I	DON	932.18
27-May-2022 1			591906	38-040	Service Engine / Motor Systems Group	10-Jun-2022 08:40:35	BSDRIL	P	DON	1,044.80
27-May-2022 1			591906	38-704-015	Service Track	10-Jun-2022 08:41:13	BSDRIL	N	DON	4,329.98
27-May-2022 1			591906	38-704-017	Service Rod Loader System	09-Jun-2022 06:54:30	BSDRIL	I	DON	5,261.32
27-May-2022 1			591906	38-705	Service Vise	10-Jun-2022 08:40:37	BSDRIL	P	DON	799.94
16-Jun-2022 1			596429	03-043-020	Replace Pump - DEF	17-Jun-2022 10:01:20	TRK400	I	DON	1,761.59
16-Jun-2022 1			596429	06-043-020	Inspect Pump - DEF	16-Jun-2022 16:11:33	TRK400	O	DON	92.94
17-Jun-2022 1			596686	03-704-008	Replace Lube System	17-Jun-2022 14:48:57	LAVSHP	B	DON	622.17
01-Jul-2022 07			599853	03-702-001	Replace Liners, Valves, and Seals	06-Jul-2022 12:57:24	LAVSHP	O	DON	8,921.50
01-Aug-2022 1	4,328	0	606374	03-098-001	Replace Ball Valve Assembly (Blowdown Valve)	02-Aug-2022 08:08:01	ME1371	O	DON	1,206.74
01-Aug-2022 1	4,328	0	606374	06-098-001	Inspect Ball Valve Assembly (Blowdown Valves)	01-Aug-2022 16:23:32	ME1371	I	DON	71.18
18-Oct-2022 01	4,659	0	624966	03-098-001	Replace Ball Valve Assembly (Blowdown Valve)	18-Oct-2022 06:50:08	LAVSHP	P	DON	1,068.20
18-Oct-2022 01	4,659	0	624966	03-704-017	Replace Rod Loader System	18-Oct-2022 15:36:13	LAVSHP	P	DON	19.26
18-Oct-2022 01	4,659	0	624966	38-704-008	Service Lube System	18-Oct-2022 07:12:46	LAVSHP	P	DON	98.66
08-Nov-2022 C	4,738	0	630603	01-065-008	Adjust Line / Tubing Assembly	08-Nov-2022 06:30:03	LAVSHP	P	DON	164.98

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: Z1123 - 2016 VERMEER D24X40III										
20-Dec-2022 0	4,749	0	640481	01-042-014	Adjust Coolant Overflow Reservoir	20-Dec-2022 06:25:09	LAVSHP	P	DON	23.66
10-Mar-2023 0	4,763	0	658333	06-702	Inspect Mud Pump	10-Mar-2023 13:19:21	TRK400	O	DON	90.06
10-Mar-2023 0	4,763	0	658333	24-704-017	Repair Rod Loader System	13-Mar-2023 10:37:55	TRK400	O	DON	507.22
10-Mar-2023 0	4,763	0	658333	03-704-001	Replace Pads and Slides	13-Mar-2023 13:18:20	TRK400	I	DON	665.49
10-Mar-2023 0	4,763	0	658333	03-705	Replace Vise	15-Mar-2023 14:37:11	TRK400	I	DON	8,786.43
10-Mar-2023 0	4,763	0	658333	06-705	Inspect Vise	10-Mar-2023 09:31:36	TRK400	O	DON	130.58
10-Mar-2023 0	4,763	0	658333	06-704	Inspect Drill Rig	10-Mar-2023 11:47:14	TRK400	P	DON	197.71
10-Mar-2023 0	4,763	0	658333	03-002-065	Replace Hood Latch	14-Mar-2023 12:01:17	TRK400	I	DON	211.05
10-Jul-2023 05	4,784	0	686650	03-065-007	Replace Hoses & Fittings	10-Jul-2023 05:47:07	LAVSHP	O	DON	23.56
19-Sep-2023 1	4,786	0	706480	02-704	Clean Drill Rig	20-Sep-2023 14:06:13	BWASH	N	DON	365.70
28-Sep-2023 0	4,787	0	708706	38-040	Service Engine / Motor Systems Group	04-Oct-2023 16:03:11	BSDRIL	N	DON	684.83
28-Sep-2023 0	4,787	0	708706	38-704-015	Service Track	04-Oct-2023 10:24:08	BSDRIL	N	DON	167.45
28-Sep-2023 0	4,787	0	708706	38-704-016	Service Stem Rack	04-Oct-2023 16:03:35	BSDRIL	N	DON	5,339.20
28-Sep-2023 0	4,787	0	708706	38-704-017	Service Rod Loader System	04-Oct-2023 16:02:59	BSDRIL	N	DON	1,589.02
28-Sep-2023 0	4,787	0	708706	38-704-022	Service Rotation Thrust / Bearing Box	04-Oct-2023 16:02:34	BSDRIL	N	DON	627.47
28-Sep-2023 0	4,787	0	708706	38-705	Service Vise	04-Oct-2023 16:02:47	BSDRIL	N	DON	177.62
26-Feb-2024 0	4,862	0	741258	03-708-007	Replace Sub Saver	26-Feb-2024 07:53:25	BSDRIL	N	DON	228.30
18-Mar-2024 0	4,883	0	747166	01-042-002	Adjust Radiator	20-Mar-2024 20:03:09	TRK030	B	DON	420.00
18-Mar-2024 0	4,883	0	747166	01-065-001	Adjust Hydraulic Systems	20-Mar-2024 20:03:44	TRK030	B	DON	158.49
14-Apr-2024 0	4,913	0	753936	03-065-007	Replace Hoses & Fittings	19-Apr-2024 09:24:36	TRK023	B	DON	393.50
18-Apr-2024 0	4,917	0	754246	24-704-019	Repair Drill Head	02-May-2024 23:33:39	TRK028	E	DON	849.94
23-Jun-2024 0	4,973	0	769472	01-032-001	Adjust Battery	28-Jun-2024 10:04:34	TRK023	B	DON	105.00
24-Jun-2024 0	4,973	0	769658	03-065-008	Replace Line / Tubing Assembly	29-Jun-2024 20:41:57	TRK030	B	DON	306.19
24-Jun-2024 0	4,973	0	769658	40-704	Standby Drill Rig	04-Aug-2024 20:49:41	TRK030	B	DON	210.00
23-Jul-2024 10		0	774217	38-705	Service Vise	23-Jul-2024 10:19:02	BSDRIL	N	DON	257.84
08-Aug-2024 1		0	778001	02-704	Clean Drill Rig	08-Aug-2024 16:00:19	BWASH	N	DON	213.42
08-Aug-2024 1		0	778093	25-063-003	Remove Transceiver - GPS Tracker	08-Aug-2024 17:00:01	BSDRIL	N	DON	66.68
09-Aug-2024 1		0	778259	25-053-005	Remove Markings - Vehicle - Decals	09-Aug-2024 16:00:01	BSDRIL	Z	DON	218.67

Unit No: Z1123

Count: 202

181,060.01