

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: B2833 - 2015 F250 CREWCAB										
14-Aug-2015	C	0	211293	06-100-DOT	Inspect DOT Federal Inspection	17-Aug-2015 07:22:52	BTRUCK	P	DON	14.47
14-Aug-2015	C	0	211293	14-002-003	Install Running Boards / Step Tubes	14-Aug-2015 17:02:40	BSETUP	C	DON	333.03
14-Aug-2015	C	0	211293	14-052-015	Install Power Inverter/Converter	14-Aug-2015 13:33:36	BSETUP	C	DON	227.86
14-Aug-2015	C	0	211293	14-053-005	Install Markings - Vehicle - Decals	14-Aug-2015 15:36:04	BSETUP	C	DON	102.68
14-Aug-2015	C	0	211293	14-034-006	Install Warning Lamps - Special Application	14-Aug-2015 11:58:29	BSETUP	C	DON	477.95
14-Aug-2015	C	0	211293	14-052-003	Install Radio Equipment	14-Aug-2015 15:34:12	BSETUP	C	DON	1,181.03
14-Aug-2015	C	0	211293	14-052-014	Install Cellular Telephone Accessories	14-Aug-2015 15:35:44	BSETUP	C	DON	52.73
14-Aug-2015	C	0	211293	14-053-014	Install Floor Mats	14-Aug-2015 15:49:43	BSETUP	C	DON	98.86
14-Aug-2015	C	0	211293	14-071-011	Install Scuff Liner / Bed Mat	14-Aug-2015 09:39:12	BSETUP	C	DON	76.99
14-Aug-2015	C	0	211293	14-078-009	Install Mud Flaps and Hanger Brackets	14-Aug-2015 15:36:23	BSETUP	C	DON	69.66
14-Aug-2015	C	0	211293	14-079-002	Install Headache Rack	14-Aug-2015 10:10:47	BSETUP	C	DON	347.85
14-Aug-2015	C	0	211293	14-506-001	Install Fuel Tank	14-Aug-2015 15:34:38	BSETUP	C	DON	1,134.15
14-Aug-2015	C	0	211293	14-510-002	Install Tool Box	17-Aug-2015 07:45:22	BSETUP	C	DON	342.85
14-Aug-2015	C	0	211293	14-517	Install Safety Equipment	14-Aug-2015 15:48:44	BSETUP	C	DON	37.15
14-Aug-2015	C	0	211293	14-044-003	Install Fuel Pump	17-Aug-2015 07:45:27	BSETUP	C	DON	19.34
10-Sep-2015	0	0	214082	24-034-002	Repair Stop, Tail, Turn & License	10-Sep-2015 07:10:21	HARSHP	I	DON	23.71
16-Sep-2015	0	0	214896	14-054-002	Install Alarm - Reverse Signal	16-Sep-2015 12:21:35	HARSHP	I	DON	170.16
13-Jan-2016	0	0	228788	06-100-PMB	Inspect B PMI	13-Jan-2016 00:00:00	HARFLD	P	DON	103.39
07-Sep-2016	0	0	259133	06-100-DOT	Inspect DOT Federal Inspection	07-Sep-2016 00:00:00	HARFLD	P	DON	32.53
07-Sep-2016	0	0	259133	06-100-PMA	Inspect A PMI	07-Sep-2016 00:00:00	HARFLD	P	DON	32.53
06-Jan-2017	1	0	272245	03-002-035	Replace Windshield Wiper & Washer	25-Mar-2017 08:14:20	BVLOFC	O	DON	28.29
06-Jan-2017	1	0	272245	03-013-001	Replace Front Brakes & Drums	25-Mar-2017 08:14:20	BVLOFC	O	DON	252.15
06-Jan-2017	1	0	272245	03-017-001	Replace Tire - Pneumatic	25-Mar-2017 08:14:13	HARSHP	P	DON	963.81
06-Jan-2017	1	0	272245	06-100-PMA	Inspect A PMI	25-Mar-2017 08:14:20	BVLOFC	P	DON	38.69
06-Jan-2017	1	0	272245	09-015	Align Steering	25-Mar-2017 08:14:20	BVLOFC	I	DON	84.09
06-Jan-2017	1	0	272245	38-025-001	Service Transfer Case Assembly	25-Mar-2017 08:14:20	BVLOFC	P	DON	101.19
07-Mar-2018	1	67,224	326438	03-032-001	Replace Battery	07-Mar-2018 12:14:15	HARSHP	I	DON	112.55
07-Mar-2018	1	67,224	326438	03-044-018	Replace Fuel Hose / Line	08-Mar-2018 07:11:20	HARSHP	I	DON	283.08
07-Mar-2018	1	67,224	326438	06-100-DOT	Inspect DOT Federal Inspection	07-Mar-2018 13:03:05	HARSHP	P	DON	47.01

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: B2833 - 2015 F250 CREWCAB										
07-Mar-2018 1	67,224	3,078	326438	06-100-PMA	Inspect A PMI	07-Mar-2018 16:00:19	HARSHP	P	DON	142.99
23-May-2018 1	75,752	3,446	336921	03-017-001	Replace Tire - Pneumatic	04-Jun-2018 10:27:29	HARSHP	J	DON	1,071.38
06-Jun-2018 0	80,557	3,676	342465	06-100-PMA	Inspect A PMI	06-Jun-2018 07:15:00	BVLOFC	P	DON	148.82
30-Jul-2018 00			351437	06-100-PMA	Inspect A PMI	30-Jul-2018 00:00:00	BTRUCK	P	DON	92.12
06-Aug-2018 1	84,823	3,827	346866	03-016-003	Replace Shock Absorber - Front	09-Aug-2018 06:36:27	HARSHP	O	DON	214.82
06-Aug-2018 1	84,823	3,827	346866	06-100-PMA	Inspect A PMI	08-Aug-2018 11:24:11	BTRUCK	P	DON	87.01
10-Sep-2018 1	92,096	4,047	355193	06-100-PMA	Inspect A PMI	10-Sep-2018 15:48:00	BVLOFC	P	DON	188.36
09-Oct-2018 0	92,838	4,067	355620	03-044-016	Replace Tank - Fuel Auxiliary	09-Oct-2018 08:26:01	HARSHP	O	DON	1,322.92
06-Dec-2018 1	97,472	4,245	363286	06-100-PMA	Inspect A PMI	06-Dec-2018 11:14:15	BVLOFC	P	DON	93.16
04-Jan-2019 0	99,347	4,336	366773	06-100-PMA	Inspect A PMI	04-Jan-2019 06:35:36	BVLOFC	P	DON	55.68
06-Feb-2019 0	102,705	4,504	371284	06-100-PMA	Inspect A PMI	06-Feb-2019 06:02:02	BVLOFC	P	DON	107.07
14-Mar-2019 0	104,856	4,586	376594	02-002	Clean Cab & Sheet Metal	15-Mar-2019 05:39:49	HARSHP	I	DON	2.71
14-Mar-2019 0	104,856	4,586	376594	03-034-002	Replace Stop, Tail, Turn & License	18-Mar-2019 09:57:54	HARSHP	I	DON	26.05
14-Mar-2019 0	104,856	4,586	376594	03-034-004	Replace Clearance & Marker Lamps	15-Mar-2019 05:30:26	HARSHP	I	DON	6.62
14-Mar-2019 0	104,856	4,586	376594	03-051-009	Replace Fire Extinguisher	14-Mar-2019 16:00:42	HARSHP	I	DON	58.49
14-Mar-2019 0	104,856	4,586	376594	03-053-017	Replace First Aid Kit	15-Mar-2019 05:42:57	HARSHP	I	DON	61.25
14-Mar-2019 0	104,856	4,586	376594	03-078-009	Replace Mud Flaps and Hanger Brackets	21-Mar-2019 16:01:02	HARSHP	I	DON	111.85
14-Mar-2019 0	104,856	4,586	376594	06-100-DOT	Inspect DOT Federal Inspection	15-Mar-2019 06:43:50	HARSHP	P	DON	17.57
14-Mar-2019 0	104,856	4,586	376594	06-100-PMA	Inspect A PMI	14-Mar-2019 14:31:11	HARSHP	P	DON	82.40
07-May-2019 0	109,913	4,894	384629	06-100-PMA	Inspect A PMI	15-May-2019 07:14:11	HARFLD	P	DON	7.82
07-May-2019 0	109,913	4,894	384629	38-100-PMA	Service A PMI	15-May-2019 07:15:53	HARFLD	P	DON	92.65
24-May-2019 0	111,298	4,969	387219	03-017-001	Replace Tire - Pneumatic	15-Jul-2019 10:04:58	HARFLD	N	DON	1,270.77
15-Jul-2019 10	117,590	5,188	394157	06-100-PMA	Inspect A PMI	29-Aug-2019 10:27:23	HARFLD	P	DON	15.63
15-Jul-2019 10	117,590	5,188	394157	14-090	Install Bulk Product Transfer Systems Group	29-Aug-2019 10:27:09	HARFLD	O	DON	566.14
15-Jul-2019 10	117,590	5,188	394157	38-100-PMA	Service A PMI	03-Sep-2019 07:25:36	HARFLD	P	DON	31.26
15-Jul-2019 10	117,590	5,188	394157	03-013	Replace Brakes	28-Sep-2019 09:18:29	HARFLD	I	DON	691.02
23-Oct-2019 0	123,830	5,587	409232	02-044	Clean Fuel System	28-Oct-2019 00:00:00	BVLOFC	N	DON	251.25
23-Oct-2019 0	123,830	5,587	409232	03-033-003	Replace Spark Plugs	28-Oct-2019 00:00:00	BVLOFC	N	DON	1,917.53
11-Nov-2019 0	125,497	5,643	412015	35-002-035	Diagnose Windshield Wiper & Washer	11-Nov-2019 07:00:00	HARFLD	B	DON	82.29

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: B2833 - 2015 F250 CREWCAB										
11-Nov-2019 0	125,497	5,643	412015	06-100-PMA	Inspect A PMI	15-Nov-2019 09:00:00	HARFLD	P	DON	82.29
11-Nov-2019 0	125,497	5,643	412015	03-002-035	Replace Windshield Wiper & Washer	11-Nov-2019 09:00:00	HARFLD	B	DON	188.24
11-Nov-2019 0	125,497	5,643	412015	38-100-PMA	Service A PMI	15-Nov-2019 12:00:00	HARFLD	P	DON	304.25
11-Nov-2019 0	125,497	5,643	412015	03-044-018	Replace Fuel Hose / Line	12-Nov-2019 08:00:00	HARFLD	B	DON	207.16
11-Nov-2019 0	125,497	5,643	412015	35-044-018	Diagnose Fuel Hose / Line	11-Nov-2019 10:00:00	HARFLD	B	DON	82.29
11-Feb-2020 0	131,974	6,016	425675	03-015-004	Replace Steering Linkage	11-Feb-2020 08:04:12	BVLOFC	I	DON	455.18
11-Feb-2020 0	131,974	6,016	425675	03-043-002	Replace Exhaust Manifold	11-Feb-2020 08:04:12	BVLOFC	O	DON	1,207.23
11-Feb-2020 0	131,974	6,016	425675	06-100-PMA	Inspect A PMI	11-Feb-2020 08:04:12	BVLOFC	P	DON	0.00
11-Feb-2020 0	131,974	6,016	425675	03-013-002	Replace Rear Brakes & Drums	11-Feb-2020 08:04:12	BVLOFC	O	DON	823.45
11-Feb-2020 0	131,974	6,016	425675	38-100-PMA	Service A PMI	11-Feb-2020 08:04:12	BVLOFC	P	DON	51.90
11-Feb-2020 0	131,974	6,016	425675	09-015	Align Steering	11-Feb-2020 08:04:12	BVLOFC	I	DON	122.85
21-Feb-2020 0	132,715	6,053	427452	03-002-035	Replace Windshield Wiper & Washer	24-Feb-2020 09:00:00	HARFLD	B	DON	505.30
21-Feb-2020 0	132,715	6,053	427452	03-017-001	Replace Tire - Pneumatic	02-Apr-2020 12:00:00	HARFLD	N	DON	1,212.23
21-Feb-2020 0	132,715	6,053	427452	06-100-DOT	Inspect DOT Federal Inspection	02-Apr-2020 13:00:00	HARFLD	P	DON	82.29
21-Feb-2020 0	132,715	6,053	427452	35-002-035	Diagnose Windshield Wiper & Washer	21-Feb-2020 08:00:00	HARFLD	B	DON	82.29
21-Feb-2020 0	132,715	6,053	427452	35-017-001	Diagnose Tire - Pneumatic	02-Apr-2020 10:00:00	HARFLD	B	DON	82.29
29-Apr-2020 0	140,729	6,341	438540	06-100-PMA	Inspect A PMI	04-May-2020 09:00:00	HARFLD	P	DON	82.29
29-Apr-2020 0	140,729	6,341	438540	38-100-PMA	Service A PMI	04-May-2020 11:00:00	HARFLD	P	DON	247.31
29-Apr-2020 0	140,729	6,341	438540	35-044-013	Diagnose Cap - Fuel Tank	30-Apr-2020 10:00:00	HARFLD	B	DON	82.29
29-Apr-2020 0	140,729	6,341	438540	03-044-013	Replace Cap - Fuel Tank	30-Apr-2020 11:00:00	HARFLD	B	DON	127.95
23-Jul-2020 13			452250	14-053-025	Install Wheel Chock	23-Jul-2020 13:51:54	HARSUP	I	DON	49.06
24-Jul-2020 06	148,647	6,571	452362	01-078	Adjust Trim & Miscellaneous Hardware	27-Jul-2020 07:27:31	HARSHP	I	DON	24.98
24-Jul-2020 06	148,647	6,571	452362	03-032-001	Replace Battery	24-Jul-2020 13:27:30	HARSHP	I	DON	142.80
24-Jul-2020 06	148,647	6,571	452362	03-034-010	Replace Socket - Trailer Light Cord	24-Jul-2020 13:01:19	HARSHP	I	DON	177.54
24-Jul-2020 06	148,647	6,571	452362	03-051-009	Replace Fire Extinguisher	28-Jul-2020 16:05:09	HARSHP	I	DON	205.38
24-Jul-2020 06	148,647	6,571	452362	06-100-PMA	Inspect A PMI	24-Jul-2020 09:51:49	HARSHP	P	DON	40.14
24-Jul-2020 06	148,647	6,571	452362	14-053-004	Install Safety Equipment	27-Jul-2020 06:43:28	HARSHP	I	DON	57.96
24-Jul-2020 06	148,647	6,571	452362	38-100-PMA	Service A PMI	24-Jul-2020 16:01:05	HARSHP	P	DON	133.03
24-Jul-2020 06	148,647	6,571	452362	03-013-001	Replace Front Brakes & Drums	24-Jul-2020 13:22:14	HARSHP	I	DON	312.52

Unit Job History

Michels Corporation

Report Printed: 26-Aug-2024 09:02:10 By User: RHEINING

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: B2833 - 2015 F250 CREWCAB										
24-Jul-2020 06	148,647	6,571	452362	06-100-007	Inspect In-Service Inspection	24-Jul-2020 08:41:02	HARSHP	P	DON	64.83
24-Jul-2020 06	148,647	6,571	452362	02-002	Clean Cab & Sheet Metal	28-Jul-2020 16:05:20	HARSHP	I	DON	0.00
24-Jul-2020 06	148,647	6,571	452362	02-002-011	Clean Cab Accessories - Interior	28-Jul-2020 16:05:15	HARSHP	I	DON	36.02
24-Oct-2020 0:	155,133	6,850	468543	03-002-035	Replace Windshield Wiper & Washer	25-Oct-2020 09:27:22	SYRFLD	B	DON	59.45
24-Oct-2020 0:	155,133	6,850	468543	03-041	Replace Air Intake System	28-Oct-2020 14:45:38	SYRFLD	B	DON	116.78
24-Oct-2020 0:	155,133	6,850	468543	06-100-PMA	Inspect A PMI	25-Oct-2020 09:27:10	SYRFLD	P	DON	34.56
24-Oct-2020 0:	155,133	6,850	468543	35-041	Diagnose Air Intake System	28-Oct-2020 08:09:41	SYRFLD	B	DON	69.12
24-Oct-2020 0:	155,133	6,850	468543	38-100-PMA	Service A PMI	25-Oct-2020 09:27:15	SYRFLD	P	DON	70.60
18-Jan-2021 0:	158,821	7,061	483699	03-034-001	Replace Headlamps / Fog Lamps	21-Jan-2021 10:51:47	SYRFLD	B	DON	284.60
24-Feb-2021 0:	161,122	7,194	490626	01-027-030	Adjust Rear Pump	14-Mar-2021 10:42:18	SYRFLD	B	DON	220.88
24-Feb-2021 0:	161,122	7,194	490626	03-090	Replace Bulk Product Transfer Systems Group	10-Mar-2021 13:14:28	SYRFLD	B	DON	210.24
24-Feb-2021 0:	161,122	7,194	490626	06-100-DOT	Inspect DOT Federal Inspection	10-Mar-2021 13:14:22	SYRFLD	P	DON	94.87
24-Feb-2021 0:	161,122	7,194	490626	35-027-029	Diagnose Oil Pump Assembly	14-Mar-2021 10:42:18	SYRFLD	B	DON	94.87
13-Apr-2021 0	164,271	7,388	501266	06-100-PMA	Inspect A PMI	18-Apr-2021 17:49:05	SYRFLD	P	DON	94.87
13-Apr-2021 0	164,271	7,388	501266	38-100-PMA	Service A PMI	18-Apr-2021 17:49:10	SYRFLD	P	DON	131.29
28-Jun-2021 0:	165,193	7,487	516623	03-034-001	Replace Headlamps / Fog Lamps	06-Jul-2021 06:25:52	SYRFLD	B	DON	189.74
02-Aug-2021 C	165,242	7,493	523168	03-013-001	Replace Front Brakes & Drums	31-Aug-2021 10:46:49	SYRFLD	I	DON	1,020.89
02-Aug-2021 C	165,242	7,493	523168	03-027-024	Replace Valve Body Assembly - Main Control	31-Aug-2021 10:46:49	SYRFLD	B	DON	2,115.22
02-Aug-2021 C	165,242	7,493	523168	03-049-001	Replace ECM Fault Code	31-Aug-2021 10:46:49	SYRFLD	B	DON	87.21
02-Aug-2021 C	165,242	7,493	523168	24-027-037	Repair Transmission Assembly - Automatic	31-Aug-2021 10:46:49	SYRFLD	B	DON	1,842.66
02-Aug-2021 C	165,242	7,493	523168	35-027-032	Diagnose Parking Lock Or Brake & Actuator As	31-Aug-2021 10:46:49	SYRFLD	B	DON	569.21
02-Aug-2021 C	165,242	7,493	523168	35-032-008	Diagnose Relay	31-Aug-2021 10:46:49	SYRFLD	B	DON	569.21
15-Sep-2021 0	165,242	7,493	531448	24-027-038	Repair Electronic Controls, Transmission, Autor	16-Sep-2021 13:25:44	SYRFLD	B	DON	1,241.25
06-Oct-2021 1:	165,242	7,493	537208	03-027	Replace Transmission - Main, Automatic	04-Nov-2021 15:53:25	SYRFLD	B	DON	1,241.25
06-Oct-2021 1:	165,242	7,493	537208	03-063-003	Replace Transceiver - GPS Tracker	04-Nov-2021 15:54:50	SCHED	Q	DON	87.46
23-Feb-2022 1:	166,626	10	569330	24-040	Repair Engine / Motor Systems Group	23-Feb-2022 13:16:43	SYRFLD	W	DON	0.00
14-Mar-2022 0	166,708		574283	06-100-DOT	Inspect DOT Federal Inspection	24-Mar-2022 08:37:01	SYRFLD	P	DON	94.87
14-Mar-2022 0	166,708		574283	06-100-PMA	Inspect A PMI	24-Mar-2022 08:37:01	SYRFLD	P	DON	94.87
14-Mar-2022 0	166,708		574283	38-100-PMA	Service A PMI	24-Mar-2022 08:37:01	SYRFLD	P	DON	152.71

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: B2833 - 2015 F250 CREWCAB										
14-Mar-2022 0	166,708		574283	03-016-005	Replace Chassis Spring - Rear	24-Mar-2022 08:37:01	SYRFLD	I	DON	2,137.42
04-Apr-2022 0	167,826		581612	31-017-001	Rotate Tire - Pneumatic	22-Apr-2022 09:25:25	SYRFLD	P	DON	94.87
27-Apr-2022 0	168,702	7,690	585548	06-100-PMA	Inspect A PMI	01-May-2022 14:18:53	SYRFLD	P	DON	94.87
27-Apr-2022 0	168,702	7,690	585548	38-100-PMA	Service A PMI	01-May-2022 14:18:53	SYRFLD	P	DON	139.53
07-Jun-2022 0	169,974		595434	03-002-035	Replace Windshield Wiper & Washer	23-Jun-2022 13:32:55	SYRFLD	N	DON	121.77
31-Aug-2022 0	171,974		613508	03-044-002	Replace Filters	25-Sep-2022 10:11:32	SYRFLD	P	DON	102.47
16-Jan-2023 0	174,268		646754	03-032-001	Replace Battery	27-Jan-2023 16:10:26	SYRFLD	B	DON	313.62
06-Mar-2023 0	176,364		657529	03-017-001	Replace Tire - Pneumatic	13-Mar-2023 12:55:30	SYRFLD	N	DON	1,453.46
06-Mar-2023 0	176,364		657529	09-010-001	Align All Axles	13-Mar-2023 12:50:11	SYRFLD	P	DON	212.44
06-Mar-2023 0	176,364		657529	03-015-007	Replace Control Valve - Tie Rod Type	13-Mar-2023 12:50:11	SYRFLD	I	DON	220.13
06-Mar-2023 0	176,364		657529	06-100-PMB	Inspect B PMI	12-Mar-2023 09:30:00	SYRFLD	P	DON	87.46
06-Mar-2023 0	176,364		657529	38-100-PMA	Service A PMI	12-Mar-2023 09:30:04	SYRFLD	P	DON	135.59
21-Apr-2023 0	182,885		669407	03-002-035	Replace Windshield Wiper & Washer	24-Apr-2023 09:13:44	SYRFLD	P	DON	115.94
21-Apr-2023 0	182,885		669407	06-100-DOT	Inspect DOT Federal Inspection	21-Apr-2023 05:00:00	SYRFLD	P	DON	174.92
24-Apr-2023 0	184,040		671054	06-100-PMA	Inspect A PMI	30-Apr-2023 11:57:42	SYRFLD	P	DON	87.46
24-Apr-2023 0	184,040		671054	38-100-PMA	Service A PMI	30-Apr-2023 11:57:48	SYRFLD	P	DON	136.40
12-Jun-2023 0	185,169	8,421	681374	03-043-007	Replace Exhaust Pipe/Elbow	19-Jun-2023 07:13:22	SYRFLD	B	DON	902.59
05-Feb-2024 0	185,169	8,421	737831	03-016-027	Replace Trac Bar	01-Apr-2024 16:11:13	SYRFLD	B	DON	252.41
05-Feb-2024 0	185,169	8,421	737831	03-018-001	Replace Front Axle Hubs & Bearings	01-Apr-2024 16:12:00	SYRFLD	B	DON	448.23
05-Feb-2024 0	185,169	8,421	737831	03-027-045	Replace Filter Assembly	01-Apr-2024 16:11:10	SYRFLD	B	DON	317.98
05-Feb-2024 0	185,169	8,421	737831	03-090	Replace Bulk Product Transfer Systems Group	01-Apr-2024 16:09:20	SYRFLD	B	DON	1,409.20
05-Feb-2024 0	185,169	8,421	737831	06-100-DOT	Inspect DOT Federal Inspection	20-Mar-2024 17:01:22	SYRFLD	P	DON	105.00
05-Feb-2024 0	185,169	8,421	737831	06-100-PMB	Inspect B PMI	12-Feb-2024 12:18:30	SYRFLD	P	DON	43.73
05-Feb-2024 0	185,169	8,421	737831	07-027	Lubricate Transmission - Main, Automatic	12-Feb-2024 12:21:28	SYRFLD	P	DON	88.31
05-Feb-2024 0	185,169	8,421	737831	38-100-PMA	Service A PMI	12-Feb-2024 12:18:46	SYRFLD	P	DON	137.61
02-Apr-2024 0	200,304	9,013	749811	03-002-035	Replace Windshield Wiper & Washer	29-Apr-2024 13:53:40	SYRFLD	B	DON	132.82
02-Apr-2024 0	200,304	9,013	749811	03-053-015	Replace Tool Box	16-Apr-2024 10:58:11	SYRFLD	B	DON	1,052.39
02-Apr-2024 0	200,304	9,013	749811	06-100-PMA	Inspect A PMI	29-Apr-2024 13:53:40	SYRFLD	P	DON	105.00
02-Apr-2024 0	200,304	9,013	749811	19-052-011	Wire/Rewire Auxiliary Power	02-Apr-2024 11:20:46	SYRFLD	B	DON	525.00

Unit Job History

Michels Corporation

Report Printed: 26-Aug-2024 09:02:10 By User: RHEENING

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: B2833 - 2015 F250 CREWCAB										
02-Apr-2024 0	200,304	9,013	749811	31-017-001	Rotate Tire - Pneumatic	16-Apr-2024 10:52:36	SYRFLD	P	DON	105.00
02-Apr-2024 0	200,304	9,013	749811	38-100-PMA	Service A PMI	29-Apr-2024 13:53:40	SYRFLD	P	DON	260.47
04-Jun-2024 0	206,585	9,317	763738	06-100-009	Inspect Safety Check	04-Jun-2024 09:48:40	BTRUCK	N	DON	82.31
25-Jun-2024 1	206,585	9,317	768756	02-002	Clean Cab & Sheet Metal	16-Aug-2024 05:51:56	BSETUP	Z	DON	194.66
25-Jun-2024 1	206,585	9,317	768756	25-051	Remove General Accessories	31-Jul-2024 07:50:15	BSETUP	Z	DON	462.99

Unit No: B2833

Count: 150

45,923.40