

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: Q1395 - 2020 JOHN DEERE 310SL										
25-Mar-2020 0	4	0	432734	01-310	Adjust Backhoe (Rubber Tire)	25-Mar-2020 15:32:06	BBKHOE	Q	DON	0.00
25-Mar-2020 0	4	0	432734	14-017-011	Install Tire - Foam Filled	25-Mar-2020 09:37:51	BBKHOE	Q	DON	880.57
25-Mar-2020 0	4	0	432734	14-034-006	Install Warning Lamps - Special Application	26-Mar-2020 05:53:28	BBKHOE	Q	DON	178.91
25-Mar-2020 0	4	0	432734	14-051	Install General Accessories	25-Mar-2020 13:29:58	BBKHOE	Q	DON	0.00
25-Mar-2020 0	4	0	432734	14-051-009	Install Fire Extinguisher	25-Mar-2020 10:03:24	BBKHOE	Q	DON	43.00
25-Mar-2020 0	4	0	432734	14-052-003	Install Radio Equipment	26-Mar-2020 12:39:57	BBKHOE	Q	DON	767.00
25-Mar-2020 0	4	0	432734	14-059-002	Install Pintle Hook Assembly	25-Mar-2020 11:27:22	BBKHOE	Q	DON	243.84
25-Mar-2020 0	4	0	432734	14-063-003	Install Transceiver - GPS Tracker	26-Mar-2020 10:32:36	BBKHOE	Q	DON	334.48
25-Mar-2020 0	4	0	432734	14-065-007	Install Hoses & Fittings	25-Mar-2020 10:13:27	BBKHOE	Q	DON	176.58
25-Mar-2020 0	4	0	432734	14-519-001	Install Front Bumper	26-Mar-2020 13:38:33	BBKHOE	Q	DON	291.34
25-Mar-2020 0	4	0	432734	26-053-005	Weld Markings - Vehicle - Decals	25-Mar-2020 11:56:25	BBKHOE	Q	DON	8.47
25-Mar-2020 0	4	0	433470	14-051-009	Install Fire Extinguisher	30-Mar-2020 09:30:16	LAVSHIP	O	DON	107.42
04-Apr-2020 1	101	0	437782	07-053-999	Lubricate Vehicle Fluids, Lubricants, Gases, & I	04-Apr-2020 10:19:59	BVLOFC	N	DON	57.69
08-May-2020 1	288	0	444232	03-053-999	Replace Vehicle Fluids, Lubricants, Gases, & Pa	08-May-2020 11:10:00	BVLOFC	N	DON	134.47
29-May-2020 1	296	0	446441	06-100-PMA	Inspect A PMI	29-May-2020 00:00:00	BVLOFC	P	DON	0.00
29-May-2020 1	296	0	446441	38-100-PMA	Service A PMI	29-May-2020 00:00:00	BVLOFC	P	DON	866.71
29-May-2020 1	296	0	446441	95-MSC	Travel Miscellaneous	29-May-2020 00:00:00	BVLOFC	P	DON	596.25
22-Jul-2020 12	441	0	451965	06-100-PMA	Inspect A PMI	22-Jul-2020 12:37:29	BBKHOE	P	DON	0.00
22-Jul-2020 12	441	0	451965	14-063-003	Install Transceiver - GPS Tracker	22-Jul-2020 12:37:16	BBKHOE	Q	DON	0.00
22-Jul-2020 12	441	0	451965	38-100-PMA	Service A PMI	22-Jul-2020 12:37:34	BHVYEQ	P	DON	2,064.35
26-Oct-2020 0	821	0	468606	06-100-PMA	Inspect A PMI	26-Oct-2020 05:38:51	BBKHOE	P	DON	0.00
26-Oct-2020 0	821	0	468606	38-100-PMA	Service A PMI	26-Oct-2020 05:38:58	BHVYEQ	P	DON	1,099.79
03-Dec-2020 1	1,008	0	475089	06-100-PMB	Inspect B PMI	03-Dec-2020 16:04:14	BBKHOE	P	DON	0.00
03-Dec-2020 1	1,008	0	475089	38-100-PMC	Service C PMI	03-Dec-2020 16:04:20	BHVYEQ	P	DON	1,564.00
23-Feb-2022 1	1,866	0	569339	03-027-042	Replace Switch - Gear Selector	23-Feb-2022 13:39:44	BVLOFC	O	DON	62.55
23-Feb-2022 1	1,866	0	569339	06-022	Inspect Axles - Driven, Rear	23-Feb-2022 13:39:44	BVLOFC	O	DON	583.86
23-Feb-2022 1	1,866	0	569339	06-100-PMA	Inspect A PMI	23-Feb-2022 13:39:44	BVLOFC	P	DON	0.00
23-Feb-2022 1	1,866	0	569339	24-042-003	Repair Fan	23-Feb-2022 13:39:44	BVLOFC	I	DON	83.17
23-Feb-2022 1	1,866	0	569339	24-065-007	Repair Hoses & Fittings	23-Feb-2022 13:39:44	BVLOFC	I	DON	632.07

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: Q1395 - 2020 JOHN DEERE 310SL										
23-Feb-2022 1	1,866	0	569339	24-514	Repair Bucket	23-Feb-2022 13:39:44	BVLOFC	I	DON	742.28
23-Feb-2022 1	1,866	0	569339	38-100-PMA	Service A PMI	23-Feb-2022 13:39:44	BVLOFC	P	DON	3,021.93
14-Sep-2022 0	2,582	0	616188	03-043-025	Replace Filter - DEF	14-Sep-2022 08:51:56	BVLOFC	P	DON	260.64
14-Sep-2022 0	2,582	0	616188	03-065-006	Replace Filters, Strainers, Screens & Housing	14-Sep-2022 08:51:56	BVLOFC	I	DON	771.48
14-Sep-2022 0	2,582	0	616188	06-100-PMB	Inspect B PMI	14-Sep-2022 08:51:56	BVLOFC	P	DON	0.00
14-Sep-2022 0	2,582	0	616188	38-100-PMB	Service B PMI	14-Sep-2022 08:51:56	BVLOFC	P	DON	2,918.39
14-Sep-2022 0	2,582	0	616188	95-MSC-004	Travel Travel Time - To/From Job Site	14-Sep-2022 08:51:56	BVLOFC	N	DON	535.83
05-Dec-2022 1	2,897	0	636928	03-065	Replace Hydraulic Systems - Special Applicatio	05-Dec-2022 14:04:13	BVLOFC	I	DON	199.36
19-Jan-2023 1	3,136	0	646426	24-052-003	Repair Radio Equipment	19-Jan-2023 13:03:15	ELEC01	N	DON	110.35
03-Mar-2023 1	3,296	0	656679	03-514-002	Replace Shanks or Teeth	03-Mar-2023 11:25:44	BBKH0E	E	DON	715.38
03-Mar-2023 1	3,296	0	656679	06-100-PMA	Inspect A PMI	03-Mar-2023 11:23:51	BBKH0E	P	DON	0.00
03-Mar-2023 1	3,296	0	656679	38-100-PMA	Service A PMI	03-Mar-2023 11:23:53	BBKH0E	P	DON	616.75
03-Mar-2023 1	3,296	0	656679	95-310	Travel Backhoe (Rubber Tire)	03-Mar-2023 11:46:50	BBKH0E	P	DON	893.20
10-Apr-2023 0	3,606	0	670702	03-027-045	Replace Filter Assembly	28-Apr-2023 06:49:41	BVLOFC	P	DON	69.04
10-Apr-2023 0	3,606	0	670702	03-034-002	Replace Stop, Tail, Turn & License	28-Apr-2023 06:49:41	BVLOFC	I	DON	133.41
10-Apr-2023 0	3,606	0	670702	03-041-007	Replace Filter - Outer	28-Apr-2023 06:49:41	BVLOFC	I	DON	74.97
10-Apr-2023 0	3,606	0	670702	03-044-002	Replace Filters	28-Apr-2023 06:49:41	BVLOFC	P	DON	98.04
10-Apr-2023 0	3,606	0	670702	03-065-006	Replace Filters, Strainers, Screens & Housing	28-Apr-2023 06:49:41	BVLOFC	P	DON	155.92
10-Apr-2023 0	3,606	0	670702	06-100-PMB	Inspect B PMI	28-Apr-2023 06:49:41	BVLOFC	P	DON	0.00
10-Apr-2023 0	3,606	0	670702	38-100-PMA	Service A PMI	28-Apr-2023 06:49:41	BVLOFC	P	DON	672.14
21-Aug-2023 1	4,156	0	698601	24-017-001	Repair Tire - Pneumatic	21-Sep-2023 14:16:13	BVLOFC	I	DON	43.80
16-Oct-2023 0	4,423	0	713096	06-100-PMA	Inspect A PMI	16-Oct-2023 07:50:57	BVLOFC	P	DON	0.00
16-Oct-2023 0	4,423	0	713096	24-065-004	Repair Cylinder	16-Oct-2023 07:50:57	BVLOFC	I	DON	1,257.38
16-Oct-2023 0	4,423	0	713096	38-100-PMA	Service A PMI	16-Oct-2023 07:50:57	BVLOFC	P	DON	1,459.99
16-Oct-2023 0	4,423	0	713096	95-MSC	Travel Miscellaneous	16-Oct-2023 07:50:57	BVLOFC	N	DON	656.70
14-Dec-2023 1	4,692	0	729597	03-031-001	Replace Generator/Alternator	14-Dec-2023 14:08:00	BVLOFC	N	DON	1,425.02
14-Dec-2023 1	4,692	0	729597	06-100-PMC	Inspect C PMI	14-Dec-2023 14:08:00	BVLOFC	P	DON	0.00
14-Dec-2023 1	4,692	0	729597	35-031-001	Diagnose Generator/Alternator	14-Dec-2023 14:08:00	BVLOFC	N	DON	324.36
14-Dec-2023 1	4,692	0	729597	38-100-PMC	Service C PMI	14-Dec-2023 14:08:00	BVLOFC	P	DON	1,403.43

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: Q1395 - 2020 JOHN DEERE 310SL										
26-Mar-2024 1	4,860	0	748692	06-100-PMB	Inspect B PMI	02-Apr-2024 21:19:36	TRK026	P	DON	551.25
26-Mar-2024 1	4,860	0	748692	38-100-PMB	Service B PMI	02-Apr-2024 21:19:41	TRK026	P	DON	513.44
07-May-2024 1	5,039	0	766756	06-310	Inspect Backhoe (Rubber Tire)	07-May-2024 00:00:00	BVLOFC	N	DON	588.23
26-Jul-2024 13		0	775210	02-310	Clean Backhoe (Rubber Tire)	01-Aug-2024 12:59:19	BWASH	N	DON	201.69
26-Jul-2024 13		0	775210	24-059-002	Repair Pintle Hook Assembly	12-Aug-2024 16:01:56	BBKHOE	P	DON	68.51
27-Jul-2024 00		0	775210	OS-310	Out-Service Backhoe (Rubber Tire)	12-Aug-2024 16:02:06	BBKHOE	Z	DON	233.29
27-Jul-2024 00		0	775875	02-002-061	Clean Seat Cushion	27-Jul-2024 00:00:00	BVLOFC	N	DON	276.87
27-Jul-2024 00		0	775875	03-002-061	Replace Seat Cushion	27-Jul-2024 00:00:00	BVLOFC	N	DON	613.57
27-Jul-2024 00		0	775875	06-100-PMC	Inspect C PMI	27-Jul-2024 00:00:00	BVLOFC	P	DON	0.00
27-Jul-2024 00		0	775875	24-014-010	Repair Toolbox Mounting	27-Jul-2024 00:00:00	BVLOFC	N	DON	178.08
27-Jul-2024 00		0	775875	38-100-PMC	Service C PMI	27-Jul-2024 00:00:00	BVLOFC	P	DON	1,836.20

Unit No: Q1395

Count: 69

34,397.41