

# Unit Job History

Michels Corporation  
Report Printed: 28-Jul-2023 13:48:42 By User: RHENNING

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost	
<b>Unit No: Z1119 - 2016 VERMEER D40XSS</b>											
15-Nov-2016	1	7	0	266774	14-063-003	Install Transceiver - GPS Tracker	21-Nov-2016 13:11:29	BDDRIL	Q	DON	2,088.88
08-Mar-2017	0	7	0	281402	24-052	Repair Electrical Accessories	08-Mar-2017 07:00:00	BVLOFC	F	DON	6,174.60
08-Mar-2017	0	7	0	281402	24-MSC-001	Repair Tools - General	08-Mar-2017 07:00:00	BVLOFC	F	DON	1,584.87
08-Mar-2017	0	7	0	281402	24-360-009	Repair Bucket Tooth / Cutting Edge	16-Mar-2017 07:00:00	BVLOFC	F	DON	759.84
08-Mar-2017	0	7	0	281402	24-065	Repair Hydraulic Systems - Special Application:	16-Mar-2017 14:12:00	BVLOFC	F	DON	1,840.75
06-Apr-2017	1	123	0	284239	34-065	Reseal Hydraulic Systems - Special Application:	26-Apr-2017 16:17:44	BVLOFC	W	DON	396.38
28-Jun-2017	08	123	0	294723	03-704-011	Replace Frame / Chassis	28-Jun-2017 15:28:26	BSDRIL	W	DON	0.00
28-Jun-2017	08	123	0	294723	03-704-013	Replace Stakedown	28-Jun-2017 15:28:29	BSDRIL	W	DON	0.00
28-Jun-2017	08	123	0	294723	03-704-016	Replace Stem Rack	28-Jun-2017 15:28:23	BSDRIL	W	DON	0.00
28-Jun-2017	08	123	0	294723	14-704-010	Install Wiring	28-Jun-2017 15:28:20	BSDRIL	W	DON	292.29
28-Jun-2017	08	123	0	294723	38-047-001	Service Engine Filter Kits	28-Jun-2017 15:28:17	BSDRIL	P	DON	1,634.19
14-Jul-2017	08	123	0	296803	03-704-017	Replace Rod Loader System	14-Jul-2017 10:46:50	BSDRIL	J	DON	193.77
14-Dec-2017	0	123	0	316043	02-704	Clean Drill Rig	14-Dec-2017 16:00:16	BWASH	J	DON	216.78
02-Jan-2018	18	123	0	317843	24-704-017	Repair Rod Loader System	08-Feb-2018 11:10:00	BSDRIL	N	DON	1,971.55
02-Jan-2018	18	123	0	317843	24-705	Repair Vis	08-Feb-2018 11:10:09	BSDRIL	N	DON	1,642.07
02-Jan-2018	18	123	0	317843	38-040	Service Engine / Motor Systems Group	08-Jan-2018 15:37:08	BSDRIL	P	DON	417.94
28-Mar-2018	0	123	0	330079	03-700	Replace Directional Drilling Group	28-Mar-2018 09:29:00	BVLOFC	F	DON	1,102.08
04-Jun-2018	07	123	0	338180	06-704	Inspect Drill Rig	04-Jun-2018 08:31:42	BSDRIL	F	DON	455.05
04-Jun-2018	07	123	0	338180	24-704-022	Repair Rotation Thrust / Bearing Box	04-Jun-2018 08:31:52	BSDRIL	F	DON	1,529.23
04-Jun-2018	07	123	0	338180	38-047-001	Service Engine Filter Kits	04-Jun-2018 08:31:56	BSDRIL	F	DON	993.03
04-Jun-2018	07	123	0	338180	95-MSC-004	Travel Travel Time - To/From Job Site	04-Jun-2018 08:31:48	BSDRIL	F	DON	1,481.55
31-Jul-2018	06	123	0	346601	24-704-022	Repair Rotation Thrust / Bearing Box	23-Aug-2018 12:54:24	BSDRIL	B	DON	98.64
31-Jul-2018	06	123	0	346601	95-MSC-004	Travel Travel Time - To/From Job Site	23-Aug-2018 12:54:24	BSDRIL	B	DON	80.31
05-Oct-2018	04	123	0	355298	24-705	Repair Vis	09-Oct-2018 13:57:39	BSDRIL	B	DON	1,735.37
05-Oct-2018	04	123	0	355298	95-MSC-004	Travel Travel Time - To/From Job Site	09-Oct-2018 13:57:39	BSDRIL	B	DON	180.81
27-Nov-2018	1	123	0	361880	02-002	Clean Cab & Sheet Metal	29-Nov-2018 11:27:08	BSETUP	I	DON	118.10
28-Nov-2018	1	1,667	0	362047	02-002	Clean Cab & Sheet Metal	29-Nov-2018 17:00:01	BSETUP	I	DON	65.21
28-Nov-2018	1	1,667	0	362047	03-704-004	Replace Drilling Subs	07-Dec-2018 13:07:36	BSDRIL	I	DON	373.75
28-Nov-2018	1	1,667	0	362047	03-704-022	Replace Rotation Thrust / Bearing Box	07-Dec-2018 13:06:41	BSDRIL	O	DON	5,358.74

# Unit Job History

Mitchels Corporation  
 Report Printed: 28-Jul-2023 13:48:42 By User: RHENNING

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: Z1119 - 2016 VERMEER D40X55										
28-Nov-2018	1,667	0	362047	24-267-003	Repair Hydraulics	07-Dec-2018 13:06:58	BSDRIL	B	DON	105.47
28-Nov-2018	1,667	0	362047	24-704-017	Repair Rod Loader System	07-Dec-2018 13:08:10	BSDRIL	I	DON	1,762.73
28-Nov-2018	1,667	0	362047	24-705	Repair Vise	07-Dec-2018 13:05:59	BSDRIL	N	DON	4,796.02
28-Nov-2018	1,667	0	362047	38-047-001	Service Engine Filter Kits	06-Dec-2018 17:01:02	BSDRIL	P	DON	858.17
28-Nov-2018	1,667	0	362047	38-702	Service Mud Pump	06-Dec-2018 15:19:50	BSDRIL	N	DON	9,895.68
28-Nov-2018	1,667	0	362047	38-704-015	Service Track	04-Dec-2018 13:53:26	BSDRIL	N	DON	931.69
28-Nov-2018	1,667	0	362047	38-704-016	Service Stem Rack	07-Dec-2018 12:56:19	BSDRIL	I	DON	21,192.64
28-Nov-2018	1,667	0	362047	38-704-017	Service Rod Loader System	03-Dec-2018 14:22:03	BSDRIL	N	DON	1,164.10
28-Nov-2018	1,667	0	362047	38-704-022	Service Rotation Thrust / Bearing Box	07-Dec-2018 13:07:55	BSDRIL	N	DON	324.26
03-Jan-2019	1,667	0	366760	03-267	Replace Drilling and Boring	09-Jan-2019 06:49:41	BVLOFC	E	DON	4,557.77
19-Mar-2019	1,667	0	377231	02-704	Clean Drill Rig	19-Mar-2019 16:06:52	BWASH	N	DON	154.49
20-Mar-2019	1,667	0	377345	06-704	Inspect Drill Rig	03-Apr-2019 16:27:50	BSDRIL	N	DON	118.72
20-Mar-2019	1,667	0	377345	38-040	Service Engine / Motor Systems Group	20-Mar-2019 15:19:28	BSDRIL	N	DON	387.48
20-Mar-2019	1,667	0	377345	38-705	Service Vise	27-Mar-2019 07:30:05	BSDRIL	I	DON	2,131.98
20-Mar-2019	1,667	0	377345	09-704-017	Align Rod Loader System	03-Apr-2019 16:27:53	BSDRIL	I	DON	408.40
20-Mar-2019	1,667	0	377345	38-704-022	Service Rotation Thrust / Bearing Box	03-Apr-2019 16:28:03	BSDRIL	N	DON	364.76
20-Mar-2019	1,667	0	377345	12-002	Refinish Cab & Sheet Metal	21-Mar-2019 16:30:45	BSDRIL	I	DON	64.45
20-Mar-2019	1,667	0	377345	24-704-017	Repair Rod Loader System	03-Apr-2019 16:28:05	BSDRIL	I	DON	429.50
30-May-2019	1,841	0	388147	06-704-017	Inspect Rod Loader System	06-Jun-2019 07:58:38	BSDRIL	B	DON	40.81
30-May-2019	1,841	0	388147	24-704-017	Repair Rod Loader System	06-Jun-2019 07:58:41	BSDRIL	B	DON	370.12
30-May-2019	1,841	0	388147	38-040	Service Engine / Motor Systems Group	06-Jun-2019 07:58:34	BSDRIL	P	DON	69.41
18-Jun-2019	2,425	0	407105	24-700	Travel Travel Time - To/From Job Site	06-Jun-2019 07:58:45	BSDRIL	B	DON	110.81
30-Oct-2019	2,460	0	410206	24-704-022	Repair Directional Drilling Group	18-Jun-2019 08:04:00	BVLOFC	N	DON	282.15
09-Nov-2019	2,498	0	411919	02-704	Clean Drill Rig	30-Oct-2019 14:53:00	BSDRIL	B	DON	1,038.26
11-Nov-2019	2,498	0	411961	38-040	Service Engine / Motor Systems Group	09-Nov-2019 10:01:51	BWASH	N	DON	243.81
11-Nov-2019	2,498	0	411961	06-704	Inspect Drill Rig	26-Nov-2019 14:51:03	BSDRIL	N	DON	898.22
11-Nov-2019	2,498	0	411961	24-704-016	Repair Stem Rack	11-Nov-2019 08:37:45	BSDRIL	P	DON	89.51
11-Nov-2019	2,498	0	411961	24-704-017	Repair Rod Loader System	26-Nov-2019 14:51:05	BSDRIL	I	DON	90.68
11-Nov-2019	2,498	0	411961	24-704-017	Repair Rod Loader System	15-Nov-2019 13:51:56	BSDRIL	I	DON	1,993.17



# Unit Job History

Michels Corporation  
Report Printed: 28-Jul-2023 13:48:42 By User: RHENNING

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
<b>Unit No: Z1119 - 2016 VERMEER D40X55</b>										
11-Nov-2019 0	2,498		411961	24-034-014	Repair Auxiliary Work / Flood Light	18-Nov-2019 14:23:44	BSDRIL	I	DON	370.83
11-Nov-2019 0	2,498		411961	24-078-003	Repair Hose Carrier	11-Nov-2019 11:14:46	BSDRIL	I	DON	38.78
11-Nov-2019 0	2,498		411961	24-704-018	Repair Operator Console / Station	26-Nov-2019 14:51:09	BSDRIL	I	DON	631.28
11-Nov-2019 0	2,498		411961	24-705	Repair Vise	12-Nov-2019 14:46:08	BSDRIL	I	DON	1,401.48
11-Nov-2019 0	2,498		411961	24-704-015	Repair Track	18-Nov-2019 17:01:32	BSDRIL	I	DON	840.25
11-Nov-2019 0	2,498		411961	24-704-022	Repair Rotation Thrust / Bearing Box	14-Nov-2019 14:04:59	BSDRIL	N	DON	5,720.71
11-Nov-2019 0	2,498		411961	03-032-009	Replace Switch - Master Disconnect	14-Nov-2019 14:38:28	BSDRIL	I	DON	84.56
11-Nov-2019 0	2,498		411961	24-706-006	Repair Hydraulic Hoses and Lines	26-Nov-2019 14:51:00	BSDRIL	I	DON	291.62
11-Nov-2019 0	2,498		411961	24-704-013	Repair Stakedown	15-Nov-2019 14:44:25	BSDRIL	I	DON	32.51
06-Dec-2019 1	2,504		415617	24-065-001	Repair Hydraulic Systems	27-Dec-2019 08:42:51	ROGSHP	W	DON	143.52
03-Apr-2020 1	2,601		434337	03-044-024	Replace Fuel / Water Separator	03-Apr-2020 13:20:06	ROGSHP	N	DON	130.42
03-Apr-2020 1	2,601		434337	03-047-001	Replace Engine Filter Kits	03-Apr-2020 13:08:24	ROGSHP	N	DON	80.74
03-Apr-2020 1	2,601		434337	06-704	Inspect Drill Rig	03-Apr-2020 13:27:45	ROGSHP	N	DON	93.47
03-Apr-2020 1	2,601		434337	24-002-065	Repair Hood Latch	03-Apr-2020 13:27:06	ROGSHP	N	DON	10.28
17-Apr-2020 1	2,656		436514	24-704-022	Repair Rotation Thrust / Bearing Box	30-Apr-2020 15:36:17	ROGSHP	B	DON	1,929.58
17-Apr-2020 1	2,656		436514	24-705	Repair Vise	08-May-2020 09:49:46	ROGSHP	B	DON	565.79
01-Jun-2020 0	2,778		443021	03-065-007	Replace Hoses & Fittings	05-Jun-2020 09:10:46	LAVSHP	B	DON	629.24
20-Jul-2020 09	2,893		451371	03-065-007	Replace Hoses & Fittings	21-Jul-2020 12:00:27	LAVSHP	B	DON	709.37
03-Sep-2020 0	2,982		459796	03-053-008	Replace Hoses & Tubings & Fittings	10-Sep-2020 15:06:57	ROGSHP	B	DON	288.57
27-Oct-2020 0:	3,051		468937	06-100-PMB	Inspect B PMI	12-Nov-2020 07:55:58	LAVSHP	P	DON	830.74
27-Oct-2020 0:	3,051		468937	24-702	Repair Mud Pump	12-Nov-2020 07:55:54	LAVSHP	I	DON	980.39
27-Oct-2020 0:	3,051		468937	26-702	Weld Mud Pump	12-Nov-2020 07:55:51	LAVSHP	I	DON	1,096.13
27-Oct-2020 0:	3,051		468937	10-705	Rebush Vise	12-Nov-2020 07:55:45	LAVSHP	I	DON	2,006.98
27-Oct-2020 0:	3,051		468937	03-708-007	Replace Sub Saver	12-Nov-2020 07:55:33	LAVSHP	I	DON	508.53
27-Oct-2020 0:	3,051		468937	38-100-PMB	Service B PMI	12-Nov-2020 07:57:08	LAVSHP	P	DON	1,596.59
27-Oct-2020 0:	3,051		468937	01-704-017	Adjust Rod Loader System	12-Nov-2020 07:55:48	LAVSHP	I	DON	351.62
27-Oct-2020 0:	3,051		468937	03-065-004	Replace Cylinder	12-Nov-2020 07:55:30	LAVSHP	I	DON	1,711.93
27-Oct-2020 0:	3,051		468937	03-044-008	Replace Engine Shutdown	12-Nov-2020 07:55:42	LAVSHP	I	DON	287.22
27-Oct-2020 0:	3,051		468937	34-702	Rescal Mud Pump	12-Nov-2020 07:55:36	LAVSHP	I	DON	2,749.62

# Unit Job History

Mitchels Corporation  
Report Printed: 28-Jul-2023 13:48:42 By User: RHENNING

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Job Status	Total Cost
Unit No: Z1119 - 2016 VERMEER D40X55											
27-Oct-2020 0:	3,051		468937	03-701-002	Replace Plumbing / Valves (water)	12-Nov-2020 07:55:39	LAVSHP	I	DON	DON	924.77
27-Oct-2020 0:	3,051		468937	03-065-005	Replace Drive - Motor / Pump	12-Nov-2020 07:55:27	LAVSHP	I	DON	DON	2,617.42
02-Apr-2021 1	3,231		498228	06-100-PMA	Inspect A PMI	02-Apr-2021 12:29:30	TRK400	P	DON	DON	43.92
02-Apr-2021 1	3,231		498228	38-100-PMA	Service A PMI	02-Apr-2021 13:10:53	TRK400	I	DON	DON	120.74
16-Jun-2021 0:	3,231		512985	06-100-PMA	Inspect A PMI	16-Jun-2021 06:05:58	TRK400	P	DON	DON	44.49
16-Jun-2021 0:	3,231		512985	38-100-PMA	Service A PMI	16-Jun-2021 07:31:56	TRK400	I	DON	DON	276.54
23-Jun-2021 1:	3,231		514525	03-002	Replace Cab & Sheet Metal		LAVSHP	O	CAN	CAN	0.00
23-Jun-2021 1:	3,231		514525	03-002-037	Replace Seat Assembly	25-Jun-2021 09:32:17	LAVSHP	O	DON	DON	737.17
13-Aug-2021 0:	3,231		524795	24-065-007	Repair Hoses & Fittings	13-Aug-2021 07:19:59	MEI371	I	DON	DON	48.70
25-Aug-2021 1	3,231		527466	03-065-007	Replace Hoses & Fittings	27-Aug-2021 11:21:15	LAVSHP	B	DON	DON	558.44
30-Sep-2021 1:	3,231		535692	06-100-PMA	Inspect A PMI	30-Sep-2021 17:07:44	SCHED	P	DON	DON	25.58
30-Sep-2021 1:	3,231		535692	38-100-PMA	Service A PMI	12-Oct-2021 18:59:28	TRK401	P	DON	DON	169.50
19-Oct-2021 0:	3,231		540174	03-704-002	Replace Guide Rollers	20-Oct-2021 08:37:42	TRK400	O	DON	DON	1,048.50
19-Oct-2021 0:	3,231		540174	06-704-017	Inspect Rod Loader System	19-Oct-2021 11:38:32	TRK400	O	DON	DON	110.56
19-Oct-2021 0:	3,231		540174	06-704-022	Inspect Rotation Thrust / Bearing Box	19-Oct-2021 12:52:17	TRK400	O	DON	DON	131.34
19-Oct-2021 0:	3,231		540174	06-042	Inspect Cooling System	19-Oct-2021 08:41:09	TRK400	O	DON	DON	38.05
19-Oct-2021 0:	3,231		540174	06-704-001	Inspect Pads and Slides	19-Oct-2021 09:37:13	TRK400	O	DON	DON	91.04
19-Oct-2021 0:	3,231		540174	03-042-014	Replace Coolant Overflow Reservoir	20-Oct-2021 12:45:25	TRK400	I	DON	DON	829.87
19-Oct-2021 0:	3,231		540174	03-704-001	Replace Pads and Slides	19-Oct-2021 13:13:10	TRK400	I	DON	DON	215.56
19-Oct-2021 0:	3,231		540174	03-065-005	Replace Drive - Motor / Pump	21-Oct-2021 15:00:58	TRK400	I	DON	DON	322.20
19-Oct-2021 0:	3,231		540174	03-002-065	Replace Hood Latch	20-Oct-2021 09:56:31	TRK400	B	DON	DON	334.75
19-Oct-2021 0:	3,231		540174	06-065	Inspect Hydraulic Systems - Special Application	25-Oct-2021 07:27:24	TRK400	O	DON	DON	46.96
19-Oct-2021 0:	3,231		540174	34-065-005	Rescal Drive - Motor / Pump	10-Nov-2021 12:51:15	TRK400	B	DON	DON	2,805.60
19-Oct-2021 0:	3,231		540174	03-704-007	Replace Hydraulic Motor	28-Oct-2021 12:32:51	TRK400	I	DON	DON	5,803.72
23-Feb-2022 1	4,199		569299	03-063-003	Replace Transceiver - GPS Tracker	24-Feb-2022 08:43:28	LAVSHP	Q	DON	DON	375.93
19-Apr-2022 0	4,199		582600	06-100-ELE	Inspect Periodic Electrical Inspection	19-Apr-2022 08:40:37	MEI371	P	DON	DON	83.76
19-Apr-2022 0	4,199		582600	06-100-PMB	Inspect B PMI	19-Apr-2022 07:06:00	MEI371	P	DON	DON	46.52
19-Apr-2022 0	4,199		582600	38-100-PMB	Service B PMI	19-Apr-2022 07:52:00	MEI371	P	DON	DON	147.94
18-May-2022 1	4,445		589624	02-042-002	Clean Radiator	10-Jun-2022 09:12:28	OTSHP	I	DON	DON	21.69



# Unit Job History

Mitchells Corporation

Report Printed: 28-Jul-2023 13:48:42 By User: RHENNING

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: Z1119 - 2016 VERMEER D40X55										
18-May-2022	4,445		589624	03-708-004	Replace Starter Rod	18-May-2022 11:16:08	OTSSHP	N	DON	1,066.96
18-May-2022	4,445		589624	03-910-001	Replace Dies - Jaw	19-May-2022 06:04:55	OTSSHP	N	DON	479.52
18-May-2022	4,445		589624	06-100-ELE	Inspect Periodic Electrical Inspection	10-Jun-2022 10:10:26	OTSSHP	P	DON	10.66
18-May-2022	4,445		589624	06-100-PMA	Inspect A PMI	10-Jun-2022 07:35:34	OTSSHP	P	DON	51.72
18-May-2022	4,445		589624	38-100-PMA	Service A PMI	10-Jun-2022 08:42:52	OTSSHP	P	DON	321.85
15-Jun-2022	4,446		596125	03-065-006	Replace Filters, Strainers, Screens & Housing	15-Jun-2022 16:26:41	TRK400	I	DON	319.19
15-Jun-2022	4,446		596125	06-065-001	Inspect Hydraulic Systems	15-Jun-2022 16:26:59	TRK400	O	DON	103.52
15-Jun-2022	4,455		596376	03-053-007	Replace Hardware - Expendable Items	11-Jul-2022 08:42:03	LAVSHP	I	DON	301.38
15-Jun-2022	4,455		596376	03-706-004	Replace Controls	11-Jul-2022 08:42:12	LAVSHP	B	DON	2,117.73
15-Jun-2022	4,455		596376	06-100-PMA	Inspect A PMI	11-Jul-2022 08:42:09	LAVSHP	P	DON	0.00
15-Jun-2022	4,455		596376	35-065-001	Diagnose Hydraulic Systems	11-Jul-2022 08:42:06	LAVSHP	B	DON	627.61
28-Jun-2022	4,477		598961	03-267-011	Replace Auger	28-Jun-2022 13:31:37	OTSSHP	I	DON	7,278.53
28-Jun-2022	4,477		598961	06-267-011	Inspect Auger	07-Jul-2022 08:00:56	OTSSHP	O	DON	8.40
22-Jul-2022	4,518		604454	03-053-008	Replace Hoses & Tubings & Fittings	22-Jul-2022 15:12:00	OTSSHP	I	DON	161.22
22-Jul-2022	4,518		604454	03-065-006	Replace Filters, Strainers, Screens & Housing	22-Jul-2022 13:24:15	OTSSHP	P	DON	204.18
16-Aug-2022	4,651		609843	38-100-PMA	Service A PMI		OTSSHP	P	CAN	0.00
16-Aug-2022	4,651		609843	06-100-PMA	Inspect A PMI	16-Aug-2022 14:53:46	OTSSHP	P	DON	64.89
16-Aug-2022	4,651		609843	24-099	Repair Safety Devices, Instruments & Gauges	16-Aug-2022 15:10:15	OTSSHP	I	DON	3.37
16-Aug-2022	4,651		609843	24-705	Repair Vise	16-Aug-2022 15:18:42	OTSSHP	I	DON	9.29
22-Aug-2022	4,661		611085	03-065-007	Replace Hoses & Fittings	22-Aug-2022 09:41:21	LAVSHP	B	DON	463.63
06-Sep-2022	4,711		614316	06-100-PMA	Inspect A PMI	06-Sep-2022 16:10:59	OTSSHP	P	DON	47.20
06-Sep-2022	4,711		614316	38-100-PMA	Service A PMI	06-Sep-2022 15:43:59	OTSSHP	P	DON	404.63
31-Oct-2022	4,952		628379	03-704-001	Replace Pads and Slides	31-Oct-2022 11:17:49	OTSSHP	N	DON	935.12
31-Oct-2022	4,952		628379	06-100-PMA	Inspect A PMI	31-Oct-2022 14:15:33	OTSSHP	P	DON	38.21
31-Oct-2022	4,952		628379	24-705	Repair Vise	31-Oct-2022 14:10:34	OTSSHP	N	DON	1,780.07
31-Oct-2022	4,952		628379	38-100-PMA	Service A PMI	31-Oct-2022 10:31:04	OTSSHP	P	DON	237.73
05-Jan-2023	5,074		642807	02-704	Clean Drill Rig	06-Jan-2023 08:16:48	BWASH	N	DON	272.57
05-Jan-2023	5,074		642807	03-044-013	Replace Cap - Fuel Tank	11-Jan-2023 05:53:25	BSDRL	I	DON	52.22
11-Jan-2023	5,074		644181	03-032-004	Replace Battery Cables and Ends	20-Jan-2023 10:15:24	BSDRL	I	DON	587.11

# Unit Job History

Michels Corporation  
Report Printed: 28-Jul-2023 13:48:42 By User: RHENNING

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
--------------	---------	---------	------------	----------	-----------------	----------------	--------------	------------	------------	------------

## Unit No: Z1119 - 2016 VERMEER D40X55

11-Jan-2023 05	5,074		644181	03-032-009	Replace Switch - Master Disconnect	20-Jan-2023 10:15:14	BSDRIL	I	DON	210.41
11-Jan-2023 05	5,074		644181	03-034-014	Replace Auxiliary Work / Flood Light	26-Jan-2023 08:22:24	BSDRIL	I	DON	50.06
11-Jan-2023 05	5,074		644181	03-042-012	Replace Clamps and Hoses	20-Jan-2023 10:15:27	BSDRIL	I	DON	523.00
11-Jan-2023 05	5,074		644181	03-045-026	Replace Tensioner - Engine Belts	20-Jan-2023 10:15:12	BSDRIL	I	DON	789.97
11-Jan-2023 05	5,074		644181	03-053-005	Replace Markings - Vehicle - Decals	03-Feb-2023 11:34:10	BSDRIL	I	DON	344.04
11-Jan-2023 05	5,074		644181	03-708-007	Replace Sub Saver	07-Feb-2023 16:18:11	BSDRIL	N	DON	324.95
11-Jan-2023 05	5,074		644181	06-100-PMA	Inspect A PMI	20-Jan-2023 10:15:02	BSDRIL	P	DON	92.09
11-Jan-2023 05	5,074		644181	06-702	Inspect Mud Pump	20-Jan-2023 10:15:20	BSDRIL	P	DON	190.06
11-Jan-2023 05	5,074		644181	24-002-065	Repair Hood Latch	01-Feb-2023 10:07:45	BSDRIL	I	DON	896.78
11-Jan-2023 05	5,074		644181	24-030	Repair Electrical Group	24-Feb-2023 09:26:45	BSDRIL	I	DON	746.65
11-Jan-2023 05	5,074		644181	24-043	Repair Exhaust System	24-Feb-2023 09:26:49	BSDRIL	I	DON	2,363.99
11-Jan-2023 05	5,074		644181	24-704-013	Repair Stakedown	26-Jan-2023 09:30:58	BSDRIL	I	DON	62.25
11-Jan-2023 05	5,074		644181	38-704	Service Drill Rig	20-Jan-2023 10:15:07	BSDRIL	P	DON	1,180.38
11-Jan-2023 05	5,074		644181	24-705	Repair Vise	20-Jan-2023 10:15:09	BSDRIL	I	DON	3,461.95
11-Jan-2023 05	5,074		644181	24-704-017	Repair Rod Loader System	20-Jan-2023 10:15:16	BSDRIL	I	DON	7,362.30
11-Jan-2023 05	5,074		644181	24-704-015	Repair Track	03-Feb-2023 11:34:06	BSDRIL	I	DON	4,301.76
11-Jan-2023 05	5,074		644181	24-704-022	Repair Rotation Thrust / Bearing Box	03-Feb-2023 11:33:50	BSDRIL	I	DON	2,666.28
11-Jan-2023 05	5,074		644181	24-702	Repair Mud Pump	20-Jan-2023 10:14:37	BSDRIL	I	DON	5,326.18
11-Jan-2023 05	5,074		644181	24-704-018	Repair Operator Console / Station	22-Feb-2023 08:27:38	BSDRIL	I	DON	1,715.42
11-Jan-2023 05	5,074		644181	24-704-011	Repair Frame / Chassis	27-Jan-2023 07:35:34	BSDRIL	I	DON	568.18
11-Jan-2023 05	5,074		644181	24-704-014	Repair Stabilizer / Outrigger	26-Jan-2023 07:57:16	BSDRIL	I	DON	173.40
11-Jan-2023 05	5,074		644181	38-704-016	Service Stem Rack	24-Feb-2023 09:26:47	BSDRIL	I	DON	721.99
17-May-2023 1			675101	02-704	Clean Drill Rig	17-May-2023 17:00:11	BWASH	N	DON	258.24
18-May-2023 1			675360	38-705	Service Vise	28-Jun-2023 08:39:27	BSDRIL	I	DON	4,144.08
18-May-2023 1			675360	06-100-PMA	Inspect A PMI	28-Jun-2023 08:39:30	BSDRIL	P	DON	0.00
18-May-2023 1			675360	38-040	Service Engine / Motor Systems Group	28-Jun-2023 08:39:32	BSDRIL	N	DON	702.25
18-May-2023 1			675360	38-704-018	Service Operator Console / Station	28-Jun-2023 08:39:35	BSDRIL	N	DON	535.25
18-May-2023 1			675360	38-704-016	Service Stem Rack	28-Jun-2023 08:39:37	BSDRIL	N	DON	2,878.36
18-May-2023 1			675360	18-704-014	Test Stabilizer / Outrigger	19-Jun-2023 08:08:07	BSDRIL	I	DON	77.32



# Unit Job History

Michels Corporation  
Report Printed: 28-Jul-2023 13:48:42 By User: RHENNING

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: Z1119 - 2016 VERMEER D40X55										
18-May-2023			675360	03-704-014	Replace Stabilizer / Outrigger	19-Jun-2023 08:08:05	BSDRIL	I	DON	1,375.96
26-Jul-2023			691580	25-053-005	Remove Markings - Vehicle - Decals	28-Jul-2023 06:58:54	BSDRIL	I	DON	311.36

Unit No: Z1119

Count: 176

194,098.41