

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: C0307 - 2005 PETERBILT 378										
18-Nov-2008	1	144,633	6188	01-023-002	Adjust Clutch Assembly	04-Dec-2008 13:56:23	BTRUCK	I	DON	25.06
18-Nov-2008	1	144,633	6188	03-002-035	Replace Windshield Wiper & Washer	04-Dec-2008 13:02:11	BTRUCK	I	DON	30.95
18-Nov-2008	1	144,633	6188	03-013-015	Replace Desiccant Cartridge Kit - Air	04-Dec-2008 12:36:02	BTRUCK	I	DON	3.33
18-Nov-2008	1	144,633	6188	03-015-002	Replace Steering Shaft Support	04-Dec-2008 15:00:00	BTRUCK	I	DON	57.63
18-Nov-2008	1	144,633	6188	03-017-001	Replace Tire - Pneumatic	28-Jan-2009 12:50:00	BTRUCK	C	DON	4,949.59
18-Nov-2008	1	144,633	6188	06-001-008	Inspect Motor - Blower	05-Dec-2008 09:00:00	BTRUCK	I	DON	50.71
18-Nov-2008	1	144,633	6188	06-100-001	Inspect DO NOT USE - PMI Service	03-Feb-2009 14:23:24	BTRUCK	P	DON	99.35
18-Nov-2008	1	144,633	6188	06-100-002	Inspect DO NOT USE - DOT Federal Insp	03-Feb-2009 14:27:23	BTRUCK	J	DON	18.99
18-Nov-2008	1	144,633	6188	14-042-009	Install Coolant Pre-Heater- Electrical	03-Feb-2009 12:45:36	BTRUCK	I	DON	137.76
18-Nov-2008	1	144,633	6188	14-079-002	Install Headache Rack	02-Feb-2009 15:00:00	BTRUCK	C	DON	3,521.22
18-Nov-2008	1	144,633	6188	21-513-004	Fabricate Specialty Attachment	27-Jan-2009 07:14:52	BWELD	C	DON	1,654.85
18-Nov-2008	1	144,633	6188	24-002	Repair Cab & Sheet Metal	28-Jan-2009 13:12:10	BTRUCK	I	DON	66.78
18-Nov-2008	1	144,633	6188	24-015	Repair Steering	03-Feb-2009 13:32:47	BTRUCK	I	DON	21.81
18-Nov-2008	1	144,633	6188	24-024-002	Repair Drive Shaft, Behind Main Transmission	04-Dec-2008 14:54:26	BTRUCK	I	DON	31.57
18-Nov-2008	1	144,633	6188	24-054-001	Repair Horn & Mounting	04-Dec-2008 14:09:54	BTRUCK	I	DON	21.14
18-Nov-2008	1	144,633	6188	25-002-003	Remove Running Boards / Step Tubes	06-Dec-2008 10:00:40	BTRUCK	I	DON	26.07
03-Aug-2009	1	153,757	18806	03-016	Replace Suspension	07-Aug-2009 16:18:13	U91011	I	DON	3,550.46
05-Aug-2009	1	153,757	19984	24-013-016	Repair Air Dryer / Purge Valve	05-Aug-2009 11:34:00	BVLOFC	F	DON	160.91
13-Aug-2009	C	153,757	20864	07-100-000	Lubricate On Road Equip / Field Service	01-Sep-2009 18:55:09	U91011	P	DON	246.51
16-Sep-2009	0	161,270	26744	24-034-001	Repair Headlamps / Fog Lamps	16-Sep-2009 09:00:00	U91012	O	DON	132.00
16-Sep-2009	0	161,270	26744	24-094-008	Repair Line - Air Supply	16-Sep-2009 09:00:00	U91012	I	DON	66.00
26-Sep-2009	0	161,270	27290	03-034-001	Replace Headlamps / Fog Lamps	26-Sep-2009 09:00:00	U91012	O	DON	66.00
30-Sep-2009	0	168,471	28438	03-042-015	Replace Fan Hub	14-Oct-2009 12:00:00	U91012	I	DON	1,438.61
30-Sep-2009	0	168,471	28438	03-042-002	Replace Radiator	14-Oct-2009 12:00:00	U91012	I	DON	66.00
30-Sep-2009	0	168,471	28438	03-044-002	Replace Filters	14-Oct-2009 12:00:00	U91012	I	DON	66.00
30-Sep-2009	0	168,471	28438	24-042-002	Repair Radiator	14-Oct-2009 12:00:00	U91012	I	DON	132.00
13-Oct-2009	0		25966	06-100-001	Inspect DO NOT USE - PMI Service	13-Oct-2009 09:00:00	U91012	P	DON	487.35
27-Nov-2009	C	168,471	28138	06-100-001	Inspect DO NOT USE - PMI Service	27-Nov-2009 09:00:00	U91012	P	DON	591.42
01-Dec-2009	0	173,564	40698	03-033-001	Replace Ignition Switch	01-Dec-2009 06:00:00	U91011	I	DON	69.45

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: C0307 - 2005 PETERBILT 378										
01-Dec-2009 0	173,564	7,550	40698	03-044-003	Replace Fuel Pump	01-Dec-2009 06:00:00	U91011	I	DON	129.83
01-Dec-2009 0	168,471	7,550	32582	24-034-006	Repair Warning Lamp	14-Dec-2009 12:00:00	U91012	I	DON	66.00
01-Dec-2009 0	168,471	7,550	32582	01-077-018	Adjust Cables - Pipe	14-Dec-2009 12:00:00	U91012	I	DON	198.00
01-Dec-2009 0	168,471	7,550	32582	03-045-027	Replace Idler Pulle	14-Dec-2009 12:00:00	U91012	I	DON	461.84
01-Dec-2009 0	168,471	7,550	32582	24-002-035	Repair Windshiel	14-Dec-2009 12:00:00	U91012	I	DON	415.09
01-Dec-2009 0	168,471	7,550	32582	03-001-008	Replace Motor	14-Dec-2009 12:00:00	U91012	I	DON	90.55
01-Dec-2009 0	168,471	7,550	32582	03-001-022	Replace Switc	14-Dec-2009 12:00:00	U91012	I	DON	0.00
01-Dec-2009 0	168,471	7,550	32582	03-002-024	Replace Glar	14-Dec-2009 12:00:00	U91012	I	DON	343.39
01-Dec-2009 0	168,471	7,550	32582	03-031-001	Replace Gr	14-Dec-2009 00:00:00	U91012	I	DON	243.34
30-Mar-2010 1	173,564	7,550	37349	03-042-016	Replace F		BTRUCK	I	CAN	0.00
30-Mar-2010 1	173,564	7,550	37349	06-100-002	Inspect	10-Apr-2010 09:33:41	BTRUCK	P	DON	246.19
30-Mar-2010 1	173,564	7,550	37349	06-100-001	Inspect	10-Apr-2010 09:33:46	BTRUCK	P	DON	363.00
30-Mar-2010 1	173,564	7,550	37349	12-018-003	Refu		BDETL	Q	CAN	0.00
30-Mar-2010 1	173,564	7,550	37349	15-018-003	Pai		BDETL	Q	CAN	0.00
30-Mar-2010 1	173,564	7,550	37349	02-002-044	C		BDETL	Q	CAN	0.00
30-Mar-2010 1	173,564	7,550	37349	24-013-009	Compressor	10-Apr-2010 09:41:29	BTRUCK	I	DON	49.00
30-Mar-2010 1	173,564	7,550	37349	03-014-003	Air Mountings	10-Apr-2010 09:39:43	BTRUCK	I	DON	619.03
30-Mar-2010 1	173,564	7,550	37349	03-015	Strapping	10-Apr-2010 09:38:21	BTRUCK	I	DON	83.52
30-Mar-2010 1	173,564	7,550	37349	24-042-012	Comps and Hoses	10-Apr-2010 09:44:39	BTRUCK	I	DON	58.27
30-Mar-2010 1	173,564	7,550	37349	24-045-01	Locker Box	10-Apr-2010 09:43:04	BTRUCK	I	DON	825.55
30-Mar-2010 1	173,564	7,550	37349	24-015-1	Lower Steering Pump	10-Apr-2010 09:35:57	BTRUCK	I	DON	60.80
30-Mar-2010 1	173,564	7,550	37349	03-016	Chassis Spring - Front	10-Apr-2010 09:34:34	BTRUCK	I	DON	206.48
30-Mar-2010 1	173,564	7,550	37349	03-017	Ice Battery	10-Apr-2010 09:51:50	BTRUCK	I	DON	256.34
30-Mar-2010 1	173,564	7,550	37349	24-016	Air Crosswalk (Deckplate) - Frame	10-Apr-2010 09:49:04	BTRUCK	I	DON	29.40
30-Mar-2010 1	173,564	7,550	37349	01-017	Lean Battery Cables and Ends		BTRUCK	I	CAN	0.00
30-Mar-2010 1	173,564	7,550	37349	01-018	Replace Filter - Cab Ventilation	12-Apr-2010 05:51:20	BTRUCK	I	DON	32.75
30-Mar-2010 1	173,564	7,550	37349	01-019	Repair Bumpers & Attaching Parts	12-Apr-2010 05:53:16	BTRUCK	I	DON	29.40
30-Mar-2010 1	173,564	7,550	37349	01-020	Repair Steering Linkage	12-Apr-2010 05:55:24	BTRUCK	I	DON	31.78
30-Mar-2010 1	173,564	7,550	37349	01-021	Repair Cover Assembly	12-Apr-2010 06:35:00	BTRUCK	I	DON	326.38

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: C0307 - 2005 PETERBILT 378										
30-Mar-2010	1	173,564	37349	24-013-017	Repair Slack Adjuster	12-Apr-2010 06:32:38	BTRUCK	I	DON	49.00
30-Mar-2010	1	173,564	37349	24-013-022	Repair Glad Hands (Service/Emergency)	12-Apr-2010 06:42:16	BTRUCK	I	DON	76.92
30-Mar-2010	1	173,564	37349	03-016-006	Replace Shock Absorber - Rear	12-Apr-2010 06:36:55	BTRUCK	I	DON	160.10
30-Mar-2010	1	173,564	37349	01-023-001	Adjust Linkage - Mechanical Clutch	12-Apr-2010 06:39:12	BTRUCK	I	DON	60.80
30-Mar-2010	1	173,564	37349	03-013-002	Replace Rear Brakes & Drums	12-Apr-2010 06:30:55	BTRUCK	I	DON	245.00
30-Mar-2010	1	173,564	37349	03-013-022	Replace Glad Hands (Service/Emergency)	12-Apr-2010 06:47:35	BTRUCK	I	DON	18.03
30-Mar-2010	1	173,564	37349	03-041-007	Replace Filter - Outer	12-Apr-2010 06:01:14	BTRUCK	I	DON	70.19
30-Mar-2010	1	173,564	37349	14-078-009	Install Mud Flaps and Hanger Brackets	12-Apr-2010 06:49:14	BTRUCK	I	DON	119.36
30-Mar-2010	1	173,564	37349	18-042	Test Cooling System	12-Apr-2010 06:05:13	BTRUCK	I	DON	14.52
30-Mar-2010	1	173,564	37349	03-015-004	Replace Steering Linkage	12-Apr-2010 06:09:47	BTRUCK	I	DON	157.45
30-Mar-2010	1	173,564	37349	24-034-008	Repair Trailer Light Cord	12-Apr-2010 06:03:03	BTRUCK	I	DON	29.40
30-Mar-2010	1	173,564	37349	03-013-001	Replace Front Brakes & Drums	12-Apr-2010 06:07:42	BTRUCK	I	DON	388.76
30-Mar-2010	1	173,564	37349	24-003-001	Repair Gauges & Warning Devices	12-Apr-2010 06:45:14	BTRUCK	I	DON	35.26
12-Apr-2010	1	173,564	38240	02-002-044	Clean Cab - Complete	12-Apr-2010 15:00:00	BDETL	Q	DON	55.21
15-Apr-2010	0	173,564	38609	03-034-003	Replace Signal, Parking, Backup Lamps	15-Apr-2010 10:29:39	BTRUCK	I	DON	5.61
15-Apr-2010	0	173,564	38609	06-001-001	Inspect Air Conditioning Assembly	26-Apr-2010 16:09:49	BTRUCK	I	DON	89.58
15-Apr-2010	0	173,564	38609	24-002-035	Repair Windshield Wiper & Washer	15-Apr-2010 10:46:30	BTRUCK	I	DON	11.17
15-Apr-2010	0	173,564	38609	06-100-001	Inspect DO NOT USE - PMI Service		BTRUCK	P	CAN	0.00
15-Apr-2010	0	173,564	38609	06-100-002	Inspect DO NOT USE - DOT Federal Insp		BTRUCK	P	CAN	0.00
15-Apr-2010	0	173,564	38609	06-100-009	Inspect Safety Check	26-Apr-2010 16:09:55	BTRUCK	P	DON	16.78
15-Apr-2010	0	173,564	38609	24-014-005	Repair Battery Support / Battery Box	26-Apr-2010 09:00:00	BTRUCK	I	DON	89.09
15-Apr-2010	0	173,564	38609	31-017-001	Rotate Tire - Pneumatic	16-Apr-2010 14:49:02	BTRUCK	I	DON	62.98
15-Apr-2010	0	173,564	38609	03-017-001	Replace Tire - Pneumatic	19-Apr-2010 06:32:51	BTRUCK	I	DON	4,022.34
21-Apr-2010	0	173,564	42239	03-001-016	Replace Filter - Cab Ventilation	31-May-2010 09:34:13	RB1003	I	DON	68.79
21-Apr-2010	0	173,564	42239	03-016	Replace Suspension	31-May-2010 09:34:13	RB1003	I	DON	717.82
21-Apr-2010	0	173,564	42239	03-034-019	Replace Switch (Other)	31-May-2010 09:34:13	U91012	I	DON	0.00
21-Apr-2010	0	173,564	42239	03-065-007	Replace Hoses & Fittings	31-May-2010 09:34:13	RB1003	I	DON	139.72
01-Jun-2010	0	196,9	45117	03-031-001	Replace Generator/Alternator	01-Nov-2010 11:14:22	U91012	O	DON	528.38
01-Jun-2010	0	196,9	45117	03-034-019	Replace Switch (Other)	01-Nov-2010 11:14:22	U91012	I	DON	0.00

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: C0307 - 2005 PETERBILT.378										
01-Jun-2010 0	196,906		45117	03-045-023	Replace Engine Belts	01-Nov-2010 11:14:22	U91012	I	DON	172.80
01-Jun-2010 0	196,906		45117	03-049-002	Replace ECM Module	01-Nov-2010 11:14:22	U91012	I	DON	4,104.93
01-Jun-2010 0	196,906		45117	06-100	Inspect PMI	01-Nov-2010 11:14:22	U91012	J	DON	414.91
29-Jul-2010 11	192,800		49585	03-017-001	Replace Tire - Pneumatic	29-Jul-2010 11:12:59	U91012	E	DON	838.03
01-Jan-2011 0	196,906		60164	06-100	Inspect PMI	14-Jun-2011 07:05:15	RB1101	J	DON	216.00
01-Feb-2011 0	196,906		62308	03-052-003	Replace Radio Equipment	16-Jan-2012 13:26:34	U91010	O	DON	193.82
01-Feb-2011 0	207,541		62616	06-100-001	Inspect DO NOT USE - PMI Service	28-Jul-2011 16:45:23	U91012	J	DON	199.11
01-Feb-2011 0	207,541		62616	24-003-015	Repair Oil Temperature Gauge	28-Jul-2011 16:45:23	U91012	I	DON	62.85
01-Feb-2011 0	207,541		62616	03-017-001	Replace Tire - Pneumatic	28-Jul-2011 16:45:23	U91012	E	DON	1,458.29
01-Feb-2011 0	200,631		65489	06-100-002	Inspect DO NOT USE - DOT Federal Insp	08-Jul-2011 12:00:00	RB1102	J	DON	27.98
01-Feb-2011 0	200,631		65489	06-100-001	Inspect DO NOT USE - PMI Service	08-Jul-2011 12:00:00	RB1102	J	DON	226.86
02-Mar-2011 0	207,541		70609	24-002-024	Repair Glass / Windshield	02-Mar-2011 09:34:26	BVLOFC	F	DON	414.20
01-Jun-2011 0	211,996		71469	02-002	Clean Cab & Sheet Metal	09-Mar-2012 12:30:50	RB1105	I	DON	216.00
01-Jun-2011 0	211,996		71469	03-001-008	Replace Motor - Blower	09-Mar-2012 12:30:50	RB1105	I	DON	151.18
01-Jun-2011 0	211,996		71469	06-100-001	Inspect DO NOT USE - PMI Service	09-Mar-2012 12:30:50	RB1105	Q	DON	427.54
27-Jul-2011 12	207,541		70010	24-001-001	Repair Air Conditioning Assembly	01-Aug-2011 12:34:03	MPNSHP	B	DON	302.53
01-Aug-2011 0	223,305		76502	06-100-001	Inspect DO NOT USE - PMI Service	14-Feb-2013 12:26:08	U91012	J	DON	398.86
01-Aug-2011 0	223,305		76502	03-001-002	Replace Heating & Ventilating	14-Feb-2013 12:26:08	U91012	F	DON	47.22
01-Aug-2011 0	223,305		76502	24-032-002	Repair Starter	14-Feb-2013 12:26:08	U91012	F	DON	254.40
01-Aug-2011 0	223,305		76502	24-017-001	Repair Tire - Pneumatic	14-Feb-2013 12:26:08	U91012	F	DON	500.24
01-Aug-2011 0	223,305		76502	03-013-001	Replace Front Brakes & Drums	14-Feb-2013 12:26:08	U91012	I	DON	314.04
28-Feb-2012 1	218,662		93953	06-100-DOT	Inspect DOT Federal Inspection	28-Feb-2012 10:01:52	BVLOFC	P	DON	0.00
03-Apr-2012 0	217,780		85008	02-002-044	Clean Cab - Complete	16-Apr-2012 12:54:10	BDETL	J	DON	3.58
30-Nov-2012 C	218,999		110402	24-017-001	Repair Tire - Pneumatic	30-Nov-2012 08:59:44	U91012	F	DON	211.36
30-Nov-2012 C	218,999		110402	06-100-002	Inspect DO NOT USE - DOT Federal Insp	07-Mar-2013 09:04:44	U91012	P	DON	474.00
11-Feb-2013 1	218,999		107471	14-052-003	Install Radio Equipment	11-Feb-2013 14:43:56	BBODY	C	DON	0.00
07-Mar-2013 0	218,999		113611	06-100-DOT	Inspect DOT Federal Inspection	07-Mar-2013 09:06:08	BVLOFC	P	DON	0.00
01-Apr-2013 0	218,999		113879	03-042-002	Replace Radiator	11-May-2013 06:15:10	U91012	B	DON	3,913.00
01-Apr-2013 0	241,416		116563	03-017-001	Replace Tire - Pneumatic	19-Jul-2013 04:17:39	U31010	J	DON	916.84

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: C0307 - 2005 PETERBILT 378										
01-Apr-2013 0	241,416		16563	03-065-007	Replace Hoses & Fittings	19-Jul-2013 04:17:39	U31010	F	DON	135.14
01-Apr-2013 0	241,416		116563	06-100-007	Inspect In-Service Inspection	19-Jul-2013 04:17:39	U31010	J	DON	191.78
01-Jun-2013 0	241,416		136834	03-042-016	Replace Fan Clutch	13-Nov-2013 07:25:38	BTRUCK	F	DON	0.00
01-Jun-2013 0	241,416		136837	24-001-010	Repair Compressor Assembly - Air Cond	13-Nov-2013 07:29:18	U31010	F	DON	92.79
01-Jul-2013 06	234,204		125642	03-013-017	Replace Slack Adjuster	26-Sep-2013 19:35:01	U31010	I	DON	144.18
01-Jul-2013 06	234,204		125642	03-017-001	Replace Tire - Pneumatic	26-Sep-2013 19:35:01	U31010	J	DON	916.90
01-Jul-2013 06	234,204		125642	03-031-006	Replace Belt - Alternator	26-Sep-2013 19:35:01	U31010	F	DON	0.00
01-Oct-2013 0	241,416		135660	03-051	Replace General Accessories	01-Nov-2013 12:15:57	21199	F	DON	162.56
22-Jun-2014 0	250,505		163365	03-063-003	Replace Transceiver - GPS Tracker	22-Jun-2014 00:00:00	BTRUCK	C	DON	233.12
25-Jul-2014 06	251,831		184120	14-034-011	Install Plug - Trailer Light Cord	25-Jul-2014 17:00:00	WASHPA	F	DON	15.47
25-Jul-2014 06	251,831		184120	19-079-002	Wire/Rewire Headache Rack	25-Jul-2014 17:00:00	WASHPA	F	DON	30.93
06-Aug-2014 0	251,831		184119	03-044-002	Replace Filters	06-Aug-2014 17:00:00	WASHPA	P	DON	27.74
14-Aug-2014 0	250,505		178126	03-017-001	Replace Tire - Pneumatic	14-Aug-2014 07:25:00	BTIRE	N	DON	6,450.63
12-Nov-2014 0	257,273		188648	03-041-004	Replace Aftercooler / Intercooler		BTRUCK	I	CAN	0.00
12-Nov-2014 0	257,273		188648	06-100-PMA	Inspect A PMI		BTRUCK	P	CAN	0.00
02-Dec-2014 1	257,273		188417	03-041-004	Replace Aftercooler / Intercooler	02-Dec-2014 16:19:34	BTRUCK	I	DON	1,447.01
02-Dec-2014 1	257,273		188417	06-100-PMA	Inspect A PMI	02-Dec-2014 16:20:25	BTRUCK	P	DON	337.50
02-Dec-2014 1	257,273		188417	03-042-002	Replace Radiator	02-Dec-2014 16:19:50	BTRUCK	I	DON	1,481.86
02-Dec-2014 1	257,273		188417	37-049-002	Calibrate ECM Module	02-Dec-2014 16:20:08	BTRUCK	I	DON	434.39
13-Feb-2015 1	257,273		203273	06-100-PMA	Inspect A PMI	13-Feb-2015 15:05:12	BTRUCK	P	DON	1,131.54
13-Feb-2015 1	257,273		203273	03-042-012	Replace Clamps and Hoses	08-Jun-2015 10:06:54	BVLOFC	I	DON	37.78
13-Feb-2015 1	257,273		203273	24-034-014	Repair Auxiliary Work / Flood Light	08-Jun-2015 10:23:43	BVLOFC	I	DON	139.70
20-Jun-2015 0	258,070		211126	14-014	Install Frame	20-Jun-2015 09:23:57	WASHPA	M	DON	73.65
24-Jul-2015 00	269,823		234306	03-044-024	Replace Fuel / Water Separator	24-Jul-2015 00:00:00	WSHSHIP	B	DON	82.06
05-Aug-2015 1	261,112		227519	06-100-PMA	Inspect A PMI	05-Aug-2015 13:13:40	WASHPA	P	DON	147.30
05-Aug-2015 1	261,112		227519	03-044-002	Replace Filters	05-Aug-2015 13:16:13	WASHPA	F	DON	18.41
10-Sep-2015 0	269,823		234320	06-013-016	Inspect Air Dryer / Purge Valve	10-Sep-2015 00:00:00	WSHSHIP	B	DON	41.03
23-Sep-2015 0	269,823		234310	03-013-016	Replace Air Dryer / Purge Valve	23-Sep-2015 00:00:00	WSHSHIP	B	DON	82.06
07-Oct-2015 0	269,823		234314	01-023-001	Adjust Linkage - Mechanical Clutch	07-Oct-2015 00:00:00	WSHSHIP	J	DON	82.06

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: C0307 - 2005 PETERBILT 378										
04-Nov-2015	1	269,823	226585	03-037-021	Replace Circuit Breaker/Fuse - Multiple Use	04-Nov-2015 15:05:49	WASHPA	O	DON	726.59
26-Feb-2016	0	270,647	235286	24-002-004	Repair Hood	03-Mar-2016 10:46:05	WSHSHP	I	DON	166.85
26-Feb-2016	0	270,647	235286	03-014-006	Replace Fuel Tank Support	03-Mar-2016 10:46:05	WSHSHP	I	DON	720.97
26-Feb-2016	0	270,647	235286	06-100-PMB	Inspect B PMI	03-Mar-2016 10:46:05	WSHSHP	P	DON	2,037.44
26-Feb-2016	0	270,647	235286	24-031-001	Repair Generator/Alternator	03-Mar-2016 10:46:05	WSHSHP	I	DON	120.06
26-Feb-2016	0	270,647	235286	24-042-002	Repair Radiator	03-Mar-2016 10:46:05	WSHSHP	I	DON	1,704.37
26-Feb-2016	0	270,647	235286	24-045-008	Repair Camshaft - Accessory Drive & Valve Me	03-Mar-2016 10:46:05	WSHSHP	I	DON	701.30
26-Feb-2016	0	270,647	235286	24-054-001	Repair Horn & Mounting	03-Mar-2016 10:46:05	WSHSHP	I	DON	145.74
26-Feb-2016	0	270,647	235286	01-002-064	Adjust Washer Fluid Reservoir	03-Mar-2016 10:46:05	WSHSHP	I	DON	3.50
26-Feb-2016	0	270,647	235286	03-015-002	Replace Steering Shaft Support	03-Mar-2016 10:46:05	WSHSHP	I	DON	743.74
26-Feb-2016	0	270,647	235286	03-044-018	Replace Fuel Hose / Line	03-Mar-2016 10:46:05	WSHSHP	I	DON	114.03
26-Feb-2016	0	270,647	235286	24-013-024	Repair Air Tank (Pri / Sec / Wet)	03-Mar-2016 10:46:05	WSHSHP	I	DON	187.81
26-Feb-2016	0	270,647	235286	24-015-005	Repair Power Steering Pump	03-Mar-2016 10:46:05	WSHSHP	I	DON	221.59
26-Feb-2016	0	270,647	235286	38-003-015	Service Oil Temperature Gauge	03-Mar-2016 10:46:05	WSHSHP	I	DON	420.13
26-Feb-2016	0	270,647	235286	03-072-011	Replace Door Seal	03-Mar-2016 10:46:05	WSHSHP	I	DON	217.55
26-Feb-2016	0	270,647	235286	03-034-020	Replace Dome / Reading Light	03-Mar-2016 10:46:05	WSHSHP	I	DON	158.84
26-Feb-2016	0	270,647	235286	03-042-017	Replace Fan Shroud	03-Mar-2016 10:46:05	WSHSHP	I	DON	1,109.54
26-Feb-2016	0	270,647	235286	03-519-001	Replace Front Bumper	03-Mar-2016 10:46:05	WSHSHP	I	DON	3,452.10
26-Feb-2016	0	270,647	235286	24-013-007	Repair Brake Lines & Fittings - Hydraulic & Ai	03-Mar-2016 10:46:05	WSHSHP	I	DON	77.16
26-Feb-2016	0	270,647	235286	03-078-009	Replace Mud Flaps and Hanger Brackets	03-Mar-2016 10:46:05	WSHSHP	I	DON	629.66
26-Feb-2016	0	270,647	235286	03-018-012	Replace Cap - Hub	03-Mar-2016 10:46:05	WSHSHP	I	DON	832.81
26-Feb-2016	0	270,647	235286	03-001-026	Replace Belt - A/C Compressor	03-Mar-2016 10:46:05	WSHSHP	I	DON	413.48
26-Feb-2016	0	270,647	235286	24-059-001	Repair Fifth Wheel - Lower Coupler Assembly	03-Mar-2016 10:46:05	WSHSHP	I	DON	374.77
26-Feb-2016	0	270,647	235286	03-002-057	Replace Occupant Safety Devices	03-Mar-2016 10:46:05	WSHSHP	I	DON	769.93
26-Feb-2016	0	270,647	235286	03-001-017	Replace A/C Hose / Line	03-Mar-2016 10:46:05	WSHSHP	I	DON	315.35
26-Feb-2016	0	270,647	235286	03-016-012	Replace Torque Rod	03-Mar-2016 10:46:05	WSHSHP	I	DON	2,268.62
26-Feb-2016	0	270,647	235286	03-013-003	Replace Brake Chamber - Parking	03-Mar-2016 10:46:05	WSHSHP	I	DON	1,084.62
26-Feb-2016	0	270,647	235286	24-013-018	Repair S-Cam	03-Mar-2016 10:46:05	WSHSHP	I	DON	3,812.12
26-Feb-2016	0	270,647	235286	24-001-006	Repair Dryer Assembly	03-Mar-2016 10:46:05	WSHSHP	I	DON	449.91

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: C0307 - 2005 PETERBILT 378										
26-Feb-2016 0	270,64		235286	24-043-007	Repair Exhaust Pipe/Elbow	03-Mar-2016 10:46:05	WSSHHP	I	DON	86.37
26-Feb-2016 0	270,64		235286	38-032-001	Service Battery	03-Mar-2016 10:46:05	WSSHHP	I	DON	32.07
26-Feb-2016 0	270,64		235286	24-053-015	Repair Tool Box	03-Mar-2016 10:46:05	WSSHHP	I	DON	394.01
26-Feb-2016 0	270,64		235286	24-003-001	Repair Gauges & Warning Devices	03-Mar-2016 10:46:05	WSSHHP	I	DON	209.17
26-Feb-2016 0	270,64		235286	06-100-DOT	Inspect DOT Federal Inspection	03-Mar-2016 10:46:05	BVLOFC	P	DON	381.42
10-Mar-2016 1	271,417		236851	08-045	Overhaul Power Plant	29-Mar-2016 13:16:12	BTRUCK	I	DON	29,120.26
10-Mar-2016 1	271,417		236851	14-034-006	Install Warning Lamps - Special Application	29-Mar-2016 13:16:12	BTRUCK	I	DON	945.53
31-Mar-2016 0	277,532		250712	24-016	Repair Suspension	31-Mar-2016 07:00:00	WSSHHP	M	DON	41.14
31-Mar-2016 0	277,532		250712	26-016	Weld Suspension	31-Mar-2016 07:00:00	WSSHHP	D	DON	41.14
31-Mar-2016 0	277,532		250712	03-042-012	Replace Clamps and Hoses	15-Jun-2016 07:00:00	WSSHHP	F	DON	41.14
31-Mar-2016 0	277,532		250712	03-045-026	Replace Tensioner - Engine Belts	15-Jun-2016 07:00:00	WSSHHP	F	DON	82.27
18-Oct-2016 0	277,532		265155	03-017-001	Replace Tire - Pneumatic	18-Oct-2016 08:07:14	BTIRE	F	DON	1,977.50
25-Jan-2017 1	295,284		274807	06-100-DOT	Inspect DOT Federal Inspection	27-Jan-2017 14:35:03	BTRUCK	P	DON	342.14
25-Jan-2017 1	295,284		274807	06-100-PMB	Inspect B PMI	27-Jan-2017 14:35:03	BTRUCK	P	DON	761.55
25-Jan-2017 1	295,284		274807	03-518-001	Replace Steps	27-Jan-2017 14:35:03	BTRUCK	I	DON	648.90
25-Jan-2017 1	295,284		274807	03-078-009	Replace Mud Flaps and Hanger Brackets	27-Jan-2017 14:35:03	BTRUCK	I	DON	323.08
25-Jan-2017 1	295,284		274807	03-014-004	Replace Cab & Body Mountings	27-Jan-2017 14:35:03	BTRUCK	I	DON	468.05
25-Jan-2017 1	295,284		274807	03-016-003	Replace Shock Absorber - Front	27-Jan-2017 14:35:03	BTRUCK	I	DON	236.45
25-Jan-2017 1	295,284		274807	03-032-001	Replace Battery	27-Jan-2017 14:35:03	BTRUCK	I	DON	419.86
25-Jan-2017 1	295,284		274807	03-034-004	Replace Clearance & Marker Lamps	27-Jan-2017 14:35:03	BTRUCK	I	DON	400.00
25-Jan-2017 1	295,284		274807	03-015-004	Replace Steering Linkage	27-Jan-2017 14:35:03	BTRUCK	I	DON	702.21
25-Jan-2017 1	295,284		274807	03-043-007	Replace Exhaust Pipe/Elbow	27-Jan-2017 14:35:03	BTRUCK	I	DON	2,823.09
25-Jan-2017 1	295,284		274807	03-049-004	Replace ECM Sensor	27-Jan-2017 14:35:03	BTRUCK	I	DON	522.32
25-Jan-2017 1	295,284		274807	03-041-001	Replace Air Cleaner	27-Jan-2017 14:35:03	BTRUCK	I	DON	104.58
25-Jan-2017 1	295,284		274807	03-016-012	Replace Torque Rod	27-Jan-2017 14:35:03	BTRUCK	I	DON	615.27
25-Jan-2017 1	295,284		274807	02-002	Clean Cab & Sheet Metal	27-Jan-2017 14:35:03	BTRUCK	I	DON	80.84
25-Jan-2017 1	295,284		274807	03-001-016	Replace Filter - Cab Ventilation	27-Jan-2017 14:35:03	BTRUCK	I	DON	65.35
25-Jan-2017 1	295,284		274807	03-013-017	Replace Slack Adjuster	27-Jan-2017 14:35:03	BTRUCK	I	DON	1,587.38
25-Jan-2017 1	295,284		274807	03-013-022	Replace Glad Hands (Service/Emergency)	27-Jan-2017 14:35:03	BTRUCK	I	DON	79.77

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: C0307 - 2005 PETERBILT 378										
25-Jan-2017 1:	295,284		74807	03-096-004	Replace Yoke	27-Jan-2017 14:35:03	BTRUCK	I	DON	4,204.33
25-Jan-2017 1:	295,284		74807	10-059-001	Rebush Fifth Wheel - Lower Coupler Assembly	27-Jan-2017 14:35:03	BTRUCK	I	DON	301.78
25-Jan-2017 1:	295,284		74807	34-045-013	Reseal Oil Pan	27-Jan-2017 14:35:03	BTRUCK	I	DON	289.50
25-Jan-2017 1:	295,284		74807	34-015-003	Reseal Steering Gear	27-Jan-2017 14:35:03	BTRUCK	I	DON	287.05
25-Jan-2017 1:	295,284		74807	24-013-017	Repair Slack Adjuster	27-Jan-2017 14:35:03	BTRUCK	I	DON	1,006.12
25-Jan-2017 1:	295,284		74807	24-094-008	Repair Line - Air Supply	27-Jan-2017 14:35:03	BTRUCK	I	DON	206.12
25-Jan-2017 1:	295,284		74807	09-016-050	Align Alignment All Wheel	27-Jan-2017 14:35:03	BTRUCK	I	DON	264.28
25-Jan-2017 1:	295,284		74807	03-013-023	Replace Air Governor	27-Jan-2017 14:35:03	BTRUCK	I	DON	369.83
25-Jan-2017 1:	295,284		74807	03-002-018	Replace Cab Or Front Door Mechanism	27-Jan-2017 14:35:03	BTRUCK	I	DON	2,349.99
25-Jan-2017 1:	295,284		74807	03-016-010	Replace Air Spring	27-Jan-2017 14:35:03	BTRUCK	I	DON	634.10
23-Feb-2017 1:	295,284		278442	03-052-003	Replace Radio Equipment	28-Feb-2017 10:47:28	GPSINS	I	DON	642.92
06-Jun-2017 2:	295,284		292408	06-100-DOT	Inspect DOT Federal Inspection	12-Jun-2017 13:23:22	BVLOFC	P	DON	0.00
06-Jun-2017 2:	295,284		292408	24-034-002	Repair Stop, Tail, Turn & License	12-Jun-2017 13:23:22	WSHSP	J	DON	115.60
22-Feb-2018 1:	303,296		324719	03-013-002	Replace Rear Brakes & Drums	09-Mar-2018 12:24:14	70955W	B	DON	485.68
22-Feb-2018 1:	303,296		324719	03-037-021	Replace Circuit Breaker/Fuse - Multiple Use	09-Mar-2018 12:24:11	70955W	B	DON	107.26
22-Feb-2018 1:	303,296		324719	03-094-008	Replace Line - Air Supply	09-Mar-2018 12:24:17	70955W	B	DON	21.42
22-Feb-2018 1:	303,296		324719	06-100-DOT	Inspect DOT Federal Inspection	09-Mar-2018 12:24:05	70955W	P	DON	98.55
22-Feb-2018 1:	303,296		324719	06-100-PMA	Inspect A PMI	09-Mar-2018 12:24:08	70955W	P	DON	452.24
02-Apr-2018 1:	305,759		329525	03-013-016	Replace Air Dryer / Purge Valve	02-Apr-2018 10:11:15	BVLOFC	O	DON	1,166.69
02-Apr-2018 1:	305,759		329525	03-034-001	Replace Headlamps / Fog Lamps	02-Apr-2018 10:18:48	BVLOFC	O	DON	67.48
02-Apr-2018 1:	305,759		329525	07-010	Lubricate Chassis Group	02-Apr-2018 10:20:03	BVLOFC	P	DON	61.44
07-Apr-2018 1:	305,759		330497	03-013-023	Replace Air Governor	12-Apr-2018 16:05:16	70955W	B	DON	9.45
07-Apr-2018 1:	305,759		330497	03-002-004	Replace Hood	22-Jun-2018 17:30:54	70955W	B	DON	29.82
27-Jul-2018 12:	305,759		345704	03-032-002	Replace Starter	27-Jul-2018 12:36:51	70955W	B	DON	335.66
02-Aug-2018 1:	305,759		346526	03-016-011	Replace Leveling Valve	02-Aug-2018 14:45:55	70955W	B	DON	31.94
02-Aug-2018 1:	314,428		348792	06-100-PMA	Inspect A PMI	17-Aug-2018 15:15:18	70955W	P	DON	38.15
01-Oct-2018 0:	314,428		357335	03-003-002	Replace Speedometer	19-Oct-2018 08:51:10	70955W	B	DON	345.25
24-Oct-2018 1:	314,428		358004	03-017-001	Replace Tire - Pneumatic	24-Oct-2018 11:48:42	BTIRE	P	DON	4,721.58
15-Nov-2018 1:	314,428		360734	24-003-002	Repair Speedometer	15-Nov-2018 06:02:20	BVLOFC	O	DON	0.00

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: C0307 - 2005 PETERBILT 378										
15-Nov-2018 C	314,428		60734	24-034-003	Repair Signal, Parking, Backup Lamps	15-Nov-2018 06:01:43	BVLOFC	O	DON	411.81
15-Nov-2018 C	314,428		60734	35-049-001	Diagnose ECM Fault Code	15-Nov-2018 06:06:17	BVLOFC	I	DON	122.90
25-Jan-2019 05	321,923		69853	03-002-026	Replace Weather Stripping, Gaskets & Bumpers	25-Jan-2019 14:12:17	WSHSHP	I	DON	116.20
25-Jan-2019 05	321,923		69853	03-013	Replace Brakes	25-Jan-2019 14:12:17	WSHSHP	E	DON	1,366.77
25-Jan-2019 05	321,923		69853	06-100-DOT	Inspect DOT Federal Inspection	25-Jan-2019 14:12:17	WSHSHP	P	DON	348.60
25-Jan-2019 05	321,923		69853	24-001	Repair Air Conditioning, Heating & Ventilating	25-Jan-2019 14:12:17	WSHSHP	E	DON	1,067.78
25-Jan-2019 05	321,923		69853	24-002-035	Repair Windshield Wiper & Washer	25-Jan-2019 14:12:17	WSHSHP	E	DON	145.25
25-Jan-2019 05	321,923		69853	24-014	Repair Frame	25-Jan-2019 14:12:17	WSHSHP	E	DON	1,742.99
25-Jan-2019 05	321,923		69853	03-518-001	Replace Steps	25-Jan-2019 14:12:17	WSHSHP	E	DON	3,268.99
25-Jan-2019 05	321,923		69853	03-042-003	Replace Fan	25-Jan-2019 14:12:17	WSHSHP	E	DON	809.04
25-Jan-2019 05	321,923		69853	24-043	Repair Exhaust System	25-Jan-2019 14:12:17	WSHSHP	I	DON	236.82
25-Jan-2019 05	321,923		69853	03-013-007	Replace Brake Lines & Fittings - Hydraulic & A	25-Jan-2019 14:12:17	WSHSHP	I	DON	174.30
25-Jan-2019 05	321,923		69853	24-078-009	Repair Mud Flaps and Hanger Brackets	25-Jan-2019 14:12:17	WSHSHP	E	DON	301.11
25-Jan-2019 05	321,923		69853	03-015-003	Replace Steering Gear	25-Jan-2019 14:12:17	WSHSHP	I	DON	1,404.61
25-Jan-2019 05	321,923		69853	03-016-003	Replace Shock Absorber - Front	25-Jan-2019 14:12:17	WSHSHP	I	DON	236.40
25-Jan-2019 05	321,923		69853	03-032-004	Replace Battery Cables and Ends	25-Jan-2019 14:12:17	WSHSHP	I	DON	234.05
25-Jan-2019 05	321,923		69853	24-045	Repair Power Plant	25-Jan-2019 14:12:17	WSHSHP	I	DON	1,699.46
25-Jan-2019 05	321,923		69853	24-052	Repair Electrical Accessories	25-Jan-2019 14:12:17	WSHSHP	O	DON	188.82
25-Jan-2019 05	321,923		69853	03-015-004	Replace Steering Linkage	25-Jan-2019 14:12:17	WSHSHP	E	DON	862.33
04-Feb-2019 1	321,923		371023	24-013-007	Repair Brake Lines & Fittings - Hydraulic & Air	04-Feb-2019 14:52:13	WSHSHP	I	DON	497.59
11-Feb-2019 1	321,923		372006	24-519-003	Repair Hitch Assembly	18-Mar-2019 11:34:15	WSHSHP	O	DON	1,012.48
22-Mar-2019 1	321,923		377771	03-002-069	Replace Support Hood Lift-Gas Charged	25-Mar-2019 13:29:56	PIPE03	B	DON	23.70
22-Mar-2019 1	321,923		177771	24-013-007	Repair Brake Lines & Fittings - Hydraulic & Air	25-Mar-2019 13:29:56	PIPE03	B	DON	84.10
12-Apr-2019 1	321,923		181036	24-059-001	Repair Fifth Wheel - Lower Coupler Assembly	17-Oct-2019 17:18:40	PIPE03	B	DON	87.85
12-Apr-2019 1	321,923		181036	03-002-037	Replace Seat Assembly	17-Oct-2019 17:18:40	PIPE03	B	DON	681.99
12-Apr-2019 1	321,923		181036	24-014-005	Repair Battery Support / Battery Box	17-Oct-2019 17:18:40	PIPE03	B	DON	798.93
12-Apr-2019 1	321,923		181036	03-001-010	Replace Compressor Assembly - Air Cond	17-Oct-2019 17:18:40	PIPE03	B	DON	540.49
18-Jul-2019 12	326,620		112317	06-100-PMA	Inspect A PMI	18-Jul-2019 23:00:00	PIPE03	P	DON	87.71
18-Sep-2019 0	331,969		103420	03-002-037	Replace Seat Assembly	18-Sep-2019 08:56:16	WSHSHP	I	DON	974.35

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: C0307 - 2005 PETERBILT 378										
18-Sep-2019 0	331,969	7,470	403420	24-016-024	Repair Leaf Spring	18-Sep-2019 08:56:16	WSHSHP	I	DON	4,766.60
18-Sep-2019 0	331,969	7,470	403420	24-001-001	Repair Air Conditioning Assembly	18-Sep-2019 08:56:16	WSHSHP	O	DON	5,422.49
18-Sep-2019 0	331,969	7,470	403420	24-014	Repair Frame	18-Sep-2019 08:56:16	WSHSHP	O	DON	7,229.81
18-Sep-2019 0	331,969	7,470	403420	24-022	Repair Axles - Driven, Rear	18-Sep-2019 08:56:16	WSHSHP	I	DON	1,446.71
18-Sep-2019 0	331,969	7,470	403420	24-059	Repair Vehicle Coupling System	18-Sep-2019 08:56:16	WSHSHP	I	DON	93.42
18-Sep-2019 0	331,969	7,470	403420	03-016-012	Replace Torque Rod	18-Sep-2019 08:56:16	WSHSHP	I	DON	529.44
18-Sep-2019 0	331,969	7,470	403420	06-100-DOT	Inspect DOT Federal Inspection	18-Sep-2019 08:56:16	WSHSHP	P	DON	75.98
18-Sep-2019 0	331,969	7,470	403420	03-018-011	Replace Seal - Wheel	18-Sep-2019 08:56:16	WSHSHP	I	DON	491.63
18-Sep-2019 0	331,969	7,470	403420	03-034-006	Replace Warning Lamps - Special Application	18-Sep-2019 08:56:16	WSHSHP	I	DON	105.58
16-Nov-2019 1	333,286	7,539	415659	24-519-001	Repair Front Bumper	16-Nov-2019 23:00:00	PIPE03	B	DON	681.67
11-Dec-2019 1	333,287	7,552	416466	24-043	Repair Exhaust System	13-Dec-2019 08:09:09	WSHSHP	I	DON	161.99
11-Dec-2019 1	333,287	7,552	416466	38-100-PMB	Service B PMI	13-Dec-2019 08:09:09	WSHSHP	P	DON	643.44
11-Dec-2019 1	333,287	7,552	416466	03-001-016	Replace Filter - Cab Ventilation	13-Dec-2019 08:09:09	WSHSHP	P	DON	72.78
11-Dec-2019 1	333,287	7,552	416466	03-518-001	Replace Steps	13-Dec-2019 08:09:09	WSHSHP	I	DON	830.71
11-Dec-2019 1	333,287	7,552	416466	24-015	Repair Steering	13-Dec-2019 08:09:09	WSHSHP	I	DON	79.42
11-Dec-2019 1	333,287	7,552	416466	24-030	Repair Electrical Group	13-Dec-2019 08:09:09	WSHSHP	I	DON	1,061.45
11-Dec-2019 1	333,287	7,552	416466	06-100-DOT	Inspect DOT Federal Inspection	13-Dec-2019 08:09:09	WSHSHP	P	DON	226.81
11-Dec-2019 1	333,287	7,552	416466	03-013-015	Replace Desiccant Cartridge Kit - Air	13-Dec-2019 08:09:09	WSHSHP	P	DON	166.18
11-Dec-2019 1	333,287	7,552	416466	03-032-001	Replace Battery	13-Dec-2019 08:09:09	WSHSHP	I	DON	527.89
11-Dec-2019 1	333,287	7,552	416466	03-034-004	Replace Clearance & Marker Lamps	13-Dec-2019 08:09:09	WSHSHP	I	DON	0.00
11-Dec-2019 1	333,287	7,552	416466	03-041-006	Replace Filter - Inner	13-Dec-2019 08:09:09	WSHSHP	P	DON	182.50
11-Dec-2019 1	333,287	7,552	416466	01-023	Adjust Clutch	13-Dec-2019 08:09:09	WSHSHP	P	DON	120.67
11-Dec-2019 1	333,287	7,552	416466	02-002	Clean Cab & Sheet Metal	13-Dec-2019 08:09:09	WSHSHP	P	DON	109.32
11-Dec-2019 1	333,287	7,552	416466	24-059	Repair Vehicle Coupling System	13-Dec-2019 08:09:09	WSHSHP	I	DON	135.75
11-Dec-2019 1	333,287	7,552	416466	24-002-035	Repair Windshield Wiper & Washer	13-Dec-2019 08:09:09	WSHSHP	I	DON	610.39
11-Dec-2019 1	333,287	7,552	416466	24-014	Repair Frame	13-Dec-2019 08:09:09	WSHSHP	I	DON	5,937.67
13-Feb-2020 0	333,302	7,565	426084	03-017-001	Replace Tire - Pneumatic	19-Feb-2020 13:54:20	WSHSHP	N	DON	4,297.97
20-May-2020 1	333,303	7,568	441771	03-052-003	Replace Radio Equipment	20-May-2020 15:22:13	ELEC02	Q	DON	700.81
02-Sep-2020 1	333,730	7,606	462485	03-002-010	Replace Mirrors	06-Sep-2020 23:00:00	WSHSHP	B	DON	101.95

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: C0307 - 2005 PETERBILT 378										
02-Sep-2020	333,730	7,606	462485	03-002-024	Replace Glass / Windshield	06-Sep-2020 23:00:00	WSHSH	B	DON	291.09
02-Sep-2020	333,730	7,606	462485	03-002-035	Replace Windshield Wiper & Washer	06-Sep-2020 23:00:00	WSHSH	N	DON	204.39
02-Sep-2020	333,730	7,606	462485	03-013-007	Replace Brake Lines & Fittings - Hydraulic & A	06-Sep-2020 23:00:00	WSHSH	B	DON	77.42
02-Sep-2020	333,730	7,606	462485	03-016-006	Replace Shock Absorber - Rear	06-Sep-2020 23:00:00	WSHSH	N	DON	547.06
02-Sep-2020	333,730	7,606	462485	03-016-015	Replace Cab/Sleeper Suspension	06-Sep-2020 23:00:00	WSHSH	B	DON	261.88
02-Sep-2020	333,730	7,606	462485	03-078-009	Replace Mud Flaps and Hanger Brackets	06-Sep-2020 23:00:00	WSHSH	B	DON	311.96
02-Sep-2020	333,730	7,606	462485	06-100-DOT	Inspect DOT Federal Inspection	06-Sep-2020 23:00:00	WSHSH	P	DON	246.31
02-Sep-2020	333,730	7,606	462485	24-013-009	Repair Air Compressor	06-Sep-2020 23:00:00	WSHSH	B	DON	269.57
02-Sep-2020	333,730	7,606	462485	24-013-022	Repair Glad Hands (Service/Emergency)	06-Sep-2020 23:00:00	WSHSH	N	DON	0.45
02-Sep-2020	333,730	7,606	462485	24-034-010	Repair Socket - Trailer Light Cord	06-Sep-2020 23:00:00	WSHSH	B	DON	154.85
02-Sep-2020	333,730	7,606	462485	24-043	Repair Exhaust System	06-Sep-2020 23:00:00	WSHSH	B	DON	5,002.19
22-Dec-2020	333,735	7,607	483361	03-032-001	Replace Battery	19-Jan-2021 23:00:00	WSHSH	N	DON	395.18
22-Dec-2020	333,735	7,607	483361	24-014-005	Repair Battery Support / Battery Box	19-Jan-2021 23:00:00	WSHSH	B	DON	439.23
22-Dec-2020	333,735	7,607	483361	24-049-003	Repair ECM Wiring Harness	19-Jan-2021 23:00:00	WSHSH	B	DON	185.82
23-Mar-2021	333,739	7,607	496524	06-100-DOT	Inspect DOT Federal Inspection	23-Mar-2021 23:00:00	WSHSH	P	DON	101.88
23-Mar-2021	333,739	7,607	496524	38-032	Service Cranking System	23-Mar-2021 23:00:00	WSHSH	N	DON	203.87
18-Jun-2021	335,656	7,716	513618	03-017-001	Replace Tire - Pneumatic	18-Nov-2021 23:00:00	WSHSH	N	DON	401.81
18-Jun-2021	335,656	7,716	513618	24-014-002	Repair Bumpers & Attaching Parts	18-Nov-2021 23:00:00	WSHSH	B	DON	2,664.89
19-Aug-2021	339,207	7,826	526335	03-013-010	Replace Air Brake Valve	08-Jul-2022 07:40:53	PIPE13	B	DON	120.35
19-Aug-2021	339,207	7,826	526335	03-032-001	Replace Battery	08-Jul-2022 07:40:53	WSHSH	N	DON	374.95
19-Aug-2021	339,207	7,826	526335	11-013-005	Rebuild Pedal Assembly - Service Brake	08-Jul-2022 07:40:53	PIPE13	N	DON	347.76
19-Aug-2021	339,207	7,826	526335	24-002-035	Repair Windshield Wiper & Washer	08-Jul-2022 07:40:53	PIPE13	B	DON	126.35
29-Oct-2021	344,126	8,193	575738	38-100-PMA	Service A PMI	24-Mar-2022 23:00:00	WSHSH	P	DON	520.61
29-Oct-2021	344,126	8,193	575738	06-100-PMA	Inspect A PMI	24-Mar-2022 23:00:00	WSHSH	P	DON	0.00
29-Oct-2021	344,126	8,193	575738	24-034-022	Repair Harness - Main	22-Jun-2022 10:27:56	WSHSH	I	DON	344.18
29-Oct-2021	344,126	8,193	575738	38-032-001	Service Battery	22-Jun-2022 10:27:56	WSHSH	N	DON	172.09
29-Oct-2021	344,126	8,193	575738	03-034-001	Replace Headlamps / Fog Lamps	24-Mar-2022 23:00:00	WSHSH	P	DON	282.11
29-Oct-2021	344,126	8,193	575738	03-013-022	Replace Glad Hands (Service/Emergency)	08-Apr-2022 15:12:24	WSHSH	B	DON	400.90
29-Oct-2021	344,126	8,193	575738	03-014-002	Replace Bumpers & Attaching Parts	22-Jun-2022 10:27:56	WSHSH	B	DON	8,448.03

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost		
Unit No: C0307 - 2005 PETERBILT 378												
29-Oct-2021	1	344,126	8,193	575738	03-016-003	Replace Shock Absorber - Front	24-Mar-2022	23:00:00	WHSHP	N	DON	239.96
29-Oct-2021	1	344,126	8,193	575738	03-041-001	Replace Air Cleaner	24-Mar-2022	23:00:00	WHSHP	P	DON	163.86
29-Oct-2021	1	344,126	8,193	575738	06-100-DOT	Inspect DOT Federal Inspection	24-Mar-2022	23:00:00	WHSHP	P	DON	1.86
29-Oct-2021	1	344,126	8,193	575738	03-013-015	Replace Desiccant Cartridge Kit - Air	24-Mar-2022	23:00:00	WHSHP	P	DON	157.03
29-Oct-2021	1	344,126	8,193	575738	02-071	Clean Body	24-Mar-2022	23:00:00	WHSHP	Q	DON	111.40
29-Oct-2021	1	344,126	8,193	575738	03-001-016	Replace Filter - Cab Ventilation	24-Mar-2022	23:00:00	WHSHP	P	DON	53.47
29-Oct-2021	1	344,126	8,193	575738	03-016-012	Replace Torque Rod	24-Mar-2022	23:00:00	WHSHP	N	DON	796.09
29-Oct-2021	1	344,126	8,193	575738	03-042-003	Replace Fan	24-Mar-2022	23:00:00	WHSHP	N	DON	981.40
29-Oct-2021	1	344,126	8,193	575738	03-002-035	Replace Windshield Wiper & Washer	24-Mar-2022	23:00:00	WHSHP	P	DON	290.19
15-Mar-2022	0	344,126	8,193	574537	03-063-003	Replace Transceiver - GPS Tracker	15-Mar-2022	10:29:43	ELEC02	Q	DON	478.86
02-Nov-2022	1	344,956		629242	06-100-PMA	Inspect A PMI	17-Nov-2022	16:39:50	WHSHP	P	DON	0.00
02-Nov-2022	1	344,956		629242	24-013-005	Repair Pedal Assembly - Service Brake	17-Nov-2022	16:39:50	WHSHP	B	DON	82.88
02-Nov-2022	1	344,956		629242	38-100-PMA	Service A PMI	17-Nov-2022	16:39:50	WHSHP	P	DON	124.32
22-Dec-2022	1	345,367		641276	06-100-PMA	Inspect A PMI			SCHED	P	CAN	0.00
19-Jan-2023	0	345,388		648052	06-100-DOT	Inspect DOT Federal Inspection	19-Jan-2023	09:00:00	WHSHP	P	DON	1,309.44
20-Apr-2023	1	345,407		669672	24-079-002	Repair Headache Rack	06-Jul-2023	14:12:04	WHSHP	I	DON	319.03
11-Jul-2023	10	345,437		687150	03-032-001	Replace Battery	07-Sep-2023	07:47:08	WHSHP	I	DON	650.31
11-Jul-2023	10	345,437		687150	03-044-002	Replace Filters	07-Sep-2023	07:47:08	WHSHP	I	DON	0.00
11-Jul-2023	10	345,437		687150	03-078-009	Replace Mud Flaps and Hanger Brackets	07-Sep-2023	07:47:08	WHSHP	I	DON	779.26
11-Jul-2023	10	345,437		687150	24-002-004	Repair Hood	07-Sep-2023	07:47:08	WHSHP	I	DON	-98.04
11-Jul-2023	10	345,437		687150	24-002-020	Repair Side Door Mechanism	07-Sep-2023	07:47:08	WHSHP	I	DON	1,492.72
11-Nov-2023	0			720474	06-100-PMA	Inspect A PMI	11-Nov-2023	08:02:41	WHSHP	P	DON	131.19
11-Nov-2023	0			720474	38-100-PMA	Service A PMI	11-Nov-2023	08:02:41	WHSHP	P	DON	218.65
11-Nov-2023	0			720474	24-013-007	Repair Brake Lines & Fittings - Hydraulic & Air	04-Jan-2024	14:22:49	WHSHP	B	DON	540.92
05-Dec-2023	1			724867	03-013-010	Replace Air Brake Valve	02-Jan-2024	07:48:10	BTRUCK	N	DON	27.59
05-Dec-2023	1			724867	02-002	Clean Cab & Sheet Metal	16-Jan-2024	16:58:26	BSETUP	N	DON	459.90
05-Dec-2023	1			724867	06-100-009	Inspect Safety Check	05-Dec-2023	17:00:44	BTRUCK	I	DON	179.85
05-Dec-2023	1			724867	03-079-003	Replace Strap, Anti-Static	02-Jan-2024	10:52:54	BTRUCK	N	DON	22.38
05-Dec-2023	1			724867	03-013-022	Replace Glad Hands (Service/Emergency)	02-Jan-2024	09:24:24	BTRUCK	N	DON	235.78

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: C0307 - 2005 PETERBILT 378										
05-Dec-2023 1	349,788		724867	24-013-012	Repair Electric Brakes	02-Jan-2024 14:36:38	BTRUCK	N	DON	138.20
05-Dec-2023 1	349,788		724867	03-051-009	Replace Fire Extinguisher	02-Jan-2024 08:48:39	BTRUCK	N	DON	168.12
05-Dec-2023 1	349,788		724867	06-094-008	Inspect Line - Air Supply	02-Jan-2024 09:47:48	BTRUCK	N	DON	55.81
05-Dec-2023 1	349,788		724867	24-053-015	Repair Tool Box	29-Dec-2023 14:58:06	BTRUCK	N	DON	12.14
05-Dec-2023 1	349,788		724867	06-100-DOT	Inspect DOT Federal Inspection	03-Jan-2024 08:52:17	BTRUCK	P	DON	59.56
05-Dec-2023 1	349,788		724867	06-100-PMB	Inspect B PMI	03-Jan-2024 07:04:04	BTRUCK	P	DON	42.47
05-Dec-2023 1	349,788		724867	38-100-PMA	Service A PMI	02-Jan-2024 12:58:09	BTRUCK	P	DON	430.61
05-Dec-2023 1	349,788		724867	03-053-005	Replace Markings - Vehicle - Decals	02-Jan-2024 08:33:22	BTRUCK	N	DON	28.02
05-Dec-2023 1	349,788		724867	24-111-006	Repair Shields and Guards	02-Jan-2024 10:09:15	BTRUCK	N	DON	13.30
05-Dec-2023 1	349,788		724867	03-013-016	Replace Air Dryer / Purge Valve	02-Jan-2024 10:29:34	BTRUCK	P	DON	49.21
05-Dec-2023 1	349,788		724867	03-079-009	Replace Tape - Reflective, Conspicuity	02-Jan-2024 16:45:06	BTRUCK	N	DON	34.58
05-Dec-2023 1	349,788		724867	24-519-001	Repair Front Bumper	02-Jan-2024 16:20:16	BTRUCK	N	DON	96.38
05-Dec-2023 1	349,788		724867	24-063-003	Repair Transceiver - GPS Tracker	02-Jan-2024 17:00:54	BTRUCK	N	DON	14.69
05-Dec-2023 1	349,788		724867	03-014-005	Replace Battery Support / Battery Box	03-Jan-2024 07:52:01	BTRUCK	N	DON	13.37
05-Dec-2023 1	349,788		724867	12-002-004	Refinish Hood	08-Mar-2024 13:59:32	BBODY	K	DON	733.95
05-Dec-2023 1	349,788		724867	24-002-004	Repair Hood	15-Jan-2024 14:38:23	BBODY	K	DON	958.68
26-Jun-2024 11	349,794		768924	06-100-009	Inspect Safety Check	27-Jun-2024 06:14:39	BTRUCK	N	DON	114.69
12-Jul-2024 15	349,795		772072	02-002	Clean Cab & Sheet Metal	24-Jul-2024 15:30:43	BSETUP	N	DON	203.70
12-Jul-2024 15	349,795		772072	25-051	Remove General Accessories	15-Jul-2024 10:50:58	BSETUP	N	DON	135.41

Unit No: C0307

Count: 367

239,032.30