

# Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
<b>Unit No: G0247 - 1999 INTERNATIONAL 4900</b>										
05-May-2009	3,029	39,828	12835	06-100-001	Inspect DO NOT USE - PMI Service	26-May-2009 09:00:00	MPNSHP	P	DON	486.72
05-May-2009	3,029	39,828	12835	06-267-001	Inspect Boom Structure	06-May-2009 08:08:50	MPNSHP	P	DON	68.75
05-May-2009	3,029	39,828	12835	03-013	Replace Brakes	01-Jun-2009 13:50:42	MPNSHP	O	DON	11.13
05-May-2009	3,029	39,828	12835	24-340-001	Repair Boom Assembly	06-May-2009 09:00:00	MPNSHP	I	DON	349.93
05-May-2009	3,029	39,828	12835	03-051-009	Replace Fire Extinguisher	06-May-2009 11:27:11	MPNSHP	I	DON	33.44
05-May-2009	3,029	39,828	12835	24-059-002	Repair Pintle Hook Assembly	06-May-2009 13:36:01	MPNSHP	I	DON	18.65
05-May-2009	3,029	39,828	12835	14-053-007	Install Hardware - Expendable Items	06-May-2009 11:58:46	MPNSHP	I	DON	14.60
05-May-2009	3,029	39,828	12835	14-079-006	Install Sign, Warning	06-May-2009 14:12:55	MPNSHP	I	DON	7.21
05-May-2009	3,029	39,828	12835	03-051-006	Replace Safety Devices	06-May-2009 13:57:19	MPNSHP	I	DON	9.85
05-May-2009	3,029	39,828	12835	01-072-006	Adjust Door Latch Mechanism	06-May-2009 14:33:31	MPNSHP	I	DON	9.52
05-May-2009	3,029	39,828	12835	03-078-009	Replace Mud Flaps and Hanger Brackets	20-May-2009 09:00:00	MPNSHP	I	DON	59.38
05-May-2009	3,029	39,828	12835	01-002-010	Adjust Mirrors	20-May-2009 07:16:40	MPNSHP	I	DON	4.98
05-May-2009	3,029	39,828	12835	03-052-003	Replace Radio Equipment	20-May-2009 15:31:04	MPNSHP	I	DON	127.93
05-May-2009	3,029	39,828	12835	03-002-035	Replace Windshield Wiper & Washer	20-May-2009 16:05:36	MPNSHP	I	DON	27.01
05-May-2009	3,029	39,828	12835	11-013-016	Rebuild Air Dryer / Purge Valve	21-May-2009 07:30:30	MPNSHP	J	DON	135.88
05-May-2009	3,029	39,828	12835	26-051-006	Weld Safety Devices	21-May-2009 09:00:00	MPNSHP	I	DON	101.71
05-May-2009	3,029	39,828	12835	24-015-004	Repair Steering Linkage	21-May-2009 09:00:00	MPNSHP	I	DON	64.68
05-May-2009	3,029	39,828	12835	35-016-002	Diagnose Chassis Spring - Front	21-May-2009 11:38:08	MPNSHP	I	DON	45.19
05-May-2009	3,029	39,828	12835	21-078-001	Fabricate Fender Assembly - Front	22-May-2009 07:53:33	MPNSHP	I	DON	110.46
05-May-2009	3,029	39,828	12835	06-100-002	Inspect DO NOT USE - DOT Federal Insp	01-Jun-2009 13:50:42	MPNSHP	P	DON	55.51
05-May-2009	3,029	39,828	12835	06-100-011	Inspect Annual Aerial/Boom Inspection	01-Jun-2009 13:50:42	MPNSHP	P	DON	1,741.13
31-Aug-2009	3,057	40,420	22315	03-065-007	Replace Hoses & Fittings	22-Sep-2009 14:58:59	MPNSHP	B	DON	139.19
23-Sep-2009	3,226	40,700	23218	06-100-002	Inspect DO NOT USE - DOT Federal Insp	06-Oct-2009 09:29:32	MPNSHP	P	DON	46.40
23-Sep-2009	3,226	40,700	23218	38-100-001	Service DO NOT USE - PMI Service	06-Oct-2009 09:29:32	MPNSHP	P	DON	77.33
22-Oct-2009	3,226	40,700	24424	03-065-001	Replace Hydraulic Systems	20-Nov-2009 11:09:19	MPNSHP	B	DON	1,964.23
22-Oct-2009	3,226	40,700	24424	03-002-010	Replace Mirrors	20-Nov-2009 14:32:07	MPNSHP	O	DON	85.61
22-Oct-2009	3,226	40,700	24424	06-100-001	Inspect DO NOT USE - PMI Service	20-Nov-2009 13:52:59	MPNSHP	P	DON	234.56
22-Oct-2009	3,226	40,700	24424	06-267-001	Inspect Boom Structure	20-Nov-2009 11:43:00	MPNSHP	P	DON	116.28
22-Oct-2009	3,226	40,700	24424	03-268-004	Replace Supports	20-Nov-2009 11:10:30	MPNSHP	I	DON	139.53

# Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: G0247 - 1999 INTERNATIONAL 4900										
22-Oct-2009 0	3,226	40,700	24424	24-514	Repair Bucket	20-Nov-2009 11:08:52	MPNSHP	I	DON	46.27
22-Oct-2009 0	3,226	40,700	24424	03-193-010	Replace Wipers	20-Nov-2009 15:00:00	MPNSHP	I	DON	22.69
22-Oct-2009 0	3,226	40,700	24424	06-053-015	Inspect Tool Box	23-Nov-2009 05:04:52	MPNSHP	I	DON	15.97
22-Oct-2009 0	3,226	40,700	24424	14-053-007	Install Hardware - Expendable Items	23-Nov-2009 14:19:19	MPNSHP	I	DON	317.55
04-Mar-2010 0	4,082	43,642	35604	14-031-006	Install Belt - Alternator	08-Mar-2010 07:19:28	MPNSHP	I	DON	35.38
04-Mar-2010 0	4,082	43,642	35604	38-100-001	Service DO NOT USE - PMI Service	08-Mar-2010 07:18:26	MPNSHP	P	DON	212.28
19-May-2010 (	4,142	44,160	41485	01-002-011	Adjust Cab Accessories - Interior	21-Jun-2010 15:31:11	MPNSHP	I	DON	9.10
19-May-2010 (	4,142	44,160	41485	01-013-017	Adjust Slack Adjuster	23-Jun-2010 09:00:00	MPNSHP	I	DON	29.57
19-May-2010 (	4,142	44,160	41485	01-053-005	Adjust Markings - Vehicle - Decals	25-Jun-2010 11:10:20	MPNSHP	I	DON	105.24
19-May-2010 (	4,142	44,160	41485	01-053-999	Adjust Vehicle Fluids, Lubricants, Gases, & Parti	24-Jun-2010 07:51:50	MPNSHP	I	DON	41.35
19-May-2010 (	4,142	44,160	41485	01-060	Adjust Special Applications Group	23-Jun-2010 08:45:30	MPNSHP	I	DON	22.10
19-May-2010 (	4,142	44,160	41485	01-078-009	Adjust Mud Flaps and Hanger Brackets	23-Jun-2010 08:03:00	MPNSHP	I	DON	25.85
19-May-2010 (	4,142	44,160	41485	01-173-004	Adjust Support	22-Jun-2010 13:16:45	MPNSHP	I	DON	29.75
19-May-2010 (	4,142	44,160	41485	01-514-004	Adjust Edges	23-Jun-2010 13:07:12	MPNSHP	I	DON	75.84
19-May-2010 (	4,142	44,160	41485	02-002-044	Clean Cab - Complete	02-Sep-2010 11:08:38	MPNSHP	Q	DON	271.62
19-May-2010 (	4,142	44,160	41485	02-010-001	Clean All Axles	24-Jun-2010 09:00:00	MPNSHP	I	DON	45.40
19-May-2010 (	4,142	44,160	41485	02-026-001	Clean Transmission Case	29-Jun-2010 13:44:55	MPNSHP	I	DON	94.87
19-May-2010 (	4,142	44,160	41485	03-002-061	Replace Seat Cushion	22-Jun-2010 15:40:28	MPNSHP	I	DON	154.11
19-May-2010 (	4,142	44,160	41485	03-026-020	Replace Seal - Output	23-Jun-2010 14:57:10	MPNSHP	I	DON	92.39
19-May-2010 (	4,142	44,160	41485	03-034-020	Replace Dome / Reading Light	23-Jun-2010 10:45:33	MPNSHP	I	DON	120.48
19-May-2010 (	4,142	44,160	41485	03-051-009	Replace Fire Extinguisher	21-Jun-2010 14:56:50	MPNSHP	I	DON	19.79
19-May-2010 (	4,142	44,160	41485	03-193-010	Replace Wipers	22-Jun-2010 08:44:04	MPNSHP	I	DON	20.58
19-May-2010 (	4,142	44,160	41485	06-025-002	Inspect Seal - Input Shaft	27-Jul-2010 06:23:01	MPNSHP	I	DON	137.06
19-May-2010 (	4,142	44,160	41485	06-026-016	Inspect Gear Shifter & Linkage	25-Jun-2010 11:36:41	MPNSHP	I	DON	38.41
19-May-2010 (	4,142	44,160	41485	06-056-001	Inspect Power Take Off	29-Jun-2010 14:26:03	MPNSHP	I	DON	70.51
19-May-2010 (	4,142	44,160	41485	06-100-001	Inspect DO NOT USE - PMI Service	27-Jul-2010 06:22:17	MPNSHP	P	DON	57.54
19-May-2010 (	4,142	44,160	41485	06-100-002	Inspect DO NOT USE - DOT Federal Insp	03-Sep-2010 06:24:20	MPNSHP	J	DON	8.29
19-May-2010 (	4,142	44,160	41485	06-100-011	Inspect Annual Aerial/Boom Inspection	21-Jun-2010 14:47:31	MPNSHP	P	DON	2,513.54
19-May-2010 (	4,142	44,160	41485	07-010-001	Lubricate All Axles	22-Jun-2010 14:28:05	MPNSHP	I	DON	37.09

# Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
<b>Unit No: G0247 - 1999 INTERNATIONAL-4900</b>										
19-May-2010	4,142	44,160	41485	11-013-016	Rebuild Air Dryer / Purge Valve	23-Jun-2010 07:13:17	MPNSHP	I	DON	159.53
19-May-2010	4,142	44,160	41485	14-050	Install Accessories Group	22-Jun-2010 11:49:14	MPNSHP	I	DON	58.38
19-May-2010	4,142	44,160	41485	24-002-061	Repair Seat Cushion	27-Jul-2010 06:22:26	MPNSHP	I	DON	6.65
07-Jan-2011	4,142	44,160	56632	02-506	Clean Tank	07-Jan-2011 15:00:00	BWASH	J	DON	54.56
15-Jul-2011	4,301	45,897	69552	06-100-011	Inspect Annual Aerial/Boom Inspection	25-Jul-2011 14:50:18	MPNSHP	P	DON	461.84
18-Jul-2011	4,301	45,897	70124	14-055-012	Install Cargo Restraints	02-Aug-2011 15:15:11	HARRIS	P	DON	55.48
20-Sep-2011	4,301	45,897	73541	03-034-004	Replace Clearance & Marker Lamps	26-Sep-2011 11:33:04	MPNSHP	I	DON	64.61
20-Sep-2011	4,301	45,897	73541	06-053-006	Inspect Tools & Diagnostic Devices	26-Sep-2011 11:34:15	MPNSHP	P	DON	193.83
20-Sep-2011	4,301	45,897	73541	06-100-001	Inspect DO NOT USE - PMI Service	26-Sep-2011 11:29:35	MPNSHP	P	DON	759.18
20-Sep-2011	4,301	45,897	73541	06-100-002	Inspect DO NOT USE - DOT Federal Insp	26-Sep-2011 11:35:49	MPNSHP	P	DON	48.46
20-Sep-2011	4,301	45,897	73541	24-034-001	Repair Headlamps / Fog Lamps	26-Sep-2011 11:32:25	MPNSHP	I	DON	48.46
04-Oct-2011	4,301	45,897	75708	24-065-007	Repair Hoses & Fittings	31-Oct-2011 09:34:37	MPNSHP	B	DON	406.18
30-Mar-2012	4,688	50,043	85044	03-002-010	Replace Mirrors	30-Mar-2012 17:00:00	SYRCNY	E	DON	61.86
20-Apr-2012	4,780	51,140	86632	35-049-001	Diagnose ECM Fault Code	20-Apr-2012 17:00:00	SYRCNY	O	DON	30.93
30-May-2012	4,780	51,140	89515	03-042-015	Replace Fan Hub	30-May-2012 17:00:00	SYRCNY	B	DON	123.72
14-Jun-2012	4,780	51,140	91412	06-100-PMA	Inspect A PMI	14-Jun-2012 17:00:00	SYRCNY	P	DON	92.79
14-Jun-2012	4,780	51,140	91412	03-043-004	Replace Turbocharger	18-Jun-2012 17:00:00	SYRCNY	O	DON	77.33
17-Jul-2012	4,906	52,635	92800	06-100-011	Inspect Annual Aerial/Boom Inspection	17-Jul-2012 17:00:00	SYRCNY	P	DON	0.00
15-Aug-2012	4,906	52,635	94562	24-268-009	Repair Boom Structure	15-Aug-2012 17:00:00	SYRCNY	I	DON	30.93
19-Sep-2012	4,906	52,635	96621	03-017-001	Replace Tire - Pneumatic	08-Oct-2012 12:18:03	SYRCNY	E	DON	1,008.61
11-Oct-2012	4,906	52,635	98773	06-100-DOT	Inspect DOT Federal Inspection	11-Oct-2012 17:00:00	SYRCNY	P	DON	0.00
30-Nov-2012	4,906	53,665	102435	06-100-DOT	Inspect DOT Federal Inspection	30-Nov-2012 17:00:00	SYRCNY	P	DON	30.93
11-Feb-2013	4,906	53,665	107442	14-052-003	Install Radio Equipment	11-Feb-2013 13:42:13	BBODY	C	DON	25.22
02-Jul-2013	4,906	53,665	127786	24-268-005	Repair Controls	24-Jul-2013 17:00:00	SYRCNY	B	DON	2,321.04
02-Aug-2013	4,906	53,665	126940	06-100-011	Inspect Annual Aerial/Boom Inspection	02-Aug-2013 17:00:00	MPNSHP	P	DON	0.00
22-Aug-2013	4,906	53,665	128441	06-268-009	Inspect Boom Structure	22-Aug-2013 17:00:00	SYRCNY	P	DON	299.09
06-Sep-2013	4,906	55,419	131818	03-017-001	Replace Tire - Pneumatic	06-Sep-2013 17:00:00	MPNSHP	I	DON	167.91
10-Sep-2013	4,906	53,665	130945	03-017-001	Replace Tire - Pneumatic	10-Sep-2013 11:06:11	BTIRE	E	DON	690.80
17-Sep-2013	4,906	55,419	131426	03-002-010	Replace Mirrors	17-Sep-2013 17:00:00	SYRCNY	I	DON	39.80

# Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: G0247 - 1999 INTERNATIONAL 4900										
17-Sep-2013 0	5,062	55,419	131426	03-002-035	Replace Windshield Wiper & Washer	17-Sep-2013 17:00:00	SYRCNY	I	DON	52.14
17-Sep-2013 0	5,062	55,419	131426	03-015-004	Replace Steering Linkage	17-Sep-2013 17:00:00	SYRCNY	I	DON	166.94
17-Sep-2013 0	5,062	55,419	131426	06-100-PMA	Inspect A PMI	17-Sep-2013 17:00:00	SYRCNY	P	DON	491.29
17-Sep-2013 0	5,062	55,419	131426	24-022	Repair Axles - Driven, Rear	17-Sep-2013 17:00:00	SYRCNY	I	DON	198.29
17-Sep-2013 0	5,062	55,419	131426	01-023-001	Adjust Linkage - Mechanical Clutch	17-Sep-2013 17:00:00	SYRCNY	I	DON	83.47
26-Nov-2013 C	5,062	55,419	138000	01-013	Adjust Brakes	10-Jan-2014 12:32:38	MPNSHP	I	DON	197.64
26-Nov-2013 C	5,062	55,419	138000	02-025-001	Clean Transfer Case Assembly	03-Jan-2014 13:47:09	MPNSHP	I	DON	16.52
26-Nov-2013 C	5,062	55,419	138000	03-002-067	Replace Keys - Door / Ignition	09-Jan-2014 11:12:06	MPNSHP	I	DON	9.08
26-Nov-2013 C	5,062	55,419	138000	03-023-002	Replace Clutch Assembly	30-Dec-2013 10:48:05	MPNSHP	B	DON	2,331.36
26-Nov-2013 C	5,062	55,419	138000	03-027-036	Replace Oil Pan & Screen Assembly	30-Dec-2013 11:03:25	MPNSHP	B	DON	725.97
26-Nov-2013 C	5,062	55,419	138000	03-027-039	Replace Cooler Assembly	30-Dec-2013 11:00:19	MPNSHP	B	DON	1,257.27
26-Nov-2013 C	5,062	55,419	138000	03-030	Replace Electrical Group	03-Jan-2014 14:20:54	MPNSHP	I	DON	22.18
26-Nov-2013 C	5,062	55,419	138000	03-032-001	Replace Battery	06-Jan-2014 12:38:01	MPNSHP	I	DON	206.22
26-Nov-2013 C	5,062	55,419	138000	03-041-001	Replace Air Cleaner	09-Jan-2014 07:07:18	MPNSHP	I	DON	33.26
26-Nov-2013 C	5,062	55,419	138000	03-043	Replace Exhaust System	30-Dec-2013 10:51:26	MPNSHP	B	DON	2,436.52
26-Nov-2013 C	5,062	55,419	138000	03-053-005	Replace Markings - Vehicle - Decals	06-Jan-2014 10:41:34	MPNSHP	I	DON	35.05
26-Nov-2013 C	5,062	55,419	138000	06-025-002	Inspect Seal - Input Shaft	09-Jan-2014 17:15:00	MPNSHP	I	DON	176.23
26-Nov-2013 C	5,062	55,419	138000	06-100-009	Inspect Safety Check	27-Jan-2014 15:34:52	MPNSHP	I	DON	158.74
26-Nov-2013 C	5,062	55,419	138000	06-100-DOT	Inspect DOT Federal Inspection	30-Dec-2013 10:47:07	MPNSHP	J	DON	706.88
26-Nov-2013 C	5,062	55,419	138000	06-100-PMA	Inspect A PMI	30-Dec-2013 10:43:15	MPNSHP	J	DON	391.80
26-Nov-2013 C	5,062	55,419	138000	14-034-012	Install Box - Junction	30-Dec-2013 11:05:51	MPNSHP	B	DON	594.97
26-Nov-2013 C	5,062	55,419	138000	14-050	Install Accessories Group	27-Jan-2014 15:34:32	MPNSHP	P	DON	373.61
26-Nov-2013 C	5,062	55,419	138000	14-053-004	Install Safety Equipment	06-Jan-2014 09:25:04	MPNSHP	I	DON	17.51
26-Nov-2013 C	5,062	55,419	138000	14-053-007	Install Hardware - Expendable Items	06-Jan-2014 13:01:52	MPNSHP	I	DON	70.19
26-Nov-2013 C	5,062	55,419	138000	14-063-003	Install Transceiver - GPS Tracker	08-Jan-2014 08:09:26	MPNSHP	I	DON	355.63
26-Nov-2013 C	5,062	55,419	138000	15-014-001	Paint Prep Frame Assembly	30-Dec-2013 10:46:53	MPNSHP	P	DON	4,389.93
26-Nov-2013 C	5,062	55,419	138000	21-014	Fabricate Frame	02-Jan-2014 11:56:10	MPNSHP	I	DON	138.51
26-Nov-2013 C	5,062	55,419	138000	24-034-002	Repair Stop, Tail, Turn & License	30-Dec-2013 10:50:09	MPNSHP	B	DON	280.48
26-Nov-2013 C	5,062	55,419	138000	24-052-003	Repair Radio Equipment	06-Jan-2014 13:55:42	MPNSHP	I	DON	24.66

# Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: G0247 - 1999 INTERNATIONAL 4900										
13-Feb-2015 0	5,062	55,419	191346	22-071-001	Design Floor / Decking / Flatbed	30-Mar-2015 06:46:06	BDRAW	D	DON	477.77
14-Oct-2015 1	5,389	57,171	218276	06-100-PMB	Inspect B PMI	01-Dec-2015 07:01:31	BTRUCK	P	DON	224.01
14-Oct-2015 1	5,389	57,171	218276	03-002-010	Replace Mirrors	15-Oct-2015 06:54:04	BTRUCK	I	DON	112.80
14-Oct-2015 1	5,389	57,171	218276	03-015-005	Replace Power Steering Pump	16-Oct-2015 07:48:59	BTRUCK	I	DON	40.32
14-Oct-2015 1	5,389	57,171	218276	03-051-009	Replace Fire Extinguisher	24-Nov-2015 07:21:23	BTRUCK	I	DON	75.62
14-Oct-2015 1	5,389	57,171	218276	03-013-015	Replace Desiccant Cartridge Kit - Air	16-Oct-2015 06:58:25	BTRUCK	I	DON	163.15
14-Oct-2015 1	5,389	57,171	218276	01-023-002	Adjust Clutch Assembly	16-Oct-2015 09:12:10	BTRUCK	I	DON	21.74
14-Oct-2015 1	5,389	57,171	218276	03-002-035	Replace Windshield Wiper & Washer	16-Oct-2015 10:13:22	BTRUCK	I	DON	22.10
14-Oct-2015 1	5,389	57,171	218276	01-014-001	Adjust Frame Assembly	28-Dec-2015 05:09:39	BTRUCK	C	DON	379.18
14-Oct-2015 1	5,389	57,171	218276	03-032-001	Replace Battery	11-Nov-2015 13:20:39	BTRUCK	I	DON	315.07
14-Oct-2015 1	5,389	57,171	218276	03-043-007	Replace Exhaust Pipe/Elbow	24-Nov-2015 08:47:33	BTRUCK	I	DON	104.88
14-Oct-2015 1	5,389	57,171	218276	14-034-006	Install Warning Lamps - Special Application	23-Nov-2015 16:24:07	BTRUCK	C	DON	350.30
14-Oct-2015 1	5,389	57,171	218276	14-078-002	Install Fender Assembly - Rear		BTRUCK	M	CAN	0.00
14-Oct-2015 1	5,389	57,171	218276	14-034-014	Install Auxiliary Work / Flood Light	23-Nov-2015 12:01:41	BTRUCK	C	DON	221.18
14-Oct-2015 1	5,389	57,171	218276	24-013-012	Repair Electric Brakes	24-Nov-2015 07:46:59	BTRUCK	I	DON	2.92
14-Oct-2015 1	5,389	57,171	218276	14-071	Install Body	23-Nov-2015 15:42:41	BTRUCK	C	DON	5,623.17
14-Oct-2015 1	5,389	57,171	218276	38-045	Service Power Plant	15-Oct-2015 11:17:24	BTRUCK	P	DON	311.21
14-Oct-2015 1	5,389	57,171	218276	24-013-035	Repair Clevis Pins	16-Oct-2015 11:07:17	BTRUCK	I	DON	29.79
14-Oct-2015 1	5,389	57,171	218276	19-071	Wire/Rewire Body	23-Nov-2015 15:37:17	BTRUCK	C	DON	672.99
14-Oct-2015 1	5,389	57,171	218276	14-032-001	Install Battery	16-Oct-2015 08:32:49	BTRUCK	I	DON	16.97
14-Oct-2015 1	5,389	57,171	218276	31-017-001	Rotate Tire - Pneumatic	16-Oct-2015 15:13:10	BTRUCK	I	DON	78.31
14-Oct-2015 1	5,389	57,171	218276	21-014-002	Fabricate Bumpers & Attaching Parts	28-Dec-2015 05:09:41	BTRUCK	C	DON	521.07
14-Oct-2015 1	5,389	57,171	218276	21-519-003	Fabricate Hitch Assembly	09-Nov-2015 08:15:53	BWELD	C	DON	2,305.19
14-Oct-2015 1	5,389	57,171	218276	15-079-002	Paint Prep Headache Rack	17-Nov-2015 10:28:14	BSAND	C	DON	209.92
14-Oct-2015 1	5,389	57,171	218276	15-519-003	Paint Prep Hitch Assembly	17-Nov-2015 10:28:10	BSAND	C	DON	248.53
14-Oct-2015 1	5,389	57,171	218276	12-519-003	Refinish Hitch Assembly	16-Nov-2015 14:05:36	BBODY	C	DON	132.41
14-Oct-2015 1	5,389	57,171	218276	12-709-002	Refinish Bearings		BBODY	C	CAN	0.00
14-Oct-2015 1	5,389	57,171	218276	12-079-002	Refinish Headache Rack	17-Nov-2015 10:28:04	BBODY	C	DON	283.58
14-Oct-2015 1	5,389	57,171	218276	14-053-015	Install Tool Box	24-Nov-2015 07:11:45	BTRUCK	I	DON	691.08

# Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
<b>Unit No: G0247 - 1999 INTERNATIONAL 4900</b>										
14-Oct-2015 I	5,389	57,171	218276	14-078-009	Install Mud Flaps and Hanger Brackets	24-Nov-2015 06:24:23	BTRUCK	I	DON	172.50
14-Oct-2015 I	5,389	57,171	218276	14-079-009	Install Tape - Reflective, Conspicuity	24-Nov-2015 07:41:42	BTRUCK	I	DON	25.70
08-Mar-2016 I	5,389	57,171	236459	02-002	Clean Cab & Sheet Metal	09-Mar-2016 06:25:18	BSETUP	J	DON	182.39
08-Mar-2016 I	5,389	57,171	236459	14-051-009	Install Fire Extinguisher	09-Mar-2016 06:40:25	BSETUP	C	DON	89.98
08-Mar-2016 I	5,389	57,171	236459	14-079-003	Install Strap, Anti-Static	08-Mar-2016 14:53:28	BSETUP	C	DON	5.43
16-Mar-2016 0	5,394	57,175	237698	03-051-009	Replace Fire Extinguisher	17-Mar-2016 07:15:58	BTRUCK	I	DON	69.02
16-Mar-2016 0	5,394	57,175	237698	24-063-003	Repair Transceiver - GPS Tracker	17-Mar-2016 08:34:22	MPNSHP	Q	DON	24.91
16-Mar-2016 0	5,394	57,175	237698	06-100-DOT	Inspect DOT Federal Inspection	06-Apr-2016 16:10:03	MPNSHP	P	DON	76.71
16-Mar-2016 0	5,394	57,175	237698	14-078-009	Install Mud Flaps and Hanger Brackets	17-Mar-2016 07:51:15	BTRUCK	I	DON	55.24
16-Mar-2016 0	5,394	57,175	237698	03-002-035	Replace Windshield Wiper & Washer	17-Mar-2016 06:24:49	BTRUCK	I	DON	62.00
16-Mar-2016 0	5,394	57,175	237698	03-045-010	Replace Oil Filler & Level Indicator	17-Mar-2016 07:07:08	BTRUCK	I	DON	120.88
16-Mar-2016 0	5,394	57,175	237698	06-013-032	Inspect ABS - ECU	21-Mar-2016 15:46:54	BTRUCK	I	DON	1,904.05
16-Mar-2016 0	5,394	57,175	237698	19-034-012	Wire/Rewire Box - Junction	06-Apr-2016 16:26:45	BTRUCK	I	DON	274.71
16-Mar-2016 0	5,394	57,175	237698	24-045-010	Repair Oil Filler & Level Indicator		BTRUCK	I	CAN	0.00
16-Mar-2016 0	5,394	57,175	237698	19-052-003	Wire/Rewire Radio Equipment	06-Apr-2016 16:26:45	BTRUCK	I	DON	50.94
16-Mar-2016 0	5,394	57,175	237698	01-022-001	Adjust Axle Housing, Rear	06-Apr-2016 16:26:45	BTRUCK	I	DON	30.56
16-Mar-2016 0	5,394	57,175	237698	24-003-001	Repair Gauges & Warning Devices	06-Apr-2016 16:26:45	BTRUCK	I	DON	50.94
26-Aug-2016 C	5,394		258022	06-100-PMB	Inspect B PMI	26-Aug-2016 06:00:00	U60952	P	DON	37.61
05-Oct-2016 I	5,404	59,634	261876	03-059-002	Replace Pintle Hook Assembly	10-Oct-2016 09:38:16	BTRUCK	I	DON	426.37
05-Oct-2016 I	5,404	59,634	261876	24-053-015	Repair Tool Box	10-Oct-2016 08:19:17	BTRUCK	I	DON	18.28
05-Oct-2016 I	5,404	59,634	261876	24-063-003	Repair Transceiver - GPS Tracker	10-Oct-2016 10:55:56	MPNSHP	Q	DON	0.00
05-Oct-2016 I	5,404	59,634	261876	06-100-009	Inspect Safety Check	10-Oct-2016 07:27:12	BTRUCK	P	DON	228.56
05-Oct-2016 I	5,404	59,634	261876	24-021-001	Repair Axle Assembly - Driven, Front Steering	01-Nov-2016 13:25:21	BTRUCK	E	DON	9,960.08
05-Oct-2016 I	5,404	59,634	261876	24-024-002	Repair Drive Shaft, Behind Main Transmission	01-Nov-2016 13:25:21	BTRUCK	I	DON	45.63
05-Oct-2016 I	5,404	59,634	261876	24-025-003	Repair Seal - Output Shaft	01-Nov-2016 13:25:21	BTRUCK	I	DON	396.96
05-Oct-2016 I	5,404	59,634	261876	03-002-035	Replace Windshield Wiper & Washer	01-Nov-2016 13:25:21	BTRUCK	I	DON	78.42
05-Oct-2016 I	5,404	59,634	261876	24-003-001	Repair Gauges & Warning Devices	01-Nov-2016 13:25:21	BTRUCK	I	DON	87.88
05-Oct-2016 I	5,404	59,634	261876	24-045-009	Repair Oil Pump & Distribution System	01-Nov-2016 13:25:21	BTRUCK	I	DON	781.28
05-Oct-2016 I	5,404	59,634	261876	24-002-023	Repair Handles - Inner & Outer	01-Nov-2016 13:25:21	BTRUCK	I	DON	40.75

# Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: G0247 - 1999 INTERNATIONAL 4900										
05-Oct-2016 1:	5,404	59,634	261876	06-100-PMB	Inspect B PMI	01-Nov-2016 13:25:21	BTRUCK	P	DON	1,304.78
05-Oct-2016 1:	5,404	59,634	261876	07-013-035	Lubricate Clevis Pins	01-Nov-2016 13:25:21	BTRUCK	I	DON	254.69
05-Oct-2016 1:	5,404	59,634	261876	24-034-020	Repair Dome / Reading Light	01-Nov-2016 13:25:21	BTRUCK	I	DON	63.03
05-Oct-2016 1:	5,404	59,634	261876	03-078	Replace Trim & Miscellaneous Hardware	01-Nov-2016 13:25:21	BTRUCK	I	DON	214.87
05-Oct-2016 1:	5,404	59,634	261876	03-094-008	Replace Line - Air Supply	01-Nov-2016 13:25:21	BTRUCK	I	DON	57.32
05-Oct-2016 1:	5,404	59,634	261876	03-078-009	Replace Mud Flaps and Hanger Brackets	01-Nov-2016 13:25:21	BTRUCK	I	DON	81.50
05-Oct-2016 1:	5,404	59,634	261876	01-023-001	Adjust Linkage - Mechanical Clutch	01-Nov-2016 13:25:21	BTRUCK	I	DON	88.29
05-Oct-2016 1:	5,404	59,634	261876	03-002-060	Replace Seat Belt	01-Nov-2016 13:25:21	BTRUCK	I	DON	354.07
05-Oct-2016 1:	5,404	59,634	261876	24-042-014	Repair Coolant Overflow Reservoir	01-Nov-2016 13:25:21	BTRUCK	I	DON	49.35
05-Oct-2016 1:	5,404	59,634	261876	24-042-009	Repair Coolant Pre-Heater- Electrical	01-Nov-2016 13:25:21	BTRUCK	I	DON	200.29
05-Oct-2016 1:	5,404	59,634	261876	09-015-001	Align Steering Wheel	01-Nov-2016 13:25:21	BTRUCK	I	DON	101.87
05-Oct-2016 1:	5,404	59,634	261876	03-013-003	Replace Brake Chamber - Parking	01-Nov-2016 13:25:21	BTRUCK	I	DON	163.57
05-Oct-2016 1:	5,404	59,634	261876	03-041-001	Replace Air Cleaner	01-Nov-2016 13:25:21	BTRUCK	I	DON	63.27
08-Jun-2017 1:	5,636	59,955	292091	03-002-035	Replace Windshield Wiper & Washer	09-Jun-2017 16:07:21	BTRUCK	I	DON	80.82
08-Jun-2017 1:	5,636	59,955	292091	03-051-009	Replace Fire Extinguisher	08-Jun-2017 12:00:13	BTRUCK	I	DON	138.10
08-Jun-2017 1:	5,636	59,955	292091	06-100-DOT	Inspect DOT Federal Inspection	12-Jun-2017 07:48:27	BTRUCK	P	DON	73.98
08-Jun-2017 1:	5,636	59,955	292091	11-013-016	Rebuild Air Dryer / Purge Valve	09-Jun-2017 15:13:51	BTRUCK	I	DON	130.35
08-Jun-2017 1:	5,636	59,955	292091	14-013-022	Install Glad Hands (Service/Emergency)	09-Jun-2017 17:00:05	BTRUCK	C	DON	107.27
08-Jun-2017 1:	5,636	59,955	292091	18-032-001	Test Battery	12-Jun-2017 06:21:07	BTRUCK	I	DON	21.61
08-Jun-2017 1:	5,636	59,955	292091	14-013-029	Install Valve - Air Brake	12-Jun-2017 06:18:57	BTRUCK	C	DON	458.34
08-Jun-2017 1:	5,636	59,955	292091	24-078-009	Repair Mud Flaps and Hanger Brackets	08-Jun-2017 14:24:35	BTRUCK	I	DON	56.52
08-Jun-2017 1:	5,636	59,955	292091	14-034-008	Install Trailer Light Cord	12-Jun-2017 06:18:18	BTRUCK	C	DON	213.88
08-Jun-2017 1:	5,636	59,955	292091	14-034-012	Install Box - Junction	12-Jun-2017 06:17:59	BTRUCK	C	DON	31.24
08-Jun-2017 1:	5,636	59,955	292091	14-013-030	Install Switch - Parking Brake	09-Jun-2017 16:28:23	BTRUCK	I	DON	28.75
09-Oct-2017 0:	5,636	59,955	308004	02-002	Clean Cab & Sheet Metal	09-Oct-2017 15:34:24	BSETUP	J	DON	334.01
24-Oct-2017 0:	5,639	59,958	309905	24-001-008	Repair Motor - Blower	24-Oct-2017 08:26:53	BTRUCK	O	DON	33.04
16-Mar-2018 0:	6,664	64,542	327811	06-100-PMC	Inspect C PMI	16-Mar-2018 11:00:00	70951M	P	DON	67.38
07-Jun-2018 0:	6,664	64,542	339336	03-013-012	Replace Electric Brakes	07-Jun-2018 11:00:00	70951M	I	DON	119.91
06-Sep-2018 0:	6,664	64,542	352299	24-003-002	Repair Speedometer	06-Sep-2018 11:00:00	70951M	I	DON	309.59

# Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
<b>Unit No: G0247 - 1999 INTERNATIONAL 4900</b>										
14-Nov-2018 C	6,664	76,098	361100	06-010	Inspect Chassis Group	23-Nov-2018 00:00:00	BVLOFC	E	DON	134.08
14-Nov-2018 C	6,664	76,098	361100	24-MSC	Repair Miscellaneous	23-Nov-2018 00:00:00	BVLOFC	E	DON	3,617.41
14-Nov-2018 C	6,664	76,098	361100	06-100-DOT	Inspect DOT Federal Inspection	23-Nov-2018 00:00:00	BVLOFC	P	DON	54.75
14-Nov-2018 C	6,664	76,098	361100	24-024	Repair Driveshafts	23-Nov-2018 00:00:00	BVLOFC	E	DON	4,183.51
05-Feb-2019 I	8,148	76,125	371168	38-100-PMB	Service B PMI	06-Feb-2019 08:34:22	WSHSHP	E	DON	489.54
05-Feb-2019 I	8,148	76,125	371168	03-013-015	Replace Desiccant Cartridge Kit - Air	06-Feb-2019 08:34:22	WSHSHP	E	DON	138.55
05-Feb-2019 I	8,148	76,125	371168	03-002-026	Replace Weather Stripping, Gaskets & Bumpers	06-Feb-2019 08:34:22	WSHSHP	E	DON	290.77
05-Feb-2019 I	8,148	76,125	371168	03-013-016	Replace Air Dryer / Purge Valve	06-Feb-2019 08:34:22	WSHSHP	I	DON	262.89
05-Feb-2019 I	8,148	76,125	371168	03-013-031	Replace Drain Valve - Air Tank	06-Feb-2019 08:34:22	WSHSHP	I	DON	175.75
05-Feb-2019 I	8,148	76,125	371168	03-013-010	Replace Air Brake Valve	06-Feb-2019 08:34:22	WSHSHP	I	DON	437.41
05-Feb-2019 I	8,148	76,125	371168	24-003	Repair Instruments, Gauges, Warning & Shutdo	06-Feb-2019 08:34:22	WSHSHP	I	DON	339.17
05-Feb-2019 I	8,148	76,125	371168	06-100-DOT	Inspect DOT Federal Inspection	06-Feb-2019 08:34:22	WSHSHP	P	DON	348.60
05-Feb-2019 I	8,148	76,125	371168	03-041-006	Replace Filter - Inner	06-Feb-2019 08:34:22	WSHSHP	E	DON	79.93
05-Feb-2019 I	8,148	76,125	371168	24-032	Repair Cranking System	06-Feb-2019 08:34:22	WSHSHP	I	DON	55.82
05-Feb-2019 I	8,148	76,125	371168	03-013	Replace Brakes	06-Feb-2019 08:34:22	WSHSHP	I	DON	1,937.98
05-Feb-2019 I	8,148	76,125	371168	24-026-016	Repair Gear Shifter & Linkage	06-Feb-2019 08:34:22	WSHSHP	I	DON	342.16
05-Feb-2019 I	8,148	76,125	371168	03-054-002	Replace Alarm - Reverse Signal	06-Feb-2019 08:34:22	WSHSHP	I	DON	601.38
05-Feb-2019 I	8,148	76,125	371168	03-034-014	Replace Auxiliary Work / Flood Light	06-Feb-2019 08:34:22	WSHSHP	E	DON	321.39
05-Feb-2019 I	8,148	76,125	371168	03-013-022	Replace Glad Hands (Service/Emergency)	06-Feb-2019 08:34:22	WSHSHP	E	DON	85.33
05-Feb-2019 I	8,148	76,125	371168	24-016-024	Repair Leaf Spring	06-Feb-2019 08:34:22	WSHSHP	I	DON	2,259.02
05-Feb-2019 I	8,148	76,125	371168	24-042	Repair Cooling System	06-Feb-2019 08:34:22	WSHSHP	I	DON	72.23
05-Feb-2019 I	8,148	76,125	371168	34-045-010	Reseal Oil Filler & Level Indicator	06-Feb-2019 08:34:22	WSHSHP	I	DON	208.96
05-Feb-2019 I	8,148	76,125	371168	03-013-003	Replace Brake Chamber - Parking	06-Feb-2019 08:34:22	WSHSHP	I	DON	958.97
05-Feb-2019 I	8,148	76,125	371168	03-034-010	Replace Socket - Trailer Light Cord	06-Feb-2019 08:34:22	WSHSHP	I	DON	281.39
05-Feb-2019 I	8,148	76,125	371168	03-044-023	Replace Primer Pump (Hand)	06-Feb-2019 08:34:22	WSHSHP	I	DON	242.70
04-Mar-2019 I	8,148	76,125	374988	24-025	Repair Transfer Case	17-Oct-2019 11:20:25	PIPE03	B	DON	476.78
04-Mar-2019 I	8,148	76,125	374988	03-018-010	Replace Stud - Wheel	17-Oct-2019 11:20:25	PIPE03	B	DON	315.88
04-Mar-2019 I	8,148	76,125	374988	03-032-002	Replace Starter	17-Oct-2019 11:20:25	PIPE03	B	DON	314.84
04-Mar-2019 I	8,148	76,125	374988	24-013-010	Repair Air Brake Valve	17-Oct-2019 11:20:25	PIPE03	B	DON	29.18



# Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
<b>Unit No: G0247 - 1999 INTERNATIONAL 4900</b>										
04-Mar-2019 1	8,148	76,125	374988	03-017-001	Replace Tire - Pneumatic	17-Oct-2019 11:20:25	PIPE03	N	DON	1,234.53
04-Mar-2019 1	8,148	76,125	375007	03-052-003	Replace Radio Equipment	04-Mar-2019 12:50:12	ELEC02	Q	DON	3.72
10-Apr-2019 1			408384	03-044-002	Replace Filters	10-Apr-2019 23:00:00	PIPE03	B	DON	7.88
14-May-2019 1	8,148		385701	24-045-001	Repair Front Covers	14-May-2019 13:19:17	WSHSHP	O	DON	8,380.19
14-Aug-2019 1	8,633	91,551	398671	03-042-016	Replace Fan Clutch	14-Aug-2019 12:32:42	WSHSHP	O	DON	0.00
14-Aug-2019 1	8,633	91,551	398671	03-049-004	Replace ECM Sensor	14-Aug-2019 12:32:42	WSHSHP	O	DON	438.44
14-Aug-2019 1	8,633	91,551	398671	24-044-003	Repair Fuel Pump	14-Aug-2019 12:32:42	WSHSHP	O	DON	1,390.65
18-Dec-2019 0	8,634		417411	03-017-001	Replace Tire - Pneumatic	20-Feb-2020 08:24:13	WSHSHP	N	DON	1,513.18
20-Feb-2020 0	8,637	91,584	427217	01-013	Adjust Brakes	24-Feb-2020 13:17:07	WSHSHP	P	DON	120.67
20-Feb-2020 0	8,637	91,584	427217	03-013-024	Replace Air Tank (Pri / Sec / Wet)	24-Feb-2020 13:17:07	WSHSHP	I	DON	1,301.62
20-Feb-2020 0	8,637	91,584	427217	03-013-029	Replace Valve - Air Brake	24-Feb-2020 13:17:07	WSHSHP	I	DON	593.60
20-Feb-2020 0	8,637	91,584	427217	03-043-007	Replace Exhaust Pipe/Elbow	24-Feb-2020 13:17:07	WSHSHP	I	DON	652.19
20-Feb-2020 0	8,637	91,584	427217	03-078-009	Replace Mud Flaps and Hanger Brackets	24-Feb-2020 13:17:07	WSHSHP	I	DON	225.49
20-Feb-2020 0	8,637	91,584	427217	03-079-009	Replace Tape - Reflective, Conspicuity	24-Feb-2020 13:17:07	WSHSHP	I	DON	105.58
20-Feb-2020 0	8,637	91,584	427217	06-100-DOT	Inspect DOT Federal Inspection	24-Feb-2020 13:17:07	WSHSHP	P	DON	226.81
20-Feb-2020 0	8,637	91,584	427217	24-034	Repair Lighting System	24-Feb-2020 13:17:07	WSHSHP	I	DON	553.47
20-Feb-2020 0	8,637	91,584	427217	34-043-002	Reseal Exhaust Manifold	24-Feb-2020 13:17:07	WSHSHP	I	DON	1,589.12
29-Apr-2020 1	8,637	91,585	438568	03-049-004	Replace ECM Sensor	06-May-2020 09:39:58	WSHSHP	O	DON	1,316.27
19-May-2020 1	8,646	91,681	441508	03-052-003	Replace Radio Equipment	19-May-2020 15:38:06	ELEC02	Q	DON	674.56
09-Jul-2020 11	8,712	92,136	449698	03-032-002	Replace Starter	17-Jul-2020 09:31:38	WSHSHP	O	DON	626.78
21-Oct-2020 1	8,778	92,886	467939	02-071	Clean Body	21-Oct-2020 23:00:00	WSHSHP	Q	DON	161.46
21-Oct-2020 1	8,778	92,886	467939	06-100-PMA	Inspect A PMI	21-Oct-2020 23:00:00	WSHSHP	P	DON	571.29
21-Oct-2020 1	8,778	92,886	467939	24-025-001	Repair Transfer Case Assembly	21-Oct-2020 23:00:00	WSHSHP	B	DON	865.89
21-Oct-2020 1	8,778	92,886	467939	06-100-DOT	Inspect DOT Federal Inspection	21-Oct-2020 23:00:00	WSHSHP	P	DON	75.98
21-Oct-2020 1	8,778	92,886	467939	03-002-010	Replace Mirrors	21-Oct-2020 23:00:00	WSHSHP	B	DON	156.00
21-Oct-2020 1	8,778	92,886	467939	03-013-015	Replace Desiccant Cartridge Kit - Air	21-Oct-2020 23:00:00	WSHSHP	P	DON	172.08
21-Oct-2020 1	8,778	92,886	467939	03-041-007	Replace Filter - Outer	21-Oct-2020 23:00:00	WSHSHP	P	DON	124.39
21-Oct-2020 1	8,778	92,886	467939	24-002-004	Repair Hood	21-Oct-2020 23:00:00	WSHSHP	B	DON	68.79
21-Oct-2020 1	8,778	92,886	467939	34-026	Reseal Transmission - Main, Manual	21-Oct-2020 23:00:00	WSHSHP	I	DON	501.33

# Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: G0247 - 1999 INTERNATIONAL 4900										
21-Oct-2020 1	8,778	92,886	467939	24-013-009	Repair Air Compressor	21-Oct-2020 23:00:00	WSHSHP	N	DON	75.88
21-Oct-2020 1	8,778	92,886	467939	03-044-014	Replace Injectors - Electronic	21-Oct-2020 23:00:00	WSHSHP	B	DON	4,203.61
21-Oct-2020 1	8,778	92,886	467939	01-043-004	Adjust Turbocharger	21-Oct-2020 23:00:00	WSHSHP	I	DON	46.59
21-Oct-2020 1	8,778	92,886	467939	03-002-008	Replace Instrument Panel	21-Oct-2020 23:00:00	WSHSHP	N	DON	1,091.68
21-Oct-2020 1	8,778	92,886	467939	03-045-009	Replace Oil Pump & Distribution System	21-Oct-2020 23:00:00	WSHSHP	B	DON	927.83
21-Oct-2020 1	8,778	92,886	467939	24-034-023	Repair Harness - Rear	21-Oct-2020 23:00:00	WSHSHP	B	DON	0.00
21-Oct-2020 1	8,778	92,886	467939	14-034-014	Install Auxiliary Work / Flood Light	21-Oct-2020 23:00:00	WSHSHP	B	DON	803.27
19-May-2021 1			507702	03-052-003	Replace Radio Equipment	19-May-2021 15:03:49	ELECO3	Q	DON	872.16
27-Jul-2021 15			521210	03-044-003	Replace Fuel Pump	06-Aug-2021 14:59:00	PIPE13	B	DON	402.93
27-Jul-2021 15			521210	03-022-008	Replace Pinion Seal	06-Aug-2021 14:59:00	PIPE13	B	DON	125.46
08-Feb-2022 1			566669	03-017-001	Replace Tire - Pneumatic	17-Feb-2022 23:00:00	WSHSHP	N	DON	1,554.11
16-Mar-2022 1			574888	03-063-003	Replace Transceiver - GPS Tracker	16-Mar-2022 10:31:48	ELECO3	Q	DON	408.03
26-Apr-2022 1			584536	03-014-003	Replace Engine Mountings	05-May-2022 23:00:00	WSHSHP	N	DON	919.16
26-Apr-2022 1			584536	03-001-016	Replace Filter - Cab Ventilation	05-May-2022 23:00:00	WSHSHP	P	DON	10.25
26-Apr-2022 1			584536	03-022-008	Replace Pinion Seal	05-May-2022 23:00:00	WSHSHP	N	DON	1,087.16
26-Apr-2022 1			584536	03-018-011	Replace Seal - Wheel	05-May-2022 23:00:00	WSHSHP	N	DON	557.71
26-Apr-2022 1			584536	03-071-001	Replace Floor / Decking / Flatbed	05-May-2022 23:00:00	WSHSHP	N	DON	5,356.88
26-Apr-2022 1			584536	06-100-DOT	Inspect DOT Federal Inspection	26-Apr-2022 16:33:00	WSHSHP	P	DON	1.11
26-Apr-2022 1			584536	06-100-PMA	Inspect A PMI	05-May-2022 23:00:00	WSHSHP	P	DON	172.67
26-Apr-2022 1			584536	03-002-035	Replace Windshield Wiper & Washer	05-May-2022 23:00:00	WSHSHP	N	DON	13.86
26-Apr-2022 1			584536	03-041-001	Replace Air Cleaner	05-May-2022 23:00:00	WSHSHP	P	DON	96.74
26-Apr-2022 1			584536	02-071	Clean Body	05-May-2022 23:00:00	WSHSHP	Q	DON	111.40
26-Apr-2022 1			584536	24-043-007	Repair Exhaust Pipe/Elbow	05-May-2022 23:00:00	WSHSHP	N	DON	172.67
26-Apr-2022 1			584536	24-013-024	Repair Air Tank (Pri / Sec / Wet)	05-May-2022 23:00:00	WSHSHP	N	DON	310.66
26-Apr-2022 1			584536	24-034-006	Repair Warning Lamps - Special Application	05-May-2022 23:00:00	WSHSHP	B	DON	528.54
26-Apr-2022 1			584536	03-034-004	Replace Clearance & Marker Lamps	05-May-2022 23:00:00	WSHSHP	B	DON	144.21
26-Apr-2022 1			584536	38-100-PMA	Service A PMI	05-May-2022 23:00:00	WSHSHP	P	DON	482.05
26-Apr-2022 1			584536	34-025	Reseal Transfer Case	05-May-2022 23:00:00	WSHSHP	N	DON	624.07
26-Apr-2022 1			584536	34-026	Reseal Transmission - Main, Manual	05-May-2022 23:00:00	WSHSHP	I	DON	244.11

# Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
<b>Unit No: G0247 - 1999 INTERNATIONAL 4900</b>										
26-Apr-2022 1			584536	34-045	Reseal Power Plant	05-May-2022 23:00:00	WSHSHP	N	DON	2,310.47
26-Apr-2022 1			584536	24-013-007	Repair Brake Lines & Fittings - Hydraulic & Air	05-May-2022 23:00:00	WSHSHP	N	DON	172.67
26-Apr-2022 1			584536	03-013-015	Replace Desiccant Cartridge Kit - Air	05-May-2022 23:00:00	WSHSHP	P	DON	153.79
26-Apr-2022 1			584536	03-002-010	Replace Mirrors	05-May-2022 23:00:00	WSHSHP	N	DON	65.95
01-Jun-2022 1:			607672	03-013-023	Replace Air Governor	01-Sep-2022 08:08:38	WSHSHP	N	DON	728.29
01-Jun-2022 1:			607672	03-034-002	Replace Stop, Tail, Turn & License	01-Sep-2022 08:08:38	WSHSHP	N	DON	135.13
01-Jun-2022 1:			607672	24-024-002	Repair Drive Shaft, Behind Main Transmission	01-Sep-2022 08:08:38	WSHSHP	N	DON	1,828.03
01-Jun-2022 1:			607672	03-013-022	Replace Glad Hands (Service/Emergency)	01-Sep-2022 08:08:38	WSHSHP	B	DON	198.95
31-Oct-2022 1			629236	24-017-001	Repair Tire - Pneumatic	11-Nov-2022 13:29:59	WSHSHP	N	DON	150.86
10-Apr-2024 1			751870	06-100-009	Inspect Safety Check	10-Apr-2024 16:13:31	BTRUCK	P	DON	157.34
26-Jun-2024 01			768864	02-002	Clean Cab & Sheet Metal	02-Jul-2024 12:15:01	BSETUP	Z	DON	279.71
26-Jun-2024 01			768864	25-051	Remove General Accessories	28-Jun-2024 09:53:45	BSETUP	Z	DON	244.64

Unit No: G0247

Count: 302

138,831.49