

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: B3249 - 2017 F250 CREWCAB										
18-Sep-2017 0	169	8	305344	01-042	Adjust Cooling System	26-Sep-2017 09:58:23	BTRUCK	I	DON	74.12
18-Sep-2017 0	169	8	305344	06-100-DOT	Inspect DOT Federal Inspection	26-Sep-2017 08:25:15	BTRUCK	P	DON	55.24
18-Sep-2017 0	169	8	305344	14-002-003	Install Running Boards / Step Tubes	25-Sep-2017 16:37:00	BSETUP	C	DON	413.29
18-Sep-2017 0	169	8	305344	14-002-063	Install Computer Stand / Dock	25-Sep-2017 14:19:53	BSETUP	C	DON	339.85
18-Sep-2017 0	169	8	305344	14-013-012	Install Electric Brakes	26-Sep-2017 11:20:38	BTRUCK	C	DON	142.05
18-Sep-2017 0	169	8	305344	14-034-006	Install Warning Lamps - Special Application	25-Sep-2017 11:09:10	BSETUP	C	DON	532.14
18-Sep-2017 0	169	8	305344	14-052-003	Install Radio Equipment	25-Sep-2017 09:15:32	BSETUP	C	DON	892.82
18-Sep-2017 0	169	8	305344	14-052-014	Install Cellular Telephone Accessories	25-Sep-2017 12:15:19	BSETUP	C	DON	61.91
18-Sep-2017 0	169	8	305344	14-052-015	Install Power Inverter/Converter	25-Sep-2017 08:36:28	BSETUP	C	DON	249.69
18-Sep-2017 0	169	8	305344	14-053-004	Install Safety Equipment	25-Sep-2017 17:00:39	BSETUP	C	DON	0.00
18-Sep-2017 0	169	8	305344	14-053-005	Install Markings - Vehicle - Decals	25-Sep-2017 17:00:25	BSETUP	C	DON	29.76
18-Sep-2017 0	169	8	305344	14-053-014	Install Floor Mats	25-Sep-2017 14:20:25	BSETUP	C	DON	117.64
18-Sep-2017 0	169	8	305344	14-063-003	Install Transceiver - GPS Tracker	25-Sep-2017 14:47:22	BSETUP	Q	DON	72.34
18-Sep-2017 0	169	8	305344	14-071-011	Install Scuff Liner / Bed Mat	25-Sep-2017 14:21:09	BSETUP	C	DON	121.50
18-Sep-2017 0	169	8	305344	14-078-009	Install Mud Flaps and Hanger Brackets	25-Sep-2017 15:15:26	BSETUP	C	DON	78.06
18-Sep-2017 0	169	8	305344	14-079-002	Install Headache Rack	25-Sep-2017 14:21:30	BSETUP	C	DON	241.69
18-Sep-2017 0	169	8	305344	14-510-002	Install Tool Box	25-Sep-2017 14:21:48	BSETUP	C	DON	400.11
16-Jan-2018 11	29,476	8	319767	38-040	Service Engine / Motor Systems Group	16-Jan-2018 13:00:00	HARFLD	P	DON	142.66
16-Jan-2018 11	29,476	8	319767	14-506-001	Install Fuel Tank	02-Apr-2018 06:54:46	HARFLD	E	DON	276.68
16-Jan-2018 11	29,476	8	319767	06-100-PMA	Inspect A PMI	02-Apr-2018 06:49:12	HARFLD	P	DON	65.06
16-Jan-2018 11	29,476	8	319767	03-034-003	Replace Signal, Parking, Backup Lamps	02-Apr-2018 07:22:19	HARFLD	B	DON	88.80
30-Apr-2018 0	29,476	8	333591	03-017-001	Replace Tire - Pneumatic	30-Apr-2018 14:33:15	HARFLD	O	DON	1,070.71
25-Jul-2018 00	48,564		346228	03-002-024	Replace Glass / Windshield	25-Jul-2018 00:00:00	HARFLD	E	DON	745.54
25-Jul-2018 00	48,564		346228	03-002-035	Replace Windshield Wiper & Washer	28-Nov-2018 06:57:08	HARFLD	O	DON	76.60
25-Jul-2018 00	48,564		346228	06-100-PMA	Inspect A PMI	20-Aug-2018 05:49:20	HARFLD	P	DON	80.12
05-Dec-2018 0	48,564		363047	03-002-024	Replace Glass / Windshield	17-Jan-2019 14:22:42	HARFLD	E	DON	858.57
05-Dec-2018 0	48,564		363047	03-013-001	Replace Front Brakes & Drums	30-Jan-2019 16:10:26	BVLOFC	I	DON	1,186.20
05-Dec-2018 0	48,564		363047	03-015	Replace Steering	30-Jan-2019 16:10:30	BVLOFC	I	DON	201.32
05-Dec-2018 0	48,564		363047	03-015-003	Replace Steering Gear	30-Jan-2019 16:10:36	BVLOFC	O	DON	1,360.89

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: B3249 - 2017 F250 CREWCAB										
05-Dec-2018 0	48,564		363047	03-015-005	Replace Power Steering Pump	30-Jan-2019 16:10:18	HARFLD	B	DON	695.07
05-Dec-2018 0	48,564		363047	03-034-002	Replace Stop, Tail, Turn & License	30-Jan-2019 16:10:33	BVLOFC	O	DON	510.81
05-Dec-2018 0	48,564		363047	06-100-PMA	Inspect A PMI	30-Jan-2019 16:10:22	BVLOFC	P	DON	60.84
05-Feb-2019 0	63,200		371226	06-100-PMA	Inspect A PMI	15-Mar-2019 06:21:04	HARFLD	P	DON	116.61
05-Feb-2019 0	63,200		371226	03-032-001	Replace Battery	17-Feb-2019 14:08:26	HARFLD	B	DON	193.04
05-Feb-2019 0	63,200		371226	03-017-001	Replace Tire - Pneumatic	11-Feb-2019 07:21:00	HARFLD	I	DON	1,126.20
21-May-2019 0	71,911		387041	03-032-001	Replace Battery	24-May-2019 05:03:43	HARFLD	I	DON	171.51
21-May-2019 0	71,911		387041	06-100-PMA	Inspect A PMI	24-May-2019 05:02:35	HARFLD	P	DON	0.00
21-May-2019 0	71,911		387041	38-100-PMA	Service A PMI	24-May-2019 05:02:35	HARFLD	P	DON	85.57
05-Sep-2019 0	80,590		401566	03-044-018	Replace Fuel Hose / Line	11-Sep-2019 14:00:56	HARFLD	O	DON	138.62
05-Sep-2019 0	80,590		401566	06-100-DOT	Inspect DOT Federal Inspection	05-Sep-2019 17:53:31	HARFLD	P	DON	103.67
05-Sep-2019 0	80,590		401566	06-100-PMA	Inspect A PMI	05-Sep-2019 08:13:05	HARFLD	P	DON	34.56
05-Sep-2019 0	80,590		401566	38-100-PMA	Service A PMI	05-Sep-2019 17:59:34	HARFLD	P	DON	175.64
13-Jan-2020 0			420729	38-100-PMA	Service A PMI	17-Jan-2020 08:46:25	HARFLD	P	DON	180.89
13-Jan-2020 0			420729	06-100-PMA	Inspect A PMI	17-Jan-2020 08:46:01	HARFLD	P	DON	34.56
13-Jan-2020 0			420729	06-013-002	Inspect Rear Brakes & Drums	31-Jan-2020 08:10:07	HARFLD	O	DON	981.35
13-Jan-2020 0			420729	03-013-002	Replace Rear Brakes & Drums	17-Feb-2020 05:56:32	HARFLD	I	DON	0.00
13-Jan-2020 0			420729	B3-049-002	Program ECM Module	17-Feb-2020 05:56:32	BVLOFC	I	DON	0.00
13-Jan-2020 0			420729	09-015	Align Steering	31-Jan-2020 08:10:39	BVLOFC	I	DON	189.89
13-Jan-2020 0			420729	03-017-001	Replace Tire - Pneumatic	31-Jan-2020 08:10:32	BVLOFC	O	DON	845.04
13-Jan-2020 0			420729	03-033-003	Replace Spark Plugs	31-Jan-2020 08:10:20	BVLOFC	I	DON	997.49
13-Jan-2020 0			420729	03-041-007	Replace Filter - Outer	31-Jan-2020 08:10:27	BVLOFC	P	DON	0.00
13-Jan-2020 0			420729	03-044-003	Replace Fuel Pump	31-Jan-2020 08:10:47	BVLOFC	I	DON	611.54
13-Jan-2020 0			420729	24-002-018	Repair Cab Or Front Door Mechanism	31-Jan-2020 08:11:02	BVLOFC	W	DON	0.00
13-Jan-2020 0			420729	24-042-009	Repair Coolant Pre-Heater- Electrical	31-Jan-2020 08:10:58	BVLOFC	W	DON	0.00
13-Jan-2020 0			420729	06-030	Inspect Electrical Group	17-Feb-2020 05:56:32	HARFLD	O	DON	69.12
14-Feb-2020 0			426481	24-037-021	Repair Circuit Breaker/Fuse - Multiple Use	03-Mar-2020 10:15:02	HARFLD	I	DON	34.56
14-Feb-2020 0	95,534		426481	06-037-021	Inspect Circuit Breaker/Fuse - Multiple Use	03-Mar-2020 10:14:50	HARFLD	O	DON	34.56
14-Feb-2020 0	95,534		426481	06-100-PMA	Inspect A PMI	03-Mar-2020 10:11:16	HARFLD	P	DON	207.35

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: B3249 - 2017 F250 CREWCAB										
14-Feb-2020 0	95,534		426481	38-100-PMA	Service A PMI	03-Mar-2020 10:14:41	HARFLD	P	DON	191.48
14-Feb-2020 0	95,534		426481	03-001-016	Replace Filter - Cab Ventilation	03-Mar-2020 10:18:49	HARFLD	I	DON	52.86
14-Feb-2020 0	95,534		426481	03-016-003	Replace Shock Absorber - Front	03-Mar-2020 10:25:19	HARFLD	P	DON	178.72
14-Feb-2020 0	95,534		426481	03-016-006	Replace Shock Absorber - Rear	03-Mar-2020 10:25:30	HARFLD	P	DON	208.16
14-Feb-2020 0	95,534		426481	03-015-012	Replace Steering Stability System	03-Mar-2020 10:25:03	HARFLD	P	DON	119.86
14-Feb-2020 0	95,534		426481	14-059-002	Install Pintle Hook Assembly	10-Mar-2020 17:55:12	HARFLD	E	DON	346.97
14-Feb-2020 0	95,534		426481	03-034-002	Replace Stop, Tail, Turn & License	10-Mar-2020 17:55:25	HARFLD	E	DON	254.08
14-Feb-2020 0	95,534		426481	03-002-003	Replace Running Boards / Step Tubes	27-Mar-2020 08:31:17	HARFLD	O	DON	499.16
14-Feb-2020 0	95,534		426481	24-002-003	Repair Running Boards / Step Tubes		HARFLD	O	WR	46.27
10-Jun-2020 1	111,551		444744	03-002-035	Replace Windshield Wiper & Washer	10-Jun-2020 11:41:42	BVLOFC	O	DON	327.37
10-Jun-2020 1	111,551		444744	03-013-001	Replace Front Brakes & Drums	10-Jun-2020 11:41:42	BVLOFC	O	DON	516.64
10-Jun-2020 1	111,551		444744	03-015-004	Replace Steering Linkage	10-Jun-2020 11:41:42	BVLOFC	O	DON	479.11
10-Jun-2020 1	111,551		444744	03-045-026	Replace Tensioner - Engine Belts	10-Jun-2020 11:41:42	BVLOFC	O	DON	365.73
10-Jun-2020 1	111,551		444744	09-015	Align Steering	10-Jun-2020 11:41:42	BVLOFC	I	DON	153.54
27-Jul-2020 05	116,187		452568	06-100-PMA	Inspect A PMI	28-Jul-2020 10:04:22	BTRUCK	P	DON	0.00
27-Jul-2020 05	116,187		452568	38-100-PMA	Service A PMI	28-Jul-2020 10:04:22	BVLOFC	P	DON	49.97
12-Oct-2020 0	120,473		466486	03-002-024	Replace Glass / Windshield	14-Oct-2020 09:18:07	CTFLD	B	DON	443.23
12-Oct-2020 0	120,473		466486	03-017-001	Replace Tire - Pneumatic	14-Oct-2020 09:10:23	CTFLD	P	DON	1,264.90
26-Oct-2020 2	122,283		469821	24-017-001	Repair Tire - Pneumatic	02-Nov-2020 08:53:17	CTFLD	B	DON	155.04
24-Nov-2020 C			473608	03-015-004	Replace Steering Linkage	24-Nov-2020 11:47:07	BVLOFC	I	DON	305.81
24-Nov-2020 C			473608	03-034-003	Replace Signal, Parking, Backup Lamps	24-Nov-2020 11:47:07	BVLOFC	I	DON	144.94
24-Nov-2020 C			473608	06-100-PMA	Inspect A PMI	24-Nov-2020 11:47:07	BTRUCK	P	DON	0.00
24-Nov-2020 C			473608	09-015	Align Steering	24-Nov-2020 11:47:07	BVLOFC	I	DON	139.61
24-Nov-2020 C			473608	38-100-PMA	Service A PMI	24-Nov-2020 11:47:07	BVLOFC	P	DON	69.33
07-Dec-2020 0	124,771		476237	24-042-006	Repair Thermostat	16-Dec-2020 07:10:40	CTFLD	B	DON	34.56
07-Dec-2020 0	124,771		476237	95-040	Travel Engine / Motor Systems Group	10-Dec-2020 08:37:32	CTFLD	B	DON	34.56
06-Jan-2021 0	129,695		480295	35-045	Diagnose Power Plant	07-Jan-2021 14:33:40	BVLOFC	O	DON	490.79
06-Jan-2021 0	129,695		480295	03-001-008	Replace Motor - Blower	07-Jan-2021 14:33:40	BVLOFC	O	DON	615.73
07-Jan-2021 0	129,695		484094	24-017-001	Repair Tire - Pneumatic	23-Jan-2021 09:03:02	CTFLD	B	DON	189.74

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: B3249 - 2017 F250 CREWCAB										
21-Jan-2021 10:00:00	129,695		485572	24-002-022	Repair Rear Door Mechanism	30-Jan-2021 14:43:55	CTFLD	B	DON	206.51
13-Apr-2021 0 129,695			500065	06-100-PMA	Inspect A PMI	18-Apr-2021 06:23:39	SCHED	P	DON	87.46
13-Apr-2021 0 129,695			500065	38-100-PMA	Service A PMI	18-Apr-2021 06:23:45	NHFLD	P	DON	144.81
13-Apr-2021 0 129,695			500065	03-002-035	Replace Windshield Wiper & Washer	18-Apr-2021 06:23:58	NHFLD	I	DON	98.67
13-Apr-2021 0 129,695			500065	25-002-024	Remove Glass / Windshield	18-Apr-2021 07:47:01	NHFLD	I	DON	94.87
13-Apr-2021 0 129,695			500065	03-044-018	Replace Fuel Hose / Line	18-Apr-2021 07:47:06	NHFLD	I	DON	94.87
13-Apr-2021 0 129,695			500065	03-034-002	Replace Stop, Tail, Turn & License	18-Apr-2021 07:47:15	NHFLD	I	DON	94.87
13-Apr-2021 0 129,695			500065	03-002-037	Replace Seat Assembly	18-Apr-2021 07:47:23	NHFLD	I	DON	313.08
13-Apr-2021 0 129,695			500065	03-013-001	Replace Front Brakes & Drums	18-May-2021 11:49:54	NHFLD	I	DON	299.28
13-Apr-2021 0 129,695			500065	03-013-002	Replace Rear Brakes & Drums	18-Apr-2021 08:13:56	NHFLD	I	DON	460.35
13-Apr-2021 0 129,695			500065	03-001-016	Replace Filter - Cab Ventilation	18-Apr-2021 08:14:05	NHFLD	I	DON	142.30
13-Apr-2021 0 129,695			500065	03-032-001	Replace Battery	18-May-2021 11:49:54	NHFLD	I	DON	160.74
28-Jun-2021 0 129,695			515849	24-044-016	Repair Tank - Fuel Auxiliary	30-Jun-2021 07:31:21	NHFLD	O	DON	189.74
09-Jul-2021 00 129,695			523085	06-100-PMA	Inspect A PMI	09-Jul-2021 00:00:00	SCHED	P	DON	0.00
09-Jul-2021 00 129,695			523085	38-100-PMA	Service A PMI	09-Jul-2021 00:00:00	SCHED	P	DON	110.75
09-Jul-2021 05 129,695			517495	06-100-PMA	Inspect A PMI	11-Jul-2021 10:58:39	SCHED	P	DON	43.73
09-Jul-2021 05 129,695			517495	06-100-PMB	Inspect B PMI	11-Jul-2021 10:59:49	SCHED	P	DON	43.73
09-Jul-2021 05 129,695			517495	24-052-015	Repair Power Inverter/Converter	11-Jul-2021 11:01:09	NHFLD	O	DON	189.74
09-Jul-2021 05 129,695			517495	38-100-PMA	Service A PMI	11-Jul-2021 11:01:05	SCHED	P	DON	195.30
24-Sep-2021 0 129,695			534038	06-100-PMA	Inspect A PMI	26-Sep-2021 10:17:10	SCHED	P	DON	87.46
24-Sep-2021 0 129,695			534038	38-100-PMA	Service A PMI	26-Sep-2021 10:17:06	SCHED	P	DON	197.65
29-Sep-2021 0 129,695			535391	03-051	Replace General Accessories	04-Oct-2021 12:29:19	NHFLD	P	DON	96.90
29-Sep-2021 0 129,695			535391	06-100-DOT	Inspect DOT Federal Inspection	29-Sep-2021 10:00:00	NHFLD	P	DON	94.87
29-Sep-2021 0 129,695			535391	95-100-DOT	Travel DOT Federal Inspection	29-Sep-2021 11:00:00	NHFLD	I	DON	94.87
12-Oct-2021 0 151,824			538482	03-002-035	Replace Windshield Wiper & Washer	12-Oct-2021 06:35:40	BVLOFC	I	DON	30.63
12-Oct-2021 0 151,824			538482	06-100-PMA	Inspect A PMI	12-Oct-2021 06:35:40	BVLOFC	P	DON	0.00
12-Oct-2021 0 151,824			538482	38-100-PMA	Service A PMI	12-Oct-2021 06:35:40	BVLOFC	P	DON	130.30
10-Nov-2021 0 151,824			546043	03-017-001	Replace Tire - Pneumatic	15-Nov-2021 09:40:02	NHFLD	I	DON	1,112.14
10-Nov-2021 0 151,824			546043	03-015-012	Replace Steering Stability System	15-Nov-2021 09:39:59	NHFLD	I	DON	54.87

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: B3249 - 2017 F250 CREWCAB										
10-Nov-2021 C	151,824		546043	06-100-PMB	Inspect B PMI	15-Nov-2021 09:39:38	NHFLD	P	DON	94.87
10-Nov-2021 C	151,824		546043	38-100-PMB	Service B PMI	15-Nov-2021 09:39:41	NHFLD	P	DON	243.67
10-Nov-2021 C	151,824		546043	03-015-004	Replace Steering Linkage	15-Nov-2021 09:39:51	NHFLD	P	DON	925.44
10-Nov-2021 C	151,824		546043	24-040	Repair Engine / Motor Systems Group	15-Nov-2021 09:39:44	NHFLD	P	DON	616.08
10-Nov-2021 C	151,824		546043	35-015-004	Diagnose Steering Linkage	15-Nov-2021 09:39:48	NHFLD	P	DON	47.43
10-Nov-2021 C	151,824		546043	35-040	Diagnose Engine / Motor Systems Group	14-Nov-2021 17:09:26	NHFLD	P	DON	189.74
10-Nov-2021 C	151,824		546043	38-027	Service Transmission - Main, Automatic	15-Nov-2021 09:39:56	NHFLD	P	DON	192.62
10-Nov-2021 C	151,824		546043	38-044-007	Service Throttle Controls	15-Nov-2021 09:39:54	NHFLD	P	DON	47.43
22-Dec-2021 0	151,824		555647	03-063-003	Replace Transceiver - GPS Tracker	19-Feb-2022 08:32:26	NHFLD	Q	DON	357.20
22-Dec-2021 0	151,824		555647	06-100-PMB	Inspect B PMI	19-Feb-2022 08:32:26	NHFLD	P	DON	189.74
22-Dec-2021 0	151,824		555647	38-100-PMA	Service A PMI	19-Feb-2022 08:32:26	NHFLD	P	DON	291.90
19-Feb-2022 0	171,724		568384	03-017-001	Replace Tire - Pneumatic	27-Feb-2022 12:20:02	NHFLD	O	DON	1,037.34
19-Feb-2022 0	171,724		568384	24-001-002	Repair Heating & Ventilating	14-Mar-2022 05:28:13	NHFLD	B	DON	632.53
17-Mar-2022 1	173,634		575312	03-016	Replace Suspension	17-Mar-2022 14:20:54	BVLOFC	I	DON	0.00
17-Mar-2022 1	173,634		575312	06-100-PMA	Inspect A PMI	17-Mar-2022 14:20:54	BVLOFC	P	DON	0.00
17-Mar-2022 1	173,634		575312	09-015	Align Steering	17-Mar-2022 14:20:54	BVLOFC	I	DON	110.29
17-Mar-2022 1	173,634		575312	38-100-PMA	Service A PMI	17-Mar-2022 14:20:54	BVLOFC	P	DON	69.21
20-May-2022 C	173,634		590505	06-100-PMA	Inspect A PMI	23-May-2022 05:59:44	SCHED	P	DON	87.46
20-May-2022 C	173,634		590505	06-100-PMB	Inspect B PMI	23-May-2022 05:59:53	SCHED	P	DON	87.46
20-May-2022 C	173,634		590505	03-034-002	Replace Stop, Tail, Turn & License	23-May-2022 05:59:49	NHFLD	I	DON	47.43
20-May-2022 C	173,634		590505	24-002-003	Repair Running Boards / Step Tubes	23-May-2022 05:59:59	HARFLD	O	DON	47.43
20-May-2022 C	173,634		590505	38-100-PMA	Service A PMI	23-May-2022 06:00:03	SCHED	P	DON	188.06
20-May-2022 C	173,634		590505	03-034-001	Replace Headlamps / Fog Lamps	23-May-2022 06:00:07	NHFLD	I	DON	47.43
29-Jul-2022 13	173,634		606004	06-100-PMA	Inspect A PMI	29-Jul-2022 13:37:56	NHFLD	P	DON	0.00
29-Jul-2022 13	173,634		606004	38-100-PMA	Service A PMI	29-Jul-2022 13:37:56	NHFLD	P	DON	86.63
29-Aug-2022 C	173,634		612595	24-015-001	Repair Steering Wheel	01-Sep-2022 21:06:43	NHFLD	I	DON	155.13
29-Aug-2022 C	173,634		612595	24-034-004	Repair Clearance & Marker Lamps	01-Sep-2022 20:33:12	NHFLD	I	DON	94.87
29-Aug-2022 C	173,634		612595	03-013-001	Replace Front Brakes & Drums	01-Sep-2022 20:33:15	NHFLD	I	DON	781.28
29-Aug-2022 C	173,634		612595	06-100-DOT	Inspect DOT Federal Inspection	01-Sep-2022 20:33:06	NHFLD	P	DON	94.87

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: B3249 - 2017 F250 CREWCAB										
27-Oct-2022 0	173,634		628268	06-024-002	Inspect Drive Shaft, Behind Main Transmission	30-Oct-2022 12:22:37	NHFLD	G	DON	189.74
27-Oct-2022 0	173,634		628268	31-017-001	Rotate Tire - Pneumatic	30-Oct-2022 12:22:41	NHFLD	I	DON	94.87
07-Nov-2022 C	173,634		632077	24-017-001	Repair Tire - Pneumatic	13-Nov-2022 22:32:45	NHFLD	E	DON	94.87
07-Nov-2022 C	173,634		632077	95-017-001	Travel Tire - Pneumatic	13-Nov-2022 22:32:36	NHFLD	E	DON	94.87
13-Mar-2023 0	173,634		659792	03-013-002	Replace Rear Brakes & Drums	20-Mar-2023 07:11:58	NHFLD	I	DON	639.15
13-Mar-2023 0	173,634		659792	03-013-028	Replace Shoe - Parking Brake	20-Mar-2023 07:12:35	NHFLD	I	DON	247.94
13-Mar-2023 0	173,634		659792	03-013-038	Replace Caliper - Rear	20-Mar-2023 07:13:15	NHFLD	I	DON	417.22
13-Mar-2023 0	173,634		659792	03-017-001	Replace Tire - Pneumatic	20-Mar-2023 06:56:48	NHFLD	I	DON	1,371.90
13-Mar-2023 0	173,634		659792	06-100-PMA	Inspect A PMI	20-Mar-2023 07:15:45	NHFLD	P	DON	43.73
13-Mar-2023 0	173,634		659792	06-100-PMB	Inspect B PMI	20-Mar-2023 07:15:41	NHFLD	P	DON	43.73
13-Mar-2023 0	173,634		659792	38-100-PMA	Service A PMI	20-Mar-2023 07:14:00	NHFLD	P	DON	181.76
14-Jun-2023 0	173,634		682413	06-100-PMA	Inspect A PMI	14-Jun-2023 08:20:00	NHFLD	P	DON	0.00
14-Jun-2023 0	173,634		682413	38-100-PMA	Service A PMI	14-Jun-2023 08:20:00	NHFLD	P	DON	130.85
01-Aug-2023 C	205,633		693190	06-100-PMA	Inspect A PMI	01-Aug-2023 08:14:02	BVLOFC	P	DON	0.00
01-Aug-2023 C	205,633		693190	38-100-PMA	Service A PMI	01-Aug-2023 08:14:02	BVLOFC	P	DON	127.46
11-Sep-2023 0	205,633		705689	06-100-PMB	Inspect B PMI	16-Sep-2023 10:15:12	NHFLD	P	DON	43.73
11-Sep-2023 0	205,633		705689	38-100-PMA	Service A PMI	16-Sep-2023 10:15:06	NHFLD	P	DON	309.92
11-Sep-2023 0	205,633		705689	06-100-DOT	Inspect DOT Federal Inspection	28-Sep-2023 09:27:10	NHFLD	P	DON	87.46
11-Sep-2023 0	205,633		705689	03-034-001	Replace Headlamps / Fog Lamps	07-Oct-2023 10:01:21	NHFLD	O	DON	87.46
11-Dec-2023 0	205,633		727314	03-044-013	Replace Cap - Fuel Tank	17-Dec-2023 09:27:30	NHFLD	N	DON	92.02
11-Dec-2023 0	205,633		727314	03-044-027	Replace Nozzle - Fuel Auxiliary	17-Dec-2023 09:27:25	NHFLD	N	DON	168.18
14-Apr-2024 1	205,633		752581	03-063-003	Replace Transceiver - GPS Tracker	14-Apr-2024 11:53:58	ELEC06	Q	DON	590.43
29-May-2024 1	218,019		762813	06-024-002	Inspect Drive Shaft, Behind Main Transmission	31-May-2024 12:01:50	BVLOFC	G	DON	0.00
29-May-2024 1	218,019		762813	35-043-027	Diagnose Catalytic Converter	31-May-2024 12:01:50	BVLOFC	B	DON	387.40
13-Jul-2024 08	218,025		772125	06-100-009	Inspect Safety Check	13-Jul-2024 09:54:37	BTRUCK	N	DON	49.24
17-Jul-2024 13	218,025		773067	25-051	Remove General Accessories	23-Jul-2024 14:10:26	BSETUP	Z	DON	212.16
17-Jul-2024 13	218,025		773067	02-002	Clean Cab & Sheet Metal	26-Jul-2024 10:41:11	BSETUP	Z	DON	684.87

Unit No: B3249

Count: 172

43,276.97