

# Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
<b>Unit No: B3429 - 2018 F250 CREWCAB</b>										
04-Jun-2018 0:	64	3	338207	06-100-007	Inspect In-Service Inspection		BTRUCK	P	CAN	0.00
04-Jun-2018 0:	64	3	338207	06-100-DOT	Inspect DOT Federal Inspection	08-Jun-2018 08:50:41	BTRUCK	P	DON	26.95
04-Jun-2018 0:	64	3	338207	07-100-007	Lubricate In-Service Inspection		BTRUCK	P	CAN	0.00
04-Jun-2018 0:	64	3	338207	14-002-003	Install Running Boards / Step Tubes	04-Jun-2018 15:25:01	BSETUP	C	DON	428.14
04-Jun-2018 0:	64	3	338207	14-002-059	Install Protector - Tail Gate	04-Jun-2018 14:19:44	BSETUP	C	DON	73.67
04-Jun-2018 0:	64	3	338207	14-002-063	Install Computer Stand / Dock	07-Jun-2018 11:53:26	BSETUP	C	DON	354.96
04-Jun-2018 0:	64	3	338207	14-034-006	Install Warning Lamps - Special Application	07-Jun-2018 12:13:34	BSETUP	C	DON	541.85
04-Jun-2018 0:	64	3	338207	14-051-005	Install Recorder - Fuel & Mileage	08-Jun-2018 10:43:22	BTRUCK	C	DON	1,241.64
04-Jun-2018 0:	64	3	338207	14-052-003	Install Radio Equipment	07-Jun-2018 12:14:29	BSETUP	C	DON	892.04
04-Jun-2018 0:	64	3	338207	14-052-014	Install Cellular Telephone Accessories	07-Jun-2018 11:54:51	BSETUP	C	DON	49.83
04-Jun-2018 0:	64	3	338207	14-052-015	Install Power Inverter/Converter	07-Jun-2018 12:14:13	BSETUP	C	DON	257.92
04-Jun-2018 0:	64	3	338207	14-053-005	Install Markings - Vehicle - Decals	06-Jun-2018 07:29:47	BSETUP	C	DON	170.29
04-Jun-2018 0:	64	3	338207	14-053-014	Install Floor Mats	07-Jun-2018 11:54:07	BSETUP	C	DON	117.82
04-Jun-2018 0:	64	3	338207	14-063-003	Install Transceiver - GPS Tracker	07-Jun-2018 12:13:53	BSETUP	Q	DON	0.07
04-Jun-2018 0:	64	3	338207	14-071-011	Install Scuff Liner / Bed Mat	04-Jun-2018 14:20:47	BSETUP	C	DON	121.57
04-Jun-2018 0:	64	3	338207	14-078-009	Install Mud Flaps and Hanger Brackets	04-Jun-2018 14:44:38	BSETUP	C	DON	82.98
04-Jun-2018 0:	64	3	338207	14-078-014	Install Tarpaulin/ Tonneau Cover	07-Jun-2018 11:58:16	BSETUP	C	DON	575.37
04-Jun-2018 0:	64	3	338207	14-506-001	Install Fuel Tank	04-Jun-2018 12:15:37	BSETUP	C	DON	1,241.38
04-Jun-2018 0:	64	3	338207	14-510-002	Install Tool Box	07-Jun-2018 11:54:25	BSETUP	C	DON	463.19
04-Jun-2018 0:	64	3	338207	14-517	Install Safety Equipment	06-Jun-2018 08:06:43	BSETUP	C	DON	131.39
14-Nov-2018 C	17,601		360636	03-002	Replace Cab & Sheet Metal	14-Dec-2018 14:34:19	BBODY	A	DON	4,686.15
14-Nov-2018 C	17,601		360636	12-002	Refinish Cab & Sheet Metal	14-Dec-2018 14:34:23	BBODY	A	DON	820.86
03-Jan-2019 I:	17,602		366700	06-100-009	Inspect Safety Check	05-Jan-2019 05:43:02	BTRUCK	P	DON	8.36
03-Jan-2019 I:	17,602		366700	38-045	Service Power Plant	04-Jan-2019 13:26:54	BTRUCK	P	DON	103.31
03-Jan-2019 I:	17,602		366700	06-100-DOT	Inspect DOT Federal Inspection	04-Jan-2019 14:58:53	BTRUCK	P	DON	42.80
03-Jan-2019 I:	17,602		366700	06-100-PMB	Inspect B PMI	04-Jan-2019 12:00:12	BTRUCK	P	DON	58.18
03-Jan-2019 I:	17,602		366700	14-051-009	Install Fire Extinguisher	04-Jan-2019 12:33:20	BTRUCK	I	DON	32.60
03-Jan-2019 I:	17,602		366700	03-002-035	Replace Windshield Wiper & Washer	04-Jan-2019 12:46:01	BTRUCK	I	DON	6.96
03-Jan-2019 I:	17,602		366700	03-032-001	Replace Battery	04-Jan-2019 13:40:53	BTRUCK	I	DON	101.19

# Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
<b>Unit No: B3429 - 2018 F250 CREWCAB</b>										
15-Jan-2019 0	17,603		368297	02-002	Clean Cab & Sheet Metal	22-Jan-2019 13:24:24	BSETUP	I	DON	658.69
11-Feb-2019 0	20,201		371927	02-002	Clean Cab & Sheet Metal	11-Feb-2019 11:12:15	BSETUP	I	DON	23.36
11-Feb-2019 0	20,201		371927	14-078-014	Install Tarpaulin/ Tonneau Cover	11-Feb-2019 11:04:50	BSETUP	I	DON	642.28
21-Feb-2019 0	22,579		373450	03-017-001	Replace Tire - Pneumatic	22-Feb-2019 12:34:12	BTRUCK	O	DON	1,030.72
21-Feb-2019 0	22,579		373450	06-100-PMB	Inspect B PMI	22-Feb-2019 07:54:26	BTRUCK	P	DON	47.76
21-Feb-2019 0	22,579		373450	38-045	Service Power Plant	22-Feb-2019 08:13:22	BTRUCK	P	DON	53.38
21-Feb-2019 0	22,579		373450	03-032-001	Replace Battery	22-Feb-2019 08:37:12	BTRUCK	I	DON	100.27
05-Apr-2019 1	29,817		379989	06-100-PMB	Inspect B PMI	06-Apr-2019 06:31:51	BTRUCK	P	DON	33.82
05-Apr-2019 1	29,817		379989	24-034-003	Repair Signal, Parking, Backup Lamps	06-Apr-2019 06:50:12	BTRUCK	O	DON	3.05
05-Apr-2019 1	29,817		379989	38-045	Service Power Plant	06-Apr-2019 06:44:38	BTRUCK	P	DON	74.42
03-May-2019 1	34,330		384268	01-042-009	Adjust Coolant Pre-Heater- Electrical	04-May-2019 07:13:10	BTRUCK	G	DON	18.45
03-May-2019 1	34,330		384268	06-100-PMB	Inspect B PMI	04-May-2019 08:15:46	BTRUCK	P	DON	23.75
03-May-2019 1	34,330		384268	24-034-011	Repair Plug - Trailer Light Cord	04-May-2019 07:51:13	BTRUCK	O	DON	10.15
03-May-2019 1	34,330		384268	38-045	Service Power Plant	04-May-2019 07:32:43	BTRUCK	P	DON	69.84
03-May-2019 1	34,330		384268	03-002-035	Replace Windshield Wiper & Washer	04-May-2019 07:23:24	BTRUCK	I	DON	5.61
06-Jun-2019 1	39,632		389005	06-100-PMB	Inspect B PMI	08-Jun-2019 07:53:08	BTRUCK	P	DON	62.61
06-Jun-2019 1	39,632		389005	24-045-021	Repair Electronic Engine Controls	10-Jun-2019 07:41:46	BTRUCK	O	DON	88.82
06-Jun-2019 1	39,632		389005	38-045	Service Power Plant	08-Jun-2019 09:07:10	BTRUCK	P	DON	84.22
06-Jun-2019 1	39,632		389005	03-044-003	Replace Fuel Pump		BTRUCK	I	WR	0.00
28-Jun-2019 1	44,213		392386	03-002-035	Replace Windshield Wiper & Washer	05-Jul-2019 11:27:21	BTRUCK	I	DON	35.03
28-Jun-2019 1	44,213		392386	03-044-003	Replace Fuel Pump	05-Jul-2019 10:03:31	BTRUCK	I	DON	181.97
28-Jun-2019 1	44,213		392386	06-100-PMB	Inspect B PMI	05-Jul-2019 10:32:29	BTRUCK	P	DON	15.89
28-Jun-2019 1	44,213		392386	24-002-016	Repair Compartment Lid - Tail & Lift Gate - Re	03-Jul-2019 17:00:31	BTRUCK	O	DON	673.52
28-Jun-2019 1	44,213		392386	37-043-001	Calibrate Emission Controls	05-Jul-2019 12:00:34	BTRUCK	P	DON	18.22
28-Jun-2019 1	44,213		392386	38-045	Service Power Plant	05-Jul-2019 11:04:38	BTRUCK	P	DON	87.01
08-Aug-2019 1	49,276		397888	06-100-PMB	Inspect B PMI	10-Aug-2019 06:59:29	BTRUCK	P	DON	32.37
08-Aug-2019 1	49,276		397888	24-002-035	Repair Windshield Wiper & Washer	10-Aug-2019 08:24:02	BTRUCK	O	DON	82.16
08-Aug-2019 1	49,276		397888	38-045	Service Power Plant	10-Aug-2019 07:31:29	BTRUCK	P	DON	77.50
13-Sep-2019 0	54,757		402832	06-100-PMB	Inspect B PMI	14-Sep-2019 09:01:58	BTRUCK	P	DON	42.23

# Unit Job History

Michels Corporation

Report Printed: 24-Jul-2024 07:52:33 By User: RHENNING

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
<b>Unit No: B3429 - 2018 F250 CREWCAB</b>										
13-Sep-2019 0	54,757		402832	38-045	Service Power Plant	14-Sep-2019 09:20:14	BTRUCK	P	DON	54.57
13-Sep-2019 0	54,757		402832	03-042-009	Replace Coolant Pre-Heater- Electrical		BTRUCK	G	WR	0.00
13-Sep-2019 0	54,757		402832	03-002-035	Replace Windshield Wiper & Washer	16-Sep-2019 05:54:19	BTRUCK	I	DON	27.98
14-Oct-2019 0	57,488		407394	03-034-001	Replace Headlamps / Fog Lamps	27-Oct-2019 09:29:17	ME1287	B	DON	609.61
22-Oct-2019 1	59,976		408820	03-017-001	Replace Tire - Pneumatic	28-Oct-2019 08:19:59	BTRUCK	O	DON	1,091.09
22-Oct-2019 1	59,976		408820	02-002	Clean Cab & Sheet Metal	29-Oct-2019 11:49:05	BSETUP	N	DON	178.29
22-Oct-2019 1	59,976		408820	24-013-001	Repair Front Brakes & Drums	28-Oct-2019 10:10:10	BTRUCK	O	DON	428.40
22-Oct-2019 1	59,976		408820	03-002-035	Replace Windshield Wiper & Washer	28-Oct-2019 07:20:42	BTRUCK	I	DON	39.72
22-Oct-2019 1	59,976		408820	24-052-015	Repair Power Inverter/Converter	29-Oct-2019 14:03:23	BSETUP	I	DON	23.09
22-Oct-2019 1	59,976		408820	38-045	Service Power Plant	28-Oct-2019 06:48:59	BTRUCK	P	DON	103.79
22-Oct-2019 1	59,976		408820	06-100-PMB	Inspect B PMI	28-Oct-2019 06:49:24	BTRUCK	P	DON	13.66
18-Dec-2019 1	66,293		417527	06-100-DOT	Inspect DOT Federal Inspection	23-Dec-2019 11:23:13	BTRUCK	P	DON	32.49
18-Dec-2019 1	66,293		417527	06-100-PMB	Inspect B PMI	23-Dec-2019 09:14:05	BTRUCK	P	DON	50.17
18-Dec-2019 1	66,293		417527	38-045	Service Power Plant	23-Dec-2019 10:24:00	BTRUCK	P	DON	82.93
18-Dec-2019 1	66,293		417527	14-051-009	Install Fire Extinguisher	23-Dec-2019 11:31:37	BTRUCK	I	DON	37.21
18-Dec-2019 1	66,293		417527	03-042-009	Replace Coolant Pre-Heater- Electrical	31-Dec-2019 08:26:38	BTRUCK	G	DON	65.22
07-Feb-2020 0	71,785		425210	03-002-035	Replace Windshield Wiper & Washer	10-Feb-2020 10:45:30	BTRUCK	I	DON	41.09
07-Feb-2020 0	71,785		425210	06-100-PMB	Inspect B PMI	10-Feb-2020 09:57:36	BTRUCK	P	DON	43.11
07-Feb-2020 0	71,785		425210	24-034-010	Repair Socket - Trailer Light Cord	10-Feb-2020 11:55:02	BTRUCK	O	DON	19.61
07-Feb-2020 0	71,785		425210	31-017-001	Rotate Tire - Pneumatic	10-Feb-2020 11:19:17	BTRUCK	P	DON	18.54
07-Feb-2020 0	71,785		425210	38-045	Service Power Plant	10-Feb-2020 10:13:48	BTRUCK	P	DON	28.84
12-Mar-2020 0	76,723		430667	06-100-PMB	Inspect B PMI	13-Mar-2020 16:14:44	BTRUCK	P	DON	18.72
12-Mar-2020 0	76,723		430667	38-045	Service Power Plant	13-Mar-2020 17:03:16	BTRUCK	P	DON	71.21
16-Apr-2020 1	81,395		436370	06-100-PMB	Inspect B PMI	17-Apr-2020 09:22:37	BTRUCK	P	DON	35.43
16-Apr-2020 1	81,395		436370	38-045	Service Power Plant	17-Apr-2020 09:48:03	BTRUCK	P	DON	33.91
16-Apr-2020 1	81,395		436370	01-042-002	Adjust Radiator	17-Apr-2020 09:59:51	BTRUCK	I	DON	28.16
16-Apr-2020 1	81,395		436370	03-002-035	Replace Windshield Wiper & Washer	17-Apr-2020 11:05:11	BTRUCK	I	DON	24.77
16-Apr-2020 1	81,395		436370	31-017-001	Rotate Tire - Pneumatic	17-Apr-2020 10:53:32	BTRUCK	I	DON	29.45
13-May-2020 1	88,049		440599	06-100-PMB	Inspect B PMI	16-May-2020 07:00:14	BTRUCK	P	DON	48.11

# Unit Job History

Michels Corporation  
Report Printed: 24-Jul-2024 07:52:33 By User: RHEINING

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: B3429 - 2018 F250 CREWCAB										
13-May-2020	88,049		440599	38-045	Service Power Plant	16-May-2020 07:24:34	BTRUCK	P	DON	61.99
13-May-2020	88,049		440599	03-002-035	Replace Windshield Wiper & Washer	16-May-2020 07:51:35	BTRUCK	I	DON	42.65
13-May-2020	88,049		440599	03-054-001	Replace Horn & Mounting	16-May-2020 08:31:33	BTRUCK	I	DON	48.31
19-Jun-2020	94,277		446554	06-100-PMB	Inspect B PMI	19-Jun-2020 16:24:54	BTRUCK	P	DON	34.44
19-Jun-2020	94,277		446554	38-045	Service Power Plant	19-Jun-2020 17:02:02	BTRUCK	P	DON	46.41
19-Jun-2020	94,277		446554	31-017-001	Rotate Tire - Pneumatic	20-Jun-2020 06:56:24	BTRUCK	I	DON	38.11
19-Jun-2020	94,277		446554	03-002-035	Replace Windshield Wiper & Washer	20-Jun-2020 06:02:55	BTRUCK	I	DON	21.71
29-Jul-2020	101,047		453469	06-100-PMA	Inspect A PMI	30-Jul-2020 09:51:27	TRK021	P	DON	91.01
22-Aug-2020	104,999		457512	24-045-021	Repair Electronic Engine Controls	24-Aug-2020 15:32:35	BTRUCK	O	DON	331.44
22-Aug-2020	104,999		457512	02-002	Clean Cab & Sheet Metal	27-Aug-2020 10:26:28	BSETUP	N	DON	503.31
15-Sep-2020	107,654		461481	03-044-018	Replace Fuel Hose / Line	15-Sep-2020 07:40:54	CTFLD	B	DON	214.45
17-Sep-2020	108,631		462020	06-100-PMB	Inspect B PMI	19-Sep-2020 07:35:40	BTRUCK	P	DON	61.73
17-Sep-2020	108,631		462020	38-045	Service Power Plant	19-Sep-2020 08:42:51	BTRUCK	P	DON	82.05
17-Sep-2020	108,631		462020	03-002-035	Replace Windshield Wiper & Washer	19-Sep-2020 07:50:17	BTRUCK	N	DON	26.36
17-Sep-2020	108,631		462020	03-044-003	Replace Fuel Pump	19-Sep-2020 10:00:38	BTRUCK	I	DON	240.66
20-Oct-2020	114,532		467627	06-100-DOT	Inspect DOT Federal Inspection	26-Oct-2020 15:18:03	BTRUCK	P	DON	36.45
20-Oct-2020	114,532		467627	06-100-PMB	Inspect B PMI	26-Oct-2020 13:36:54	BTRUCK	P	DON	50.89
20-Oct-2020	114,532		467627	38-045	Service Power Plant	26-Oct-2020 14:22:17	BTRUCK	P	DON	44.85
20-Oct-2020	114,532		467627	03-017-001	Replace Tire - Pneumatic	26-Oct-2020 16:24:46	BTIRE	I	DON	1,161.10
20-Oct-2020	114,532		467627	03-002-035	Replace Windshield Wiper & Washer	26-Oct-2020 14:24:13	BTRUCK	N	DON	17.02
20-Oct-2020	114,532		467627	14-051-009	Install Fire Extinguisher	26-Oct-2020 14:26:54	BTRUCK	Q	DON	34.72
04-Dec-2020	120,284		475331	03-002-065	Replace Hood Latch	05-Dec-2020 09:07:16	BTRUCK	I	DON	58.36
04-Dec-2020	120,284		475331	06-100-PMB	Inspect B PMI	05-Dec-2020 06:00:41	BTRUCK	P	DON	38.15
04-Dec-2020	120,284		475331	38-045	Service Power Plant	05-Dec-2020 06:41:41	BTRUCK	P	DON	56.78
04-Dec-2020	120,284		475331	31-017-001	Rotate Tire - Pneumatic	05-Dec-2020 06:25:12	BTRUCK	P	DON	17.47
04-Dec-2020	120,284		475331	03-034-004	Replace Clearance & Marker Lamps	05-Dec-2020 07:22:43	BTRUCK	I	DON	195.16
04-Dec-2020	120,284		475331	03-002-035	Replace Windshield Wiper & Washer	05-Dec-2020 07:27:10	BTRUCK	N	DON	19.13
14-Jan-2021	127,031		482060	03-001-007	Replace Expansion Valve	15-Jan-2021 13:25:31	BTRUCK	I	DON	111.98
14-Jan-2021	127,031		482060	03-002-035	Replace Windshield Wiper & Washer	15-Jan-2021 13:25:44	BTRUCK	I	DON	17.11

# Unit Job History

Michels Corporation

Report Printed: 24-Jul-2024 07:52:33 By User: RHEENING

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
<b>Unit No: B3429 - 2018 F250 CREWCAB</b>										
14-Jan-2021 08	127,031		482060	03-013-001	Replace Front Brakes & Drums	15-Jan-2021 12:02:05	BTRUCK	I	DON	382.65
14-Jan-2021 08	127,031		482060	06-100-PMB	Inspect B PMI	15-Jan-2021 07:31:13	BTRUCK	P	DON	77.49
14-Jan-2021 08	127,031		482060	24-013-002	Repair Rear Brakes & Drums	15-Jan-2021 11:11:26	BTRUCK	I	DON	579.91
14-Jan-2021 08	127,031		482060	31-017-001	Rotate Tire - Pneumatic	15-Jan-2021 11:12:28	BTRUCK	I	DON	0.68
14-Jan-2021 08	127,031		482060	38-045	Service Power Plant	15-Jan-2021 13:44:40	BTRUCK	P	DON	84.46
24-Mar-2021 0	127,031		496433	06-100-PMA	Inspect A PMI	25-Mar-2021 07:50:27	SCHED	P	DON	0.00
24-Mar-2021 0	127,031		496433	06-003-001	Inspect Gauges & Warning Devices	25-Mar-2021 07:48:57	MB2290	I	DON	104.56
24-Mar-2021 0	127,031		496433	38-100-PMA	Service A PMI	25-Mar-2021 07:50:40	MB2290	I	DON	306.47
07-May-2021 1	141,187		505305	06-100-PMB	Inspect B PMI	08-May-2021 06:54:43	SCHED	P	DON	52.41
07-May-2021 1	141,187		505305	24-017-001	Repair Tire - Pneumatic	08-May-2021 08:13:47	BTRUCK	O	DON	39.31
07-May-2021 1	141,187		505305	38-100-PMA	Service A PMI	08-May-2021 07:19:19	SCHED	P	DON	94.87
07-May-2021 1	141,187		505305	03-001-016	Replace Filter - Cab Ventilation	08-May-2021 07:48:57	BTRUCK	I	DON	29.79
07-May-2021 1	141,187		505305	03-002-035	Replace Windshield Wiper & Washer	08-May-2021 07:31:04	BTRUCK	I	DON	25.42
11-Jun-2021 08	146,329		512153	38-100-PMA	Service A PMI	11-Jun-2021 16:20:50	BTRUCK	P	DON	67.24
11-Jun-2021 08	146,329		512153	06-100-PMA	Inspect A PMI	11-Jun-2021 15:48:54	BTRUCK	P	DON	30.75
11-Jun-2021 08	146,329		512153	03-002-035	Replace Windshield Wiper & Washer	11-Jun-2021 15:50:50	BTRUCK	I	DON	15.71
11-Jun-2021 08	146,329		512153	31-017-001	Rotate Tire - Pneumatic	11-Jun-2021 15:58:37	BTRUCK	P	DON	7.69
23-Jul-2021 14	153,048		520494	03-002-010	Replace Mirrors	26-Jul-2021 07:57:01	BTRUCK	I	DON	81.18
23-Jul-2021 14	153,048		520494	03-018-001	Replace Front Axle Hubs & Bearings	26-Jul-2021 07:37:16	BTRUCK	I	DON	320.15
23-Jul-2021 14	153,048		520494	06-100-DOT	Inspect DOT Federal Inspection	26-Jul-2021 10:13:19	BTRUCK	P	DON	89.83
23-Jul-2021 14	153,048		520494	06-100-PMA	Inspect A PMI	26-Jul-2021 05:50:48	BTRUCK	P	DON	35.02
23-Jul-2021 14	153,048		520494	14-051-009	Install Fire Extinguisher	26-Jul-2021 07:07:16	BTRUCK	Q	DON	37.90
23-Jul-2021 14	153,048		520494	38-100-PMA	Service A PMI	26-Jul-2021 06:58:52	BTRUCK	P	DON	121.44
05-Aug-2021 1	155,262		523305	24-051-005	Repair Recorder - Fuel & Mileage	09-Aug-2021 07:51:44	BTRUCK	O	DON	118.89
05-Aug-2021 1	155,262		523305	03-034-014	Replace Auxiliary Work / Flood Light	07-Aug-2021 09:37:51	BTRUCK	I	DON	99.91
05-Aug-2021 1	155,262		523305	06-100-009	Inspect Safety Check	07-Aug-2021 07:55:46	BTRUCK	P	DON	42.08
05-Aug-2021 1	155,262		523305	24-045-021	Repair Electronic Engine Controls	07-Aug-2021 09:27:24	BTRUCK	O	DON	230.77
05-Aug-2021 1	155,262		523305	03-032-001	Replace Battery	09-Aug-2021 09:44:46	BTRUCK	I	DON	170.94
03-Sep-2021 0	160,181		529269	03-001-016	Replace Filter - Cab Ventilation	03-Sep-2021 09:29:40	BTRUCK	I	DON	62.24

# Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
<b>Unit No: B3429 - 2018 F250 CREWCAB</b>										
03-Sep-2021 0	160,181		529269	03-002-035	Replace Windshield Wiper & Washer	03-Sep-2021 08:09:19	BTRUCK	I	DON	23.09
03-Sep-2021 0	160,181		529269	06-100-PMA	Inspect A PMI	03-Sep-2021 07:39:42	BTRUCK	P	DON	10.91
03-Sep-2021 0	160,181		529269	38-100-PMA	Service A PMI	03-Sep-2021 07:55:13	BTRUCK	P	DON	76.93
22-Sep-2021 0	163,403		533209	03-017-001	Replace Tire - Pneumatic	27-Sep-2021 09:26:59	BTRUCK	O	DON	1,044.66
13-Oct-2021 1	166,418		539002	02-002	Clean Cab & Sheet Metal	16-Oct-2021 08:35:25	BSETUP	N	DON	526.80
13-Oct-2021 1	166,418		539002	03-001-016	Replace Filter - Cab Ventilation	14-Oct-2021 16:46:25	BTRUCK	I	DON	15.07
13-Oct-2021 1	166,418		539002	03-002-035	Replace Windshield Wiper & Washer	14-Oct-2021 16:41:15	BTRUCK	I	DON	56.88
13-Oct-2021 1	166,418		539002	06-100-PMB	Inspect B PMI	14-Oct-2021 14:07:56	BTRUCK	P	DON	43.17
13-Oct-2021 1	166,418		539002	38-100-PMA	Service A PMI	14-Oct-2021 16:03:13	BTRUCK	P	DON	80.09
18-Nov-2021 0	166,418		547924	06-100-PMA	Inspect A PMI	22-Nov-2021 20:19:03	MB2290	P	DON	0.00
18-Nov-2021 0	166,418		547924	38-100-PMA	Service A PMI	18-Nov-2021 19:28:17	MB2290	P	DON	180.36
18-Jan-2022 1	166,418		560404	06-100-PMA	Inspect A PMI	26-Jan-2022 20:39:26	MB2290	P	DON	0.00
18-Jan-2022 1	166,418		560404	38-100-PMA	Service A PMI	26-Jan-2022 20:43:01	MB2290	P	DON	327.09
25-Jan-2022 0	166,418		561496	03-017-001	Replace Tire - Pneumatic	26-Jan-2022 06:10:02	BTRUCK	O	DON	67.75
25-Jan-2022 0	166,418		561496	03-034-002	Replace Stop, Tail, Turn & License	25-Jan-2022 12:04:53	BTRUCK	I	DON	214.29
25-Jan-2022 0	166,418		561496	20-010	Tow Chassis Group	25-Jan-2022 11:03:31	BVLOFC	B	DON	148.88
14-Mar-2022 1	166,418		575447	06-100-PMA	Inspect A PMI	18-Mar-2022 07:52:01	MB2290	P	DON	0.00
14-Mar-2022 1	166,418		575447	06-100-PMB	Inspect B PMI	18-Mar-2022 07:52:08	MB2290	P	DON	0.00
14-Mar-2022 1	166,418		575447	38-100-PMA	Service A PMI	18-Mar-2022 07:52:18	MB2290	P	DON	320.42
25-Apr-2022 0	166,418		585378	06-100-PMA	Inspect A PMI	09-May-2022 08:29:34	ME1798	P	DON	0.00
25-Apr-2022 0	166,418		585378	38-100-PMA	Service A PMI	09-May-2022 08:30:37	ME1798	P	DON	359.80
02-Jun-2022 1	193,841		593141	02-002	Clean Cab & Sheet Metal	30-Jun-2022 11:42:04	BSETUP	I	DON	476.65
02-Jun-2022 1	193,841		593141	03-002-035	Replace Windshield Wiper & Washer	29-Jun-2022 10:51:03	BTRUCK	I	DON	37.55
02-Jun-2022 1	193,841		593141	03-034-006	Replace Warning Lamps - Special Application	30-Jun-2022 09:37:51	BSETUP	N	DON	24.92
02-Jun-2022 1	193,841		593141	03-051-006	Replace Safety Devices	30-Jun-2022 08:58:06	BSETUP	Q	DON	37.87
02-Jun-2022 1	193,841		593141	03-053-005	Replace Markings - Vehicle - Decals	01-Jul-2022 16:00:32	BSETUP	N	DON	32.84
02-Jun-2022 1	193,841		593141	03-053-015	Replace Tool Box	30-Jun-2022 10:16:29	BSETUP	I	DON	191.35
02-Jun-2022 1	193,841		593141	06-024-002	Inspect Drive Shaft, Behind Main Transmission	29-Jun-2022 10:06:23	BTRUCK	G	DON	-21.84
02-Jun-2022 1	193,841		593141	06-100-009	Inspect Safety Check	29-Jun-2022 06:35:41	BTRUCK	I	DON	97.44

# Unit Job History

Michels Corporation

Report Printed: 24-Jul-2024 07:52:33 By User: RHENNING

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
<b>Unit No: B3429 - 2018 F250 CREWCAB</b>										
02-Jun-2022	193,841		593141	06-100-DOT	Inspect DOT Federal Inspection	29-Jun-2022 13:36:47	BTRUCK	P	DON	23.24
02-Jun-2022	193,841		593141	06-100-PMA	Inspect A PMI	29-Jun-2022 07:33:03	BTRUCK	P	DON	37.81
02-Jun-2022	193,841		593141	14-044-001	Install Tank - Fuel, Liquid	01-Jul-2022 15:31:23	BSETUP	I	DON	155.56
02-Jun-2022	193,841		593141	14-051-009	Install Fire Extinguisher	29-Jun-2022 09:26:28	BTRUCK	Q	DON	44.52
02-Jun-2022	193,841		593141	24-034-002	Repair Stop, Tail, Turn & License	29-Jun-2022 08:37:37	BTRUCK	I	DON	234.03
02-Jun-2022	193,841		593141	24-044-007	Repair Throttle Controls	29-Jun-2022 13:01:31	BTRUCK	I	DON	304.67
02-Jun-2022	193,841		593141	31-017-001	Rotate Tire - Pneumatic	29-Jun-2022 10:23:35	BTRUCK	I	DON	24.52
02-Jun-2022	193,841		593141	38-100-PMA	Service A PMI	29-Jun-2022 09:46:23	BTRUCK	P	DON	128.56
12-Jul-2022	00	193,841	601974	03-052-005	Replace Transmitter - CB	12-Jul-2022 12:28:01	TRK001	O	DON	97.43
12-Jul-2022	07	193,841	601812	03-052-003	Replace Radio Equipment	12-Jul-2022 07:23:39	BCOMM	Q	DON	40.76
22-Jul-2022	05	193,841	604359	24-037	Repair Electrical - Modules/Relays		BTRUCK	O	WR	95.36
07-Oct-2022	01	201,895	622526	06-100-PMA	Inspect A PMI	07-Oct-2022 08:58:40	BVLOFC	P	DON	0.00
07-Oct-2022	01	201,895	622526	38-100-PMA	Service A PMI	07-Oct-2022 08:58:40	BVLOFC	P	DON	53.57
05-Dec-2022	0	213,093	636716	24-037	Repair Electrical - Modules/Relays	05-Dec-2022 17:00:09	BTRUCK	O	DON	318.24
05-Dec-2022	0	213,093	636716	38-100-PMA	Service A PMI	05-Dec-2022 09:58:02	BTRUCK	P	DON	179.83
05-Dec-2022	0	213,093	636716	03-063-003	Replace Transceiver - GPS Tracker	05-Dec-2022 11:37:52	BTRUCK	Q	DON	36.47
05-Dec-2022	0	213,093	636716	06-100-PMB	Inspect B PMI	05-Dec-2022 08:21:39	BTRUCK	P	DON	38.21
05-Dec-2022	0	213,093	636716	06-017-001	Inspect Tire - Pneumatic	05-Dec-2022 12:00:07	BTRUCK	O	DON	14.66
05-Dec-2022	0	213,093	636716	03-002-035	Replace Windshield Wiper & Washer	05-Dec-2022 15:12:14	BTRUCK	I	DON	37.90
05-Dec-2022	0	213,093	636716	03-013-001	Replace Front Brakes & Drums	05-Dec-2022 14:53:34	BTRUCK	I	DON	162.04
05-Dec-2022	0	213,093	636716	03-044-016	Replace Tank - Fuel Auxiliary	05-Dec-2022 10:42:32	BTRUCK	I	DON	35.53
05-Dec-2022	0	213,093	636716	03-045-023	Replace Engine Belts	05-Dec-2022 13:22:15	BTRUCK	I	DON	79.09
05-Dec-2022	0	213,093	636716	24-015-004	Repair Steering Linkage	05-Dec-2022 15:31:37	BTRUCK	I	DON	73.50
05-Dec-2022	0	213,093	636716	03-017-001	Replace Tire - Pneumatic	06-Dec-2022 06:41:50	BTIRE	I	DON	1,375.32
08-May-2023	1	222,791	672949	03-002-035	Replace Windshield Wiper & Washer	11-May-2023 09:40:44	BTRUCK	I	DON	20.68
08-May-2023	1	222,791	672949	03-044-002	Replace Filters	11-May-2023 15:14:19	BTRUCK	I	DON	38.26
08-May-2023	1	222,791	672949	24-043-003	Repair Muffler	11-May-2023 14:22:25	BTRUCK	I	DON	50.95
08-May-2023	1	222,791	672949	31-017-001	Rotate Tire - Pneumatic	11-May-2023 11:05:02	BTRUCK	I	DON	18.82
08-May-2023	1	222,791	672949	24-024	Repair Driveshafts	11-May-2023 11:41:39	BTRUCK	I	DON	47.96

# Unit Job History

Michels Corporation

Report Printed: 24-Jul-2024 07:52:33 By User: RHENNING

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
<b>Unit No: B3429 - 2018 F250 CREWCAB</b>										
08-May-2023	1	222,791	672949	38-100-PMA	Service A PMI	11-May-2023 10:22:24	BTRUCK	P	DON	101.69
08-May-2023	1	222,791	672949	06-100-DOT	Inspect DOT Federal Inspection	11-May-2023 16:03:37	BTRUCK	P	DON	30.57
08-May-2023	1	222,791	672949	06-100-PMB	Inspect B PMI	11-May-2023 09:36:17	BTRUCK	P	DON	46.12
08-May-2023	1	222,791	672949	14-051-009	Install Fire Extinguisher	11-May-2023 08:29:17	BTRUCK	Q	DON	81.82
08-May-2023	1	222,791	672949	24-017-010	Repair Sensor - Air Pressure	11-May-2023 15:34:35	BTRUCK	I	DON	143.63
08-May-2023	1	222,791	672949	24-034-002	Repair Stop, Tail, Turn & License	11-May-2023 10:34:41	BTRUCK	I	DON	7.62
19-Jul-2023	09	228,938	689340	06-100-PMA	Inspect A PMI	19-Jul-2023 13:37:40	BTRUCK	P	DON	63.03
19-Jul-2023	09	228,938	689340	24-017-010	Repair Sensor - Air Pressure	19-Jul-2023 12:47:33	BTRUCK	I	DON	60.69
19-Jul-2023	09	228,938	689340	38-100-PMA	Service A PMI	19-Jul-2023 12:47:44	BTRUCK	P	DON	81.22
19-Jul-2023	09	228,938	689340	31-017-001	Rotate Tire - Pneumatic	19-Jul-2023 12:00:36	BTRUCK	I	DON	23.48
19-Jul-2023	09	228,938	689340	02-002	Clean Cab & Sheet Metal	20-Jul-2023 09:16:45	BSETUP	N	DON	160.58
19-Jul-2023	09	228,938	689340	03-510-002	Replace Tool Box	20-Jul-2023 08:40:56	BSETUP	I	DON	29.99
04-Mar-2024	1	228,938	743121	02-002	Clean Cab & Sheet Metal	25-Mar-2024 13:41:17	BSETUP	N	DON	277.32
04-Mar-2024	1	228,938	743121	03-032-001	Replace Battery	25-Mar-2024 13:44:15	BSETUP	N	DON	114.95
26-Jun-2024	01	235,204	768910	06-100-009	Inspect Safety Check	26-Jun-2024 16:30:09	BTRUCK	N	DON	44.22
17-Jul-2024	13	235,204	773066	02-002	Clean Cab & Sheet Metal	22-Jul-2024 11:06:48	BSETUP	Z	DON	247.86
17-Jul-2024	13	235,204	773066	25-051	Remove General Accessories	19-Jul-2024 17:00:19	BSETUP	Z	DON	410.66

Unit No: B3429

Count: 220

37,267.22