

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: C0384 - 2012 KENWORTH T800										
11-Apr-2011	547	0	63137	06-100-002	Inspect DO NOT USE - DOT Federal Insp	28-Jun-2011 07:55:28	BTRUCK	P	DON	154.15
11-Apr-2011	547	0	63137	23-513-004	Burn / Cut Specialty Attachment	28-Jun-2011 08:44:13	BWELD	E	DON	610.04
11-Apr-2011	547	0	63137	14-078-002	Install Fender Assembly - Rear	27-Jun-2011 15:00:00	BTRUCK	C	DON	2,741.14
11-Apr-2011	547	0	63137	14-052-003	Install Radio Equipment	21-Jun-2011 09:00:00	BBODY	C	DON	1,143.73
11-Apr-2011	547	0	63137	14-052-005	Install Transmitter - CB	22-Jun-2011 11:32:22	BBODY	E	DON	219.42
11-Apr-2011	547	0	63137	14-052-014	Install Cellular Telephone Accessories	22-Jun-2011 09:00:00	BBODY	C	DON	391.24
11-Apr-2011	547	0	63137	14-053-005	Install Markings - Vehicle - Decals	22-Jun-2011 14:08:19	BBODY	C	DON	64.96
11-Apr-2011	547	0	63137	14-063-003	Install Transceiver - GPS Tracker	21-Jun-2011 13:09:00	BBODY	C	DON	389.69
11-Apr-2011	547	0	63137	14-071-019	Install Insulation	22-Jun-2011 11:33:04	BBODY	C	DON	337.35
11-Apr-2011	547	0	63137	15-519-003	Paint Prep Hitch Assembly	06-Jul-2011 06:38:13	BSAND	C	DON	13.67
11-Apr-2011	547	0	63137	12-519-003	Refinish Hitch Assembly	05-Jul-2011 13:53:07	BBODY	C	DON	161.77
11-Apr-2011	547	0	63137	19-079-002	Wire/Rewire Headache Rack	27-Jun-2011 10:36:23	BTRUCK	I	DON	1,929.89
11-Apr-2011	547	0	63137	14-079-002	Install Headache Rack	06-Jul-2011 15:00:00	BTRUCK	C	DON	4,543.71
11-Apr-2011	547	0	63137	19-034-003	Wire/Rewire Signal, Parking, Backup Lamps	06-Jul-2011 12:09:48	BTRUCK	C	DON	416.17
11-Apr-2011	547	0	63137	14-002-010	Install Mirrors	27-Jun-2011 12:41:05	BTRUCK	C	DON	80.98
11-Apr-2011	547	0	63137	14-002-038	Install Deflector - Non-Aerodynamic	27-Jun-2011 09:00:00	BTRUCK	C	DON	269.18
11-Apr-2011	547	0	63137	14-014-010	Install Toolbox Mounting	27-Jun-2011 15:00:00	BTRUCK	C	DON	147.71
11-Apr-2011	547	0	63137	03-078-009	Replace Mud Flaps and Hanger Brackets	28-Jun-2011 07:57:41	BTRUCK	C	DON	96.26
11-Apr-2011	547	0	63137	21-513	Fabricate Attachment	29-Jun-2011 15:00:00	BWELD	C	DON	667.96
01-Jun-2011	1,261	49	72252	03-065-007	Replace Hoses & Fittings	28-Dec-2011 23:00:00	U11033	F	DON	49.16
27-Jul-2011	1,261	49	69676	24-059-001	Repair Fifth Wheel - Lower Coupler Assembly	27-Jul-2011 09:00:00	BTRUCK	I	DON	163.90
27-Jul-2011	1,261	49	69676	14-078-009	Install Mud Flaps and Hanger Brackets	01-Aug-2011 08:08:39	BTRUCK	I	DON	157.53
27-Jul-2011	1,261	49	69676	01-015	Adjust Steering	02-Aug-2011 10:22:07	BTRUCK	O	DON	0.00
27-Jul-2011	1,261	49	69676	14-034-006	Install Warning Lamps - Special Application	30-Jul-2011 10:09:58	BTRUCK	I	DON	170.24
02-Sep-2011	1,261	49	72289	07-010	Lubricate Chassis Group	06-Sep-2011 06:38:44	BTRUCK	P	DON	23.05
06-Oct-2011	18,612	597	74195	03-041-009	Replace Hose Aftercooler / Intercooler	08-Oct-2011 11:09:24	BTRUCK	I	DON	61.07
06-Oct-2011	18,612	597	74195	06-100-001	Inspect DO NOT USE - PMI Service	08-Oct-2011 05:11:03	BTRUCK	P	DON	364.51
06-Oct-2011	18,612	597	74195	24-016-050	Repair Alignment All Wheel	11-Oct-2011 08:36:48	BTRUCK	I	DON	193.36
06-Oct-2011	18,612	597	74195	31-017-001	Rotate Tire - Pneumatic	08-Oct-2011 10:47:15	BTRUCK	I	DON	34.24

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: C0384 - 2012 KENWORTH T800										
29-Oct-2011 0'	24,427	783	75646	07-010	Lubricate Chassis Group	29-Oct-2011 08:36:20	BTRUCK	P	DON	33.63
29-Oct-2011 0'	24,427	783	75646	24-078-009	Repair Mud Flaps and Hanger Brackets	29-Oct-2011 10:22:04	BTRUCK	O	DON	65.91
14-Nov-2011 1	28,636	914	76538	07-010	Lubricate Chassis Group	14-Nov-2011 16:35:37	BTRUCK	P	DON	38.65
05-Dec-2011 0	31,854	1,012	77455	24-017-001	Repair Tire - Pneumatic	05-Dec-2011 08:21:13	BTRUCK	O	DON	63.72
10-Jan-2012 0:	37,386	1,207	78981	24-034-011	Repair Plug - Trailer Light Cord	10-Jan-2012 06:27:33	BTRUCK	O	DON	13.93
13-Jan-2012 1:	38,287	1,240	79410	06-100-PMB	Inspect B PMI	13-Jan-2012 15:00:00	BTRUCK	P	DON	523.38
13-Jan-2012 1:	38,287	1,240	79410	01-059-001	Adjust Fifth Wheel - Lower Coupler Assembly	18-Jan-2012 09:00:16	BTRUCK	O	DON	11.17
13-Jan-2012 1:	38,287	1,240	79410	24-034-008	Repair Trailer Light Cord	17-Jan-2012 10:01:56	BTRUCK	O	DON	18.34
06-Feb-2012 1	39,853	1,240	81273	03-042-016	Replace Fan Clutch	06-Feb-2012 16:03:08	BTRUCK	W	DON	0.00
15-Feb-2012 1:	43,832	1,449	81737	03-001-015	Replace Cable - Water Shut-Off Valve	15-Feb-2012 15:00:00	BTRUCK	O	DON	119.09
10-Mar-2012 0	49,479	1,633	83494	24-017-001	Repair Tire - Pneumatic	12-Mar-2012 07:36:44	BTRUCK	I	DON	17.57
10-Mar-2012 0	49,479	1,633	83494	01-023-002	Adjust Clutch Assembly	10-Mar-2012 07:02:51	BTRUCK	O	DON	19.37
10-Mar-2012 0	49,479	1,633	83494	07-010	Lubricate Chassis Group	10-Mar-2012 08:16:11	BTRUCK	P	DON	48.34
10-Mar-2012 0	49,479	1,633	83494	24-013-011	Repair Anti-Lock Sensor Assembly		BTRUCK	O	WR	0.00
23-Mar-2012 1	53,038	1,748	84469	24-018-011	Repair Seal - Wheel	23-Mar-2012 17:05:06	BTRUCK	O	DON	25.78
23-Mar-2012 1	53,038	1,748	84469	24-013-011	Repair Anti-Lock Sensor Assembly	23-Mar-2012 16:23:44	BTRUCK	O	DON	16.84
13-Apr-2012 1	58,867	1,930	85903	06-100-PMB	Inspect B PMI	16-Apr-2012 06:03:58	BTRUCK	P	DON	393.76
13-Apr-2012 1	58,867	1,930	85903	31-017-001	Rotate Tire - Pneumatic	14-Apr-2012 10:00:48	BTRUCK	I	DON	69.21
13-Apr-2012 1	58,867	1,930	85903	03-051-009	Replace Fire Extinguisher	14-Apr-2012 07:53:54	BTRUCK	I	DON	39.56
13-Apr-2012 1	58,867	1,930	85903	06-100-DOT	Inspect DOT Federal Inspection	14-Apr-2012 08:15:48	BTRUCK	P	DON	14.44
10-May-2012 1	66,433	2,161	87797	07-010-001	Lubricate All Axles	12-May-2012 06:43:25	BTRUCK	P	DON	65.61
10-May-2012 1	66,433	2,161	87797	24-015-003	Repair Steering Gear	11-May-2012 07:39:28	BTRUCK	I	DON	239.77
24-May-2012 1	70,189	2,273	88755	24-045-014	Repair Ventilating System	25-May-2012 09:57:01	BTRUCK	O	DON	146.46
26-Jun-2012 1:	80,118	2,567	90872	24-017-001	Repair Tire - Pneumatic	30-Jun-2012 10:31:21	BTRUCK	O	DON	158.79
26-Jun-2012 1:	80,118	2,567	90872	06-100-PMB	Inspect B PMI	02-Jul-2012 07:09:08	BTRUCK	P	DON	394.70
26-Jun-2012 1:	80,118	2,567	90872	24-044-001	Repair Tank - Fuel, Liquid		BTRUCK	I	WR	0.00
17-Jul-2012 16	83,789	2,667	92349	06-031	Inspect Charging System	18-Jul-2012 06:17:52	BTRUCK	O	DON	48.23
10-Aug-2012 C			94024	07-010-001	Lubricate All Axles	11-Aug-2012 08:19:13	BTRUCK	P	DON	92.13
10-Aug-2012 C			94024	31-017-001	Rotate Tire - Pneumatic	11-Aug-2012 08:48:51	BTRUCK	I	DON	28.65

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: C0384 - 2012 KENWORTH T800										
10-Aug-2012 C			94024	03-078-009	Replace Mud Flaps and Hanger Brackets	11-Aug-2012 09:30:31	BTRUCK	I	DON	27.46
20-Aug-2012 C	86,021	2,853	94544	24-506-001	Repair Fuel Tank	27-Aug-2012 07:58:38	BWELD	W	DON	55.59
20-Aug-2012 C	86,021	2,853	94544	03-044-002	Replace Filters	23-Aug-2012 06:55:30	BTRUCK	O	DON	127.50
20-Aug-2012 C	86,021	2,853	94544	03-044-024	Replace Fuel / Water Separator		BTRUCK	I	WR	69.89
30-Aug-2012 I	86,021	2,853	95419	07-020	Lubricate Drivetrain Group	31-Aug-2012 05:32:13	BTRUCK	P	DON	16.86
30-Aug-2012 I	86,021	2,853	95419	03-044-024	Replace Fuel / Water Separator	31-Aug-2012 06:12:57	BTRUCK	I	DON	0.00
30-Aug-2012 I	86,021	2,853	95419	24-044	Repair Fuel System	31-Aug-2012 06:15:43	BTRUCK	O	DON	24.17
07-Sep-2012 I	97,843	3,080	95850	06-100-DOT	Inspect DOT Federal Inspection	14-Sep-2012 05:38:54	BTRUCK	P	DON	0.00
07-Sep-2012 I	97,843	3,080	95850	03-001-016	Replace Filter - Cab Ventilation	14-Sep-2012 13:37:30	BTRUCK	I	DON	69.37
07-Sep-2012 I	97,843	3,080	95850	03-002-011	Replace Cab Accessories - Interior	14-Sep-2012 13:37:22	BTRUCK	I	DON	68.42
07-Sep-2012 I	97,843	3,080	95850	03-013-016	Replace Air Dryer / Purge Valve	14-Sep-2012 13:37:35	BTRUCK	I	DON	550.58
07-Sep-2012 I	97,843	3,080	95850	03-018-011	Replace Seal - Wheel	14-Sep-2012 13:37:25	BTRUCK	I	DON	580.33
07-Sep-2012 I	97,843	3,080	95850	03-041-001	Replace Air Cleaner	14-Sep-2012 13:37:33	BTRUCK	I	DON	465.50
07-Sep-2012 I	97,843	3,080	95850	24-013-007	Repair Brake Lines & Fittings - Hydraulic & Air	14-Sep-2012 13:37:17	BTRUCK	I	DON	116.54
07-Sep-2012 I	97,843	3,080	95850	24-015-003	Repair Steering Gear	14-Sep-2012 13:37:28	BTRUCK	I	DON	88.54
07-Sep-2012 I	97,843	3,080	95850	24-045-014	Repair Ventilating System	14-Sep-2012 13:37:20	BTRUCK	I	DON	154.92
07-Sep-2012 I	97,843	3,080	95850	02-002	Clean Cab & Sheet Metal	28-Sep-2012 09:28:48	BDETL	C	DON	64.40
07-Sep-2012 I	97,843	3,080	95850	06-100-PMA	Inspect A PMI	14-Sep-2012 13:37:11	BTRUCK	P	DON	394.51
07-Sep-2012 I	97,843	3,080	95850	01-045-022	Adjust Overhead (Valves)	14-Sep-2012 05:02:55	BTRUCK	P	DON	396.19
07-Sep-2012 I	97,843	3,080	95850	01-023-002	Adjust Clutch Assembly	14-Sep-2012 05:03:09	BTRUCK	O	DON	48.45
07-Sep-2012 I	97,843	3,080	95850	03-017-001	Replace Tire - Pneumatic	18-Sep-2012 07:44:39	BTRUCK	O	DON	73.23
07-Sep-2012 I	97,843	3,080	95850	24-044-001	Repair Tank - Fuel, Liquid	14-Sep-2012 09:00:00	BTRUCK	I	DON	86.72
07-Sep-2012 I	97,843	3,080	95850	24-049-004	Repair ECM Sensor	01-Oct-2012 14:29:42	BTRUCK	O	DON	443.27
07-Sep-2012 I	97,843	3,080	95850	03-078-009	Replace Mud Flaps and Hanger Brackets	14-Sep-2012 05:03:15	BTRUCK	O	DON	91.19
12-Oct-2012 O	102,648	3,230	98401	07-010-001	Lubricate All Axles	12-Oct-2012 08:05:11	BTRUCK	P	DON	72.38
24-Oct-2012 O	105,674	3,230	99365	24-034-003	Repair Signal, Parking, Backup Lamps	24-Oct-2012 06:06:33	BTRUCK	O	DON	109.43
01-Nov-2012 C	105,674	3,230	99894	01-013	Adjust Brakes	01-Nov-2012 06:45:42	BTRUCK	O	DON	37.46
14-Nov-2012 C	113,126	3,552	100714	07-010-001	Lubricate All Axles	21-Nov-2012 15:00:00	BTRUCK	P	DON	85.34
14-Nov-2012 C	113,126	3,552	100714	03-013-002	Replace Rear Brakes & Drums		BTRUCK	I	WR	0.00

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: C0384 - 2012 KENWORTH T800										
14-Nov-2012 C	113,126	3,552	100714	24-044-024	Repair Fuel / Water Separator	21-Nov-2012 14:59:10	BTRUCK	O	DON	146.47
12-Dec-2012 0	117,878	3,700	102530	24-042-012	Repair Clamps and Hoses	14-Dec-2012 14:55:18	BTRUCK	I	DON	25.23
12-Dec-2012 0	117,878	3,700	102530	38-045	Service Power Plant	19-Dec-2012 11:24:13	BTRUCK	P	DON	234.02
12-Dec-2012 0	117,878	3,700	102530	06-100-PMB	Inspect B PMI	14-Dec-2012 14:16:25	BTRUCK	I	DON	56.22
15-Jan-2013 0	122,645	3,854	104717	07-020	Lubricate Drivetrain Group	15-Jan-2013 09:39:33	BTRUCK	P	DON	26.87
15-Jan-2013 0	122,645	3,854	104717	01-002-004	Adjust Hood	15-Jan-2013 10:46:28	BTRUCK	O	DON	24.49
22-Jan-2013 0	123,639	3,898	105359	03-044-002	Replace Filters	22-Jan-2013 09:00:00	BTRUCK	I	DON	421.87
13-Feb-2013 1	123,639	3,898	107922	14-052-003	Install Radio Equipment	13-Feb-2013 13:51:15	BBODY	C	DON	0.00
23-Feb-2013 0	123,639	3,898	109250	24-043-001	Repair Emission Controls	23-Feb-2013 10:32:01	BTRUCK	O	DON	206.59
23-Feb-2013 0	123,639	3,898	109250	03-044	Replace Fuel System	21-Mar-2013 15:21:54	BTRUCK	I	DON	0.00
23-Feb-2013 0	123,639	3,898	109250	24-049-001	Repair ECM Fault Code	21-Mar-2013 15:21:33	BTRUCK	O	DON	0.00
23-Feb-2013 0	123,639	3,898	109250	24-017-001	Repair Tire - Pneumatic	08-Mar-2013 07:10:40	BTRUCK	I	DON	39.70
21-Mar-2013 1	135,020	4,300	111742	01-023-002	Adjust Clutch Assembly	03-Apr-2013 05:43:18	BTRUCK	I	DON	48.45
21-Mar-2013 1	135,020	4,300	111742	03-001-016	Replace Filter - Cab Ventilation	03-Apr-2013 05:43:18	BTRUCK	I	DON	60.01
21-Mar-2013 1	135,020	4,300	111742	03-041-001	Replace Air Cleaner	03-Apr-2013 05:43:18	BTRUCK	I	DON	467.91
21-Mar-2013 1	135,020	4,300	111742	03-045-023	Replace Engine Belts	03-Apr-2013 05:43:18	BTRUCK	I	DON	269.71
21-Mar-2013 1	135,020	4,300	111742	06-100-DOT	Inspect DOT Federal Inspection	03-Apr-2013 05:42:08	BTRUCK	P	DON	0.00
21-Mar-2013 1	135,020	4,300	111742	06-100-PMB	Inspect B PMI	03-Apr-2013 05:42:05	BTRUCK	P	DON	585.78
21-Mar-2013 1	135,020	4,300	111742	07-059-001	Lubricate Fifth Wheel - Lower Coupler Assembl	03-Apr-2013 05:43:18	BTRUCK	I	DON	145.27
21-Mar-2013 1	135,020	4,300	111742	24-002-035	Repair Windshield Wiper & Washer	03-Apr-2013 05:43:18	BTRUCK	I	DON	35.85
21-Mar-2013 1	135,020	4,300	111742	24-013-007	Repair Brake Lines & Fittings - Hydraulic & Ai	03-Apr-2013 05:43:18	BTRUCK	I	DON	101.10
21-Mar-2013 1	135,020	4,300	111742	24-013-031	Repair Drain Valve - Air Tank	03-Apr-2013 05:43:18	BTRUCK	I	DON	160.20
21-Mar-2013 1	135,020	4,300	111742	24-018-004	Repair Trailer, Converter, Tag & Pusher Axle H	03-Apr-2013 05:43:18	BTRUCK	I	DON	146.63
21-Mar-2013 1	135,020	4,300	111742	24-042-012	Repair Clamps and Hoses	03-Apr-2013 05:43:18	BTRUCK	I	DON	260.62
21-Mar-2013 1	135,020	4,300	111742	24-044-001	Repair Tank - Fuel, Liquid	03-Apr-2013 05:43:18	BTRUCK	I	DON	630.18
21-Mar-2013 1	135,020	4,300	111742	38-013-016	Service Air Dryer / Purge Valve	03-Apr-2013 05:43:18	BTRUCK	I	DON	281.08
09-Apr-2013 0	138,843	4,409	113260	24-049-001	Repair ECM Fault Code	09-Apr-2013 16:55:47	BTRUCK	O	DON	80.71
09-Apr-2013 0	138,843	4,409	113260	24-042	Repair Cooling System	10-Apr-2013 05:25:11	BTRUCK	O	DON	6.96
09-Apr-2013 0	138,843	4,409	113260	24-014-006	Repair Fuel Tank Support	10-Apr-2013 05:12:27	BTRUCK	O	DON	49.38

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: C0384 - 2012 KENWORTH T800										
09-Apr-2013 0	138,843	4,409	113260	03-043-007	Replace Exhaust Pipe/Elbow	15-Apr-2013 10:28:30	BTRUCK	I	DON	695.64
09-Apr-2013 0	138,843	4,409	113260	24-014-011	Repair Quarter Fenders	15-Apr-2013 10:38:20	BWELD	I	DON	40.40
19-Apr-2013 1	140,877		114736	03-053-005	Replace Markings - Vehicle - Decals	19-Apr-2013 15:33:07	BBODY	I	DON	27.65
19-Apr-2013 1	140,877		114736	02-002-044	Clean Cab - Complete	22-Apr-2013 06:10:29	BDETL	J	DON	42.36
19-Apr-2013 1	140,877		114736	24-049-001	Repair ECM Fault Code	08-May-2013 08:00:37	BTRUCK	I	DON	593.31
18-Jul-2013 07	143,334		124279	06-100-PMA	Inspect A PMI	18-Jul-2013 07:41:44	BTRUCK	P	DON	644.18
18-Jul-2013 07	143,334		124279	24-034-004	Repair Clearance & Marker Lamps	18-Jul-2013 07:44:23	BTRUCK	I	DON	237.25
05-Nov-2013 C	158,051		139321	03-063-003	Replace Transceiver - GPS Tracker	05-Nov-2013 00:00:00	BTRUCK	C	DON	221.39
18-Jan-2014 0			191177	03-001-026	Replace Belt - A/C Compressor		BVLOFC	F	CAN	0.00
18-Jan-2014 0			191177	03-002-065	Replace Hood Latch		BVLOFC	F	CAN	0.00
18-Jan-2014 0			191177	35-040	Diagnose Engine / Motor Systems Group		BVLOFC	F	CAN	0.00
18-Jan-2014 0			191177	03-002-010	Replace Mirrors		BVLOFC	F	CAN	0.00
05-Feb-2014 0	174,842		153117	03-044-002	Replace Filters	05-Feb-2014 17:00:00	BVLOFC	P	DON	167.65
23-Apr-2014 0	190,084		158726	01-059-001	Adjust Fifth Wheel - Lower Coupler Assembly	23-Apr-2014 17:00:00	BVLOFC	I	DON	82.12
23-Apr-2014 0	190,084		158726	06-100-PMA	Inspect A PMI	23-Apr-2014 17:00:00	BVLOFC	P	DON	489.95
23-Apr-2014 0	190,084		158726	03-034-004	Replace Clearance & Marker Lamps	23-Apr-2014 17:00:00	BVLOFC	I	DON	84.35
25-Jun-2014 0	198,864		168097	03-043-009	Replace Diesel Particulate Filter - DPF	27-Jun-2014 17:00:00	BVLOFC	F	DON	809.29
25-Jun-2014 0	198,864		168097	24-040	Repair Engine / Motor Systems Group	27-Jun-2014 17:00:00	BVLOFC	F	DON	537.84
25-Jun-2014 0	198,864		168097	24-094	Repair Lines, Tubes, Hoses & Fittings - Bulk Pr.	27-Jun-2014 17:00:00	BVLOFC	F	DON	1,003.32
25-Jun-2014 0	198,864		168097	35-001-001	Diagnose Air Conditioning Assembly	27-Jun-2014 17:00:00	BVLOFC	F	DON	114.20
25-Jun-2014 0	198,864		168097	03-049-004	Replace ECM Sensor	27-Jun-2014 17:00:00	BVLOFC	F	DON	614.60
25-Jun-2014 0	198,864		168097	35-003-001	Diagnose Gauges & Warning Devices	27-Jun-2014 17:00:00	BVLOFC	F	DON	72.19
17-Oct-2014 1			192334	03-017-001	Replace Tire - Pneumatic	17-Oct-2014 13:32:11	BTIRE	N	DON	6,166.86
04-Nov-2014 C	217,388		188654	03-043-007	Replace Exhaust Pipe/Elbow	04-Nov-2014 06:40:06	BTRUCK	I	DON	334.89
04-Nov-2014 C	217,388		188654	03-044-003	Replace Fuel Pump	04-Nov-2014 07:56:43	BTRUCK	W	DON	0.00
19-Dec-2014 1			188257	03-017-001	Replace Tire - Pneumatic	19-Dec-2014 15:59:11	BTIRE	E	DON	763.54
09-Jan-2015 0			191723	38-044	Service Fuel System	09-Jan-2015 17:00:00	BVLOFC	F	DON	710.51
18-Jan-2015 0	224,143		191183	03-001-026	Replace Belt - A/C Compressor	18-Jan-2015 17:00:00	BVLOFC	F	DON	288.73
18-Jan-2015 0	224,143		191183	03-002-010	Replace Mirrors	18-Jan-2015 17:00:00	BVLOFC	F	DON	160.60

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: C0384 - 2012 KENWORTH T800										
18-Jan-2015 00	224,143		191183	03-002-065	Replace Hood Latch	18-Jan-2015 17:00:00	BVLOFC	F	DON	136.98
18-Jan-2015 00	224,143		191183	35-040	Diagnose Engine / Motor Systems Group	18-Jan-2015 17:00:00	BVLOFC	F	DON	2,467.56
18-Jan-2015 00	224,770		191187	35-049	Diagnose Electronic Management System	18-Jan-2015 17:00:00	BVLOFC	F	DON	613.14
03-Apr-2015 0	230,407		203766	24-016-009	Repair Air Leaf Suspension	03-Apr-2015 09:46:49	BVLOFC	O	DON	345.27
24-Apr-2015 1	230,618		203771	24-012-001	Repair Axle - Non-Driven, Rear	24-Apr-2015 10:07:07	BVLOFC	O	DON	1,249.08
06-May-2015 1	230,901		203276	06-100-PMA	Inspect A PMI	06-May-2015 15:18:33	BTRUCK	P	DON	903.01
06-May-2015 1	230,901		203276	24-003-010	Repair Air Pressure Gauge (Pri/Sec)	06-May-2015 15:20:15	BVLOFC	O	DON	0.00
02-Jul-2015 16	230,618		207315	03-017-001	Replace Tire - Pneumatic	02-Jul-2015 16:30:04	BTIRE	F	DON	474.92
16-Sep-2015 1	260,608		215029	24-049-001	Repair ECM Fault Code	07-Oct-2015 09:07:30	BVLOFC	O	DON	2,956.60
16-Sep-2015 1	260,608		215029	03-043-007	Replace Exhaust Pipe/Elbow	07-Oct-2015 09:14:23	BVLOFC	I	DON	902.31
16-Sep-2015 1	260,608		215029	24-045	Repair Power Plant	07-Oct-2015 09:13:36	BVLOFC	W	DON	0.00
17-Dec-2015 1	275,426		227554	03-017-001	Replace Tire - Pneumatic	17-Dec-2015 14:17:16	BTIRE	F	DON	703.40
11-Jan-2016 14	275,426		228394	03-044-002	Replace Filters	12-Jan-2016 11:24:05	LAVSHP	P	DON	81.13
18-Jan-2016 10	275,426		229441	03-044-015	Replace Fuel Heater - Electrical	20-Jan-2016 07:40:18	LAVSHP	I	DON	150.76
26-Jan-2016 10	275,426		230782	06-100-PMA	Inspect A PMI	26-Jan-2016 13:04:19	LAVSHP	P	DON	10.78
26-Jan-2016 10	275,426		230782	03-002-010	Replace Mirrors	29-Jan-2016 14:49:34	LAVSHP	I	DON	70.88
29-Jan-2016 00			271521	35-049-001	Diagnose ECM Fault Code	03-Jan-2017 12:53:43	LAVSHP	B	DON	821.74
15-Feb-2016 00	288,451		233367	03-016-007	Replace Stabilizer (Sway) Bar - Rear	16-Feb-2016 16:26:20	LAVSHP	I	DON	124.45
15-Feb-2016 00	288,451		233367	03-016-010	Replace Air Spring	19-Feb-2016 13:34:48	LAVSHP	I	DON	525.48
15-Feb-2016 00	288,451		233367	06-100-DOT	Inspect DOT Federal Inspection	29-Feb-2016 08:00:22	LAVSHP	P	DON	513.58
15-Feb-2016 00	288,451		233367	24-044-015	Repair Fuel Heater - Electrical	25-Feb-2016 11:16:34	LAVSHP	O	DON	170.23
15-Feb-2016 00	288,451		233367	24-059-001	Repair Fifth Wheel - Lower Coupler Assembly	19-Feb-2016 14:35:59	LAVSHP	I	DON	156.43
17-Feb-2016 1			233760	03-013-015	Replace Desiccant Cartridge Kit - Air	17-Feb-2016 15:19:53	BVLOFC	O	DON	970.48
14-Mar-2016 0	295,972		237280	24-043-020	Repair Pump - DEF	18-Mar-2016 09:57:07	LAVSHP	O	CAN	0.00
14-Mar-2016 0	295,972		237280	35-043-009	Diagnose Diesel Particulate Filter - DPF	18-Mar-2016 09:57:14	LAVSHP	O	DON	789.14
14-Mar-2016 0	295,972		237280	03-043-009	Replace Diesel Particulate Filter - DPF	18-Mar-2016 09:57:14	LAVSHP	I	DON	2,476.91
14-Mar-2016 0	295,972		237280	03-044-024	Replace Fuel / Water Separator	18-Mar-2016 09:57:27	LAVSHP	I	DON	86.32
14-Mar-2016 0	295,972		237280	37-049-002	Calibrate ECM Module	18-Mar-2016 10:06:50	LAVSHP	I	DON	379.54
14-Mar-2016 0	295,972		237280	24-041	Repair Air Intake System	18-Mar-2016 10:02:18	LAVSHP	I	DON	218.02

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: C0384 - 2012 KENWORTH T800										
12-Apr-2016 0	295,972	240843	240843	24-034-008	Repair Trailer Light Cord	12-Apr-2016 07:14:48	BVLOFC	O	DON	117.21
18-Apr-2016 0	296,272	241443	241443	24-013-022	Repair Glad Hands (Service/Emergency)	18-Apr-2016 10:13:55	LAVSHP	B	DON	16.73
02-May-2016 0	302,703	243048	243048	35-049-001	Diagnose ECM Fault Code	11-May-2016 10:13:38	LAVSHP	O	DON	46.31
02-May-2016 0	302,703	243048	243048	31-017-001	Rotate Tire - Pneumatic	11-May-2016 10:16:22	LAVSHP	P	DON	72.74
02-May-2016 0	302,703	243048	243048	03-016-003	Replace Shock Absorber - Front	11-May-2016 10:15:50	LAVSHP	I	DON	537.81
02-May-2016 0	302,703	243048	243048	03-049-004	Replace ECM Sensor	11-May-2016 10:14:45	LAVSHP	I	DON	874.12
23-May-2016 0	302,703	245399	245399	01-013-002	Adjust Rear Brakes & Drums	23-May-2016 07:27:29	LAVSHP	O	DON	7.32
24-May-2016 1	309,007	245604	245604	14-079-009	Install Tape - Reflective, Conspicuity	25-May-2016 09:00:16	LAVSHP	I	DON	54.38
24-May-2016 1	309,007	245604	245604	06-100-PMA	Inspect A PMI	25-May-2016 10:49:11	BTRUCK	P	DON	206.37
21-Jun-2016 1	309,007	249025	249025	03-017-001	Replace Tire - Pneumatic	29-Jun-2016 14:31:30	BTIRE	F	DON	720.50
21-Jun-2016 1	309,007	249025	249025	06-002-035	Inspect Windshield Wiper & Washer	22-Jun-2016 15:28:21	LAVSHP	B	DON	145.03
21-Jun-2016 1	309,007	249025	249025	24-002-035	Repair Windshield Wiper & Washer	05-Jul-2016 17:36:17	LAVSHP	W	DON	56.70
13-Jul-2016 07	321,005	251672	251672	38-100-PMA	Service A PMI		LAVSHP	O	CAN	0.00
13-Jul-2016 07	321,005	251672	251672	24-078-009	Repair Mud Flaps and Hanger Brackets	13-Jul-2016 11:25:53	LAVSHP	O	DON	40.46
13-Jul-2016 07	321,005	251672	251672	06-100-PMA	Inspect A PMI	14-Jul-2016 09:12:29	LAVSHP	P	DON	205.97
14-Jul-2016 08	321,005	253065	253065	24-017-001	Repair Tire - Pneumatic	14-Jul-2016 08:45:32	BTIRE	F	DON	50.71
17-Aug-2016 1	331,378	10,077	255962	03-094-008	Replace Line - Air Supply	26-Aug-2016 11:06:13	LAVSHP	I	DON	152.03
17-Aug-2016 1	331,378	10,077	255962	06-094-008	Inspect Line - Air Supply	17-Aug-2016 12:38:13	LAVSHP	O	DON	31.99
17-Aug-2016 1	331,378	10,077	255962	11-013-007	Rebuild Brake Lines & Fittings - Hydraulic & A	18-Aug-2016 10:37:57	LAVSHP	I	DON	226.56
17-Aug-2016 1	331,378	10,077	255962	06-100-PMB	Inspect B PMI	26-Aug-2016 13:08:21	BTRUCK	P	DON	224.36
06-Sep-2016 0	337,015	260713	260713	03-017-001	Replace Tire - Pneumatic	06-Sep-2016 08:59:53	BTIRE	F	DON	1,332.16
23-Sep-2016 0	337,015	260559	260559	03-054-002	Replace Alarm - Reverse Signal	23-Sep-2016 12:28:01	LAVSHP	I	DON	76.10
23-Sep-2016 0	337,015	260559	260559	35-054-002	Diagnose Alarm - Reverse Signal	23-Sep-2016 08:30:24	LAVSHP	O	DON	17.81
27-Sep-2016 1	337,015	260887	260887	24-032-002	Repair Starter	27-Sep-2016 12:55:18	BVLOFC	O	DON	293.91
07-Oct-2016 0	338,923	262131	262131	03-052-005	Replace Transmitter - CB	07-Oct-2016 08:31:56	LAVSHP	B	DON	55.19
26-Oct-2016 1	344,302	264582	264582	03-013-017	Replace Slack Adjuster	31-Oct-2016 11:50:25	LAVSHP	B	DON	178.00
26-Oct-2016 1	344,302	264582	264582	06-100-PMA	Inspect A PMI	31-Oct-2016 12:14:55	BTRUCK	P	DON	289.55
15-Nov-2016 1	349,269	266727	266727	03-043-001	Replace Emission Controls	15-Nov-2016 10:59:10	LAVSHP	B	DON	80.69
15-Nov-2016 1	349,269	266727	266727	35-049-001	Diagnose ECM Fault Code	17-Nov-2016 14:18:07	LAVSHP	I	DON	308.82

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: C0384 - 2012 KENWORTH T800										
13-Dec-2016 0	349,269		269464	03-044-002	Replace Filters	14-Dec-2016 08:26:41	LAVSHP	O	DON	43.85
13-Dec-2016 0	349,269		269464	03-002-010	Replace Mirrors	15-Dec-2016 14:26:20	LAVSHP	B	DON	294.11
05-Jan-2017 0	349,269		271960	03-034-011	Replace Plug - Trailer Light Cord	05-Jan-2017 08:28:28	LAVSHP	O	DON	25.21
17-Feb-2017 1	358,030		277729	03-013-002	Replace Rear Brakes & Drums	03-Mar-2017 09:29:21	BTRUCK	I	DON	81.59
17-Feb-2017 1	358,030		277729	03-017-008	Replace Valve Assembly	20-Feb-2017 09:53:19	LAVSHP	I	DON	245.33
17-Feb-2017 1	358,030		277729	03-018-011	Replace Seal - Wheel	20-Feb-2017 17:51:21	LAVSHP	I	DON	124.21
17-Feb-2017 1	358,030		277729	03-034-004	Replace Clearance & Marker Lamps	20-Feb-2017 16:57:46	LAVSHP	I	DON	55.69
17-Feb-2017 1	358,030		277729	03-094-008	Replace Line - Air Supply		LAVSHP	I	WR	0.00
17-Feb-2017 1	358,030		277729	06-094-008	Inspect Line - Air Supply	20-Feb-2017 08:14:54	LAVSHP	O	DON	51.78
17-Feb-2017 1	358,030		277729	06-100-DOT	Inspect DOT Federal Inspection	20-Feb-2017 11:00:54	BTRUCK	P	DON	304.43
17-Feb-2017 1	358,030		277729	06-100-PMA	Inspect A PMI	20-Feb-2017 12:30:53	BTRUCK	P	DON	82.29
14-Apr-2017 1	359,380		285235	03-013-011	Replace Anti-Lock Sensor Assembly	14-Apr-2017 11:50:35	BVLOFC	O	DON	238.85
14-Apr-2017 1	359,380		285235	35-013-011	Diagnose Anti-Lock Sensor Assembly	14-Apr-2017 11:48:21	BVLOFC	O	DON	92.00
14-Apr-2017 1	359,443	10,891	285439	06-032-001	Inspect Battery	25-Apr-2017 16:07:59	LAVSHP	B	DON	14.45
14-Apr-2017 1	359,443	10,891	285439	03-032-001	Replace Battery	26-Apr-2017 05:28:48	LAVSHP	I	DON	58.61
14-Apr-2017 1	359,443	10,891	285439	35-049-001	Diagnose ECM Fault Code	24-Apr-2017 09:35:01	LAVSHP	B	DON	568.93
02-May-2017 1	359,551	10,906	287396	03-043-001	Replace Emission Controls	04-May-2017 18:11:04	LAVSHP	I	DON	61.53
02-May-2017 1	359,551	10,906	287396	06-018-011	Inspect Seal - Wheel	02-May-2017 18:02:00	LAVSHP	O	DON	22.30
02-May-2017 1	359,551	10,906	287396	06-023-002	Inspect Clutch Assembly	02-May-2017 17:16:40	LAVSHP	O	DON	15.44
08-May-2017 1	359,677	10,912	288022	03-043-025	Replace Filter - DEF	08-May-2017 18:25:46	LAVSHP	O	DON	165.78
12-May-2017 1	359,693	10,914	289101	03-049-003	Replace ECM Wiring Harness	17-May-2017 08:43:32	LAVSHP	B	DON	2,264.11
12-May-2017 1	359,693	10,914	289101	24-017-001	Repair Tire - Pneumatic	17-May-2017 08:48:59	BTIRE	F	DON	86.19
01-Jun-2017 0	360,659	10,955	291137	06-100-PMA	Inspect A PMI	01-Jun-2017 10:24:18	LAVSHP	P	DON	75.96
01-Jun-2017 0	360,659	10,955	291137	06-023	Inspect Clutch	01-Jun-2017 11:10:49	LAVSHP	O	DON	25.54
01-Jun-2017 0	360,659	10,955	291137	03-094	Replace Lines, Tubes, Hoses & Fittings - Bulk P	01-Jun-2017 14:08:49	LAVSHP	I	DON	387.45
01-Jun-2017 0	360,659	10,955	291137	03-094-008	Replace Line - Air Supply	01-Jun-2017 18:40:36	LAVSHP	I	DON	83.57
02-Jun-2017 1			291471	24-026-001	Repair Transmission Case	05-Jun-2017 09:02:56	ROGSHP	B	DON	17.21
06-Jun-2017 0	360,659	10,955	294052	14-052-017	Install Electronic Log Device (ELD)	06-Jun-2017 10:45:00	LAVSHP	E	DON	0.00
13-Jul-2017 10	363,318	11,024	296657	06-023-002	Inspect Clutch Assembly	17-Jul-2017 09:27:28	LAVSHP	O	DON	212.43

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: C0384 - 2012 KENWORTH T800										
13-Jul-2017 10	363,318	11,024	296657	06-032-004	Inspect Battery Cables and Ends	17-Jul-2017 07:37:56	LAVSHP	O	DON	85.94
13-Jul-2017 10	363,318	11,024	296657	06-042-012	Inspect Clamps and Hoses	13-Jul-2017 17:01:57	LAVSHP	O	DON	23.00
13-Jul-2017 10	363,318	11,024	296657	03-042-012	Replace Clamps and Hoses	14-Jul-2017 16:07:05	LAVSHP	I	DON	289.40
13-Jul-2017 10	363,318	11,024	296657	03-017-001	Replace Tire - Pneumatic	17-Jul-2017 09:45:49	BTIRE	F	DON	811.63
10-Aug-2017 1	365,507	11,086	300497	03-044-002	Replace Filters	10-Aug-2017 16:29:54	LAVSHP	O	DON	88.95
19-Sep-2017 1	367,821	11,183	305608	06-100-PMA	Inspect A PMI	19-Sep-2017 13:52:39	LAVSHP	P	DON	171.41
17-Oct-2017 1	370,360	11,265	309176	03-043-002	Replace Exhaust Manifold	19-Oct-2017 18:55:35	LAVSHP	I	DON	935.80
17-Oct-2017 1	370,360	11,265	309176	24-017-001	Repair Tire - Pneumatic	23-Oct-2017 09:20:19	BTIRE	F	DON	62.97
01-Nov-2017 1	370,360	11,265	311024	03-014-008	Replace Attaching Devices - Hoses, Lines, Tube	01-Nov-2017 13:04:47	LAVSHP	B	DON	27.94
08-Nov-2017 1	370,360	11,265	311829	19-037-021	Wire/Rewire Circuit Breaker/Fuse - Multiple Us	08-Nov-2017 10:37:27	LAVSHP	O	DON	20.20
15-Nov-2017 1	373,500	11,367	312617	06-023-002	Inspect Clutch Assembly	15-Nov-2017 10:55:47	LAVSHP	O	DON	24.42
15-Nov-2017 1	373,500	11,367	312617	03-023-007	Replace Clutch Brake	16-Nov-2017 09:29:44	LAVSHP	I	DON	201.63
04-Dec-2017 1	373,500	11,367	314608	03-023-002	Replace Clutch Assembly	04-Dec-2017 15:37:17	LAVSHP	B	DON	2,659.89
11-Dec-2017 0	373,530	11,376	315467	06-032-001	Inspect Battery	11-Dec-2017 07:46:20	LAVSHP	I	DON	9.08
11-Dec-2017 0	373,530	11,376	315467	03-032-001	Replace Battery	11-Dec-2017 08:41:55	LAVSHP	I	DON	645.66
05-Jan-2018 11	374,488	11,379	318401	25-052-017	Remove Electronic Log Device (ELD)	05-Jan-2018 11:50:52	LAVSHP	Q	DON	21.62
05-Jan-2018 11	374,488	11,379	318401	14-052-017	Install Electronic Log Device (ELD)	05-Jan-2018 15:14:41	LAVSHP	Q	DON	118.64
05-Jan-2018 11	374,488	11,379	318401	35-043-008	Diagnose EGR Valve / System	01-Feb-2018 12:32:17	LAVSHP	B	DON	693.35
05-Jan-2018 11	374,488	11,379	318401	03-043-001	Replace Emission Controls	01-Feb-2018 12:32:24	LAVSHP	I	DON	2,452.47
05-Jan-2018 11	374,488	11,379	318401	03-043-008	Replace EGR Valve / System	01-Feb-2018 12:32:21	LAVSHP	I	DON	4,838.26
05-Jan-2018 11	374,488	11,379	318401	35-049-001	Diagnose ECM Fault Code	01-Feb-2018 12:34:44	LAVSHP	B	DON	264.51
12-Feb-2018 1	374,488	11,379	323330	03-078-009	Replace Mud Flaps and Hanger Brackets	12-Feb-2018 18:20:20	LAVSHP	O	DON	12.56
01-Mar-2018 1	377,760	11,552	325651	06-100-DOT	Inspect DOT Federal Inspection	01-Mar-2018 12:32:28	LAVSHP	P	DON	44.62
01-Mar-2018 1	377,760	11,552	325651	03-018-011	Replace Seal - Wheel	01-Mar-2018 16:18:46	LAVSHP	I	DON	90.14
01-Mar-2018 1	377,760	11,552	325651	06-100-PMA	Inspect A PMI	01-Mar-2018 14:47:46	LAVSHP	P	DON	305.31
01-Mar-2018 1	377,760	11,552	325651	03-013-002	Replace Rear Brakes & Drums	02-Mar-2018 14:00:00	LAVSHP	I	DON	419.34
01-Mar-2018 1	377,760	11,552	325651	03-044-002	Replace Filters	06-Mar-2018 12:16:48	LAVSHP	B	DON	34.84
12-Mar-2018 1	378,094	11,572	326965	03-013-004	Replace Brake Chamber - Service	13-Mar-2018 07:08:32	LAVSHP	O	DON	104.53
19-Mar-2018 1	378,129		327846	06-026	Inspect Transmission - Main, Manual	20-Mar-2018 13:50:53	LAVSHP	B	DON	88.16

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: C0384 - 2012 KENWORTH T800										
19-Mar-2018 1	378,129		327846	35-003-001	Diagnose Gauges & Warning Devices	20-Mar-2018 09:24:12	LAVSHP	O	DON	67.32
19-Mar-2018 1	378,129		327846	03-042-008	Replace Oil Cooler	20-Mar-2018 13:50:57	LAVSHP	I	DON	1,104.98
22-Mar-2018 1	378,129		328302	01-042-012	Adjust Clamps and Hoses	22-Mar-2018 17:12:27	LAVSHP	I	DON	85.61
22-Mar-2018 1	378,129		328302	03-027-045	Replace Filter Assembly	23-Mar-2018 13:21:04	LAVSHP	I	DON	19.79
22-Mar-2018 1	378,129		328302	06-042	Inspect Cooling System	22-Mar-2018 11:25:10	LAVSHP	O	DON	19.79
03-Apr-2018 1	378,129		329768	06-003-001	Inspect Gauges & Warning Devices	03-Apr-2018 15:41:09	LAVSHP	O	DON	43.86
03-Apr-2018 1	378,129		329768	06-043-001	Inspect Emission Controls	09-Apr-2018 06:57:48	LAVSHP	I	DON	92.67
03-Apr-2018 1	378,129		329768	03-043-001	Replace Emission Controls	05-Apr-2018 12:07:28	LAVSHP	I	DON	177.91
20-Apr-2018 1	379,718	11,651	332262	35-049-001	Diagnose ECM Fault Code	01-May-2018 11:32:51	LAVSHP	B	DON	1,672.30
20-Apr-2018 1	379,718	11,651	332262	24-022-002	Repair Shaft - Rear Axle	26-Apr-2018 08:59:57	LAVSHP	O	DON	59.35
20-Apr-2018 1	379,718	11,651	332262	06-049-001	Inspect ECM Fault Code	26-Apr-2018 14:13:18	LAVSHP	Q	DON	33.90
20-Apr-2018 1	379,718	11,651	332262	03-043-001	Replace Emission Controls	26-Apr-2018 17:22:05	LAVSHP	I	DON	131.08
24-Apr-2018 1	379,384		332752	24-017-001	Repair Tire - Pneumatic	24-Apr-2018 17:00:14	BTRUCK	O	DON	31.46
24-Apr-2018 1	379,384		332752	03-044-002	Replace Filters	25-Apr-2018 05:57:35	BTRUCK	I	DON	92.16
24-Apr-2018 1	379,384		332752	06-100-009	Inspect Safety Check	25-Apr-2018 07:02:57	BTRUCK	I	DON	35.26
06-Jun-2018 1	382,934	11,701	338691	35-049-001	Diagnose ECM Fault Code	08-Jun-2018 09:05:01	LAVSHP	B	DON	227.57
06-Jun-2018 1	382,934	11,701	338691	03-043-022	Replace Injector - DEF	08-Jun-2018 09:04:56	LAVSHP	I	DON	499.45
06-Jun-2018 1	382,934	11,701	338691	03-042-016	Replace Fan Clutch	08-Jun-2018 09:04:52	LAVSHP	I	DON	2,348.39
22-Oct-2018 1	389,273	12,555	357695	03-052-013	Replace Antenna and Mounting	22-Oct-2018 16:02:18	LAVSHP	O	DON	100.66
01-Nov-2018 1	391,409	12,555	359221	06-100-PMA	Inspect A PMI	02-Nov-2018 16:02:40	LAVSHP	P	DON	274.53
01-Nov-2018 1	391,409	12,555	359221	06-042	Inspect Cooling System	05-Nov-2018 11:18:21	LAVSHP	O	DON	76.48
01-Nov-2018 1	391,409	12,555	359221	03-045-013	Replace Oil Pan	02-Nov-2018 15:25:27	LAVSHP	I	DON	2,062.95
01-Nov-2018 1	391,409	12,555	359221	03-044-021	Replace Seal / O-ring	05-Nov-2018 09:05:17	LAVSHP	I	DON	72.57
01-Nov-2018 1	391,409	12,555	359221	03-094-008	Replace Line - Air Supply	05-Nov-2018 10:26:51	LAVSHP	I	DON	61.96
01-Nov-2018 1	391,409	12,555	359221	03-034-002	Replace Stop, Tail, Turn & License	05-Nov-2018 11:16:33	LAVSHP	I	DON	38.21
01-Nov-2018 1	391,409	12,555	359221	06-002-010	Inspect Mirrors	05-Nov-2018 13:52:53	LAVSHP	O	DON	85.33
01-Nov-2018 1	391,409	12,555	359221	03-002-010	Replace Mirrors	05-Nov-2018 13:53:29	LAVSHP	I	DON	0.00
01-Nov-2018 1	391,409	12,555	359221	03-002-024	Replace Glass / Windshield	08-Nov-2018 10:58:05	LAVSHP	B	DON	432.45
29-Nov-2018 1	391,426	12,555	362339	35-042	Diagnose Cooling System	30-Nov-2018 11:17:11	LAVSHP	B	DON	2,092.58

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: C0384 - 2012 KENWORTH T800										
29-Nov-2018	1	391,426	12,555	362339	03-045-007	30-Nov-2018 11:17:04	LAVSHP	I	DON	14,898.19
03-Dec-2018	0	391,460	12,555	362683	06-003-001	03-Dec-2018 09:24:31	LAVSHP	O	DON	66.12
03-Dec-2018	0	391,460	12,555	362683	06-042	05-Dec-2018 14:53:11	LAVSHP	O	DON	39.13
03-Dec-2018	0	391,460	12,555	362683	03-017-001	06-Dec-2018 09:49:35	BTIRE	B	DON	1,016.64
14-Feb-2019	1	395,419	12,555	372591	02-002-035	14-Feb-2019 14:39:36	LAVSHP	B	DON	11.23
14-Feb-2019	1	395,419	12,555	372591	03-002-010	14-Feb-2019 14:39:18	LAVSHP	B	DON	21.60
14-Feb-2019	1	395,419	12,555	372591	03-013-022	14-Feb-2019 14:39:28	LAVSHP	B	DON	6.41
14-Feb-2019	1	395,419	12,555	372591	03-002-035	14-Feb-2019 15:01:45	LAVSHP	B	DON	13.44
21-Feb-2019	0	395,419	12,555	373512	24-054-002	22-Feb-2019 08:47:31	LAVSHP	I	DON	126.09
13-Mar-2019	1	396,463	376498	06-100-DOT	Inspect DOT Federal Inspection	14-Mar-2019 15:52:28	LAVSHP	P	DON	87.23
26-Apr-2019	0	396,463	382990	06-003-001	Inspect Gauges & Warning Devices	26-Apr-2019 08:56:10	LAVSHP	O	DON	27.65
26-Apr-2019	0	396,463	382990	03-040	Replace Engine / Motor Systems Group		LAVSHP	I	CAN	0.00
26-Apr-2019	0	396,463	382990	03-044-002	Replace Filters	26-Apr-2019 09:42:26	LAVSHP	I	DON	28.55
02-May-2019	1	397,641	384076	06-022-001	Inspect Axle Housing, Rear	08-May-2019 08:54:24	LAVSHP	B	DON	319.51
02-May-2019	1	397,641	384076	34-044-014	Reseal Injectors - Electronic	08-May-2019 08:54:21	LAVSHP	W	DON	0.00
14-May-2019	1	397,641	385726	03-034-006	Replace Warning Lamps - Special Application	14-May-2019 16:50:13	LAVSHP	O	DON	495.60
29-May-2019	1	399,375	387669	35-049-001	Diagnose ECM Fault Code	17-Jun-2019 09:52:52	LAVSHP	O	DON	71.11
29-May-2019	1	399,375	387669	03-034-004	Replace Clearance & Marker Lamps	30-May-2019 17:33:02	LAVSHP	O	DON	136.79
29-May-2019	1	399,375	387669	06-001	Inspect Air Conditioning, Heating & Ventilating	06-Jun-2019 18:03:43	LAVSHP	O	DON	360.12
29-May-2019	1	399,375	387669	03-017-001	Replace Tire - Pneumatic	29-May-2019 13:23:57	BTIRE	P	DON	2,547.07
29-May-2019	1	399,375	387669	03-034-001	Replace Headlamps / Fog Lamps	30-May-2019 19:08:00	LAVSHP	I	DON	67.92
29-May-2019	1	399,375	387669	03-013-007	Replace Brake Lines & Fittings - Hydraulic & A	17-Jun-2019 11:22:10	LAVSHP	I	DON	131.32
29-May-2019	1	399,375	387669	03-001-017	Replace A/C Hose / Line	06-Jun-2019 10:12:00	LAVSHP	I	DON	835.74
15-Jul-2019	12	403,872	14,151	394203	24-044-004	15-Jul-2019 12:43:49	BVLOFC	O	DON	1,287.54
17-Jul-2019	08	403,872	14,151	394555	03-013-007	17-Jul-2019 08:44:28	LAVSHP	I	DON	54.73
23-Jul-2019	06	403,891	14,154	395323	03-034-001	23-Jul-2019 12:03:14	LAVSHP	I	DON	34.58
23-Jul-2019	06	403,891	14,154	395323	03-045-023	23-Jul-2019 12:48:28	LAVSHP	I	DON	120.99
23-Jul-2019	06	403,891	14,154	395323	06-100-PMA	23-Jul-2019 07:48:00	LAVSHP	P	DON	63.95
23-Jul-2019	06	403,891	14,154	395323	38-100-PMA	23-Jul-2019 11:15:30	LAVSHP	P	DON	376.06

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: C0384 - 2012 KENWORTH T800										
02-Aug-2019	1	403,911	397064	03-044-014	Replace Injectors - Electronic	05-Aug-2019 09:04:49	LAVSHP	B	DON	4,131.92
07-Aug-2019	1	404,534	397641	06-031	Inspect Charging System	07-Aug-2019 12:14:59	LAVSHP	O	DON	77.86
07-Aug-2019	1	404,534	397641	03-031-001	Replace Generator/Alternator	08-Aug-2019 07:18:42	LAVSHP	I	DON	499.42
14-Aug-2019	1	405,616	398722	06-001	Inspect Air Conditioning, Heating & Ventilating	14-Aug-2019 17:35:31	LAVSHP	O	DON	71.14
14-Aug-2019	1	405,616	398722	03-034-014	Replace Auxiliary Work / Flood Light	21-Aug-2019 13:22:30	LAVSHP	O	DON	253.62
14-Oct-2019	0	411,249	407368	03-016-019	Replace Locking Device - Ride Height	28-Oct-2019 14:42:53	LAVSHP	I	DON	99.83
14-Oct-2019	0	411,249	407368	03-013-024	Replace Air Tank (Pri / Sec / Wet)	28-Oct-2019 17:37:10	LAVSHP	I	DON	1,181.30
14-Oct-2019	0	411,249	407368	03-016-006	Replace Shock Absorber - Rear	16-Oct-2019 11:01:10	LAVSHP	I	DON	709.94
14-Oct-2019	0	411,249	407368	03-018-012	Replace Cap - Hub	17-Oct-2019 10:53:29	LAVSHP	I	DON	22.23
14-Oct-2019	0	411,249	407368	03-013-002	Replace Rear Brakes & Drums	17-Oct-2019 07:44:36	LAVSHP	I	DON	952.93
14-Oct-2019	0	411,249	407368	03-042-007	Replace Coolant Filter	17-Oct-2019 10:52:49	LAVSHP	I	DON	103.05
08-Nov-2019	1	413,891	411799	03-002-035	Replace Windshield Wiper & Washer	08-Nov-2019 10:48:50	LAVSHP	O	DON	45.99
08-Nov-2019	1	413,891	411799	03-017-001	Replace Tire - Pneumatic	13-Nov-2019 11:14:23	BTIRE	P	DON	4,517.27
08-Nov-2019	1	413,891	411799	06-100-PMA	Inspect A PMI	08-Nov-2019 10:42:30	LAVSHP	P	DON	18.46
08-Nov-2019	1	413,891	411799	38-100-PMA	Service A PMI	08-Nov-2019 16:00:03	LAVSHP	P	DON	382.89
21-Jan-2020	0	420,190	422105	03-044-024	Replace Fuel / Water Separator	21-Jan-2020 10:49:33	ME1371	B	DON	90.61
23-Jan-2020	1	420,194	422606	03-042-007	Replace Coolant Filter	23-Jan-2020 13:31:44	LAVSHP	I	DON	102.95
23-Jan-2020	1	420,194	422606	03-042-012	Replace Clamps and Hoses	23-Jan-2020 13:31:40	LAVSHP	I	DON	343.17
23-Jan-2020	1	420,194	422606	06-100-PMA	Inspect A PMI	23-Jan-2020 13:34:52	LAVSHP	P	DON	57.19
23-Jan-2020	1	420,194	422606	24-013-018	Repair S-Cam	23-Jan-2020 13:31:50	LAVSHP	I	DON	42.79
23-Jan-2020	1	420,194	422606	24-019-006	Repair Block Assembly - Grease Distribution	23-Jan-2020 13:31:46	LAVSHP	I	DON	229.93
23-Jan-2020	1	420,194	422606	34-018-004	Reseal Trailer, Converter, Tag & Pusher Axle H	23-Jan-2020 13:31:37	LAVSHP	I	DON	249.04
23-Jan-2020	1	420,194	422606	38-100-PMA	Service A PMI	23-Jan-2020 13:34:48	LAVSHP	I	DON	547.95
05-Feb-2020	0	423,955	424819	03-013-001	Replace Front Brakes & Drums	05-Feb-2020 10:10:11	BTRUCK	O	DON	418.34
11-Mar-2020	1	424,271	430509	06-100-DOT	Inspect DOT Federal Inspection	12-Mar-2020 06:17:13	LAVSHP	P	DON	108.88
11-Mar-2020	1	424,271	430509	06-017-001	Inspect Tire - Pneumatic	11-Mar-2020 16:19:23	LAVSHP	I	DON	64.44
21-Apr-2020	1	424,942	437159	03-017-001	Replace Tire - Pneumatic	22-Apr-2020 05:19:50	BTIRE	B	DON	29.99
03-Jun-2020	1	426,994	443540	03-001-017	Replace A/C Hose / Line	08-Jun-2020 09:29:33	LAVSHP	I	DON	849.22
03-Jun-2020	1	426,994	443540	06-001	Inspect Air Conditioning, Heating & Ventilating	03-Jun-2020 11:45:20	LAVSHP	O	DON	22.63

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: C0384 - 2012 KENWORTH T800										
23-Jun-2020 0	427,808	14,951	446959	03-001-017	Replace A/C Hose / Line	23-Jun-2020 17:37:53	LAVSHP	I	DON	376.78
23-Jun-2020 0	427,808	14,951	446959	24-002-024	Repair Glass / Windshield	30-Jun-2020 12:35:32	LAVSHP	O	DON	71.76
29-Jul-2020 14	429,308	15,019	453284	06-001-001	Inspect Air Conditioning Assembly	29-Jul-2020 17:15:08	LAVSHP	I	DON	110.55
29-Jul-2020 14	429,308	15,019	453284	06-034-003	Inspect Signal, Parking, Backup Lamps		LAVSHP	I	CAN	0.00
29-Jul-2020 14	429,308	15,019	453284	03-054-002	Replace Alarm - Reverse Signal	30-Jul-2020 06:04:30	LAVSHP	I	DON	77.06
29-Jul-2020 14	429,308	15,019	453284	03-001-012	Replace Condenser Assembly	03-Aug-2020 09:43:00	LAVSHP	I	DON	694.01
30-Jul-2020 07	429,499	15,026	453401	03-034-001	Replace Headlamps / Fog Lamps	30-Jul-2020 07:47:25	ROGSHP	N	DON	15.68
14-Aug-2020 1	430,224	15,059	456185	06-100-PMA	Inspect A PMI	14-Aug-2020 13:42:59	LAVSHP	P	DON	42.96
14-Aug-2020 1	430,224	15,059	456185	38-100-PMA	Service A PMI	14-Aug-2020 16:16:01	LAVSHP	P	DON	323.93
26-Aug-2020 1	431,470	15,106	458205	03-001-010	Replace Compressor Assembly - Air Cond	28-Aug-2020 10:46:22	LAVSHP	P	DON	2,080.47
02-Nov-2020 C	436,009	15,331	470246	06-045-021	Inspect Electronic Engine Controls	09-Nov-2020 00:00:00	BVLOFC	B	DON	1,426.25
01-Dec-2020 0	438,905	15,376	474334	06-034-004	Inspect Clearance & Marker Lamps	01-Dec-2020 08:56:07	LAVSHP	O	DON	9.27
01-Dec-2020 0	438,905	15,376	474334	35-049-001	Diagnose ECM Fault Code	10-Dec-2020 08:54:03	LAVSHP	B	DON	768.82
01-Dec-2020 0	438,905	15,376	474334	03-043-009	Replace Diesel Particulate Filter - DPF	10-Dec-2020 08:54:00	LAVSHP	B	DON	7,063.23
11-Feb-2021 0	440,431	15,424	487484	03-044-002	Replace Filters	11-Feb-2021 10:10:15	TRK400	P	DON	166.53
15-Mar-2021 1	440,431	15,424	494239	38-100-PMA	Service A PMI	16-Mar-2021 07:26:34	LAVSHP	P	DON	369.54
15-Mar-2021 1	440,431	15,424	494239	03-044-017	Replace Indicator/Sender - Fuel Level	23-Mar-2021 11:46:32	LAVSHP	O	DON	634.46
15-Mar-2021 1	440,431	15,424	494239	06-100-DOT	Inspect DOT Federal Inspection	16-Mar-2021 08:20:05	LAVSHP	P	DON	90.50
15-Mar-2021 1	440,431	15,424	494239	03-013-018	Replace S-Cam	22-Mar-2021 12:05:06	LAVSHP	I	DON	951.61
15-Mar-2021 1	440,431	15,424	494239	03-013-020	Replace Break Away Battery		LAVSHP	P	CAN	0.00
15-Mar-2021 1	440,431	15,424	494239	03-018-004	Replace Trailer, Converter, Tag & Pusher Axle	25-Mar-2021 14:55:30	LAVSHP	I	DON	632.68
15-Mar-2021 1	440,431	15,424	494239	25-079-002	Remove Headache Rack	25-Mar-2021 16:42:59	LAVSHP	Z	DON	115.87
15-Mar-2021 1	440,431	15,424	494239	06-100-PMA	Inspect A PMI	29-Mar-2021 12:41:33	SCHED	P	DON	0.00
12-Apr-2021 1	440,524	15,424	500035	24-045	Repair Power Plant	27-Apr-2021 09:16:53	BTRUCK	I	DON	784.93
12-Apr-2021 1	440,524	15,424	500035	01-042	Adjust Cooling System	28-Apr-2021 08:39:27	BTRUCK	I	DON	195.96
12-Apr-2021 1	440,524	15,424	500035	03-002-035	Replace Windshield Wiper & Washer	20-Apr-2021 10:49:22	BTRUCK	I	DON	27.64
12-Apr-2021 1	440,524	15,424	500035	03-016-002	Replace Chassis Spring - Front	21-May-2021 14:14:17	BTRUCK	I	DON	960.29
12-Apr-2021 1	440,524	15,424	500035	03-016-008	Replace Air Ride Suspension	23-Apr-2021 12:00:03	BTRUCK	I	DON	439.72
12-Apr-2021 1	440,524	15,424	500035	03-013-010	Replace Air Brake Valve	20-Apr-2021 13:39:18	BTRUCK	I	DON	295.69

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: C0384 - 2012 KENWORTH T800										
12-Apr-2021	1	440,524	15,424	500035	03-051-009	Replace Fire Extinguisher	BTRUCK	Q	DON	136.60
12-Apr-2021	1	440,524	15,424	500035	03-078-009	Replace Mud Flaps and Hanger Brackets	BTRUCK	I	DON	165.68
12-Apr-2021	1	440,524	15,424	500035	03-024-005	Replace Universal Joint	BTRUCK	I	CAN	0.00
12-Apr-2021	1	440,524	15,424	500035	03-026-020	Replace Seal - Output	BTRUCK	I	DON	1,108.17
12-Apr-2021	1	440,524	15,424	500035	14-013-022	Install Glad Hands (Service/Emergency)	BTRUCK	I	DON	101.97
12-Apr-2021	1	440,524	15,424	500035	19-079-002	Wire/Rewire Headache Rack	BTRUCK	I	DON	848.02
12-Apr-2021	1	440,524	15,424	500035	24-013-032	Repair ABS - ECU	BTRUCK	I	DON	53.77
12-Apr-2021	1	440,524	15,424	500035	24-022-004	Repair Power Divider & Inter-Axle Differential	BTRUCK	I	CAN	0.00
12-Apr-2021	1	440,524	15,424	500035	24-042-009	Repair Coolant Pre-Heater- Electrical	BTRUCK	I	DON	31.42
12-Apr-2021	1	440,524	15,424	500035	24-043	Repair Exhaust System	BTRUCK	I	DON	817.99
12-Apr-2021	1	440,524	15,424	500035	24-078-002	Repair Fender Assembly - Rear	BTRUCK	I	DON	747.58
12-Apr-2021	1	440,524	15,424	500035	26-014-001	Weld Frame Assembly	BTRUCK	I	DON	270.43
12-Apr-2021	1	440,524	15,424	500035	24-042	Repair Cooling System	BTRUCK	O	DON	173.63
12-Apr-2021	1	440,524	15,424	500035	06-100-009	Inspect Safety Check	BTRUCK	P	DON	251.04
12-Apr-2021	1	440,524	15,424	500035	02-002	Clean Cab & Sheet Metal	BSETUP	I	DON	780.70
12-Apr-2021	1	440,524	15,424	500035	03-015-004	Replace Steering Linkage	BTRUCK	I	DON	202.79
12-Apr-2021	1	440,524	15,424	500035	06-001-017	Inspect A/C Hose / Line	BTRUCK	I	DON	131.43
12-Apr-2021	1	440,524	15,424	500035	14-079-002	Install Headache Rack	BTRUCK	I	DON	404.95
12-Apr-2021	1	440,524	15,424	500035	03-518-003	Replace Catwalk	BTRUCK	I	DON	42.08
12-Apr-2021	1	440,524	15,424	500035	03-506-001	Replace Fuel Tank	BTRUCK	I	DON	315.39
12-Apr-2021	1	440,524	15,424	500035	24-506-001	Repair Fuel Tank	BWELD	N	DON	390.52
12-Apr-2021	1	440,524	15,424	500035	06-100-PMB	Inspect B PMI	SCHED	P	DON	41.23
12-Apr-2021	1	440,524	15,424	500035	03-002-061	Replace Seat Cushion	BTRUCK	I	DON	179.15
12-Apr-2021	1	440,524	15,424	500035	03-034-002	Replace Stop, Tail, Turn & License	BTRUCK	I	DON	30.52
12-Apr-2021	1	440,524	15,424	500035	03-054-002	Replace Alarm - Reverse Signal	BTRUCK	I	DON	38.72
12-Apr-2021	1	440,524	15,424	500035	03-014-006	Replace Fuel Tank Support	BTRUCK	I	DON	92.51
12-Apr-2021	1	440,524	15,424	500035	24-012-001	Repair Axle - Non-Driven, Rear	BTRUCK	O	DON	54.75
17-Aug-2021	1	440,525	15,424	525767	06-100-009	Inspect Safety Check	BTRUCK	P	DON	40.15
17-Aug-2021	1	440,525	15,424	525767	03-032-001	Replace Battery	BTRUCK	I	DON	408.84

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: C0384 - 2012 KENWORTH T800										
17-Aug-2021	440,525	15,424	525767	03-034-001	Replace Headlamps / Fog Lamps	17-Aug-2021 16:00:46	BTRUCK	I	DON	42.18
17-Aug-2021	440,525	15,424	525767	03-034-004	Replace Clearance & Marker Lamps	17-Aug-2021 17:08:04	BTRUCK	I	DON	113.64
24-Aug-2021	441,315	15,424	527093	20-010	Tow Chassis Group	07-Sep-2021 11:42:45	BVLOFC	B	DON	1,065.83
24-Aug-2021	441,315	15,424	527093	03-013-009	Replace Air Compressor	07-Sep-2021 11:42:32	BVLOFC	B	DON	6,169.73
24-Aug-2021	441,315	15,424	527093	03-032-001	Replace Battery	07-Sep-2021 11:42:36	BVLOFC	I	DON	1,651.99
24-Aug-2021	441,315	15,424	527093	24-030	Repair Electrical Group	07-Sep-2021 11:42:41	BVLOFC	I	DON	190.04
24-Aug-2021	441,315	15,424	527093	03-045-026	Replace Tensioner - Engine Belts	07-Sep-2021 11:48:59	BVLOFC	I	DON	740.79
14-Sep-2021	441,315	15,424	531352	24-013-016	Repair Air Dryer / Purge Valve	15-Sep-2021 05:29:06	BVLOFC	I	DON	1,291.09
08-Dec-2021	444,484	15,424	552103	03-044-002	Replace Filters	09-Dec-2021 06:22:38	BTRUCK	O	DON	261.78
08-Dec-2021	444,484	15,424	552103	03-054-002	Replace Alarm - Reverse Signal	10-Dec-2021 06:53:31	BTRUCK	I	DON	100.21
08-Dec-2021	444,484	15,424	552103	03-043-004	Replace Turbocharger	07-Mar-2022 06:31:26	BTRUCK	I	DON	8,201.64
08-Dec-2021	444,484	15,424	552103	03-044-003	Replace Fuel Pump	09-Dec-2021 16:16:31	BTRUCK	I	DON	23.57
08-Dec-2021	444,484	15,424	552103	03-063-003	Replace Transceiver - GPS Tracker	09-Dec-2021 07:56:14	BTRUCK	Q	DON	400.79
08-Dec-2021	444,484	15,424	552103	03-052-014	Replace Cellular Telephone Accessories	09-Dec-2021 09:44:38	BTRUCK	I	DON	75.06
08-Dec-2021	444,484	15,424	552103	02-002	Clean Cab & Sheet Metal	07-Mar-2022 06:27:58	BSETUP	I	DON	423.41
08-Dec-2021	444,484	15,424	552103	14-034-011	Install Plug - Trailer Light Cord	07-Mar-2022 06:27:41	BTRLR	O	DON	42.90
08-Dec-2021	444,484	15,424	552103	24-002-017	Repair Cab Or Front Door Panels	07-Mar-2022 13:20:06	BTRUCK	I	DON	40.75
08-Dec-2021	444,484	15,424	552103	14-002-060	Install Seat Belt	07-Mar-2022 11:36:33	BTRUCK	P	DON	12.44
08-Dec-2021	444,484	15,424	552103	03-078-009	Replace Mud Flaps and Hanger Brackets	07-Mar-2022 11:21:30	BTRUCK	I	DON	24.82
08-Dec-2021	444,484	15,424	552103	06-100-DOT	Inspect DOT Federal Inspection	07-Mar-2022 10:43:50	BTRUCK	P	DON	27.37
08-Dec-2021	444,484	15,424	552103	06-100-PMB	Inspect B PMI	07-Mar-2022 10:02:18	BTRUCK	P	DON	60.74
08-Dec-2021	444,484	15,424	552103	03-013-022	Replace Glad Hands (Service/Emergency)	07-Mar-2022 07:58:11	BTRUCK	P	DON	10.92
08-Dec-2021	444,484	15,424	552103	03-051-009	Replace Fire Extinguisher	07-Mar-2022 08:30:08	BTRUCK	Q	DON	172.90
07-Feb-2022	444,484	15,424	564539	14-052-017	Install Electronic Log Device (ELD)	07-Feb-2022 07:26:39	BSETUP	Q	DON	111.67
12-Apr-2022	444,484	15,424	581229	02-002	Clean Cab & Sheet Metal	13-Apr-2022 07:36:28	BSETUP	N	DON	459.34
12-Apr-2022	444,484	15,424	581229	03-052-014	Replace Cellular Telephone Accessories	19-May-2022 10:38:32	BSETUP	N	DON	26.72
13-May-2022	444,484	15,424	588757	03-043-022	Replace Injector - DEF	18-May-2022 20:54:35	MA0722	B	DON	1,378.64
13-May-2022	444,484	15,424	588757	35-043-022	Diagnose Injector - DEF	15-May-2022 15:19:12	MA0722	B	DON	1,045.58
13-May-2022	444,484	15,424	588757	06-043-030	Inspect Aftertreatment Regeneration Device (AF	19-May-2022 06:38:01	MB2290	I	DON	470.51

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: C0384 - 2012 KENWORTH T800										
16-May-2022	444,484	15,424	589088	03-043-020	Replace Pump - DEF	19-May-2022 16:40:07	BVLOFC	I	DON	2,912.12
03-Jun-2022	444,484	15,424	593447	24-044-001	Repair Tank - Fuel, Liquid	03-Jun-2022 18:18:34	TRK022	B	DON	104.56
03-Jun-2022	444,484	15,424	593447	01-023-002	Adjust Clutch Assembly	12-Jun-2022 21:35:54	MA0722	B	DON	235.26
17-Jun-2022	444,484	15,424	596847	01-003	Adjust Instruments, Gauges, Warning & Shutdo	19-Jun-2022 19:22:03	MB2290	I	DON	104.56
17-Jun-2022	444,484	15,424	596847	03-044-001	Replace Tank - Fuel, Liquid	24-Jun-2022 09:41:58	MB2290	I	DON	2,822.96
17-Jun-2022	444,484	15,424	596847	03-026-017	Replace Shifter Knob	25-Jun-2022 08:48:15	TRK022	B	DON	634.89
15-Aug-2022	444,484	15,424	610899	01-044-024	Adjust Fuel / Water Separator	20-Aug-2022 18:36:35	MA0722	B	DON	104.56
24-Aug-2022	444,484	15,424	612047	01-013	Adjust Brakes	25-Aug-2022 14:48:40	MB2290	I	DON	313.68
30-Aug-2022	444,484	15,424	613229	06-100-PMA	Inspect A PMI	30-Aug-2022 16:29:03	TRK022	P	DON	0.00
30-Aug-2022	444,484	15,424	613229	06-100-PMB	Inspect B PMI	30-Aug-2022 16:29:08	TRK022	P	DON	0.00
30-Aug-2022	444,484	15,424	613229	38-100-PMA	Service A PMI	27-Sep-2022 09:43:01	TRK022	P	DON	1,342.90
15-Sep-2022	444,484	15,424	616892	06-003-001	Inspect Gauges & Warning Devices	16-Sep-2022 09:50:31	MB2290	I	DON	209.12
15-Sep-2022	444,484	15,424	616892	01-002-060	Adjust Seat Belt	17-Sep-2022 13:14:53	TRK026	O	DON	52.28
15-Sep-2022	444,484	15,424	616892	03-002-060	Replace Seat Belt	12-Oct-2022 13:16:28	TRK026	O	DON	213.43
15-Sep-2022	444,484	15,424	616892	03-002-065	Replace Hood Latch	21-Sep-2022 07:23:21	TRK023	O	DON	51.03
15-Sep-2022	444,484	15,424	616892	01-059-005	Adjust King Pin Assembly	29-Sep-2022 18:36:56	MB2290	I	DON	209.12
10-Oct-2022	444,484	15,424	623041	25-052-017	Remove Electronic Log Device (ELD)	10-Oct-2022 13:00:14	ELEC02	Q	DON	45.61
02-Nov-2022	444,484	15,424	629212	01-049-001	Adjust ECM Fault Code	03-Nov-2022 07:23:04	MB2290	O	DON	392.09
02-Nov-2022	444,484	15,424	629212	03-017-001	Replace Tire - Pneumatic	05-Dec-2022 14:55:26	MB2290	N	DON	2,494.64
21-Nov-2022	444,484	15,424	650658	03-017-001	Replace Tire - Pneumatic	21-Nov-2022 10:42:00	MB2290	N	DON	196.83
21-Nov-2022	444,484	15,424	644651	03-017-001	Replace Tire - Pneumatic	05-Dec-2022 07:48:30	MB2290	N	CAN	0.00
05-Dec-2022	444,484	15,424	636711	38-100-PMA	Service A PMI	05-Dec-2022 07:48:00	TRK022	P	DON	211.70
05-Dec-2022	444,484	15,424	636711	06-100-PMA	Inspect A PMI	05-Dec-2022 07:48:00	TRK022	P	DON	0.00
07-Dec-2022	444,484	15,424	637439	01-002-002	Adjust Fenders	16-Dec-2022 09:41:58	MB2290	O	CAN	0.00
07-Dec-2022	444,484	15,424	637439	03-059-005	Replace King Pin Assembly	11-Dec-2022 08:58:53	MB2290	I	DON	125.89
08-Feb-2023	444,484	15,424	651864	25-002-002	Remove Fenders	10-Feb-2023 10:10:21	MB2290	E	DON	174.92
08-Feb-2023	444,484	15,424	651864	03-002-002	Replace Fenders	05-Mar-2023 15:26:48	MB2290	E	DON	417.35
08-Feb-2023	444,484	15,424	651864	01-013-022	Adjust Glad Hands (Service/Emergency)	23-Feb-2023 07:22:14	MB2290	E	DON	574.25
22-Mar-2023	444,484	15,424	660943	03-017-001	Replace Tire - Pneumatic	03-Apr-2023 06:27:38	MPNSHIP	I	DON	9.63

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: C0384 - 2012 KENWORTH T800										
22-Mar-2023 0	444,484	15,424	660943	06-100-DOT	Inspect DOT Federal Inspection	28-Mar-2023 11:28:27	MPNSHP	P	DON	242.39
22-Mar-2023 0	444,484	15,424	660943	06-100-PMB	Inspect B PMI	28-Mar-2023 11:30:15	MPNSHP	P	DON	149.85
22-Mar-2023 0	444,484	15,424	660943	03-034-006	Replace Warning Lamps - Special Application	23-Mar-2023 13:58:16	MPNSHP	I	DON	54.96
22-Mar-2023 0	444,484	15,424	660943	03-051-009	Replace Fire Extinguisher	23-Mar-2023 06:10:49	MPNSHP	Q	DON	47.86
22-Mar-2023 0	444,484	15,424	660943	03-026-020	Replace Seal - Output	29-Mar-2023 07:23:13	MPNSHP	I	DON	234.80
22-Mar-2023 0	444,484	15,424	660943	03-034-014	Replace Auxiliary Work / Flood Light	23-Mar-2023 14:43:32	MPNSHP	I	DON	65.93
22-Mar-2023 0	444,484	15,424	660943	03-042-012	Replace Clamps and Hoses	03-Apr-2023 06:12:06	MPNSHP	I	DON	647.47
22-Mar-2023 0	444,484	15,424	660943	14-052-013	Install Antenna and Mounting	24-Mar-2023 11:58:43	MPNSHP	I	DON	62.63
22-Mar-2023 0	444,484	15,424	660943	03-054-002	Replace Alarm - Reverse Signal	23-Mar-2023 08:22:50	MPNSHP	I	DON	83.13
22-Mar-2023 0	444,484	15,424	660943	03-052-009	Replace Speakers	23-Mar-2023 15:21:00	MPNSHP	I	DON	79.70
22-Mar-2023 0	444,484	15,424	660943	03-052-014	Replace Cellular Telephone Accessories	23-Mar-2023 15:43:18	MPNSHP	I	DON	40.32
22-Mar-2023 0	444,484	15,424	660943	14-078-009	Install Mud Flaps and Hanger Brackets	28-Mar-2023 10:43:56	MPNSHP	E	DON	3,022.44
22-Mar-2023 0	444,484	15,424	660943	03-034-012	Replace Box - Junction	23-Mar-2023 15:51:45	MPNSHP	I	DON	157.63
22-Mar-2023 0	444,484	15,424	660943	38-100-PMA	Service A PMI	24-Mar-2023 14:54:30	MPNSHP	P	DON	209.78
22-Mar-2023 0	444,484	15,424	660943	24-015-005	Repair Power Steering Pump	28-Mar-2023 11:31:52	MPNSHP	I	DON	44.79
22-Mar-2023 0	444,484	15,424	660943	01-033-001	Adjust Ignition Switch	23-Mar-2023 15:56:09	MPNSHP	I	DON	4.09
18-Apr-2023 0	444,484	15,424	668122	03-042-002	Replace Radiator	20-Apr-2023 20:09:14	TRK022	B	DON	4,622.20
18-Apr-2023 0	444,484	15,424	668122	35-042-002	Diagnose Radiator	03-May-2023 09:50:01	TRK022	B	DON	262.38
18-Apr-2023 0	444,484	15,424	668122	95-MSC-005	Travel Parts - Serialized	22-Apr-2023 17:40:50	TRK022	B	DON	393.57
27-Jun-2023 0	444,484	15,424	685556	03-013-003	Replace Brake Chamber - Parking	30-Jun-2023 18:00:02	TRK022	B	DON	348.38
27-Jun-2023 0	444,484	15,424	685556	03-032-002	Replace Starter	30-Jun-2023 17:58:52	TRK022	B	DON	587.03
27-Jun-2023 0	444,484	15,424	685556	35-013-010	Diagnose Air Brake Valve	30-Jun-2023 18:07:52	TRK022	B	DON	262.38
27-Jun-2023 0	444,484	15,424	685556	35-032-002	Diagnose Starter	30-Jun-2023 17:56:21	TRK022	B	DON	262.38
27-Jun-2023 0	444,484	15,424	685556	95-032-002	Travel Starter	30-Jun-2023 18:05:13	TRK022	B	DON	524.76
27-Jun-2023 0	444,484	15,424	685556	03-013-010	Replace Air Brake Valve	30-Jun-2023 18:05:13	TRK022	B	WR	183.99
27-Jun-2023 0	444,484	15,424	685556	07-059-001	Lubricate Fifth Wheel - Lower Coupler Assembl	30-Jun-2023 18:10:40	TRK022	B	DON	131.19
10-Jul-2023 00	444,484	15,424	687718	03-016-011	Replace Leveling Valve	10-Jul-2023 00:00:00	ME1287	B	DON	174.92
08-Aug-2023 0	444,484	15,424	696344	03-013-007	Replace Brake Lines & Fittings - Hydraulic & A	08-Aug-2023 00:00:00	ME1287	B	DON	243.87
29-Aug-2023 2	444,484	15,424	702226	35-013-007	Diagnose Brake Lines & Fittings - Hydraulic &	03-Sep-2023 21:01:43	TRK026	I	DON	327.98

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: C0384 - 2012 KENWORTH T800										
29-Aug-2023 2	444,484	15,424	702226	03-016-011	Replace Leveling Valve	21-Sep-2023 00:00:00	TRK026	I	DON	532.64
29-Aug-2023 2	444,484	15,424	702226	03-059-001	Replace Fifth Wheel - Lower Coupler Assembly	20-Sep-2023 00:00:00	ME1287	I	DON	391.95
05-Oct-2023 0	444,484	15,424	710978	24-059-001	Repair Fifth Wheel - Lower Coupler Assembly	05-Oct-2023 00:00:00	ME1287	B	DON	218.65
16-Oct-2023 0	444,484	15,424	713435	06-100-WIN	Inspect Winterization Inspection	16-Oct-2023 00:00:00	ME1287	P	DON	43.73
16-Oct-2023 0	444,484	15,424	713435	03-016-008	Replace Air Ride Suspension	19-Oct-2023 06:49:56	TRK022	B	DON	330.28
18-Oct-2023 0	444,484	15,424	714075	01-023-001	Adjust Linkage - Mechanical Clutch	19-Oct-2023 06:52:44	TRK022	B	DON	262.38
18-Oct-2023 0	444,484	15,424	714075	03-026-018	Replace Range Selector Hi / Low	25-Oct-2023 17:45:32	TRK022	B	DON	633.03
18-Oct-2023 0	444,484	15,424	714075	03-078-009	Replace Mud Flaps and Hanger Brackets	29-Oct-2023 13:17:36	TRK022	B	DON	271.87
01-Nov-2023 C	444,484	15,424	717917	03-026-018	Replace Range Selector Hi / Low	11-Dec-2023 08:43:03	ME1287	B	DON	634.37
01-Nov-2023 C	444,484	15,424	717917	35-003-001	Diagnose Gauges & Warning Devices	29-Nov-2023 00:00:00	ME1287	B	DON	174.92
11-Dec-2023 0	444,484	15,424	727072	06-100-PMC	Inspect C PMI	11-Dec-2023 00:00:00	ME1287	P	DON	87.46
28-Dec-2023 0	444,484	15,424	729314	14-053-102	Install VIN Tag/Plate	28-Dec-2023 00:00:00	ME1287	N	DON	43.73
08-Jan-2024 0	444,484	15,424	730983	03-023-002	Replace Clutch Assembly	31-Jan-2024 14:40:03	BVLOFC	N	DON	1,746.67
08-Jan-2024 0	444,484	15,424	730983	03-026-012	Replace Transmission Assembly - Manual	31-Jan-2024 14:40:06	BVLOFC	B	DON	11,129.62
08-Jan-2024 0	444,484	15,424	730983	35-026	Diagnose Transmission - Main, Manual	31-Jan-2024 14:39:56	BVLOFC	B	DON	0.00
31-Jan-2024 0	444,484	15,424	736273	06-100-PMB	Inspect B PMI	05-Feb-2024 00:00:00	TRK022	P	DON	87.46
31-Jan-2024 0	444,484	15,424	736273	38-100-PMB	Service B PMI	05-Feb-2024 00:00:00	TRK022	P	DON	621.80
31-Jan-2024 0	444,484	15,424	736273	03-013-002	Replace Rear Brakes & Drums	04-Feb-2024 12:21:32	TRK022	B	DON	2,033.28
31-Jan-2024 0	444,484	15,424	736273	03-044-002	Replace Filters	02-Feb-2024 05:39:05	TRK022	B	DON	232.41
31-Jan-2024 0	444,484	15,424	736273	03-013-003	Replace Brake Chamber - Parking	02-Feb-2024 05:38:05	TRK022	B	DON	298.28
31-Jan-2024 0	444,484	15,424	736273	03-013-007	Replace Brake Lines & Fittings - Hydraulic & A	02-Feb-2024 05:40:25	TRK022	B	DON	135.92
31-Jan-2024 0	444,484	15,424	736273	95-026-001	Travel Transmission Case	02-Feb-2024 05:41:30	TRK022	B	DON	262.38
19-Feb-2024 0	444,484	15,424	740903	38-100-DOT	Service DOT Federal Inspection	19-Feb-2024 00:00:00	ME1287	P	DON	315.00
19-Feb-2024 0	444,484	15,424	740903	06-100-DOT	Inspect DOT Federal Inspection	19-Feb-2024 09:15:36	ME1287	P	DON	0.00
27-Feb-2024 0	444,484	15,424	742860	03-013-022	Replace Glad Hands (Service/Emergency)	27-Feb-2024 00:00:00	ME1287	N	DON	157.50
28-Mar-2024 0	444,484	15,424	749283	03-013-010	Replace Air Brake Valve		TRK022	B	CAN	0.00
28-Mar-2024 0	444,484	15,424	749283	07-010	Lubricate Chassis Group	02-May-2024 23:16:20	TRK028	P	DON	210.00
31-Jul-2024 10	465,462		776254	24-002-004	Repair Hood	12-Aug-2024 06:26:24	MPNSHP	N	DON	42.50
31-Jul-2024 10	465,462		776254	38-100-PMA	Service A PMI		MPNSHP	P	WR	8.32

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: C0384 - 2012 KENWORTH T800										
31-Jul-2024	10	465,462	776254	06-100-PMA	Inspect A PMI	01-Aug-2024 08:05:28	MPNSHP	P	DON	308.72
31-Jul-2024	10	465,462	776254	03-002-035	Replace Windshield Wiper & Washer	02-Aug-2024 14:30:05	MPNSHP	N	DON	30.25
31-Jul-2024	10	465,462	776254	14-036-014	Install Driver Risk Management Camera System	01-Aug-2024 08:14:05	MPNSHP	Q	DON	61.93
31-Jul-2024	10	465,462	776254	24-042-009	Repair Coolant Pre-Heater- Electrical		MPNSHP	N	WR	507.11
31-Jul-2024	10	465,462	776254	03-013-004	Replace Brake Chamber - Service		MPNSHP	N	WR	107.77
31-Jul-2024	10	465,462	776254	03-013-031	Replace Drain Valve - Air Tank	05-Aug-2024 07:26:16	MPNSHP	N	DON	39.40
31-Jul-2024	10	465,462	776254	14-002-067	Install Keys - Door / Ignition	02-Aug-2024 14:00:39	MPNSHP	N	DON	38.98
31-Jul-2024	10	465,462	776254	24-018-004	Repair Trailer, Converter, Tag & Pusher Axle Hi	09-Aug-2024 06:40:56	MPNSHP	N	DON	1,746.16
31-Jul-2024	10	465,462	776254	03-017-001	Replace Tire - Pneumatic	02-Aug-2024 08:40:27	MPNSHP	N	DON	5,836.93
31-Jul-2024	10	465,462	776254	24-059-001	Repair Fifth Wheel - Lower Coupler Assembly	12-Aug-2024 06:29:17	MPNSHP	N	DON	178.69
31-Jul-2024	10	465,462	776254	03-042-012	Replace Clamps and Hoses	09-Aug-2024 09:25:55	MPNSHP	N	DON	193.17
15-Aug-2024	C	465,463	779534	06-100-009	Inspect Safety Check	15-Aug-2024 08:47:20	BTRUCK	N	DON	67.87
15-Aug-2024	C	465,463	779534	03-017-001	Replace Tire - Pneumatic	16-Aug-2024 12:00:13	BTRUCK	N	DON	145.01
15-Aug-2024	C	465,463	779534	25-063-003	Remove Transceiver - GPS Tracker	16-Aug-2024 08:27:14	BTRUCK	Z	DON	53.53
15-Aug-2024	C	465,463	779534	25-051	Remove General Accessories	17-Aug-2024 06:21:05	BSETUP	Z	DON	283.69
15-Aug-2024	C	465,463	779534	02-002	Clean Cab & Sheet Metal	19-Aug-2024 10:03:15	BSETUP	Z	DON	393.72