

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: B3006 - 2016 F250 CREWCAB										
01-Aug-2016 1	60	0	254038	06-100-DOT	Inspect DOT Federal Inspection	05-Aug-2016 11:27:47	BTRUCK	P	DON	102.60
01-Aug-2016 1	60	0	254038	14-002-003	Install Running Boards / Step Tubes	04-Aug-2016 11:43:01	BSETUP	C	DON	348.52
01-Aug-2016 1	60	0	254038	14-002-059	Install Protector - Tail Gate	04-Aug-2016 15:28:03	BSETUP	C	DON	78.80
01-Aug-2016 1	60	0	254038	14-014-010	Install Toolbox Mounting		BSETUP	C	CAN	0.00
01-Aug-2016 1	60	0	254038	14-034-006	Install Warning Lamps - Special Application	04-Aug-2016 14:45:57	BSETUP	C	DON	571.34
01-Aug-2016 1	60	0	254038	14-044-001	Install Tank - Fuel, Liquid		BSETUP	C	CAN	0.00
01-Aug-2016 1	60	0	254038	14-052-003	Install Radio Equipment	03-Aug-2016 17:00:35	BSETUP	C	DON	1,356.47
01-Aug-2016 1	60	0	254038	14-052-014	Install Cellular Telephone Accessories	04-Aug-2016 06:49:07	BSETUP	C	DON	90.12
01-Aug-2016 1	60	0	254038	14-052-015	Install Power Inverter/Converter	03-Aug-2016 11:18:00	BSETUP	C	DON	330.24
01-Aug-2016 1	60	0	254038	14-053-005	Install Markings - Vehicle - Decals	04-Aug-2016 12:58:56	BSETUP	C	DON	157.43
01-Aug-2016 1	60	0	254038	14-053-014	Install Floor Mats	04-Aug-2016 15:12:11	BSETUP	C	DON	121.34
01-Aug-2016 1	60	0	254038	14-063-003	Install Transceiver - GPS Tracker	02-Aug-2016 10:59:53	BSETUP	Q	DON	0.00
01-Aug-2016 1	60	0	254038	14-071-011	Install Scuff Liner / Bed Mat	04-Aug-2016 08:17:33	BSETUP	C	DON	89.18
01-Aug-2016 1	60	0	254038	14-078-009	Install Mud Flaps and Hanger Brackets	04-Aug-2016 08:26:08	BSETUP	C	DON	92.47
01-Aug-2016 1	60	0	254038	14-078-012	Install Tie-Down - Tarpsulin	04-Aug-2016 12:03:51	BSETUP	J	DON	518.89
01-Aug-2016 1	60	0	254038	14-078-014	Install Tarpsulin/ Tonneau Cover	09-Aug-2016 12:02:58	BSETUP	C	DON	3.34
01-Aug-2016 1	60	0	254038	14-079-002	Install Headache Rack	04-Aug-2016 07:04:00	BSETUP	C	DON	247.52
01-Aug-2016 1	60	0	254038	14-506-001	Install Fuel Tank	04-Aug-2016 08:16:46	BSETUP	C	DON	856.51
01-Aug-2016 1	60	0	254038	14-510-002	Install Tool Box	04-Aug-2016 10:08:37	BSETUP	C	DON	429.19
01-Aug-2016 1	60	0	254038	14-517	Install Safety Equipment	04-Aug-2016 07:45:10	BSETUP	C	DON	150.01
11-Nov-2016 0	10,870	0	266371	20-706	Tow Power Unit	11-Jan-2017 14:41:31	MONSHP	A	DON	533.55
11-Nov-2016 0	10,870	0	266371	24-002-001	Repair Radiator Grille	11-Jan-2017 14:41:45	MONSHP	A	DON	14,016.35
11-Nov-2016 0	10,870	0	266371	14-016-005	Install Chassis Spring - Rear	29-Dec-2016 08:09:55	MONSHP	O	DON	610.06
11-Nov-2016 0	10,870	0	266371	38-100-PMA	Service A PMI	28-Dec-2016 12:40:34	MONSHP	P	DON	2.92
06-Jan-2017 11	10,345	0	288976	06-100-PMA	Inspect A PMI	06-Jan-2017 11:24:43	BVLOFC	P	DON	43.50
18-Mar-2017 1	18,126	0	290639	06-100-PMA	Inspect A PMI	18-Mar-2017 12:25:04	BVLOFC	P	DON	43.63
18-Mar-2017 1	18,126	0	290639	24-017-001	Repair Tire - Pneumatic	18-Mar-2017 12:26:12	BVLOFC	O	DON	30.16
20-Jun-2017 1:	25,292		300964	06-100-PMA	Inspect A PMI	20-Jun-2017 15:06:00	BVLOFC	P	DON	86.47
19-Jul-2017 08	27,220		297344	03-032-001	Replace Battery	20-Jul-2017 13:06:27	MONSHP	I	DON	140.99

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: B3006 - 2016 F250 CREWCAB										
03-Jan-2018 11	41,075	1,412	317994	03-017-001	Replace Tire - Pneumatic	03-Jan-2018 11:37:38	BTIRE	N	DON	1,098.95
12-Jan-2018 07	44,772	1,541	324263	06-100-PMA	Inspect A PMI	12-Jan-2018 07:14:00	BVLOFC	P	DON	91.82
07-Feb-2018 0	43,923	1,516	322638	03-002-024	Replace Glass / Windshield	07-Feb-2018 15:05:54	MONSHP	O	DON	301.08
30-May-2018 1	54,268	1,839	337625	06-100-PMB	Inspect B PMI	30-May-2018 10:40:27	MONSHP	P	DON	42.74
01-Sep-2018 1	66,100	2,308	355522	06-100-PMA	Inspect A PMI	01-Sep-2018 11:21:00	BVLOFC	P	DON	116.23
22-Feb-2019 0	76,074	2,664	373655	03-002-024	Replace Glass / Windshield	26-Feb-2019 13:59:53	MONSHP	O	DON	262.62
08-Mar-2019 0	77,499	2,712	375716	06-100-PMA	Inspect A PMI	08-Mar-2019 09:18:23	BVLOFC	P	DON	54.69
01-Apr-2019 0	79,324	2,775	379007	03-013-001	Replace Front Brakes & Drums	03-Apr-2019 10:01:45	MONSHP	I	DON	149.13
01-Apr-2019 0	79,324	2,775	379007	03-013-002	Replace Rear Brakes & Drums	03-Apr-2019 10:01:49	MONSHP	I	DON	217.84
01-Apr-2019 0	79,324	2,775	379007	06-100-DOT	Inspect DOT Federal Inspection	03-Apr-2019 10:01:42	MONSHP	P	DON	18.92
01-Apr-2019 0	79,324	2,775	379007	24-034-004	Repair Clearance & Marker Lamps	03-Apr-2019 10:01:52	MONSHP	I	DON	8.51
08-Nov-2019 1	94,783	3,223	411822	06-100-PMA	Inspect A PMI	11-Nov-2019 08:42:13	MONSHP	P	DON	0.00
08-Nov-2019 1	94,783	3,223	411822	38-100-PMA	Service A PMI	08-Nov-2019 11:15:44	MONSHP	P	DON	73.42
21-Apr-2020 0	110,584	3,580	436931	06-100-DOT	Inspect DOT Federal Inspection	21-Apr-2020 09:18:57	MONSHP	P	DON	17.01
21-Apr-2020 0	110,584	3,580	436931	06-100-PMB	Inspect B PMI	21-Apr-2020 09:18:39	MONSHP	P	DON	8.51
21-Apr-2020 0	110,584	3,580	436931	24-034-004	Repair Clearance & Marker Lamps	21-Apr-2020 09:19:05	MONSHP	I	DON	42.53
21-Apr-2020 0	110,584	3,580	436931	38-100-PMB	Service B PMI	21-Apr-2020 09:18:48	MONSHP	P	DON	44.33
18-Jun-2020 0	112,975	3,699	446303	24-001	Repair Air Conditioning, Heating & Ventilating	26-Jun-2020 13:19:53	MONSHP	O	DON	161.60
24-Jun-2020 1	113,045	3,701	447315	03-017-001	Replace Tire - Pneumatic	10-Jul-2020 10:05:45	BTIRE	P	DON	1,194.08
19-Jan-2021 0	125,912	4,107	483095	03-041-007	Replace Filter - Outer	19-Jan-2021 08:22:46	BVLOFC	P	DON	38.98
19-Jan-2021 0	125,912	4,107	483095	06-100-PMA	Inspect A PMI	19-Jan-2021 08:22:46	BTRUCK	P	DON	0.00
19-Jan-2021 0	125,912	4,107	483095	38-100-PMA	Service A PMI	19-Jan-2021 08:22:46	BVLOFC	P	DON	71.11
18-Jun-2021 0	135,341	4,816	513530	03-002-024	Replace Glass / Windshield	02-Jul-2021 10:48:41	FKVSHP	O	DON	370.29
18-Jun-2021 0	135,341	4,816	513530	03-013-001	Replace Front Brakes & Drums	22-Jun-2021 06:52:48	FKVSHP	O	DON	362.57
18-Jun-2021 0	135,341	4,816	513530	03-013-037	Replace Caliper - Front	21-Jun-2021 16:59:52	FKVSHP	O	DON	129.33
18-Jun-2021 0	135,341	4,816	513530	03-051-009	Replace Fire Extinguisher	21-Jun-2021 07:18:57	FKVSHP	I	DON	21.26
18-Jun-2021 0	135,341	4,816	513530	06-100-DOT	Inspect DOT Federal Inspection	21-Jun-2021 09:13:24	FKVSHP	P	DON	23.74
18-Jun-2021 0	135,341	4,816	513530	06-100-PMA	Inspect A PMI	02-Jul-2021 10:48:39	FKVSHP	P	DON	0.00
18-Jun-2021 0	135,341	4,816	513530	38-100-PMA	Service A PMI	18-Jun-2021 17:06:59	FKVSHP	P	DON	151.08

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: B3006 - 2016 F250 CREWCAB										
18-Jun-2021 0	135,341	4,816	513530	06-013	Inspect Brakes	21-Jun-2021 17:04:38	FKVSHP	O	DON	204.49
18-Jun-2021 0	135,341	4,816	513530	31-018-003	Rotate Wheels	21-Jun-2021 08:41:04	FKVSHP	P	DON	58.10
18-Jun-2021 0	135,341	4,816	513530	14-053-017	Install First Aid Kit	21-Jun-2021 07:19:52	FKVSHP	I	DON	19.48
02-Dec-2021 1	151,477	5,729	550641	03-063-003	Replace Transceiver - GPS Tracker	02-Dec-2021 14:00:29	ELEC03	Q	DON	319.70
06-Jan-2022 0	153,962	5,915	557405	03-013-002	Replace Rear Brakes & Drums	07-Jan-2022 08:17:51	MONSHP	I	DON	262.96
06-Jan-2022 0	153,962	5,915	557405	03-013-032	Replace ABS - ECU	10-Jan-2022 14:34:43	MONSHP	I	DON	162.99
06-Jan-2022 0	153,962	5,915	557405	03-033-002	Replace Distributor / Coil Pack	07-Jan-2022 08:17:44	MONSHP	I	DON	1,112.38
06-Jan-2022 0	153,962	5,915	557405	03-034	Replace Lighting System	10-Jan-2022 14:34:59	MONSHP	I	DON	15.06
06-Jan-2022 0	153,962	5,915	557405	06-100-PMB	Inspect B PMI	07-Jan-2022 08:17:37	MONSHP	P	DON	159.89
06-Jan-2022 0	153,962	5,915	557405	38-100-PMB	Service B PMI	07-Jan-2022 08:17:41	MONSHP	P	DON	107.32
24-Feb-2022 1	153,968		569769	03-002-068	Replace Service Body / Utility Box	24-Feb-2022 14:39:58	MONSHP	O	DON	126.38
24-Mar-2022 2	156,479		577489	24-052-003	Repair Radio Equipment	26-Mar-2022 21:36:57	TRK026	O	DON	156.84
25-Mar-2022 0	156,351		577205	06-100-PMA	Inspect A PMI	25-Mar-2022 07:02:10	BVLOFC	P	DON	0.00
25-Mar-2022 0	156,351		577205	38-100-PMA	Service A PMI	25-Mar-2022 07:02:10	BTRUCK	P	DON	87.04
08-Apr-2022 0	158,492		580506	03-017-001	Replace Tire - Pneumatic	29-Apr-2022 16:16:08	BVLOFC	P	DON	1,461.21
08-Apr-2022 0	158,492		580506	06-100-PMA	Inspect A PMI	19-Apr-2022 06:26:40	BVLOFC	P	DON	0.00
08-Apr-2022 0	158,492		580506	38-100-PMA	Service A PMI	19-Apr-2022 06:26:40	BVLOFC	P	DON	89.09
11-Apr-2022 0	159,187		581773	03-013-001	Replace Front Brakes & Drums	11-Apr-2022 00:00:00	ME1287	B	DON	80.79
22-Apr-2022 0	161,844		583944	03-015-005	Replace Power Steering Pump	02-May-2022 09:32:06	TRK026	I	DON	456.61
09-May-2022 ;	164,714		588367	03-TLS-521	Replace Fuel Pumps	12-May-2022 20:06:21	TRK026	I	DON	812.43
09-May-2022 ;	164,714		588367	06-100-PMA	Inspect A PMI	18-May-2022 14:58:29	TRK026	P	DON	0.00
09-May-2022 ;	164,714		588367	38-100-PMA	Service A PMI	18-May-2022 14:58:34	TRK026	P	DON	109.98
06-Jun-2022 1	166,170		595171	06-100-DOT	Inspect DOT Federal Inspection	11-Jun-2022 11:19:33	TRK026	P	DON	156.84
17-Jun-2022 0	166,565		596742	03-045-026	Replace Tensioner - Engine Belts	29-Jun-2022 07:48:19	BVLOFC	I	DON	334.20
17-Jun-2022 0	166,565		596742	03-045-027	Replace Idler Pulley	29-Jun-2022 07:48:27	BVLOFC	I	DON	250.65
17-Jun-2022 0	166,565		596742	24-002-017	Repair Cab Or Front Door Panels	06-Sep-2022 14:14:00	BVLOFC	A	DON	3,285.03
23-Aug-2022 C	167,079		611810	95-002-017	Travel Cab Or Front Door Panels	24-Aug-2022 20:09:14	TRK026	O	DON	261.40
07-Sep-2022 0	167,097		614927	24-002-017	Repair Cab Or Front Door Panels	11-Sep-2022 20:04:44	TRK022	A	DON	0.00
07-Sep-2022 0	167,097		614927	95-002-019	Travel Side Door Panels & Ramps	08-Sep-2022 17:59:26	TRK026	A	DON	418.23

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: B3006 - 2016 F250 CREWCAB										
14-Oct-2022	169,782		624585	03-002-035	Replace Windshield Wiper & Washer	16-Oct-2022 13:20:02	TRK026	O	DON	24.07
26-Oct-2022	170,788	6,928	628174	06-100-PMA	Inspect A PMI	29-Oct-2022 08:00:28	TRK026	P	DON	0.00
26-Oct-2022	170,788	6,928	628174	38-100-PMA	Service A PMI	29-Oct-2022 08:00:34	TRK026	P	DON	241.03
26-Oct-2022	170,788	6,928	628174	03-002-035	Replace Windshield Wiper & Washer	29-Oct-2022 07:59:53	TRK026	I	DON	10.07
26-Oct-2022	170,788	6,928	628174	03-034-002	Replace Stop, Tail, Turn & License	30-Oct-2022 08:27:29	TRK026	I	DON	143.89
26-Oct-2022	170,788	6,928	628174	95-034-002	Travel Stop, Tail, Turn & License	30-Oct-2022 08:28:08	TRK026	I	DON	156.84
14-Nov-2022	172,316		632841	24-034-001	Repair Headlamps / Fog Lamps	16-Nov-2022 06:36:16	TRK026	I	DON	187.29
20-Nov-2022	172,723		633824	03-002-035	Replace Windshield Wiper & Washer	09-Dec-2022 06:05:49	TRK026	I	DON	33.65
01-Feb-2023	177,915		649746	03-002-035	Replace Windshield Wiper & Washer	01-Feb-2023 13:07:55	BVLOFC	I	DON	25.48
01-Feb-2023	177,915		649746	06-100-PMA	Inspect A PMI	01-Feb-2023 13:07:55	BVLOFC	P	DON	0.00
01-Feb-2023	177,915		649746	38-100-PMA	Service A PMI	01-Feb-2023 13:07:55	BVLOFC	P	DON	87.64
13-Mar-2023	181,080		660159	06-100-PMA	Inspect A PMI	18-Mar-2023 18:20:34	TRK026	P	DON	0.00
13-Mar-2023	181,080		660159	38-100-PMA	Service A PMI	18-Mar-2023 18:20:41	TRK026	P	DON	338.55
06-Apr-2023	183,152		665402	03-013-001	Replace Front Brakes & Drums	15-Apr-2023 09:49:31	TRK026	B	DON	545.01
06-Apr-2023	183,152		665402	03-013-002	Replace Rear Brakes & Drums	07-Apr-2023 13:11:21	TRK026	B	DON	591.98
06-Apr-2023	183,152		665402	03-013-028	Replace Shoe - Parking Brake	11-Apr-2023 17:13:50	TRK026	I	DON	486.93
06-Apr-2023	183,152		665402	95-013-001	Travel Front Brakes & Drums	15-Apr-2023 09:52:51	TRK026	B	DON	196.79
06-Apr-2023	183,152		665402	95-013-002	Travel Rear Brakes & Drums	08-Apr-2023 18:47:43	TRK026	I	DON	131.19
20-Apr-2023	184,615		668847	03-059-002	Replace Pintle Hook Assembly	30-Apr-2023 15:21:09	TRK028	N	DON	131.19
03-May-2023	186,342		672028	06-100-PMA	Inspect A PMI	04-May-2023 16:24:00	TRK028	P	DON	0.00
03-May-2023	186,342		672028	38-100-PMA	Service A PMI	04-May-2023 16:24:00	TRK028	P	DON	312.04
03-May-2023	186,342		672028	06-100-DOT	Inspect DOT Federal Inspection	04-May-2023 16:24:56	TRK028	P	DON	131.19
03-May-2023	186,342		672028	06-016	Inspect Suspension	16-May-2023 09:30:25	TRK028	E	DON	174.92
03-May-2023	186,342		672028	02-016	Clean Suspension	14-May-2023 20:07:02	TRK028	E	DON	349.84
03-May-2023	186,342		672028	95-016	Travel Suspension	16-May-2023 09:30:19	TRK028	E	DON	306.11
03-May-2023	186,342		672028	03-015-012	Replace Steering Stability System	16-May-2023 09:30:12	TRK028	E	DON	183.18
11-Jul-2023	188,333	8,058	687067	03-017-001	Replace Tire - Pneumatic	18-Jul-2023 15:47:01	BTRUCK	I	DON	1,025.05
11-Jul-2023	188,333	8,058	687067	06-100-009	Inspect Safety Check	12-Jul-2023 16:30:25	BTRUCK	P	DON	65.84
11-Jul-2023	188,333	8,058	687067	03-042-002	Replace Radiator	18-Jul-2023 12:01:08	BTRUCK	I	DON	645.50

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: B3006 - 2016 F750 CREWCAB										
11-Jul-2023 08	188,333	8,058	687067	24-001-012	Repair Condenser Assembly	18-Jul-2023 07:21:16	BTRUCK	I	DON	99.90
11-Jul-2023 08	188,333	8,058	687067	03-014-004	Replace Cab & Body Mountings	17-Jul-2023 17:00:50	BTRUCK	I	DON	86.21
11-Jul-2023 08	188,333	8,058	687067	24-043-007	Repair Exhaust Pipe/Elbow	18-Jul-2023 17:00:16	BTRUCK	I	DON	68.12
11-Jul-2023 08	188,333	8,058	687067	14-051-009	Install Fire Extinguisher	17-Jul-2023 14:29:56	BTRUCK	Q	DON	44.88
11-Jul-2023 08	188,333	8,058	687067	03-018-001	Replace Front Axle Hubs & Bearings	17-Jul-2023 16:22:22	BTRUCK	I	DON	525.19
11-Jul-2023 08	188,333	8,058	687067	06-100-PMB	Inspect B PMI	17-Jul-2023 13:12:07	BTRUCK	P	DON	10.66
11-Jul-2023 08	188,333	8,058	687067	38-100-PMA	Service A PMI	17-Jul-2023 14:18:32	BTRUCK	P	DON	148.11
11-Jul-2023 08	188,333	8,058	687067	24-052-003	Repair Radio Equipment	19-Jul-2023 08:31:48	BTRUCK	I	DON	279.95
11-Jul-2023 08	188,333	8,058	687067	24-013-034	Repair Parking Brake - Complete	19-Jul-2023 10:05:09	BTRUCK	I	DON	184.53
11-Jul-2023 08	188,333	8,058	687067	03-043-002	Replace Exhaust Manifold	18-Jul-2023 15:30:54	BTRUCK	I	DON	358.22
11-Jul-2023 08	188,333	8,058	687067	03-002-035	Replace Windshield Wiper & Washer	17-Jul-2023 14:24:16	BTRUCK	I	DON	23.25
11-Jul-2023 08	188,333	8,058	687067	24-034-002	Repair Stop, Tail, Turn & License	18-Jul-2023 05:25:22	BTRUCK	I	DON	16.15
11-Jul-2023 08	188,333	8,058	687067	02-002	Clean Cab & Sheet Metal	24-Jul-2023 09:37:24	BSETUP	N	DON	273.72
11-Jul-2023 08	188,333	8,058	687067	03-053-005	Replace Markings - Vehicle - Decals	20-Jul-2023 11:48:07	BSETUP	I	DON	62.85
11-Jul-2023 08	188,333	8,058	687067	03-034-006	Replace Warning Lamps - Special Application	20-Jul-2023 11:10:44	BSETUP	Q	DON	31.61
11-Jul-2023 08	188,333	8,058	687067	12-002-003	Refinish Running Boards / Step Tubes	20-Jul-2023 16:00:02	BSETUP	I	DON	119.24
11-Jul-2023 08	188,333	8,058	687067	14-510-002	Install Tool Box	20-Jul-2023 15:07:17	BSETUP	C	DON	119.94
11-Aug-2023 0	189,159		696044	14-051-009	Install Fire Extinguisher	11-Aug-2023 12:03:05	BEDSHP	Q	DON	18.60
11-Aug-2023 0	189,159		696044	06-037-021	Inspect Circuit Breaker/Fuse - Multiple Use	11-Aug-2023 11:40:31	BEDSHP	O	DON	55.80
11-Aug-2023 0	189,159		696044	03-037-001	Replace Modules - Multiple Use	12-Sep-2023 08:48:34	BEDSHP	I	DON	0.00
15-Nov-2023 C	191,929		720880	03-031-001	Replace Generator/Alternator	15-Nov-2023 16:09:50	BEDSHP	B	DON	362.91
15-Nov-2023 C	191,929		720880	06-031-001	Inspect Generator/Alternator	15-Nov-2023 16:04:51	BEDSHP	B	DON	93.00
10-Jan-2024 0	193,535		731486	06-100-PMA	Inspect A PMI	10-Jan-2024 13:15:20	BEDSHP	P	DON	18.60
10-Jan-2024 0	193,535		731486	38-100-PMA	Service A PMI	10-Jan-2024 13:15:23	BEDSHP	P	DON	110.32
09-Feb-2024 0	194,618		738014	03-032-002	Replace Starter	13-Feb-2024 13:27:46	BEDSHP	N	DON	296.33
08-Apr-2024 0	196,624		751041	03-044-027	Replace Nozzle - Fuel Auxiliary	09-Apr-2024 13:32:13	BEDSHP	N	DON	76.80
15-May-2024 (196,710		759832	06-100-DOT	Inspect DOT Federal Inspection	15-May-2024 09:43:42	MTIFLD	P	DON	52.50
15-May-2024 (196,710		759832	06-100-PMB	Inspect B PMI	15-May-2024 09:43:45	MTIFLD	P	DON	78.75
15-May-2024 (196,710		759832	03-032-001	Replace Battery	15-May-2024 09:43:48	MTIFLD	N	DON	225.87

Unit Job History

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: B3006 - 2016 F250 CREWCAB										
13-Jul-2024 07	196,712	8,726	772122	06-100-009	Inspect Safety Check	13-Jul-2024 08:26:40	BTRUCK	N	DON	43.74
25-Jul-2024 07	196,712	8,726	774772	02-002	Clean Cab & Sheet Metal	30-Aug-2024 06:17:57	BSETUP	Z	DON	145.50
25-Jul-2024 07	196,712	8,726	774772	25-051	Remove General Accessories	26-Jul-2024 09:34:37	BSETUP	Z	DON	253.69

47,443.28

Count: 148

Unit No: B3006